

CITY OF RANCHO PALOS VERDES MASTER PLAN OF DRAINAGE

Michael Baker
INTERNATIONAL

TECHNICAL APPENDIX C

CCTV INSPECTIONS

CITY OF RANCHO PALOS VERDES MASTER PLAN OF DRAINAGE

Michael Baker
INTERNATIONAL

TECHNICAL APPENDIX C-1

**CCTV INSPECTIONS
2014-2015**

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
1	1	1	1	1955	18" CMP	Pipe runs along 5503 Graylog property from CB located at end of Graylog cul-de-sac to OS behind the property	SM-PVN-SD-CB1609-GB2656, SM-PVN-SD-GB2656-SD-GB2659-GB2659, SM-PVN-SD-GB2659-JS1604	CB1609 to JS1604	189	189	6/4/14	Heavy corrosion throughout the pipe. CMP pipe deformed (~40%) at 93'. The first 85' of line is RCP; the rest is CMP. CMP is heavily corroded. Inspection abandoned due to void at 120'
2	2	2	2	1955	30" RCP & 24" CMP	Pipe starts at CB in front of 5417 Bayridge to OS on 5507 Graylog St. property	ML-PVN-SD-CB1607-CB1608	CB1608 to OS1610	120	350	6/4/14	Heavy corrosion throughout the pipe. Missing invert from 0' to 6'; abandoned due to hole at 221.5'.
3	3	3	3	1955	18" CMP	Pipe starts from CB at end of Bayridge cul-de-sac to OS in the canyon behind property	ML-PVN-SD-CB1603-GB2660, ML-PVN-SD-GB2660-GB2661, ML-PVN-SD-GB2661-OS1602, SM-PVN-SD-CB1602-OS1602, SM					

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
30	30	291	60		18" RCP & CMP	Line starts at CB in front of property to MH in front of 31033 Hawthorne Dr.	SM-OSE-SD-CB0411-GB0410, SM-OSE-SD-GB0410-GB2375, SM-OSE-SD-GB2375-MH0409	CB0411 to MH0409	191	455	9/16/14	The first 200' from MH0409 are RCP in good condition. 18" CMP starts thereafter; paved invert has been washed off (light corrosion). The first 110' from CB0411 are RCP in good condition. CMP starts thereafter; paved invert has been washed off (light corrosion). Inspection abandoned at 190' due to hole in the pipe.
31	31	301	39		48" CMP	Line runs from CB at corner of PVOS and Div Road to OS on southeast corner of PVOS & Seaview	SM-OSW-SD-CB0666-CB0665	CB0666 to OS0666-JS0666 / MH0660	85	85	9/12/14	Holes at various locations. Heavy corrosion throughout pipe.
32	32	330	37		30" CMP	Line starts at IS approx. 540' east of Crestmont on PVOS westbound approx. 475' west of Crestmont	SM-OSW-SD-IS0636-CB0634	IS0636 to CB0634	15	95	8/28/14	Heavy corrosion throughout pipe. Hole at 5'. Inspection abandoned at 14.7' due to hole in pipe
33	33	341	36		18" CMP	Line starts at IS approx. 255' east of Crestmont on PVOS westbound to CB on median east of Crestmont		IS0642 to CB0638	19	90	9/2/14	Inspection abandoned due to hole in pipe at 19'. Medium corrosion throughout the pipe. The first 15.5' of pipe is RCP from CB0543; the rest is CMP. The first 10' from CB are RCP; the rest of the pipe is at 17.3'. Missing invert at beginning of inspection from CB0544.
34	34	341	36		30" RCP & 30" CMP	Line runs from CB 800' west of Crestmont to CB on PVOS median eastbound	SM-OSW-SD-CB0544-CB0543	CB0544 to CB0543	17	95	9/12/14	Heavy corrosion. Missing invert throughout the pipe. Inspection abandoned at 63' due to heavy sediment & debris in pipe -50%. Holes at various locations: 11.4', 17.7', 29.6' & 50.5'. Deformed pipe at 25.3'; top portion of pipe is broken. Survey abandoned due to debris blockage -95% (mainly sand and rocks).
35	35	350	56		18" CMP	Line starts at CB on cul-de-sac end to OS on back of property	LA-LAN-SD-CB0925-OS0926	CB0925 to OS0926	63	150		
36	36	360	55		24" CMP	Line runs from 28935 PVODE to 28956 PVODE		CB0933 to OS0933	60	7	12/15/14	
37	37	4	1	1955	18" CMP	Line runs from CB in front of 26307 Silver Spur to OS in canyon	ML-PVN-SD-CB1600-OS1599	CB1600 to OS1599	125	125	6/4/14	Heavy corrosion throughout the pipe.
38	38	2	3	1960	30" CMP	Pipe runs along center of road from MH in front of 5910 Ironwood to MH in front of 5824 Ironwood	SM-PVN-SD-MH1590-MH1592	MH1590 to MH1592	173	173	6/3/14	Heavy corrosion throughout the pipe.
39	39	3	1	1960	18" CMP	Line runs from CB in front of 5823 Ironwood to MH in front of 5824 Ironwood	SM-PVN-SD-CB1591-MH1592	CB1591 to MH1592	24	24	6/3/14	Heavy corrosion throughout the pipe.
40	40	4	3	1960	18" CMP	Line runs from CB 1593 in front of 5916 Ironwood to JS3559	SM-PVN-SD-CB1593-JS3559	CB1593 to JS3559	10	10	6/3/14	Heavy corrosion throughout the pipe.
41	41	5	3	1960	30" CMP	Line runs from 28309 Barkstone Dr. to OS behind 28359	SM-PVN-SD-MH1593-TS1579, SM-PVN-SD-TS1579-TS3560, SM-PVN-SD-TS3560-OS1596	MH1593 to OS1596	217	217	6/9/14	Heavy corrosion throughout the pipe.
42	42	6	3	1960	18" CMP	Line runs from CB in front of 5913 Ironwood to MH in corner of same property	SM-PVN-SD-CB1594-MH1595	CB1594 to MH1595	18	18	6/3/14	Heavy corrosion throughout the pipe.
43	43	7	8		18" RCP	Hawthorne southbound to CB across Hawthorne northbound	ML-RHE-SD-CB3324-MH3328	MH3328 to CB3324	53	53	9/4/14	Hard deposits -40% from 17' to 36'. Pipe is in good condition.
44	44	8	10		24" CMP	Line runs from JS on Silver Spur behind 5745 De La Brea to OS on Silver Spur	ML-RHE-SD-CB3341-JS3140	CB3341 to JS3140	19.6	20	6/20/14	Heavy corrosion throughout the pipe.
45	45	9	12		18" CMP	Line runs from CB in front of 27900 Loma Dr. to JS in the middle of Loma Dr.	SM-PVN-SD-CB3032-JS3042	CB3032 to JS3042	27	27	6/12/14	Pipe has been lined previously; lining is severely wrinkled. The first 248' from JS2060 is RCP in good condition. Unmapped MH & CB at 248'. Pipe is CMP from 248' to 255'; this line is heavily corroded.
46	46	10	20		30" RCP & 30" CMP	Line runs from MH approx. 245' south of intersection to JS approx. 525' northwest	ML-RHE-SD-JS2060-MH1001	MH1001 to JS2060	559	559	8/20/14	
47	47	11	20		36" CMP	Line runs from CB in front of property to OS in property backyard	ML-RHE-SD-MH3488-OS1015	MH3488 to OS1015	81.5	82	8/20/14	Heavy corrosion throughout the pipe.
48	48	12	22		24" RCP	Line runs from MH adjacent to home on Greenhaw trail to OS in canyon	SM-OSS-SD-MH3475-OS3476	MH3475 to OS3476	249	249	7/29/14	Pipe rebar is exposed (top of the pipe) at the beginning of the pipe from 3' to 7'. The rest of the pipe is in good condition.
49	49	13	24		30" CMP	Line starts at CB approx. 110' east of intersection to CB approx. 30' west	SM-OSW-SD-CB1060-CB1061	CB1060 to CB1061	30	30	8/18/14	Heavy corrosion throughout the pipe.
50	50	14	25		30" RCP & 30" CMP	Line runs from MH 240' west of Sea Terrace to CB 75' north across Crest westbound	SM-OSW-SD-JS2919-TS2920, SM-OSW-SD-TS3202A-MH2645	CB1070 to MH2645	63	63	8/15/14	The first 22' from CB are CMP; heavily corroded. The rest of the pipe is RCP in good condition.
51	51	15	27		60" CMP	Line runs from MH on Hawthorne northbound to OS in canyon (east side of Hawthorne) to OS in canyon west side of Hawthorne	SM-PVN-SD-JS2915-OS1432, SM-PVN-SD-MH1433-JS2915, SM-PVN-SD-MH1434-MH1433	MH1434 to OS1432	203	7	8/25/14	Heavy corrosion throughout the pipe. Survey abandoned at 203' due to bulk blocked and unnecessary. Holes at 269', 271', 281' and 303' from JS. Missing invert at the end of the pipe from 303' to approx. 310'.
52	52	16	27		48" CMP	Line runs from CB 110' east of Hawthorne on Crest eastbound to CB 30' west	SM-PVN-SD-OS1106-JS1102	JS1102 to OS1106	303	310	9/3/14	Heavy corrosion throughout the pipe.
53	53	17	28		30" CMP	Line runs from CB 80' east of Hawthorne on Crest eastbound to CB 30' west	SM-OWW-SD-CB1088-CB1095	CB1088 to CB1095	24	25	8/19/14	Heavy corrosion throughout the pipe.
54	54	18	28		30" CMP	Line runs from CB 45' east of Hawthorne on Crest eastbound to JS in the middle of Hawthorne	SM-OWW-SD-JS2901-MH2679	CB1095 to CB1089	31	31	8/19/14	Heavy corrosion throughout the pipe.
55	55	19	28		30" RCP	Line runs from JS on Hawthorne southbound to JS 505' south	SM-OWW-SD-CB1089-JS2901	CB1089 to JS2901	82	82	8/19/14	Heavy corrosion throughout the pipe.
56	56	20	28		36" CMP	Line runs from Los Verdes Dr. to CB across Hawthorne on southbound side	SM-OWW-SD-JS2901-MH2679	JS2901 to JS2679	527	527	8/19/14	Medium to heavy corrosion throughout the pipe.
57	57	21	31		30" RCP & 30" CMP	Line runs from CB at southeast corner to MH at southwest corner	SM-OWW-SD-CB1115-CB1154	CB1115 to CB1154	79	79	8/21/14	Heavy corrosion throughout the pipe.
58	58	22	33		30" RCP & 30" CMP	Line runs from CB on PVODE at Bronco to JS on Bronco at PVODE	SM-OWW-SD-CB3306-MH3484, LA-LAN-SD-CB0891-GB3451, LA-LAN-SD-GB3451-JS3450	CB3306 to MH3484	161	161	8/25/14	The first 10' from CB are RCP; the rest of the pipe is CMP. Heavy corrosion throughout the pipe.
59	59	23	54		18" RCP	Line starts at CB on Western southbound to mainline	LA-LAE-SD-CB0043-JS45732	CB0043 to Mainline	5	50	9/25/14	Debris at pipe junction (~80% obstruction); plastic blocking most of the pipe.
60	60	24	56		18" CMP	Line starts at IS north of PVOS (approx. 450' west of PVODE) to OS south of PVOS	SM-OSE-SD-IS0020-GB2699, SM-OSE-SD-TS0319-GB3478	IS0020 to OS0319	363	363	8/11/14	Inspection abandoned due to hole at the beginning of the pipe. Hole in pipe at 123'; rebar is visible from 11' to 1'. Joint separation at 165'. The rest of the pipe is in good condition.
61	61	25	49		48" RCP	Line runs from CB on northwest corner to OS across PVOS	SM-OSS-SD-CB03456-GB03459	CB3456 to ??	111	111	8/29/14	Separated pipe at 111'; soil is visible.
62	62	26	41		24" CMP	Line runs from CB 475' west of Crestmont to CB on median west of Crestmont	SM-OSW-SD-CB0538-CB0539	CB0538 to CB0539	83.5	84	9/2/14	Medium corrosion throughout the pipe. Hole on left side of pipe at 17'. Large joint offset at 81' (water standing). Medium corrosion throughout the pipe.
63	63	27	343		24" CMP & 18" RCP	Line runs from 6003 Lightfoot Pl to MH behind 6007 Via Sonoma Property	SM-PVN-SD-CB1570-MH1566, SM-PVN-SD-MH1566-MH1572	CB1570 to MH1572	545	545	6/9/14	Moderate corrosion throughout the pipe.
64	64	1	15	1962								

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments (Phase II)	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
65	2	12	4	1962	18" CMP	Pipe runs along 6007 Via Sonoma property from CB at end of cul-de-sac to MH behind property	SM-PVN-SD-CB1567-MH1566	CB1567 to MH1566	100	100	6/9/14	Existing lining is wearing off. Visible corrosion through the pipe. RCP line from 0' to 239' (end of RCP line) looks in good condition. 38" CMP starts at 239' and ends at 583.6'; moderate corrosion throughout.
66	3	45	11	HAVE PLANS 24370	36" RCP & 30" CMP	RCP Pipe runs along center of roadway then transitions to CMP before running along prop line and into canyon drainage	SM-PVN-SD-JS3396-CB3397, SM-PVN-SD-CB3397-CB1575, SM-PVN-SD-CB1575-CB1574, SM-PVN-SD-CB1574-CB3396, SM-PVN-SD-CB3396-CB1573	CB4426 to JS3396 to OS1573	583	584	6/11/14	
67	4	65.1	15		18" RCP	Line runs from CB on Hawthorne median at Blackhorse to MH on Hawthorne median	ML-RHE-SD-CB1510-MH1489, ML-RHE-SD-MH1489-JS48130, ML-RHE-SD-JS48130-MH1521	MH1519 to MH1521	511	511	9/5/14	Longitudinal crack on both sides of the pipe at 0' to 5'. Joint offset medium at 225'
68	5	80	19		18" RCP	Line starts at CB in front of property to CB across Middle Crest Rd.	ML-RHE-SD-CB1011-JS2683, ML-RHE-SD-JS2683-JS2684, ML-RHE-SD-JS2684-JS2684	CB1011 to CB1012	26	26	7/30/14	Medium to heavy corrosion throughout the pipe
69	6	80	20		30" RCP	Line runs from CB on southwest corner of intersection to MH approx. 245' south	ML-RHE-SD-CB1027-MH1001	CB1027 to MH1001	240	240	8/20/14	Hard deposits (minimum) from 216' to 228'. Overall pipe looks clean and in good condition.
70	7	88	20		30" RCP	Line runs from MH approx. 245' south of intersection to MH across Cranshaw northbound	ML-RHE-SD-MH1001-JS21820, ML-RHE-SD-JS21820-MH3518	MH1001 to MH3518	83	83	8/20/14	The RCP line is clean and in good condition. Line has a small CMP section from 54.6' to 57'; this section has medium corrosion.
71	8	90	20		18" RCP	Line runs from CB in the median approx. 212 south of intersection to CB across Cranshaw northbound	ML-RHE-SD-CB1002-CB1022	CB1002 to CB1022	47.5	48	8/21/14	Pipe has a fracture around its circumference at 2'. Broken pipe at 17' from S to 9 o'clock.
72	9	99	22		18" RCP	Line starts at CB in parking lot to CB across Park Pl	SM-OSS-SD-CB0978-CB0979	CB0978 to CB0979	25	25	7/28/14	Circumferential crack at the beginning of the pipe. Overall pipe is in good condition.
73	10	100	22		24" RCP	Line runs from CB in parking lot to OS in canyon	SM-OSS-SD-CB0979-OS0980	CB0979 to OS0980	172	?	7/28/14	Overall pipe is in good condition. Standing water at 172' approx. 95% (inspection abandoned).
74	11	117	24		36" CMP	Line starts at CB approx. 30' east of intersection to CB approx. 30' west	SM-OSW-SD-CB1061-CB1062	CB1061 to CB1062	27	27	8/19/14	Medium corrosion throughout the pipe.
75	12	118	24		30" CMP	Line starts at CB intersection to TS on southeast corner of intersection	SM-OSW-SD-CB1062-JS2677	CB1062 to JS2677	123	123	8/19/14	Medium corrosion throughout the pipe.
76	13	129	25		30" CMP	Line runs from MH in the middle of the road (Crest eastbound) to MH 130' west in middle of road	SM-OSW-SD-MH1342-MH1079	MH1342 to MH1079	119	119	8/15/14	Medium corrosion throughout the pipe.
77	14	182	31		24" CMP	Line starts at CB on Hawthorne northbound 285' north of Los Verdes Dr. to CB 30' south	SM-OWW-SD-CB1114-CB1115	CB1114 to CB1115	29	29	8/21/14	Medium to heavy corrosion throughout the pipe.
78	15	200	50		18" RCP	Ponlevedra Dr. property to CB on De La Soria (southwest corner of intersection)	LA-LAE-SD-CB0166-CB0167	CB0166 to CB0167	63.4	64	5/20/14	Hard deposits from 8' to 9'. Moderate corrosion. Line from CB0167 to JS2561 at 73.1' has been lined previously. Line from JS2561 to CB0166 has medium corrosion. Voids at 201' ft. Last 15' of pipe has sediment and debris.
79	16	242	55		18" CMP	Line starts at CB at the end of the cul-de-sac to OS behind 28684 Road Rd. property	LA-LAN-SD-CB0887-JS3561, LA-LAN-SD-JS3561-OS0888	CB0887 to OS0888	220	220	6/2/14	Line runs from CB0887 to OS0888 (medium corrosion) Pipe is lined up to 130.5 ft. Fractured pipe at 109 ft. & at 130 ft. No lining after 130.5 ft (medium corrosion).
80	17	244	55		18" CMP	Line starts at CB north of 28800 PVDE to JS on PVDE	LA-LAN-SD-CB0801-JS2709	CB0801 to JS2709	40.8	41	6/23/14	Line runs from CB0801 to OS0802 (medium corrosion) Pipe is lined up to 130.5 ft (medium corrosion).
81	18	249	56		18" CMP	Line starts at CB on cul-de-sac and to OS on 30	LA-LAN-SD-CB0927-OS0928	CB0927 to OS0928	231	231	6/2/14	Medium to heavy corrosion; inspection abandoned due to void at 19.4 ft.
82	19	251	56		18" CMP	Line starts at CB on cul-de-sac and to OS on 8 Bridge Ln. property	LA-LAE-SD-CB0928-OS0919	CB0928 to OS0919	19.5	180	6/2/14	Medium corrosion throughout the pipe.
83	20	264	58		30" CMP	Line starts at CB on Western northbound to mainline	LA-LAE-SD-CB0945-JS45733	CB0945 to Mainline	26	26	9/25/14	
84	21	292	47		24" RCP	Line runs from CB in front of 32433 Aqua Vida to OS west of PVDS	CB0366 to OS0665 MH	CB0366 to OS0665 MH	436	??	8/7/14	Exposed rebar and from 14.22' from 15' to 2' (approx. 10' with) Hard deposits at 12' and 132' (inspected for 200'). Line from end of OS to 12' needs a 25' with a MH (to be done location).
85	22	324	40		18" RCP	Line runs from CB across PVDS eastbound to CB on median west of nursery school gate	SM-OSS-SD-CB00702-CB00703	CB0702 to CB0703	44	44	9/8/14	Tap break-in intruding at the beginning of the line. Overall the line looks clean and in good condition.
86	23	327	40		24" RCP	Line starts at CB on PVDS westbound (approx. 965' west of nursery) to CB on median	CB1703 to CB0703	CB1703 to CB0703	52	52	9/8/14	Broken pipe at 18' from 10 to 12. Overall pipe is clean and in good condition.
87	24	337	38		18" RCP	Line runs from CB on southeast corner to IS	SM-OSW-SD-CB0653-JS44524	CB0653 to JS44524	32.5	33	8/28/14	Cracked/broken pipe at 179'. Overall pipe is clean and in good condition.
88	25	339	38		18" RCP	Line runs from IS on southeast corner to OS on Saahill	SM-OSW-SD-JS44524-OS0656	JS44524 to OS0656	208	208	8/28/14	Moderate corrosion throughout the pipe. Rocks accumulated - 10% from 200' to 210'. Deposit settled - 40% from 425' to 473' out.
89	1	21	6	1958	34" CMP	Pipe runs across Montielalaga Dr. from the North to the South	SM-PVN-SD-CB3333-CB3334, SM-PVN-SD-CB3334-CB3335, SM-PVN-SD-CB3335-CB3336	CB3333 to CB3336	473	473	6/11/14	Invert repaired previously throughout the pipe.
90	2	23	6	-1958	30" CMP	Line runs from CB in front of 26513 Blosswood to OS in 5621 Montielalaga property	SM-PVN-SD-CB1563-CB48134, SM-PVN-SD-CB48134-OS1564	CB1563 to OS1564	630	630	6/10/14	Light to medium corrosion throughout the pipe.
91	3	123	25		30" CMP	Line runs from MH (CB1669) approx. 630' from Country Machine to MH on eastbound	SM-OSW-SD-JS2349-MH1078, SM-OSW-SD-JS2349-MH1078	MH2347 to OS0495 to MH1078	91	91	8/4/14	Light to medium corrosion throughout the pipe.
92	4	134	25		30" CMP	Line runs from MH 535' east of Sea Terrace to MH 140' west	SM-OSW-SD-MH1078-MH1070	MH1078 to MH1070	121	121	8/15/14	Light to medium corrosion throughout the pipe.
93	5	135	25		30" CMP	Line runs from MH 390' east of Sea Terrace to MH 140' west	SM-OSW-SD-MH1070-MH1072	MH1070 to MH1072	282	282	8/15/14	Light to medium corrosion throughout the pipe.
94	6	138	25		30" CMP	Line starts from MH 111' east of Sea Terrace to MH in the middle of the road (Crest eastbound)	SM-OSW-SD-MH1072-MH1342	MH1072 to MH1342	176	176	8/15/14	Light to medium corrosion throughout the pipe.
95	7	133	25		30" CMP	Line runs from MH in the middle of Crest eastbound to MH 105' west	SM-OSW-SD-MH1079-MH2645	MH1079 to MH2645	108	109	8/15/14	Light to medium corrosion throughout the pipe.
96	8	149	27		18" CMP	Line starts at CB 270' south of Ludovica to Mainline northbound to IS in PVIC entrance island	SM-PVN-SD-CB1431-JS28515, SM-OWW-SD-IS0561-CB36920, SM-OWW-SD-CB36920-CB48133	CB1431 to Mainline	15.5	16	8/25/14	Moderate corrosion. Overall pipe looks in good condition. Top portion of pipe is determined at 63' (~20%). Light to medium corrosion throughout the pipe.
97	9	191.1	34		18" CMP	Line runs from CB south of PVIC entrance to OS on mainline	SM-OWW-SD-CB0559-OS0559	CB0559 to OS0559	71	71	9/9/14	Deposits settle gravel from 17' to end of pipe (~15%). Pipe has moderate corrosion.
98	10	193	34		24" RCP	Line starts at CB on Aqua Vista eastbound to CB on westbound	SM-OSE-SD-CB0367-CB0366	CB0367 to CB0366	33	33	9/14	Circumferential fracture at 5' (1.5' max). Hard deposits starting at 20' to 33' from 3' to 5'.
99	11	291	47		18" RCP	Line starts at CB southeast corner of intersection to JS on mainline	SM-OSE-SD-CB2786-JS2789	CB2786 to JS2789	85	85	8/7/14	Exposed rebar in two areas at 6' (approx. Ø 8"). Overall pipe is clean and in good condition.
100	12	305	45		18" RCP							

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point (Approx.)	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
101	11	201	57	18" RCP	18" RCP	Line starts at CB in front of property to CB across Monterena	LA-LAE-SD-CB137-CB0136	CB0137 to CB0136	47.5	48	5/20/14	Hard deposits from 28" to 39" - Moderata approx. 10%. Overall the line is clean and in good condition.
102	1	135	25	18" CMP	18" CMP	Line runs from CB 355' east of Saa Terrace to MH13' north	SM-OSW-SD-CB1071-MH1070	CB1071 to MH1070	9	9	8/15/14	Light corrosion.
103	2	136	25	24" CMP	24" CMP	Line starts at CB 120' west of Saa Terrace to MH18' north	SM-OSW-SD-CB1073-MH1079	CB1073 to MH1079	12	12	8/15/14	Light corrosion.
104	1	144	27	24" CMP	24" CMP	Line starts at CB 50' north of Indian Valley to MH of 2312 Coll Rd.	SM-PVW-SD-CB1430-MH1434	CB1430 to MH1434	19	19	8/25/14	Light to medium corrosion.
105	4	203	56	18" CMP	18" CMP	Line starts at CB in front of the property to CB in front of 2312 Coll Rd.	LA-LAE-SD-CB3272-CB3271	CB3272 to CB3271	35	35	6/2/14	Light corrosion. Overall pipe looks in good condition.
106	5	204	57	30" RCP	30" RCP	Line runs from JS on south side of property to JS on Toscana Dr.	LA-LAE-SD-JS4673A-JS3214	JS3214 to JS0155	308.7	309	5/20/14	Gravel at 195
107	4	206	46	18" RCP	18" RCP	Line starts at CB on Farnside southbound 115' north of PVDS to JS on mainline	SM-OSE-SD-CB2761-JS2763	CB2761 to JS2763	30	30	8/6/14	Concrete lumps at 20' from 4 to 5. Exposed rebar at 20'. Overall pipe is clean and in good condition.
108	1	21	8	18" RCP	18" RCP	Line runs from CB on Hawthorne median (behind 4559 Rockaway approx.) to CB on Hawthorne median (60' south of Hawthorne) to CB on Hawthorne median at Blackhorse	ML-RHE-SD-CB1510-MH1488, ML-RHE-SD-MH1488-JS4673A, ML-RHE-SD-JS4673A-MH1021	CB3171 to CB3172	10	10	9/4/14	Pipe might need further cleaning. Pipe looks in good condition.
109	9	63.1	15	18" RCP	18" RCP	Line runs from CB on Hawthorne northbound to CB on southbound. Line is approx. 230' south of CB at intersection with Blackhorse	ML-RHE-SD-CB1510-MH1488, ML-RHE-SD-MH1488-JS4673A, ML-RHE-SD-JS4673A-MH1021	MH1521 to CB3172, MH1510 to MH1510	57	57	9/8/14	Circumferential crack at the beginning of the pipe and at 54'. Overall pipe is in good condition.
110	9	64	15	18" RCP	18" RCP	Line runs from CB on Hawthorne northbound to CB on southbound. Line is approx. 230' south of CB at intersection with Blackhorse	ML-RHE-SD-CB1510-MH1488, ML-RHE-SD-MH1488-JS4673A, ML-RHE-SD-JS4673A-MH1021	MH1521 to CB3172, MH1510 to MH1510	57	57	9/8/14	Circumferential crack at the beginning of the pipe. Hard deposit at 37' & 43' (approx. ~5%). Overall pipe is in good condition.
111	31	64.1	15	18" RCP	18" RCP	Line runs from CB on Hawthorne northbound to CB on southbound. Line is approx. 230' south of CB at intersection with Blackhorse	ML-RHE-SD-CB1510-MH1488, ML-RHE-SD-MH1488-JS4673A, ML-RHE-SD-JS4673A-MH1021	CB3171 to CB3172	15.5	16	9/8/14	Circumferential crack at the beginning of the pipe. Overall pipe is in good condition.
112	31	65	16	18" RCP	18" RCP	Line runs from CB 385' north of intersection on Hawthorne southbound to JS in canyon west of Hawthorne	SM-PVW-SD-CB1103-JS1102	CB1103 to JS1102	215	215	9/5/14	Pipe has been lined previously (living failure at 213'). Line looks in good condition.
113	12	65.2	27	18" RCP	18" RCP	Line starts at CB north of PVDS entrance on PVDW northbound to CB across PVDW on southbound	SM-PVW-SD-CB1103-JS1102	CB1103 to JS1102	138	138	9/4/14	Light corrosion throughout the pipe. Overall pipe looks clean and in good condition.
114	31	66	34	18" CMP	18" CMP	Line starts at CB on PVDW eastbound approx. 1000' north of Hawthorne	SM-OWW-SD-CB0564-CB0563	CB0564 to CB0563	73.5	74	9/9/14	Light to medium corrosion.
115	39	66	60	24" RCP	24" RCP	Line starts at CB in front of property to CB in front of 3843 Custard Dr.	SM-OWW-SD-CB0564-CB0563	CB0564 to CB0563	31	31	9/16/14	Hard deposits starting at 22' to 31' (~10%). Overall pipe looks clean and in good condition.
116	31	66.3	44	18" RCP	18" RCP	Line starts at CB on PVDW eastbound approx. 1000' north of Hawthorne	SM-OWW-SD-CB0564-CB0563	CB0564 to CB0563	73	73	8/11/14	Hard deposits at 34' and 62' from 4 to 6 ~10%. Overall pipe is clean and in good condition.
117	31	67	42	18" CMP	18" CMP	Line starts at CB on northeast corner to CB on northwest corner	SM-OSE-SD-CB0530-OS0529	CB0530 to OS0529	955	955	9/11/14	Light rusting throughout the pipe. Overall pipe looks clean and in good condition.
118	17	3.6	41	18" CMP	18" CMP	Line starts at CB on northeast corner to CB on PVDS median between Nardissa and gate entrance to nursery school	SM-OSS-SD-CB0345-CB0346	CB0345 to CB0346	48	48	8/27/14	Light rusting throughout the pipe. Overall pipe looks clean and in good condition.
119	31	208	40	24" CMP	24" CMP	Line starts at CB on PVDS westbound in front of park entrance to CB on median PVDS eastbound	SM-OSS-SD-CB00704-JS00706	CB00704 to JS00706	152	152	9/3/14	Buckled black coating on top of the pipe at 58'.
120	39	209	39	24" CMP	24" CMP	Line starts at CB on PVDS westbound in front of park entrance to CB on median PVDS eastbound	SM-OSS-SD-CB00704-JS00706	CB00704 to JS00706	85	85	9/12/14	Light corrosion throughout pipe. Uninspected CB in median PVDS eastbound.
121	36	207	36	30" CMP	30" CMP	Line starts at JS approx. 800' west of Crescent to CB on PVDS southbound. Line is approx. 800' west of Crescent	IS0536 to CB0534	IS0536 to CB0534	305	305	9/2/14	up a screen full of rocks at IS0536. Line continues pasting 1500'. Inspection abandoned due to pipe inclination. Overall line is in good condition.
122	31	208	59	24" RCP	24" RCP	Line starts at CB on Farnside southbound 75' north of PVDS to JS on mainline	CB0100 to MH0102	CB0100 to MH0102	31	31	5/29/15	Hard deposits at 18' to 19' approx. 5%. Overall line looks clean and in good condition.
123	1	27	8	18" RCP	18" RCP	Line starts at CB on Hawthorne median (approx. 565' north of Hawthorne)	ML-RHE-SD-CB3175-CB3176	CB3175 to CB3176	5	5		Inspection not needed for CBs are next to each other
124	2	34	8	30" RCP	30" RCP	Line runs from MH on Hawthorne southbound (approx. 1450' north of Hawthorne) to JS approx. 270'	MH3328 to JS3330	MH3328 to JS3330	320.7	321	9/4/14	Pipe looks clean and in good condition.
125	3	279	49	24" RCP	24" RCP	Line starts at CB on PVDE (southeast corner of PVDW) to CB on PVDE (northwest corner of PVDW)	CB0314 to CB0315	CB0314 to CB0315	179	179	8/8/14	Pipe looks clean and in good condition.
126	4	286	46	18" RCP	18" RCP	Line starts at CB on Farnside southbound 75' north of PVDS to JS on mainline	CB2761 to JS2763	CB2761 to JS2763	9.6	10	8/6/14	Pipe looks clean and in good condition.
127	5	174	30	18" RCP	18" RCP	Line starts at CB on Paseo De La Luz northbound approx. 100' south of Via Del Cielo to MH in the middle of the street	SM-OWW-SD-CB1723-MH1722	CB1723 to MH1722	20	20	7/31/15	Pipe looks clean and in good condition.
128	6	178	31	27" RCP	27" RCP	Line runs from CB 130' north of Rhone Dr. to MH in the middle of Hawthorne northbound	SM-OWW-SD-CB1153-MH1113	CB1153 to MH1113	299	300	7/31/15	No video in the folder provided by Performance Pipeline.
129	7	204	51	18" CMP	18" CMP	Line starts at CB at the end of the cul-de-sac to OS on PVDW southbound	LA-LAN-SD-CB0630-OS0631	CB0630 to OS0631	157	157	10/7/15	Pipe has been lined previously. Overall line is clean and in good condition.
130	8	205	51	18" CMP	18" CMP	Line starts at CB in front of 2822 Sunnyside Ridge to CB in front of 2507 Sunnyside Ridge	LA-LAN-SD-CB0632-CB0633	CB0632 to CB0633	51	51	5/29/15	Pipe has been lined previously. Overall line is clean and in good condition.
131	9	206	51	18" CMP	18" CMP	Line runs from CB in front of 2507 Sunnyside Ridge to OS behind the same property.	LA-LAN-SD-CB0632-CB0633	CB0632 to CB0633	194	194	5/29/15	Pipe has been lined previously. Overall line is clean and in good condition.
132	10	259	57	78" RCP	78" RCP	Line runs from JS behind property to TS	LA-LAE-SD-MH3206-TS3207	JS3214 to TS3207	508	508	5/20/14	Pipe looks clean and in good condition.
133	11	267	59	33" RCP	33" RCP	Line starts at CB in front of 3485 Newridge to MH in the middle of the road	LA-LAE-SD-MH3206-TS3207	JS3214 to TS3207	20.6	21	5/29/15	Pipe looks clean and in good condition.
134	12	245	55	18" RCP	18" RCP	Line starts at CB on PVDE northbound to OS on 2nd Ave. Rd.	LA-LAN-SD-CB0101-MH0102	CB0101 to MH0102	42	42	12/15/14	Pipe has been lined previously. Line is clean and in good condition.
135	13	248	55	18" RCP	18" RCP	Line starts at CB south of Rockingham to OS on 10 Rockingham Rd.	LA-LAN-SD-CB0101-MH0102	CB0101 to MH0102	30	30	12/15/14	Pipe has been lined previously. Line is clean and in good condition.
136	14	15	4	18" CMP	18" CMP	Line runs from CB to CB in front of 6003 Lightfoot Pl	SM-PVW-SD-CB1571-CB1570	CB1571 to CB1570	17	17	6/9/14	Overall pipe is in good condition.
	15	20	5	18" CMP	18" CMP	Pipe runs from CB in front of 26603 Manonette Pl to MH behind same property	SM-PVW-SD-CB3282-CB3286, SM-PVW-SD-CB1283	CB3282 to MH3283	147	147	6/10/14	Pipe has been lined previously. Line looks in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
137	16	22	6	-1956	18" RCP	Line starts at CB in front of 5536 Montemalaga to CB in front of 28513 Basswood	SM-PVN-SD-CB1562-CB1563	CB1562 to CB1563	32		6/10/14	Overall pipe is in good condition. There are deposits at end of pipe.
138	17	28	8		18" RCP	Line starts at CB on Hawthorne median (approx. 565' north of Hawthorne) to CB approx. 380' north on Hawthorne median	ML-RHE-SD-CB3176-CB3174	CB3176 to CB3174	352		9/4/14	Pipe looks clean and in good condition.
139	18	29	8		18" RCP	5025 Rockvalley approx. to CB approx. 350' north on Hawthorne median	ML-RHE-SD-CB3174-CB3173	CB3174 to CB3173	362		9/4/14	Pipe looks clean and in good condition.
140	19	30	8		18" RCP	4889 Rockvalley approx. to CB approx. 120' north on Hawthorne median	ML-RHE-SD-CB3173-CB3171	CB3173 to CB3171	125		9/4/14	Pipe looks clean and in good condition.
141	20	32	8		18" RCP	4857 Rockvalley approx. to CB across southbound on Hawthorne	ML-RHE-SD-CB3171-CB3327	CB3171 to CB3327	49		9/8/14	Pipe looks clean and in good condition.
142	21	33	8		18" RCP	1450' north of Hawthorne to MH in the middle of Hawthorne southbound	ML-RHE-SD-CB3327-MH3326	CB3327 to MH3326	8		9/4/14	Pipe looks clean and in good condition.
143	22	35	8		18" RCP	1450' north of Hawthorne to CB across Hawthorne northbound	ML-RHE-SD-CB3326-MH3326	MH3326 to CB3329	61		9/4/14	Pipe looks clean and in good condition.
144	23	36	8		30" RCP	1450' north of Hawthorne to MH approx. 450' northbound	ML-RHE-SD-MH3326-JS3331, ML-RHE-SD-JS3331-MH3329	MH3326 to MH3328	505		9/4/14	Pipe looks clean and in good condition.
145	24	37.1	8		18" RCP	Hawthorne southbound to CB across Hawthorne northbound	ML-RHE-SD-CB3325-MH3328	MH3328 to CB3328 (RPV) to MH3332 (RHE)	13		9/4/14	Pipe looks clean and in good condition.
146	25	38	8		30" RCP	Line runs from MH on Hawthorne southbound (approx. 145' from City boundary line)	JS2775, SM-PVN-SD-JS2775-GB2765, SM-PVN-SD-GB2765-OS2766	MH3332 to OS2766	505		9/4/14	Pipe looks clean and in good condition.
147	26	46	11		42" CMP	OS behind 26747 Basswood	SM-PVN-SD-MH3031-GB3046, SM-PVN-SD-GB3046-JS3042, SM-PVN-SD-JS3042-MH3039	MH3031 to MH3039	160		6/12/14	Pipe has been paved previously. Line looks in good condition.
148	27	47	12		36" CMP	Line runs from MH in front of 28003 Lomo to MH in front of 6542 Monero to MH in front of 6550 Monero	SM-PVN-SD-MH3039-MH3040	MH3039 to MH3040	305		6/12/14	Pipe has been paved previously. Line looks in good condition.
149	28	48	12		36" CMP	Line starts at CB in front of 6542 Monero to CB in front of 6550 Monero	SM-PVN-SD-CB3034-CB3035	CB3034 to CB3035	163		6/12/14	Pipe invert has been paved previously. Overall pipe is in ok condition.
150	29	49	12		24" CMP	Line runs from CB in front of 6550 Monero to MH3040	SM-PVN-SD-CB3035-MH3040	CB3035 to MH3040	17		6/12/14	Pipe invert has been paved previously. Overall pipe is in ok condition.
151	30	50	12		30" CMP	Line runs from CB in front of 6550 Monero to MH3040	SM-PVN-SD-CB3035-MH3040	CB3035 to MH3040	15		6/12/14	Pipe has been lined previously. Overall pipe is in good condition.
152	31	51	12		18" CMP	Line runs from CB in front of 6549 to MH in front of 6550 Monero	SM-PVN-SD-CB3036-MH3040	CB3036 to MH3040	29		6/12/14	The City Limits, 48" RCP starts at 282' to 1600' in good condition. The entire RCP line seems to be part of Palos Verdes
153	32	52	12		48" CMP & 48" RCP	Line runs from MH in front of 6542 Monero to MH in front of 6550 Monero	SM-PVN-SD-MH3040-CB3044, SM-PVN-SD-GB3044-OS3041	MH3040 to OS3041	325		6/12/14	Pipe has been lined previously (moderate wrinkled). Overall pipe is in good condition.
154	33	54	12		18" CMP	Line is on the north side of 27904 Lomo Dr. to JS on Monero Dr.	SM-PVN-SD-CB3033-JS3038	CB3033 to JS3038	13		6/12/14	Pipe has been lined previously. Line looks in good condition.
155	34	56	13		36" CMP	Line runs from Ridgegate Dr. to MH on Hawthorne (behind 28128 Lomo property)	SM-PVN-SD-CB1580-MH3029	CB1580 to MH3029	110		6/19/14	CMP invert has been paved previously. Line looks in good condition. Might need a little cleaning.
156	35	57	13		36" CMP	Line runs from MH behind property 28128 Lomo to MH on Corner of Lomo & La Garita	SM-PVN-SD-GB3045-MH3030	MH3029 to MH3030	505		6/17/14	Overall pipe is in good condition. Might need a little cleaning.
157	36	58	13		36" CMP	Line runs along Lomo Dr. from MH at La Garita & Lomo intersection to MH in front of 28003 Monero	SM-PVN-SD-MH3030-MH3031	MH3030 to MH3031	505		6/17/14	CMP invert has been paved previously. Line looks in good condition.
158	37	59	14		24" RCP	Line starts at CB in front of 6544 La Garita to CB in front of 28084 Ella Rd.	SM-PVN-SD-CB3026-CB3027	CB3026 to CB3027	40		6/17/14	Pipe is in good condition.
159	38	60	14		30" RCP	Line runs from CB in front of 28084 Ella Rd. to CB in front of 28087 Ella Rd.	SM-PVN-SD-CB3027-CB3028	CB3027 to CB3028	70		6/17/14	Pipe is in good condition.
160	39	63	15		18" RCP	Line runs from MH on Hawthorne southbound (approx. 60' south of Hawthorne) to CB on Hawthorne median at Baschorse	ML-RHE-SD-CB1512-MH1521	CB1512 to MH1521	15		9/8/14	Pipe looks clean and in good condition.
161	40	65	15		24" RCP	Line runs from CB on Hawthorne median at Baschorse to JS behind property 28128 Lomo	ML-RHE-SD-CB1510-MH1485, ML-RHE-SD-JS2886-MH1485	CB1510 to MH1485	512		9/5/14	Pipe looks clean and in good condition.
162	41	66	15		18" RCP	Line runs from CB on Hawthorne median at Baschorse to CB on northbound. Line is approx. 775' south of Baschorse intersection	ML-RHE-SD-CB1508-JS2686	CB1508 to JS2686	18		9/5/14	Pipe looks clean and in good condition.
163	42	66.1	15		18" RCP	Line runs across Hawthorne from CB on southbound to CB on northbound. Line is approx. 775' south of Baschorse intersection	ML-RHE-SD-CB1507-JS2686	CB1507 to JS2686	59.5		9/5/14	Pipe looks clean and in good condition.
164	43	67	16		24" RCP	Line runs from JS on Hawthorne median to CB on median approx. 570' south	ML-RHE-SD-CB1507-JS2686	CB1507 to JS2686	520		9/5/14	Pipe looks clean and in good condition.
165	44	68	16		18" RCP	Line runs from CB on southbound (approx. 800' northeast of Silver Spur) to CB on Hawthorne median	ML-RHE-SD-CB1507-JS2686	CB1507 to JS2686	29		9/5/14	Pipe looks clean and in good condition.
166	45	70	16		24" RCP	Line runs from CB on northbound (approx. 700' northeast of Silver Spur) to CB in front of 5131 Silver Arrow Dr.	ML-RHE-SD-CB1507-JS2686	CB1507 to JS2686	221		9/6/14	Pipe looks clean and in good condition.
167	46	71	16		18" RCP	Line runs from CB in front of 5131 Silver Arrow to 5134 Silver Arrow	ML-RHE-SD-CB1487-CB1488	CB1487 to CB1488	39		8/21/14	Pipe looks clean and in good condition.
168	47	78	19		48" CMP	Line starts at CB 430' from Indian Peak on Crenshaw to MH approx. 1330' east on Crenshaw northbound	ML-RHE-SD-CB1412-MH21826, ML-RHE-SD-MH21826-MH21813, ML-RHE-SD-MH21813-MH21804, ML-RHE-SD-MH21804-MH32115, ML-RHE-SD-MH32115-JS1413	CB1412 to MH1413	1220		7/29/14	Pipe looks clean and in good condition.
169	48	79	19		18" RCP	Line runs from MH approx. 265' west of Silver Spur on Crenshaw northbound to CB across Crenshaw	PIPE FOUND	MH1413 to CB1414	35		8/21/14	Pipe looks clean and in good condition.
170	49	81	19		18" RCP	Line starts at CB in front of property to JS approx. 50' south	ML-RHE-SD-JS2684-JS2684	CB1012 to JS2684	25.5		9/23/14	Light to medium corrosion throughout the pipe.
171	50	82	19		48" CMP	JS is on 5230 Middlecrest property to OS on 5219 Middlecrest property	ML-RHE-SD-JS2684-JS2684, ML-RHE-SD-JS2684-JS2684	JS1014 to OS1013	136		7/30/14	Pipe line has been paved previously. Line is in good condition.
172	51	83	20		24" RCP	Line starts at CB on northwest corner of intersection to CB on the same corner	ML-RHE-SD-CB1030-CB1029	CB1030 to CB1029	27		8/20/14	Pipe looks clean and in good condition.
173	52	84	20		24" RCP	Line runs from CB on northwest corner of intersection to CB on southwest corner	ML-RHE-SD-CB1029-CB1027	CB1029 to CB1027	67		8/20/14	Pipe looks clean and in good condition.
174	53	85	20		18" RCP	Line runs from CB on southwest corner of intersection to CB approx. 95' northwest	ML-RHE-SD-CB1028-CB1027	CB1028 to CB1027	91		8/20/14	Pipe looks clean and in good condition.
175	54	89	20		30" RCP	Line runs from MH approx. 176' south of southeast corner of intersection to MH in front of 28041 Crenshaw Rd. property	ML-RHE-SD-GB1021-MH1003, ML-RHE-SD-MH3318-GB1021	MH3318 to MH1003	237		8/20/14	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments (Phase II)	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
176	55	91	20	18" RCP	Line runs from CB 166' south of southeast corner of intersection to MH 10' north	ML-RHE-SD-CB1022-MH3518	CB1022 to MH3518	10			8/21/14	Pipe looks clean and in good condition.
177	56	102	23	15" RCP	Line starts at CB on Whitley Collins median to JS	SM-OSS-SD-CB01049-JS02080	CB1049 to JS2080	32			8/5/14	Pipe looks clean and in good condition.
178	57	103	23	48" RCP	Line starts at CB on northeast corner of intersection to JS	SM-OSS-SD-CB01047-JS02080	CB1047 to JS2080	30			8/5/14	Pipe looks clean and in good condition.
179	58	104	23	21" RCP	Line starts at CB on northeast corner of intersection to CB on southeast corner	SM-OSS-SD-CB01048-JS02080, SM-OSS-SD-JS02080-CB01046	CB1048 to CB1046	105.5			8/5/14	Pipe looks clean and in good condition.
180	59	105	23	27" RCP	Line runs from CB on northeast corner of intersection to CB on northeast corner of Whitley Collins Dr. & Crest Rd.	SM-OSS-SD-CB01046-CB01044	CB1046 to CB1044	72			8/5/14	Pipe looks clean and in good condition.
181	60	106	23	18" RCP	Line runs from CB on northeast corner of intersection to CB on southeast corner of intersection	SM-OSS-SD-CB01040-MH04486, SM-OSS-SD-MH04486-MH01050	CB1040 to MH1050	100.5			8/5/14	Inspected MH1051 at 10' Pipe looks clean and in good condition.
182	61	107	23	48" RCP	Line runs from CB on southeast corner of intersection to CB 45' south	SM-OSS-SD-CB01039-CB01040	CB1039 to CB1040	47			8/5/14	Pipe looks clean and in good condition.
183	62	108	23	18" RCP	Line runs from CB on southeast corner of intersection to mainline 75' west	SM-OSS-SD-CB01041-MH04486	CB1041 to Mainline	65.5			8/5/14	Pipe looks clean and in good condition.
184	63	109	23	18" RCP	Line starts at CB in front of property to CB in front of 29719 Whitley Collins	SM-OSS-SD-CB01043	CB1043 to CB1043	34			8/5/14	Pipe looks clean and in good condition.
185	64	110	23	15" RCP	Line runs from CB in median to CB in front of 29719 Whitley Collins	SM-OSS-SD-CB01042-CB01043	CB1042 to CB1043	39			8/5/14	Pipe looks clean and in good condition.
186	65	111	23	21" RCP	Line runs from CB in front of property to JS on Crest westbound	SM-OSS-SD-CB01043-JS02081	CB1043 to JS2081	59			8/5/14	Pipe looks clean and in good condition.
187	66	112	23	48" RCP & UNKNOWN	Line runs from MH on Crest westbound to MH 520' west in median	SM-OSS-SD-MH01050-JS02081, SM-OSS-SD-JS02081-MH01051	MH1050 to MH1051	464			8/14/14	Pipe looks clean and in good condition.
188	67	113	23	48" RCP	Line runs from MH in median approx. 400' west from intersection to OS in canyon south of Crest	SM-OSS-SD-MH01051-JS01056, SM-OSS-SD-JS01056-CB02676, SM-OSS-SD-CB02676-CB01055	MH1051 to OS1055	612			8/14/14	Pipe looks clean and in good condition.
189	68	114	23	18" RCP	Line runs from CB approx. 830' west of Whitley Collins Dr to CB 30' west	SM-OSS-SD-CB01052-CB01053	MH1052 to CB1053	30			8/14/14	Pipe looks clean and in good condition.
190	69	115	23	30" RCP	Line runs from CB approx. 860' west of Whitley Collins Dr to JS in median across Crest westbound	SM-OSS-SD-CB01053-CB02676	CB1053 to JS2676	16			8/14/14	Pipe looks clean and in good condition.
191	70	119	25	27" RCP	Line starts at CB in Mary Anna Rd. to MH on Crest westbound	SM-OSS-SD-TS3245-MH3246, SM-OSW-SD-CB3244-TS3245	CB3244 to MH3246	259			8/14/14	Pipe looks clean and in good condition.
192	71	120	25	27" RCP	Line runs from MH approx. 690' from Highridge to MH 205' west	MH3246 to MH3247	MH3246 to MH3247	144			8/14/14	Pipe looks clean and in good condition.
193	72	134	26	30" RCP	Line starts at CB 545' west of Sea Terrace to MH in median	SM-OWW-SD-CB3191-MH3190	CB3191 to MH3190	118			8/18/14	Pipe looks clean and in good condition.
194	73	135	26	18" RCP	Line starts at CB 205' west of Anacapa to MH in median	SM-OWW-SD-CB3192-MH3190	CB3192 to MH3190	65			8/20/14	Pipe looks clean and in good condition.
195	74	136	26	24" RCP	Line runs from MH approx. 235' west of east end of median to MH 400' west	SM-OWW-SD-MH3190-MH3189, SM-OWW-SD-MH3189-MH3187	MH3190 to MH3187	365			8/18/14	Pipe looks clean and in good condition.
196	75	137	26	18" RCP	Line starts at CB 575' west of Anacapa to MH 70' west	SM-OWW-SD-CB3188-MH3187	CB3188 to MH3187	70			8/21/14	Pipe looks clean and in good condition.
197	76	138	26	24" RCP	Line runs from MH 820' east of west end of median to MH 480' west	SM-OWW-SD-MH3187-MH3186, SM-OWW-SD-MH3186-MH3185	CB3187 to MH3185	485			8/18/14	Pipe looks clean and in good condition.
198	77	139	26	18" RCP	Line starts at CB approx. 1020' west of Anacapa to MH 85' southwest in median	SM-OWW-SD-CB3182-MH3185	CB3182 to MH3185	80.5			8/21/14	Pipe looks clean and in good condition.
199	78	140	26	24" RCP	Line runs from MH 135' east of west end of median to CB 115' west	SM-OWW-SD-MH3185-CB3183	MH3185 to CB3183	134			8/18/14	Pipe looks clean and in good condition.
200	79	141	26	18" RCP	Line starts at CB 80' east of La Croix Dr. to CB in median	SM-OWW-SD-CB3184-CB3183, SM-OWW-SD-CB3183-CB3181	CB3184 to CB3183	47			8/19/14	Pipe looks clean and in good condition.
201	80	142	26	24" RCP	Line runs from CB 20' east of west end of median to MH 75' west of east end of median (west of La Croix Dr.)	SM-OWW-SD-CB3183-MH1081	CB3183 to MH1081	171			8/21/14	Pipe looks clean and in good condition.
202	81	143	26	18" RCP	MH in median west of La Croix	SM-OWW-SD-CB3194-MH1081	CB3194 to MH1081	77.5			8/18/14	Pipe looks clean and in good condition.
203	82	144	26	24" RCP	Line runs from MH 75' west of east end of median to MH 155' north	SM-OWW-SD-MH1081-MH3195	MH1081 to MH3195	190			8/18/14	Pipe looks clean and in good condition.
204	83	147	26	24" RCP	Line runs from MH 285' south of west end of median to MH 155' east of Cresta Verde on Crest westbound	SM-OWW-SD-CB3195-CB3196, SM-OWW-SD-CB3196-MH1092	MH3195 to MH1092	200			8/18/14	Pipe looks clean and in good condition.
205	84	148	26	24" RCP	Line runs from MH 160' south of Cresta Verde to MH 15' west	SM-OWW-SD-TS46932-MH1092, SM-OWW-SD-CB46931-TS46932	CB1091 to MH1092	27			8/21/14	Pipe looks clean and in good condition.
206	85	152	27	36" CIP	Line starts at IS approx. 520' north of Crest Rd. in canyon (east side of Hawthorne) to OS in canyon west side of Hawthorne)	SM-PWW-SD-IS1105-JS1102	JS1102 to IS1105	424			9/3/14	Light corrosion throughout the pipe. Overall pipe looks clean and in good condition.
207	86	154	28	18" RCP	Line starts at CB 315' east of Hawthorne on Crest westbound to MH	SM-OWW-SD-CB1086-MH1093	CB1086 to MH1093	5			8/19/14	Pipe looks clean and in good condition.
208	87	155	28	24" RCP	Line runs from MH 305' east of Hawthorne to MH 170' west	SM-OWW-SD-MH1093-MH1094	MH1093 to MH1094	180			8/19/14	Pipe looks clean and in good condition.
209	88	156	28	18" RCP	Line starts at CB 130' east of Hawthorne on Crest westbound to MH	SM-OWW-SD-CB1087-MH1094	CB1087 to MH1094	6			8/19/14	Pipe looks clean and in good condition.
210	89	157	28	30" RCP	Line runs from CB 80' east of Hawthorne on Crest westbound to MH	SM-OWW-SD-MH1094-CB1095	CB1095 to MH1094	97.5			8/19/14	Pipe looks clean and in good condition.
211	90	161	28	24" RCP	Line starts at CB 557' north of Crest on Hawthorne northbound to JS in the middle of Hawthorne southbound	SM-OWW-SD-GE02001-JS2901, SM-OWW-SD-CB2899-GE02000	CB2899 to JS2901	149			8/19/14	Pipe looks clean and in good condition.
212	91	163	29	18" RCP	Line starts at CB on southeast corner of intersection to CB in front of 30503 Rue Langlois	SM-OWW-SD-CB3301-CB3302	CB3301 to CB3302	43			7/30/14	Pipe is in good condition.
213	92	164	29	18" RCP	Line starts at CB on Rue De La Pierre (southeast corner of intersection) to CB in front of 30307 Rue De La Pierre	SM-OWW-SD-CB3300-CB3299	CB3300 to CB3299	32			7/30/14	Pipe is in good condition.
214		165	29	24" RCP	Line starts at CB on southwest corner of intersection to CB in front of 30503 Rue Langlois	SM-OWW-SD-CB3299-CB3302	CB3299 to CB3302	32			7/30/14	Pipe is in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
215	94	167	30	24" RCP	Line runs from MH on median approx. 60' west of Calle SM-OWW-SD-G846943-OS1184. SM-OWW-SD-Enridero to OS on northwest corner of intersection	MH1185-G846943	MH1185 to OS1184	171		9/17/14	Pipe looks clean and in good condition.
216	95	167.1	30	18" RCP	Line runs from CB on PVDW eastbound to MH on median approx. 60' west of Calle Enridero (IS is at end of open channel eastside of PVDW (approx. 300' south of Calle Enridero) to OS on west side of PVDW	PIPE FOUND	CB1185.1 to MH1185	20		9/17/14	Pipe looks clean and in good condition.
217	96	166	30	18" RCP	Line starts at CB in median (approx. 160' south of Calle Enridero) to CB on PVDW eastbound	SM-OWW-SD-CB1715-CB1716	IS0567 to OS0569	427		9/17/14	Inspect 18" at 172 not at 204 from IS. Pipe looks clean and in good condition.
218	97	169	30	18" RCP	Line starts at CB on PVDW eastbound (125' south of Calle Enridero) to CB 45' south	SM-OWW-SD-CB1713-CB1716	CB1715 to CB1716	34		9/15/14	Pipe looks clean and in good condition.
219	98	170	30	18" RCP	Line starts at CB on PVDW eastbound (200' south of Calle Enridero) to CB 25' north	SM-OWW-SD-CB1714-CB1716	CB1715 to CB1716	25		9/15/14	Pipe looks clean and in good condition.
220	99	171	30	18" RCP	Line starts at CB on PVDW eastbound (170' south of Calle Enridero) to MH in southwest property of Calle Enridero	SM-OWW-SD-CB1716-CB1717, SM-OWW-SD-CB1717-MH1712	CB1714 to CB1716	25		9/15/14	Pipe looks clean and in good condition.
221	100	172	30	18" RCP	Line runs from TS in southwest property approx. 330' from Calle Enridero to southwest property approx. 330' from Calle Enridero	SM-OWW-SD-MH1712-G81720, SM-OWW-SD-CB1720-G81721, SM-OWW-SD-G81721-MH1722	CB1716 to MH1712	202		9/15/14	Pipe looks clean and in good condition.
222	101	173	30	18" RCP	Line starts at CB on Paseo De La Luz southbound approx. 115' south of Via Del Cielo to MH in the middle of the street	SM-OWW-SD-CB1724-MH1722	MH1712 to MH1722	187		9/15/14	Pipe looks clean and in good condition.
223	102	173.1	30	18" RCP	Line starts at CB in front of property to CB in front of 30095 Carlier Dr.	SM-OWW-SD-CB1110-CB1152, SM-OWW-SD-G83442-G83443, SM-OWW-SD-G83443-G83444, SM-OWW-SD-G83444-G83445, SM-OWW-SD-	TS1719 to MH1712	65.5		9/15/14	Pipe looks clean and in good condition.
224	103	175	18	RCP	Line starts at CB in front of property to CB in front of 30095 Carlier Dr.	SM-OWW-SD-CB1111-CB1112	CB1724 to MH1722	24		7/31/14	Pipe looks in good condition.
225	104	176	31	18" RCP	Line runs from CB in front of property to CB behind property on Hawthorne Blvd.	SM-OWW-SD-CB1112-MH1113	CB1110 to CB1152	40		7/31/14	Pipe looks in good condition.
226	105	177	31	24" RCP	Line starts at CB on Hawthorne 60' south of Rhone Dr. to CB 30' south	SM-OWW-SD-CB1154-G82531, SM-OWW-SD-G82531-MH1155	CB1152 to CB1153	258		7/31/14	Pipe has been lined previously. Pipe looks in good condition.
227	106	179	31	18" RCP	Line runs from CB on Hawthorne 90' south of Rhone Dr. to MH 20' southwest on Hawthorne northbound	SM-OWW-SD-CB1154-G82531, SM-OWW-SD-G82531-MH1155	CB1111 to CB1112	30		7/31/14	Pipe looks clean and in good condition.
228	107	180	31	18" RCP	Line runs from CB on Hawthorne 90' south of Rhone Dr. to MH 20' southwest on Hawthorne northbound	SM-OWW-SD-CB1112-MH1113	CB1112 to MH1113	15.6		7/31/14	Pipe looks clean and in good condition.
229	108	181	31	30" RCP	Line runs from CB on Hawthorne 90' south of Rhone Dr. to MH 20' southwest on Hawthorne northbound	SM-OWW-SD-CB1112-MH1113	CB1113 to MH1113	257		7/31/14	Pipe looks clean and in good condition.
230	109	184	31	36" RCP	Line runs from CB on Hawthorne southbound 255' north of Los Verdes Dr. to MH in the 30332 Avenida Selecta backyard	SM-OWW-SD-CB1154-G82531, SM-OWW-SD-G82531-MH1155	CB1154 to MH1155	75		8/21/14	Pipe looks clean and in good condition.
231	110	186	33	18" RCP	Line starts at CB at the northeast corner of intersection to CB at southeast corner	SM-OWW-SD-CB3305-CB3306	CB3305 to CB3306	90		8/25/14	Pipe looks clean and in good condition.
232	111	188	33	36" RCP	Line runs from MH at southwest corner to OS 245' south	SM-OWW-SD-MH3484-JS3485, PIPE FOUND	MH3484 to OS0575	858		8/25/14	OS 245' not at 245' from MH. Pipe looks clean and in good condition.
233	112	191	34	36" RCP	Line starts at CB by PVC entrance on PVDW northbound to IS in PVC entrance island	SM-OWW-SD-CB0559-OS0559	CB0559 to OS0559	80		9/9/14	OS 245' not at 245' from MH. Pipe looks clean and in good condition.
234	113	192	34	18" RCP	Line starts at CB south of PVC entrance on PVDW westbound to CB across PVDW eastbound	SM-OWW-SD-CB0559-OS0559	CB0559 to OS0559	96.5		9/9/14	Pipe has been lined previously. Line looks in good condition.
235	114	201	50	21" RCP	Line runs from CB on De La Sonde (at the southwest corner of intersection) to CB on De La Sonde (northwest corner of intersection)	LA-LAE-SD-CB0167-CB0168	CB0560 to CB0558	31.2		5/20/14	Line has been cleaned. Pipe looks in good condition.
236	115	202	50	24" RCP	Line runs from CB on De La Sonde (northwest corner of intersection) to MH on Western southbound	LA-LAE-SD-CB0168-MH1907	CB0168 to MH1907	97.5		5/20/14	Line has been cleaned. Pipe looks in good condition.
237	116	230	54	24" RCP	Line runs from CB behind 16 Station to MH behind 24 Station	LA-LAN-SD-CB0894-MH3493	CB0894 to MH3493	185.6		6/3/14	Pipe looks clean and in good condition.
238	117	231	54	24" RCP	Line runs from MH behind 24 Station to MH on PVDW at Bronco	LA-LAN-SD-MH3493-MH3491	MH3493 to MH3491	230		6/3/14	Pipe looks clean and in good condition.
239	118	235	54	18" RCP	Line runs from CB on Bronco at PVDW to JS on Bronco	LA-LAN-SD-CB0890-JS3449	CB0890 to JS3449	24.7		6/2/14	Line has been cleaned. Pipe looks in good condition.
240	119	253	56	24" CMP	Line runs from CB in front of the property to OS in canyon behind the property	LA-LAE-SD-CB3271-G83270, LA-LAE-SD-G83270-G83268, LA-LAE-SD-G83268-JS3273	CB3271 to OS3273	339		6/2/14	Pipe has been lined previously. Line looks in good condition.
241	120	254	57	18" RCP	Line runs from CB in front of property to CB in front of 1803 Toscanini	LA-LAE-SD-CB0146-CB0145	CB0146 to CB0145	33.8		5/20/14	Line has been cleaned. Pipe looks in good condition.
242	121	255	57	24" RCP	Line runs from CB in front of property to CB across Toscanini Dr.	LA-LAE-SD-CB0145-CB0146	CB0145 to CB0146	35.6		5/20/14	Line has been cleaned. Pipe looks in good condition.
243	122	256	57	18" RCP	Line runs from CB at southwest corner to CB 40' east	LA-LAE-SD-CB0147-CB0146	CB0146 to CB0147	32		5/20/14	Line has been cleaned. Pipe looks in good condition.
244	123	257	57	24" RCP	Line runs from CB at southwest corner to JS on Western (south of Toscanini Dr.)	LA-LAE-SD-CB0146-JS0140	CB0146 to JS0140	110.7		5/20/14	Line has been cleaned. Pipe looks in good condition.
245	124	262	58	24" RCP	Line starts at CB on Western (northwest corner) to CB 65' north	LA-LAE-SD-CB0151-CB0152	CB0151 to CB0152	32		9/25/14	Pipe looks clean and in good condition.
246	125	263	59	18" RCP	Line runs from CB on Western (northwest corner) to next structure	LA-LAE-SD-CB0151-CB0152	CB0152 to MH0152	87		9/25/14	Pipe looks clean and in good condition.
247	126	265a	58	18" RCP	Line runs from CB on Western (northwest corner) to next structure	LA-LAE-SD-CB0044-JS1920	CB0044 to JS1920	33.5		5/20/14	Line has been cleaned. Pipe looks in good condition.
248	127	265b	58	48" RCP	Line runs from MH on parking lot behind Cinemas to MH in front of shopping plaza on Western	LA-LAE-SD-MH1916-MH1914	MH1916 to MH1914	522		10/7/14	Pipe looks clean and in good condition.
249	128	265c	58	48" RCP	Line runs from MH on parking lot behind Cinemas to IS (location 7)	LA-LAE-SD-MH1916-MH1914	MH1916 to IS1916	427		10/6/14	Pipe looks clean and in good condition.
250	129	268	59	33" RCP	Line runs from MH in the middle of the road to OS in 14' from the property	LA-LAS-SD-MH0102-TS0103, LA-LAS-SD-TS0103-G80104, LA-LAS-SD-G80104-OS2285	MH0102 to OS2285	629		8/11/14	OS 2285 not at 2285 from MH. Pipe looks in good condition. Cuts into road and looks.
251	130	271	61	18" RCP	Line starts at CB on Miralste to CB in front of property on Chandelour Dr.	CB0263 to CB0264	CB0263 to CB0264	202		9/23/14	Pipe looks clean and in good condition.
252	131	272	61	27" RCP	Line runs from CB in front of property to CB on southwest corner of intersection	CB0264 to CB0265	CB0264 to CB0265	30		9/23/14	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
253	132	273	61	27" RCP	Line runs from CB on southwest corner to MH on Milestate northbound	Line runs from CB on southwest corner to MH on Milestate northbound	SM-OSE-SD-150317-JS2696	CB8034 to MH1865	130'		9/23/14	Burned JS at 130'. Pipe looks clean and in good condition.
254	133	273.1	61	27" RCP	Line runs from CB on southwest corner to MH on Milestate northbound	Line runs from CB on southwest corner to MH on Milestate northbound	SM-OSE-SD-150317-JS2696	CB8034 to MH1865	189		9/23/14	Unmapped MH at 131'. Pipe looks clean and in good condition.
255	134	274	61	27" RCP	Line runs from MH on Milestate northbound to OS on eastside of Milestate Dr.	Line runs from MH on Milestate northbound to OS on eastside of Milestate Dr.	SM-OSE-SD-150317-JS2696	MH1865 to OS1026	98		9/23/14	Unmapped MH at 170'. Pipe looks clean and in good condition.
256	135	277	49	42" RCP	Line starts at JS on northeast corner of intersection to OS south of PVDS	Line starts at JS on northeast corner of intersection to OS south of PVDS	SM-OSE-SD-150317-JS2696	MH1865 to OS1026	22		8/8/14	Pipe looks clean and in good condition.
257	136	277.1	49	42" RCP	Line starts at JS on northeast corner of intersection to OS south of PVDS	Line starts at JS on northeast corner of intersection to OS south of PVDS	SM-OSE-SD-150317-JS2696	MH1865 to OS1026	448		8/8/14	Pipe looks clean and in good condition.
258	137	281	48	18" RCP	Line starts at CB on PVDS westbound (approx. 350' east of intersection) to MH in PVDS median (approx. 330' east of median west end)	Line starts at CB on PVDS westbound (approx. 350' east of intersection) to MH in PVDS median (approx. 330' east of median west end)	SM-OSE-SD-CB1865-CB1867	JS2696 to OS10316	14		8/27/14	Pipe looks clean and in good condition.
259	138	282	48	18" RCP	Line runs from MH in PVDS median (approx. 330' east of median west end) to MH at intersection south of PVDS	Line runs from MH in PVDS median (approx. 330' east of median west end) to MH at intersection south of PVDS	SM-OSE-SD-CB1865-CB1867	CB1865 to MH1865	31		8/27/14	Pipe looks clean and in good condition.
260	139	283	48	30" RCP	Line runs from CB on PVDS eastbound to JS on Milestate	Line runs from CB on PVDS eastbound to JS on Milestate	SM-OSE-SD-MH1865-JS1946	MH1865 to MH1865	372		8/27/14	MH1865 is buried. Pipe looks good and in good condition.
261	140	284	48	18" RCP	Line starts at CB on PVDS eastbound to JS on Milestate	Line starts at CB on PVDS eastbound to JS on Milestate	SM-OSE-SD-CB1865-JS1946	CB1865 to JS1946	11		8/27/14	Pipe looks clean and in good condition.
262	141	285	48	21" RCP	Line starts at CB on northwest corner of intersection to JS	Line starts at CB on northwest corner of intersection to JS	SM-OSE-SD-CB1865-JS3031	CB8034 to JS3031	83.5		8/8/14	Pipe looks clean and in good condition.
263	142	286	48	21" RCP	Line starts at CB on Scuffiff Dr. to CB on PVDS north from intersection to CB 25' south	Line starts at CB on Scuffiff Dr. to CB on PVDS north from intersection to CB 25' south	SM-OSE-SD-CB0345-CB0347	CB0345 to CB0347	59		8/8/14	Hard deposits from 23' to 30' about 15%. Overall pipe is clean and in good condition.
264	143	287	48	18" RCP	Line runs from CB on Scuffiff Dr. to CB on PVDS northeast corner of intersection	Line runs from CB on Scuffiff Dr. to CB on PVDS northeast corner of intersection	SM-OSE-SD-CB0345-JS6521	CB0347 to CB0348	28		8/8/14	Pipe looks clean and in good condition.
265	144	288	48	21" RCP	Line runs from CB on Scuffiff Dr. to CB on PVDS northeast corner of intersection	Line runs from CB on Scuffiff Dr. to CB on PVDS northeast corner of intersection	SM-OSE-SD-CB0345-JS6521	CB0347 to MH1865	122		8/8/14	Pipe looks clean and in good condition.
266	145	289	47	24" RCP	Line starts at CB (aerial shows CB in median) might be on PVDS westbound approx. 515' from intersection to MH	Line starts at CB (aerial shows CB in median) might be on PVDS westbound approx. 515' from intersection to MH	SM-OSE-SD-JS3031-MH1865	CB0347 to MH1865	16		8/26/14	Unmapped MH at 197' & 516'. Pipe looks clean and in good condition.
267	146	290	47	30" RCP	Line runs from MH to OS west of PVDS	Line runs from MH to OS west of PVDS	SM-OSE-SD-CB2776-CB2777	CB2776 to CB2777	526		8/26/14	Pipe looks clean and in good condition.
268	147	293	46	30" RCP	Line starts at CB on Forestal approx. 105' north of PVDS to CB 10' south	Line starts at CB on Forestal approx. 105' north of PVDS to CB 10' south	SM-OSE-SD-CB2776-CB2777	CB2776 to JS2780	11		8/6/14	Pipe looks clean and in good condition.
269	148	294	46	30" RCP	Line starts at CB on Forestal approx. 95' north of PVDS to JS	Line starts at CB on Forestal approx. 95' north of PVDS to JS	SM-OSE-SD-CB2776-JS2780	CB2776 to JS2780	39.5		8/6/14	Pipe looks clean and in good condition.
270	149	295.1	46	18" RCP	Line runs from CB on Forestal/Aqua Vista corner to MH	Line runs from CB on Forestal/Aqua Vista corner to MH	SM-OSE-SD-CB2776-JS2780	CB2776 to JS2780	40		8/6/14	Pipe looks clean and in good condition.
271	150	297	46	18" RCP	Line starts at CB on Forestal southbound 105' north of PVDS to OS 15' south	Line starts at CB on Forestal southbound 105' north of PVDS to OS 15' south	SM-OSE-SD-CB2776-CB2776	CB2776 to CB2776	16.5		8/6/14	Pipe looks clean and in good condition.
272	151	298	46	24" RCP	Line starts at CB on Forestal southbound 90' north of PVDS to JS on mainline	Line starts at CB on Forestal southbound 90' north of PVDS to JS on mainline	SM-OSE-SD-CB2776-MH2784	CB2776 to JS2801	37		8/6/14	Pipe looks clean and in good condition.
273	152	299.1	46	18" RCP	Line runs from CB on northwest corner of intersection to ?	Line runs from CB on northwest corner of intersection to ?	SM-OSE-SD-CB2776-MH2784	CB2776 to JS2801	25		8/6/14	Pipe looks clean and in good condition.
274	153	301	46	42" RCP	Line runs from MH on northwest corner to OS south of PVDS	Line runs from MH on northwest corner to OS south of PVDS	SM-OSE-SD-CB2776-MH2784	CB2776 to JS2801	516		8/7/14	Unmapped MH at 197' & 516'. Pipe looks clean and in good condition.
275	154	302	46	18" RCP	Line starts at CB on Aqua Vista median to CB on PVDS median	Line starts at CB on Aqua Vista median to CB on PVDS median	SM-OSE-SD-CB2793-CB2794	CB2793 to CB2794	23		8/7/14	Pipe looks clean and in good condition.
276	155	303	46	24" RCP	Line runs from CB on Aqua Vista/PVDS median to JS on mainline	Line runs from CB on Aqua Vista/PVDS median to JS on mainline	SM-OSE-SD-CB2793-JS2794	CB2793 to JS2794	63.5		8/7/14	Pipe looks clean and in good condition.
277	156	304	45	30" RCP	Line runs from JS on Forestal Dr. approx. 110' north of intersection to MH on Trump National Dr. southbound	Line runs from JS on Forestal Dr. approx. 110' north of intersection to MH on Trump National Dr. southbound	SM-OSE-SD-JS2793-MH2794	JS2793 to MH2793	365		8/6/14	Pipe looks clean and in good condition.
278	157	306	45	36" RCP	Line runs from MH west of Trump National to OS 275' west of Trump National	Line runs from MH west of Trump National to OS 275' west of Trump National	SM-OSE-SD-MH2793-CB2794	JS2793 to MH2793	298		8/6/14	Pipe looks clean and in good condition.
279	158	309	44	18" RCP	Line runs from CB on parking area island to OS west of Schooner to OS south of PVDS	Line runs from CB on parking area island to OS west of Schooner to OS south of PVDS	SM-OSE-SD-CB2793-JS2794	MH2793 to JS2794	6		8/11/14	Pipe looks clean and in good condition.
280	159	312	43	30" RCP	Line starts at CB on PVDS westbound (approx. 515' west of Schooner) to OS south of PVDS	Line starts at CB on PVDS westbound (approx. 515' west of Schooner) to OS south of PVDS	SM-OSE-SD-CB3405-JS3405	CB3405 to OS3405	35		8/27/14	Line has been lined previously. It is clean and in good condition.
281	160	312.1	43	30" RCP	Line starts at CB on PVDS westbound (approx. 530' west of Schooner) to CB on PVDS eastbound	Line starts at CB on PVDS westbound (approx. 530' west of Schooner) to CB on PVDS eastbound	SM-OSE-SD-CB3405-JS3405	CB3405 to OS3405	70		8/27/14	Pipe looks clean and in good condition.
282	161	313.1	42	18" RCP	Line starts at CB on PVDS westbound approx. 1000' west of Schooner to CB on PVDS eastbound	Line starts at CB on PVDS westbound approx. 1000' west of Schooner to CB on PVDS eastbound	SM-OSE-SD-CB14511-CB6532	CB6532 to OS6531	62		9/11/14	Pipe looks clean and in good condition.
283	162	313.2	42	18" RCP	Line starts at CB in front of the property to CB on PVDS westbound	Line starts at CB in front of the property to CB on PVDS westbound	SM-OSE-SD-CB14511-CB6532	CB6532 to OS6531	42		9/11/14	Pipe looks clean and in good condition.
284	163	319	40	120" CMP	Line starts at IS east of Narcissa to OS west of PVDS	Line starts at IS east of Narcissa to OS west of PVDS	SM-OSS-SD-1500697-GB04503	OS6531 to OS6531	679		8/29/14	Invert has been paved previously. Catch basin at 380.5'. Line looks clean and in good condition.
285	164	320.1	40	24" CMP	Line starts at CB on PVDS westbound 350' west of Narcissa to CB on PVDS eastbound 60' east from nursery school gate entrance	Line starts at CB on PVDS westbound 350' west of Narcissa to CB on PVDS eastbound 60' east from nursery school gate entrance	SM-OSS-SD-GB04504	OS6531 to OS6531	181		9/3/14	Pipe looks clean and in good condition.
286	165	321	40	18" CMP	Line runs from CB on median between Narcissa and nursery school gate to CB on median west of nursery school gate	Line runs from CB on median between Narcissa and nursery school gate to CB on median west of nursery school gate	SM-OSS-SD-JS00706-JS02682	OS6531 to OS6531	43.5		9/3/14	Pipe looks clean and in good condition.
287	166	323	40	36" CMP	Line runs from CB on median west of nursery school gate to CB on median west of nursery school gate	Line runs from CB on median west of nursery school gate to CB on median west of nursery school gate	SM-OSS-SD-JS00706-JS02682	OS6531 to OS6531	369		9/3/14	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments (Phase II)	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
288	167	325	40	24" RCP	Line runs from CB on median west of nursery school gate (approx. 355' east end of median) to CB 200' east. Line runs from CB on median west of nursery school gate (approx. 560' east end of median) to CB 200' east. Line starts at CB on west side of Waylener's Chapel entrance to OS south of PVDOS. Line starts at CB on PVDOS eastbound median to CB on PVDOS westbound median. Line runs from CB on PVDOS eastbound by Park exit to OS adjacent to Abalone Cove Parking.	SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0703.1 to CB0703.1	200	9/8/14	Pipe looks clean and in good condition.		
289	168	326	40	24" RCP		SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	208	9/8/14	Pipe looks clean and in good condition.		
290	169	329	40	24" RCP		Line starts at CB on PVDOS eastbound median to CB on PVDOS westbound median.	SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	117	9/11/14	Pipe looks clean and in good condition.	
291	170	330.1	39	24" RCP		Line starts at CB on PVDOS eastbound median to CB on PVDOS westbound median.	SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	51	9/2/14	Pipe looks clean and in good condition.	
292	171	330.2	39	24" RCP	Line starts at CB on median west of Sacoche to JS southeast corner of intersection. Line starts at CB on median east of Crestmont to OS south of PVDOS.	SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	59	9/12/14	Pipe looks clean and in good condition.		
293	172	334	39	18" RCP		SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	199	9/12/14	Pipe looks clean and in good condition.		
294	173	336	38	18" RCP	Line starts at CB on median east of Crestmont to OS south of PVDOS.	SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	16.5	8/28/14	Pipe looks clean and in good condition.		
295	174	340	37	30" RCP		SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	56	8/28/14	Pipe looks clean and in good condition.		
296	175	340.1	37	30" RCP	Line starts at CB approx. 200' east of Terranea Way on PVDOS eastbound to MH.	SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	239	8/28/14	Pipe looks clean and in good condition.		
297	176	341	37	18" RCP		SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	22	8/28/14	Pipe looks clean and in good condition.		
298	177	344	36	30" RCP	Line runs from CB on median west of Crestmont (approx. 430' west of east end of median) to CB on PVDOS eastbound approx. 415' west of Terranea Way to JS south of PVDOS.	SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	32	9/2/14	Pipe looks clean and in good condition.		
299	178	345	36	30" RCP		SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0696.1 to OS0696.0	116	9/2/14	Pipe looks clean and in good condition.		
300	1	41	10	UNKN	PIPE FOUND	SM-PVN-SD-CB1455-JS2688, SM-PVN-SD-CB1456-JS2688	CB1534 to CB1535	75'		These catch basins were not able to be located in the field.		
301	2	42	18	UNKN	Line starts at CB on Hawthorne southwest corner of intersection to CB on Hawthorne southeast corner. Line runs from CB on Hawthorne southwest corner of intersection to CB on Hawthorne southwest corner.	SM-PVN-SD-CB1455-JS2688, SM-PVN-SD-CB1456-JS2688	CB1456 to CB1458.1	240'		This line was not video inspected for the camera did not fit through any of the access points.		
302	3	43	18	UNKN		SM-PVN-SD-CB1455-JS2688, SM-PVN-SD-CB1456-JS2688	CB1455 to CB1458	60'		This line was not video inspected for the camera did not fit through any of the access points.		
303	4	44	18	UNKN	Line runs from CB on Hawthorne southwest corner of intersection to CB on Hawthorne southwest corner (line not shown on GIS).	SM-PVN-SD-CB1455-JS2688, SM-PVN-SD-CB1456-JS2688	CB1454 to JS2687	150'		This line was not video inspected for the camera did not fit through any of the access points.		
304	5	45	48	UNKN		SM-PVN-SD-CB1455-JS2688, SM-PVN-SD-CB1456-JS2688	MH1885 to East			Line was not video inspected for MH is buried and camera cannot make sharp turns		
305	1	145	26	18" RCP	Line starts at CB 210' north of La Croix to Mainline. Line starts at CB 415' south of Crestia Verde to Mainline.	DNE	CB3179 to Mainline	35		Per contractor, this line does not exist.		
306	2	146	26	18" RCP		DNE	CB3178 to Mainline	45		Per contractor, this line does not exist.		
307	3	346	36	UNKN	Verify that line runs through the middle of median (approx. 880' west of east end of median) to unmaped MH5646.1 south of PVDOS.	SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0539 to 77	77		Line does not exist.		
308	4	347	36	18" RCP		SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0543 to MH5646.1	52	9/12/14	Pipe looks clean and in good condition.		
309	5	348	36	18" RCP	Line runs from unmaped MH5646.1 south of PVDOS (approx. 850' west of Crestmont/Terranea Way) to JS0545/MH5646.	SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	MH5646.1 to MH5646	25	9/12/14	Pipe looks clean and in good condition.		
310	6	349	36	18" RCP		SM-OSW-SD-CB068510-CB068660, SM-OSW-SD-CB068661-CB068810	CB0547 to mainline	35	9/17/14	Pipe looks clean and in good condition.		
311	7	61	14	36" CMP	Line runs along property from CB in front of 28087 Ella to MH on San Nicolas. Line starts in Rolling Hills Estates and ends in canyon OS behind 26441 Silver Spur. Line runs from MH in front of 26635 Whitehorn to MC behind same property. Line starts at CB on northwest corner of intersection (approx. 50' west from the traffic light) to MH on southwest corner of intersection. Pipe runs along Hawthorne from MH on corner of Hawthorne and Indian Peak to CB located west of Indian Peak.	SM-PVN-SD-TS2001-CB1292, SM-PVN-SD-TS2001-CB1292						

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
323	12	196	35	UNKN	Line runs from CB on PYDOS median eastbound to CB across PYDOS eastbound		C94551-46-C94560	35'	35		This line was replaced with Line No. 197.1
324	13	197	35	UNKN	Line runs from CB on PYDOS eastbound off of parking lot entrance/west to OS		C94560 to C94563	30'	30		
14	197.1	35	18" RCP		Line runs from CB on PYDOS eastbound off of parking lot entrance/west to OS		MH4550 to MH4553	205.8	208	11/18/15	Pipe looks clean and in good condition.
15	197.2	35	18" RCP		Line runs from CB on PYDOS eastbound off of parking lot entrance/west to OS		MH4553 to MH4556	58	35	11/18/15	Pipe looks clean and in good condition.
16	197.3	35	18" RCP		Line runs from MH to MH across the full by intersection to OS		MH4556 to MH4559.1	117.3	112.5	11/18/15	Pipe looks clean and in good condition.
17	197.4	35	18" RCP		Line runs from MH to MH across the full by intersection to OS		MH4559.1 to MH4562.2	117.4	112.5	11/18/15	Pipe looks clean and in good condition.
18	197.5	35	18" RCP		Line runs from MH to MH across the full by intersection to OS		MH4562.2 to MH4565.3	201.8	207.8	11/18/15	Pipe looks clean and in good condition.
19	197.6	35	18" RCP		Line runs from MH to MH across the full by intersection to OS		MH4565.3 to MH4568.4	201.8	207.8	11/18/15	Pipe looks clean and in good condition.
20	197.7	35	18" RCP		Line runs from MH to MH across the full by intersection to OS		MH4568.4 to MH4571.5	48.3	48.3	11/18/15	Pipe looks clean and in good condition.
21	197.8	35	18" RCP		Line runs from MH to MH across the full by intersection to OS		MH4571.5 to MH4574.6	114.1	114	11/18/15	Pipe looks clean and in good condition.
22	197.9	35	18" RCP		Line runs from MH to MH across the full by intersection to OS		MH4574.6 to MH4577.7	211.3	211.6	11/18/15	Pipe looks clean and in good condition.
325	23	198	35	UNKN	Line starts at US on PYDOS westbound (approx. 345' east of Japanese Garden entrance) to OS south of PYDOS eastbound		IS4549 to OS4548	155'	155		Pipe looks clean and in good condition.
24	198.1	35	18" RCP		Line runs from MH to MH across the full by intersection to OS		MH4550.3 to MH4553.3	160.6	161	11/18/15	Pipe looks clean and in good condition.
25					Line runs from MH to MH across the full by intersection to OS						
326	24	199	35	UNKN	Line starts at US next to the Japanese Garden to OS on south of PYDOS eastbound (approx. 680' east of Japanese Garden entrance)	SM-OSW-SD-JS1741-GB1747, SM-OSW-SD-GB1747-GB1748, SM-OSW-SD-GB1748-GB1749, SM-OSW-SD-GB1749-GB1750, SM-OSW-SD-GB1750-GB1751, SM-OSW-SD-GB1751-GB1752, SM-OSW-SD-GB1752-GB1753, SM-OSW-SD-GB1753-GB1754, SM-OSW-SD-GB1754-GB1755, SM-OSW-SD-GB1755-GB1756, SM-OSW-SD-GB1756-GB1757, SM-OSW-SD-GB1757-GB1758, SM-OSW-SD-GB1758-GB1759, SM-OSW-SD-GB1759-GB1760, SM-OSW-SD-GB1760-GB1761, SM-OSW-SD-GB1761-GB1762, SM-OSW-SD-GB1762-GB1763, SM-OSW-SD-GB1763-GB1764, SM-OSW-SD-GB1764-GB1765, SM-OSW-SD-GB1765-GB1766, SM-OSW-SD-GB1766-GB1767, SM-OSW-SD-GB1767-GB1768, SM-OSW-SD-GB1768-GB1769, SM-OSW-SD-GB1769-GB1770, SM-OSW-SD-GB1770-GB1771, SM-OSW-SD-GB1771-GB1772, SM-OSW-SD-GB1772-GB1773, SM-OSW-SD-GB1773-GB1774, SM-OSW-SD-GB1774-GB1775, SM-OSW-SD-GB1775-GB1776, SM-OSW-SD-GB1776-GB1777, SM-OSW-SD-GB1777-GB1778, SM-OSW-SD-GB1778-GB1779, SM-OSW-SD-GB1779-GB1780, SM-OSW-SD-GB1780-GB1781, SM-OSW-SD-GB1781-GB1782, SM-OSW-SD-GB1782-GB1783, SM-OSW-SD-GB1783-GB1784, SM-OSW-SD-GB1784-GB1785, SM-OSW-SD-GB1785-GB1786, SM-OSW-SD-GB1786-GB1787, SM-OSW-SD-GB1787-GB1788, SM-OSW-SD-GB1788-GB1789, SM-OSW-SD-GB1789-GB1790, SM-OSW-SD-GB1790-GB1791, SM-OSW-SD-GB1791-GB1792, SM-OSW-SD-GB1792-GB1793, SM-OSW-SD-GB1793-GB1794, SM-OSW-SD-GB1794-GB1795, SM-OSW-SD-GB1795-GB1796, SM-OSW-SD-GB1796-GB1797, SM-OSW-SD-GB1797-GB1798, SM-OSW-SD-GB1798-GB1799, SM-OSW-SD-GB1799-GB1800, SM-OSW-SD-GB1800-GB1801, SM-OSW-SD-GB1801-GB1802, SM-OSW-SD-GB1802-GB1803, SM-OSW-SD-GB1803-GB1804, SM-OSW-SD-GB1804-GB1805, SM-OSW-SD-GB1805-GB1806, SM-OSW-SD-GB1806-GB1807, SM-OSW-SD-GB1807-GB1808, SM-OSW-SD-GB1808-GB1809, SM-OSW-SD-GB1809-GB1810, SM-OSW-SD-GB1810-GB1811, SM-OSW-SD-GB1811-GB1812, SM-OSW-SD-GB1812-GB1813, SM-OSW-SD-GB1813-GB1814, SM-OSW-SD-GB1814-GB1815, SM-OSW-SD-GB1815-GB1816, SM-OSW-SD-GB1816-GB1817, SM-OSW-SD-GB1817-GB1818, SM-OSW-SD-GB1818-GB1819, SM-OSW-SD-GB1819-GB1820, SM-OSW-SD-GB1820-GB1821, SM-OSW-SD-GB1821-GB1822, SM-OSW-SD-GB1822-GB1823, SM-OSW-SD-GB1823-GB1824, SM-OSW-SD-GB1824-GB1825, SM-OSW-SD-GB1825-GB1826, SM-OSW-SD-GB1826-GB1827, SM-OSW-SD-GB1827-GB1828, SM-OSW-SD-GB1828-GB1829, SM-OSW-SD-GB1829-GB1830, SM-OSW-SD-GB1830-GB1831, SM-OSW-SD-GB1831-GB1832, SM-OSW-SD-GB1832-GB1833, SM-OSW-SD-GB1833-GB1834, SM-OSW-SD-GB1834-GB1835, SM-OSW-SD-GB1835-GB1836, SM-OSW-SD-GB1836-GB1837, SM-OSW-SD-GB1837-GB1838, SM-OSW-SD-GB1838-GB1839, SM-OSW-SD-GB1839-GB1840, SM-OSW-SD-GB1840-GB1841, SM-OSW-SD-GB1841-GB1842, SM-OSW-SD-GB1842-GB1843, SM-OSW-SD-GB1843-GB1844, SM-OSW-SD-GB1844-GB1845, SM-OSW-SD-GB1845-GB1846, SM-OSW-SD-GB1846-GB1847, SM-OSW-SD-GB1847-GB1848, SM-OSW-SD-GB1848-GB1849, SM-OSW-SD-GB1849-GB1850, SM-OSW-SD-GB1850-GB1851, SM-OSW-SD-GB1851-GB1852, SM-OSW-SD-GB1852-GB1853, SM-OSW-SD-GB1853-GB1854, SM-OSW-SD-GB1854-GB1855, SM-OSW-SD-GB1855-GB1856, SM-OSW-SD-GB1856-GB1857, SM-OSW-SD-GB1857-GB1858, SM-OSW-SD-GB1858-GB1859, SM-OSW-SD-GB1859-GB1860, SM-OSW-SD-GB1860-GB1861, SM-OSW-SD-GB1861-GB1862, SM-OSW-SD-GB1862-GB1863, SM-OSW-SD-GB1863-GB1864, SM-OSW-SD-GB1864-GB1865, SM-OSW-SD-GB1865-GB1866, SM-OSW-SD-GB1866-GB1867, SM-OSW-SD-GB1867-GB1868, SM-OSW-SD-GB1868-GB1869, SM-OSW-SD-GB1869-GB1870, SM-OSW-SD-GB1870-GB1871, SM-OSW-SD-GB1871-GB1872, SM-OSW-SD-GB1872-GB1873, SM-OSW-SD-GB1873-GB1874, SM-OSW-SD-GB1874-GB1875, SM-OSW-SD-GB1875-GB1876, SM-OSW-SD-GB1876-GB1877, SM-OSW-SD-GB1877-GB1878, SM-OSW-SD-GB1878-GB1879, SM-OSW-SD-GB1879-GB1880, SM-OSW-SD-GB1880-GB1881, SM-OSW-SD-GB1881-GB1882, SM-OSW-SD-GB1882-GB1883, SM-OSW-SD-GB1883-GB1884, SM-OSW-SD-GB1884-GB1885, SM-OSW-SD-GB1885-GB1886, SM-OSW-SD-GB1886-GB1887, SM-OSW-SD-GB1887-GB1888, SM-OSW-SD-GB1888-GB1889, SM-OSW-SD-GB1889-GB1890, SM-OSW-SD-GB1890-GB1891, SM-OSW-SD-GB1891-GB1892, SM-OSW-SD-GB1892-GB1893, SM-OSW-SD-GB1893-GB1894, SM-OSW-SD-GB1894-GB1895, SM-OSW-SD-GB1895-GB1896, SM-OSW-SD-GB1896-GB1897, SM-OSW-SD-GB1897-GB1898, SM-OSW-SD-GB1898-GB1899, SM-OSW-SD-GB1899-GB1900, SM-OSW-SD-GB1900-GB1901, SM-OSW-SD-GB1901-GB1902, SM-OSW-SD-GB1902-GB1903, SM-OSW-SD-GB1903-GB1904, SM-OSW-SD-GB1904-GB1905, SM-OSW-SD-GB1905-GB1906, SM-OSW-SD-GB1906-GB1907, SM-OSW-SD-GB1907-GB1908, SM-OSW-SD-GB1908-GB1909, SM-OSW-SD-GB1909-GB1910, SM-OSW-SD-GB1910-GB1911, SM-OSW-SD-GB1911-GB1912, SM-OSW-SD-GB1912-GB1913, SM-OSW-SD-GB1913-GB1914, SM-OSW-SD-GB1914-GB1915, SM-OSW-SD-GB1915-GB1916, SM-OSW-SD-GB1916-GB1917, SM-OSW-SD-GB1917-GB1918, SM-OSW-SD-GB1918-GB1919, SM-OSW-SD-GB1919-GB1920, SM-OSW-SD-GB1920-GB1921, SM-OSW-SD-GB1921-GB1922, SM-OSW-SD-GB1922-GB1923, SM-OSW-SD-GB1923-GB1924, SM-OSW-SD-GB1924-GB1925, SM-OSW-SD-GB1925-GB1926, SM-OSW-SD-GB1926-GB1927, SM-OSW-SD-GB1927-GB1928, SM-OSW-SD-GB1928-GB1929, SM-OSW-SD-GB1929-GB1930, SM-OSW-SD-GB1930-GB1931, SM-OSW-SD-GB1931-GB1932, SM-OSW-SD-GB1932-GB1933, SM-OSW-SD-GB1933-GB1934, SM-OSW-SD-GB1934-GB1935, SM-OSW-SD-GB1935-GB1936, SM-OSW-SD-GB1936-GB1937, SM-OSW-SD-GB1937-GB1938, SM-OSW-SD-GB1938-GB1939, SM-OSW-SD-GB1939-GB1940, SM-OSW-SD-GB1940-GB1941, SM-OSW-SD-GB1941-GB1942, SM-OSW-SD-GB1942-GB1943, SM-OSW-SD-GB1943-GB1944, SM-OSW-SD-GB1944-GB1945, SM-OSW-SD-GB1945-GB1946, SM-OSW-SD-GB1946-GB1947, SM-OSW-SD-GB1947-GB1948, SM-OSW-SD-GB1948-GB1949, SM-OSW-SD-GB1949-GB1950, SM-OSW-SD-GB1950-GB1951, SM-OSW-SD-GB1951-GB1952, SM-OSW-SD-GB1952-GB1953, SM-OSW-SD-GB1953-GB1954, SM-OSW-SD-GB1954-GB1955, SM-OSW-SD-GB1955-GB1956, SM-OSW-SD-GB1956-GB1957, SM-OSW-SD-GB1957-GB1958, SM-OSW-SD-GB1958-GB1959, SM-OSW-SD-GB1959-GB1960, SM-OSW-SD-GB1960-GB1961, SM-OSW-SD-GB1961-GB1962, SM-OSW-SD-GB1962-GB1963, SM-OSW-SD-GB1963-GB1964, SM-OSW-SD-GB1964-GB1965, SM-OSW-SD-GB1965-GB1966, SM-OSW-SD-GB1966-GB1967, SM-OSW-SD-GB1967-GB1968, SM-OSW-SD-GB1968-GB1969, SM-OSW-SD-GB1969-GB1970, SM-OSW-SD-GB1970-GB1971, SM-OSW-SD-GB1971-GB1972, SM-OSW-SD-GB1972-GB1973, SM-OSW-SD-GB1973-GB1974, SM-OSW-SD-GB1974-GB1975, SM-OSW-SD-GB1975-GB1976, SM-OSW-SD-GB1976-GB1977, SM-OSW-SD-GB1977-GB1978, SM-OSW-SD-GB1978-GB1979, SM-OSW-SD-GB1979-GB1980, SM-OSW-SD-GB1980-GB1981, SM-OSW-SD-GB1981-GB1982, SM-OSW-SD-GB1982-GB1983, SM-OSW-SD-GB1983-GB1984, SM-OSW-SD-GB1984-GB1985, SM-OSW-SD-GB1985-GB1986, SM-OSW-SD-GB1986-GB1987, SM-OSW-SD-GB1987-GB1988, SM-OSW-SD-GB1988-GB1989, SM-OSW-SD-GB1989-GB1990, SM-OSW-SD-GB1990-GB1991, SM-OSW-SD-GB1991-GB1992, SM-OSW-SD-GB1992-GB1993, SM-OSW-SD-GB1993-GB1994, SM-OSW-SD-GB1994-GB1995, SM-OSW-SD-GB1995-GB1996, SM-OSW-SD-GB1996-GB1997, SM-OSW-SD-GB1997-GB1998, SM-OSW-SD-GB1998-GB1999, SM-OSW-SD-GB1999-GB2000, SM-OSW-SD-GB2000-GB2001, SM-OSW-SD-GB2001-GB2002, SM-OSW-SD-GB2002-GB2003, SM-OSW-SD-GB2003-GB2004, SM-OSW-SD-GB2004-GB2005, SM-OSW-SD-GB2005-GB2006, SM-OSW-SD-GB2006-GB2007, SM-OSW-SD-GB2007-GB2008, SM-OSW-SD-GB2008-GB2009, SM-OSW-SD-GB2009-GB2010, SM-OSW-SD-GB2010-GB2011, SM-OSW-SD-GB2011-GB2012, SM-OSW-SD-GB2012-GB2013, SM-OSW-SD-GB2013-GB2014, SM-OSW-SD-GB2014-GB2015, SM-OSW-SD-GB2015-GB2016, SM-OSW-SD-GB2016-GB2017, SM-OSW-SD-GB2017-GB2018, SM-OSW-SD-GB2018-GB2019, SM-OSW-SD-GB2019-GB2020, SM-OSW-SD-GB2020-GB2021, SM-OSW-SD-GB2021-GB2022, SM-OSW-SD-GB2022-GB2023, SM-OSW-SD-GB2023-GB2024, SM-OSW-SD-GB2024-GB2025, SM-OSW-SD-GB2025-GB2026, SM-OSW-SD-GB2026-GB2027, SM-OSW-SD-GB2027-GB2028, SM-OSW-SD-GB2028-GB2029, SM-OSW-SD-GB2029-GB2030, SM-OSW-SD-GB2030-GB2031, SM-OSW-SD-GB2031-GB2032, SM-OSW-SD-GB2032-GB2033, SM-OSW-SD-GB2033-GB2034, SM-OSW-SD-GB2034-GB2035, SM-OSW-SD-GB2035-GB2036, SM-OSW-SD-GB2036-GB2037, SM-OSW-SD-GB2037-GB2038, SM-OSW-SD-GB2038-GB2039, SM-OSW-SD-GB2039-GB2040, SM-OSW-SD-GB2040-GB2041, SM-OSW-SD-GB2041-GB2042, SM-OSW-SD-GB2042-GB2043, SM-OSW-SD-GB2043-GB2044, SM-OSW-SD-GB2044-GB2045, SM-OSW-SD-GB2045-GB2046, SM-OSW-SD-GB2046-GB2047, SM-OSW-SD-GB2047-GB2048, SM-OSW-SD-GB2048-GB2049, SM-OSW-SD-GB2049-GB2050, SM-OSW-SD-GB2050-GB2051, SM-OSW-SD-GB2051-GB2052, SM-OSW-SD-GB2052-GB2053, SM-OSW-SD-GB2053-GB2054, SM-OSW-SD-GB2054-GB2055, SM-OSW-SD-GB2055-GB2056, SM-OSW-SD-GB2056-GB2057, SM-OSW-SD-GB2057-GB2058, SM-OSW-SD-GB2058-GB2059, SM-OSW-SD-GB2059-GB2060, SM-OSW-SD-GB2060-GB2061, SM-OSW-SD-GB2061-GB2062, SM-OSW-SD-GB2062-GB2063, SM-OSW-SD-GB2063-GB2064, SM-OSW-SD-GB2064-GB2065, SM-OSW-SD-GB2065-GB2066, SM-OSW-SD-GB2066-GB2067, SM-OSW-SD-GB2067-GB2068, SM-OSW-SD-GB2068-GB2069, SM-OSW-SD-GB2069-GB2070, SM-OSW-SD-GB2070-GB2071, SM-OSW-SD-GB2071-GB2072, SM-OSW-SD-GB2072-GB2073, SM-OSW-SD-GB2073-GB2074, SM-OSW-SD-GB2074-GB2075, SM-OSW-SD-GB2075-GB2076, SM-OSW-SD-GB2076-GB2077, SM-OSW-SD-GB2077-GB2078, SM-OSW-SD-GB2078-GB2079, SM-OSW-SD-GB2079-GB2080, SM-OSW-SD-GB2080-GB2081, SM-OSW-SD-GB2081-GB2082, SM-OSW-SD-GB2082-GB2083, SM-OSW-SD-GB2083-GB2084, SM-OSW-SD-GB2084-GB2085, SM-OSW-SD-GB2085-GB2086, SM-OSW-SD-GB2086-GB2087, SM-OSW-SD-GB2087-GB2088, SM-OSW-SD-GB2088-GB2089, SM-OSW-SD-GB2089-GB2090, SM-OSW-SD-GB2090-GB2091, SM-OSW-SD-GB2091-GB2092, SM-OSW-SD-GB2092-GB2093, SM-OSW-SD-GB2093-GB2094, SM-OSW-SD-GB2094-GB2095, SM-OSW-SD-GB2095-GB2096, SM-OSW-SD-GB2096-GB2097, SM-OSW-SD-GB2097-GB2098, SM-OSW-SD-GB2098-GB2099, SM-OSW-SD-GB2099-GB2100, SM-OSW-SD-GB2100-GB2101, SM-OSW-SD-GB2101-GB2102, SM-OSW-SD-GB2102-GB2103, SM-OSW-SD-GB2103-GB2104, SM-OSW-SD-GB2104-GB2105, SM-OSW-SD-GB2105-GB2106, SM-OSW-SD-GB2106-GB2107, SM-OSW-SD-GB2107-GB2108, SM-OSW-SD-GB2108-GB2109, SM-OSW-SD-GB2109-GB2110, SM-OSW-SD-GB2110-GB2111, SM-OSW-SD-GB2111-GB2112, SM-OSW-SD-GB2112-GB2113, SM-OSW-SD-GB2113-GB2114, SM-OSW-SD-GB2114-GB2115, SM-OSW-SD-GB2115-GB2116, SM-OSW-SD-GB2116-GB2117, SM-OSW-SD-GB2117-GB2118, SM-OSW-SD-GB2118-GB2119, SM-OSW-SD-GB2119-GB2120, SM-OSW-SD-GB2120-GB2121, SM-OSW-SD-GB2121-GB2122, SM-OSW-SD-GB2122-GB2123, SM-OSW-SD-GB2123-GB2124, SM-OSW-SD-GB2124-GB2125, SM-OSW-SD-GB2125-GB2126, SM-OSW-SD-GB2126-GB2127, SM-OSW-SD-GB2127-GB2128, SM-OSW-SD-GB2128-GB2129, SM-OSW-SD-GB2129-GB2130, SM-OSW-SD-GB2130-GB2131, SM-OSW-SD-GB2131-GB2132, SM-OSW-SD-GB2132-GB2133, SM-OSW-SD-GB2133-GB2134, SM-OSW-SD-GB2134-GB2135, SM-OSW-SD-GB2135-GB2136, SM-OSW-SD-GB2136-GB2137, SM-OSW-SD-GB2137-GB2138, SM-OSW-SD-GB2138-GB2139, SM-OSW-SD-GB2139-GB2140, SM-OSW-SD-GB2140-GB2141, SM-OSW-SD-GB2141-GB2142, SM-OSW-SD-GB2142-GB2143, SM-OSW-SD-GB2143-GB2144, SM-OSW-SD-GB2144-GB2145, SM-OSW-SD-GB2145-GB2146, SM-OSW-SD-GB2146-GB2147, SM-OSW-SD-GB2147-GB2148, SM-OSW-SD-GB2148-GB2149, SM-OSW-SD-GB2149-GB2150, SM-OSW-SD-GB2150-GB2151, SM-OSW-SD-GB2151-GB2152, SM-OSW-SD-GB2152-GB2153, SM-OSW-SD-GB2153-GB2154, SM-OSW-SD-GB2154-GB2155, SM-OSW-SD-GB2155-GB2156, SM-OSW-SD-GB2156-GB2157, SM-OSW-SD-GB2157-GB2158, SM-OSW-SD-GB2158-GB2159, SM-OSW-SD-GB2159-GB2160, SM-OSW-SD-GB2160-GB2161, SM-OSW-SD-GB2161-GB2162, SM-OSW-SD-GB2162-GB2163, SM-OSW-SD-GB2163-GB2164, SM-OSW-SD-GB2164-GB2165, SM-OSW-SD-GB2165-GB2166, SM-OSW-SD-GB2166-GB2167, SM-OSW-SD-GB2167-GB2168, SM-OSW-SD-GB2168-GB2169, SM-OSW-SD-GB2169-GB2170, SM-OSW-SD-GB2170-GB2171, SM-OSW-SD-GB2171-GB2172, SM-OSW-SD-GB2172-GB2173, SM-OSW-SD-GB2173-GB2174, SM-OSW-SD-GB2174-GB2175, SM-OSW-SD-GB2175-GB2176, SM-OSW-SD-GB2176-GB2177, SM-OSW-SD-GB2177-GB2178, SM-OSW-SD-GB2178-GB2179, SM-OSW-SD-GB2179-GB2180, SM-OSW-SD-GB2180-GB2181, SM-OSW-SD-GB2181-GB2182, SM-OSW-SD-GB2182-GB2183, SM-OSW-SD-GB2183-GB2184, SM-OSW-SD-GB2184-GB2185, SM-OSW-SD-GB2185-GB2186, SM-OSW-SD-GB2186-GB2187, SM-OSW-SD-GB2187-GB2188, SM-OSW-SD-GB2188-GB2189, SM-OSW-SD-GB2189-GB2190, SM-OSW-SD-GB2190-GB2191, SM-OSW-SD-GB2191-GB2192, SM-OSW-SD-GB2192-GB2193, SM-OSW-SD-GB2193-GB2194, SM-OSW-SD-GB2194-GB2195, SM-OSW-SD-GB2195-GB2196, SM-OSW-SD-GB2196-GB2197, SM-OSW-SD-GB2197-GB2198, SM-OSW-SD-GB2198-GB2199, SM-OSW-SD-GB2199-GB2200, SM-OSW-SD-GB2200-GB2201, SM-OSW-SD-GB2201-GB2202, SM-OSW-SD-GB2202-GB2203, SM-OSW-SD-GB2203-GB2204, SM-OSW-SD-GB2204-GB2205, SM-OSW-SD-GB2205-GB2206, SM-OSW-SD-GB2206-GB2207, SM-OSW-SD-GB2207-GB2208, SM-OSW-SD-GB2208-GB2209, SM-OSW-SD-GB2209-GB2210, SM-OSW-SD-GB2210-GB2211, SM-OSW-SD-GB2211-GB2212, SM-OSW-SD-GB2212-GB2213, SM-OSW-SD-GB2213-GB2214, SM-OSW-SD-GB2214-GB2215, SM-OSW-SD-GB2215-GB2216, SM-OSW-SD-GB2216-GB2217, SM-OSW-SD-GB2217-GB2218, SM-OSW-SD-GB2218-GB2219, SM-OSW-SD-GB2219-GB2220, SM-OSW-SD-GB2220-GB2221, SM-OSW-SD-GB2221-GB2222, SM-OSW-SD-GB2222-GB2223, SM-OSW-SD-GB2223-GB2224, SM-OSW-SD-GB2224-GB2225, SM-OSW-SD-GB2225-GB2226, SM-OSW-SD-GB2226-GB2227, SM-OSW-SD-GB2227-GB2228, SM-OSW-SD-GB2228-GB2229, SM-OSW-SD-GB2229-GB2230, SM-OSW-SD-GB2230-GB2231, SM-OSW-SD-GB2231-GB2232, SM-OSW-SD-GB2232-GB2233, SM-OSW-SD-GB2233-GB2234, SM-OSW-SD-GB2234-GB2235, SM-OSW-SD-GB2235-GB2236, SM-OSW-SD-GB2236-GB2237, SM-OSW-SD-GB2237-GB2238, SM-OSW-SD-GB2238-GB2239, SM-OSW-SD-GB2239-GB2240, SM-OSW-SD-GB2240-GB2241, SM-OSW-SD-GB2241-GB2242, SM-OSW-SD-GB2242-GB2243, SM-OSW-SD-GB2243-GB2244, SM-OSW-SD-GB2244-GB2245, SM-OSW-SD-GB2245-GB2246, SM-OSW-SD-GB2246-GB2247, SM-OSW-SD-GB2247-GB2248, SM-OSW-SD-GB2248-GB2249, SM-OSW-SD-GB2249-GB2250, SM-OSW-SD-GB2250-GB2251, SM-OSW-SD-GB2251-GB2252, SM-OSW-SD-GB2252-GB2253, SM-OSW-SD-GB2253-GB2254, SM-OSW-SD-GB2254-GB2255, SM-OSW-SD-GB2255-GB2256, SM-OSW-SD-GB2256-GB2257, SM-OSW-SD-GB2257-GB2258, SM-OSW-SD-GB2258-GB2259, SM-OSW-SD-GB2259-GB2260, SM-OSW-SD-GB2260-GB2261, SM-OSW-SD-GB2261-GB2262, SM-OSW-SD-GB2262-GB2263, SM-OSW-SD-GB2263-GB2264, SM-OSW-SD-GB2264-GB2265, SM-OSW-SD-GB2265-GB2266, SM-OSW-SD-GB2266-GB2267, SM-OSW-SD-GB2267-GB2268, SM-OSW-SD-GB2268-GB2269, SM-OSW-SD-GB2269-GB2270, SM-OSW-SD-GB2270-GB2271, SM-OSW-SD-GB2271-GB2272, SM-OSW-SD-GB2272-GB2273, SM-OSW-SD-GB2273-GB2274, SM-OSW-SD-GB2274-GB2275, SM-OSW-SD-GB2275-GB2276, SM-OSW-SD-GB2276-GB2277, SM-OSW-SD-GB2277-GB2278, SM-OSW-SD-GB2278-GB2279, SM-OSW-SD-GB2279-GB2280, SM-OSW-SD-GB2280-GB2281, SM-OSW-SD-GB2281-GB2282, SM-OSW-SD-GB2282-GB2283, SM-OSW-SD-GB2283-GB2284, SM-OSW-SD-GB2284-GB2285, SM-OSW-SD-GB2285-GB2286, SM-OSW-SD-GB2286-GB2287, SM-OSW-SD-GB2287-GB2288, SM-OSW-SD-GB2288-GB2289, SM-OSW-SD-GB2289-GB2290, SM-OSW-SD-GB2290-GB2291, SM-OSW-SD-GB2291-GB2292, SM-OSW-SD-GB2292-GB2293, SM-OSW-SD-GB2293-GB2294, SM-OSW-SD-GB2294-GB2295, SM-OSW-SD-GB2295-GB2296, SM-OSW-SD-GB2296-GB2297, SM-OSW-SD-GB2297-GB2298, SM-OSW-SD-					

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
351	49	232	54		36" RCP	Line runs from MH on PVDE at Bronco Dr. to MH on PVDE at West Headland Dr.	LA-LAN-SD-MH3491-JS3492, LA-LAN-SD-JS3492-MH3498	MH3491 to MH3498	403.5	403.5	11/21/15	Pipe looks clean and in good condition.
352	50	233	54		18" RCP	Line runs from CB in front of west corner of property to JS in mainline	LA-LAN-SD-SD-CB3490-JS3492, LA-LAN-SD-MH3491-JS3492	CB3490 to JS3491	16	16	12/1/15	Pipe looks clean and in good condition.
353	51	236	54		36" RCP	Line runs from MH on PVDE at West Headland to MH on PVDE at East Headland	LA-LAN-SD-MH3496-GB3497, LA-LAN-SD-GB3497-MH3498	MH3496 to MH3498	404.5	404.5	11/21/15	Pipe looks clean and in good condition.
354	52	237	54		36" RCP	Line runs from MH on PVDE at East Headland to MH in front of 28214 PVDE	LA-LAN-SD-MH3498-GB3499, LA-LAN-SD-GB3499-JS3500, LA-LAN-SD-JS3500-MH3501	MH3498 to MH3501	467	467	11/21/15	Pipe looks clean and in good condition.
355	53	238	54		18" RCP	Line runs from CB in front of 28217 PVDE to JS in mainline	LA-LAN-SD-CB0686-JS3500	CB0686 to JS3500	18.5	18.5	12/1/15	Pipe looks clean and in good condition.
356	54	239	54		36" RCP	Line runs from MH in front of 28215 PVDE to MH in front of 28191 PVDE	LA-LAN-SD-MH3501-MH3502, LA-LAN-SD-MH3502-JS3503, LA-LAN-SD-JS3503-MH3504, LA-LAN-SD-MH3504-GB3505, LA-LAN-SD-GB3505-JS3507, LA-LAN-SD-JS3507-TS3508, LA-LAN-SD-TS3508-JS3505	MH3501 to MH3502	384	384	11/21/15	Pipe looks clean and in good condition.
357	55	240	54		36" RCP	Line runs from MH in front of 28191 PVDE to OS in 28180 PVDE property	LA-LAN-SD-MH3501-MH3502, LA-LAN-SD-MH3502-JS3503, LA-LAN-SD-JS3503-MH3504, LA-LAN-SD-MH3504-GB3505, LA-LAN-SD-GB3505-JS3507, LA-LAN-SD-JS3507-TS3508, LA-LAN-SD-TS3508-JS3505	MH3502 to OS3505	309	309	11/21/15	Pipe looks clean and in good condition.
358	56	241	54		18" RCP	Line runs from CB in front of 28191 PVDE to JS in mainline	LA-LAN-SD-CB3504-JS3503	CB3504 to JS3503	12	12	12/1/15	Pipe looks clean and in good condition. Pipe was named CB0686 to JS3500 in the video by accident but it is for CB3504 to JS3503
359	57	343	55		36" CMP	Line starts at inlet behind 5 Mustang Rd. property to OS on 28683 Roan		Cannot access to OS3503	41	41	6/23/14	Check if E2003 exists. Light is not visible in inspection. No pipe.
360	58	246	55		UNKWN	Line starts at CB south of Mustang to JS 30' north	LA-LAN-SD-CB0911-JS2708	CB0911 to JS2708	30'	30'		No inspection nor reports given. Might not exist.
361	59	247	55		UNKWN	Line starts at inlet south of Mustang to outlet on 9' Rockinghorse	LA-LAN-SD-SD-OS0910-JS2708, LA-LAN-SD-JS2708-OS0912	IS0910 to OS0912	150'	150'		No inspection nor reports given. Might not exist.
362	60	275	49		48" RCP	Line runs from CB off of main IS north of PVDS (approx. 450' west of PVDE) to JS on mainline		CB0318 to JS2699	10'	10'		No inspection nor reports given. Might not exist.
363	61	278	49		24" RCP	Line runs from CB on PVDE approx. 50' east of PVDS to JS on mainline		CB0315 to JS2696	75'	75'		No inspection nor reports given. Might not exist.
364	62	280	48		UNKWN	Line runs from MH in PVDS median (approx. 335' east of median west end) to ??		MH1865 to ??	20'	20'		No inspection nor reports given. Might not exist.
365	63	295	46		18" RCP	Line starts at CB on Forrestal approx. 70' north of Aqua Vista to JS on mainline	SM-OSE-SD-CB2778-JS2780, SM-OSE-SD-JS2780-JS2783	CB2778 to JS2783	100'	100'		No inspection nor reports given. Might not exist.
366	64	300	46		UNKWN	Line starts all IS north of PVDS to OS south of PVDS	SM-OSE-SD-IS2796-JS2796	IS2796 to OS2797	75'	75'		Line exists but IS has not been located. Line is shown on video from MH2793 to OS2797
367	65	307	45		18" RCP	Line starts at CB on PVDS to OS south of PVDS	SM-OSE-SD-OS3405-MH0477	MH3405 to OS3477	??	??		No inspection nor reports given. Might not exist.
368	66	309.1	44		UNKWN	Line starts at OS south of Trump National to OS	SM-OSE-SD-CB3406-JS3409	CB3406 to ??	??	??		No inspection nor reports given. Might not exist.
369	67	310	44		UNKWN	Line starts at CB off of parking area to ??		CB0488 to OS3487	180'	180'		No inspection nor reports given. Might not exist.
370	68	311	43		UNKWN	Line starts at OS south of PVDS		OS3488 to CB 225.35	107.6	108	1/22/15	Uninspected buried MH at 97.35 from IS. Overall line looks clean and in good condition. Video stops at the JS Turner video is needed to inspect line to the OS.
371	69	314	42		32" CMP	Line starts at US east end of Gateway Parking area to OS south of PVDS		IS0706 to OS0707	205'	205'		No inspection nor reports given. Might not exist.
372	70	315	42		30" CMP	Line runs from CB on northwest corner to OS across PVDS	SM-OSS-SD-IS00708-TS00707	CB3468 to OS3467	180'	180'		No inspection nor reports given. Might not exist.
373	71	318	41		24" STL	Line runs from CB on PVDS eastbound 60' east from nursery school gate entrance to JS		OS0698 to JS2682	115'	115'		Does NOT exist
374	72	322	40		UNKWN	Line starts at IS below Wayfarer's Chapel to CB on PVDS median	SM-OSS-SD-IS00916-JS0911, SM-OSS-SD-IS00911-JS00701, SM-OSS-SD-IS00701-CB00703	IS0912 to CB0703	800'	800'		Does NOT exist
375	73	328	40		24" CMP	Line runs from CB on median east of Saco Dr. to ??		CB0687 to ??	??	??		Does NOT exist
376	74	331	39		UNKWN	Line starts all IS west of dirt road to CB at corner of PVDS and Dirt Road		IS0687 to CB0686	20'	20'		Does NOT exist
377	75	332	39		UNKWN	Line runs from CB at southwest corner of PVDS & Saco Dr. to JS		CB0664 to JS2681	70'	70'		Does NOT exist
378	76	335	39		UNKWN	Existing line in front of JS2681 running towards the ocean (not shown on GIS).						shown on GIS. Line was not video inspected due to sand and debris. There is a defect in the future to make improvements to the storm drain lines in the area.
379	77	335.1	39		UNKWN							

Storm Drain Video Inspection Legend

not reviewed)	
Line is in good condition	
Light/minor defect condition	
Moderate defect condition	
Average defect condition	
Heavy defect condition	
Severe defect condition	
to inspect	
Line does not exist	

11,035

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
------------------------------------	---	---------------------	---------------------------	---------------	-----------------	------------------	----------------	-----------------------------------	--------------------------------------	----------------	------------	----------

GIS update needed

Storm Drain Video Inspection & Cleaning Services FY 10 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
375	1	116	73	18" CMP	Line starts at CB on Crenshaw Blvd. southbound (approx. 780' north of Crest Rd.) to MH on Crenshaw Blvd. northbound	ML-RHE-SD-CB3447-CB48532	CB3447 to MH3399	60		11/11/2014	Heavy corrosion throughout the pipe. Holes at various locations. Inspection abandoned at 38' due to hole in pipe.
376	2	428	78	30" CMP & RCP	Line runs from CB on Hawthorne (approx. 445' south from intersection) to MH on vacant lot behind Ralph's	SM-OWW-SD-CB1096-JS48132, SM-OWW-SD-JS48132-MH1101	MH1096 to MH1101	116		11/13/2014	Pipe is CMP for the first 30' from MH1096; heavy corrosion and holes throughout the pipe. Pipe is RCP from 30' to 94'; clean and in good condition. Pipe changes to CMP from 94' to 116'; pipe has heavy corrosion and holes.
377	3	476	104	18" RCP	Line runs from CB on Seacove between Barkenline & Packet to JS	SM-OSW-SD-CB0679-JS3538	CB0679 to JS3538	20		10/21/2014	Line is completely blocked by debris at the JS. Overall line is in good condition.
378	4	581	58	36" CMP	Line starts at CB on Hawthorne northbound approx. 265' south of intersection to MH on median	265' SM-PWV-SD-CB1338-JS28915, SM-PWV-SD-JS28915-MH1345	CB1338 to MH1345	20		11/10/2014	Holes throughout the pipe. Inspection abandoned at 20' due to voids.
379	5	614	88	18" CMP	Line starts at CB in front of property to MH in property's backyard	SM-OSW-SD-CB2914, SM-OSW-SD-CB2914-CB2915, SM-OSW-SD-CB2915-MH2910	CB2911 to MH2910	389		11/15/2014	Pipe has been lined previously. Collapsed pipe at 389'. Overall line is clean and in good condition.
380	6	619	98	24" CMP	Line runs from MH in front of 31311 Marne Dr. to OS in canyon behind property	SM-OSW-SD-MH1619-CB1900, SM-OSW-SD-CB1900-CB1899, SM-OSW-SD-CB1899-CB1897, SM-OSW-SD-CB1897-CB1898, SM-OSW-SD-CB1898-CB1896, SM-OSW-SD-CB1896-OS0720	MH1619 to OS0720	265		11/15/2014	Hole at the end of the OS pipe. Overall line is clean and in good condition.
381	7	666	138	24" CMP	Line starts at CB on Western Ave. southbound (approx. 750' north of Green Hills Dr.) to	LA-LAN-SD-CB0213-CB0212	CB0213 to CB0212	87		10/15/2014	Heavy corrosion throughout the pipe. Debris and sand starting at 60' to 87' (approx. 20% to 40%). Inspection abandoned at 87' due to hole and debris.
382	8	684	82	30" CMP	Line runs from MH on Crenshaw Blvd. southbound (approx. 240' south of San Clemente Pl.) to IS across Crenshaw Blvd.	SM-OSS-SD-JS03292-MH00996, SM-OSS-SD-IS03291-JS03292	MH0096 to IS03291	8	120	12/8/2014	Medium to heavy corrosion throughout the pipe. Portion of the pipe invert live lifted up. Inspection abandoned at 7' 5' due to broken pipe.
383	9	677	93	48" CMP	Line runs from CB on PWDW northbound (approx. 670' south of Hawthorne) to JS	SM-OSF-SD-CB0389-JS0392	CB0389 to JS2856	79	?	12/8/2014	Pipe is clogged 100% with soil and rocks. Inspection abandoned
384	10	774	119	18" RCP	Line runs from CB in front of property to JS		CB0413 2b OS0413.3	82	82	11/20/2014	Pipe has a hole from 10 to 2 o'clock at 49' to 51'; visible rebar and debris intrusion. Also cracks around the hole at 49'. Outlet is covered by tree or bush branches.
385	11	812	110	18" RCP & CMP	Line runs from CB on Crest northbound (approx. 165' south of Ganado Dr.) to ??		CB0413 2b OS0413.3	132	?	12/15/2014	The first 27' are RCP in good condition. Thereafter is CMP with light to moderate corrosion. Holes throughout the line. Inspection abandoned at 132' due to hole in pipe.
386	12	894	109	30" RCP	Line runs from MH adjacent to the road to CB in the grass area next to the Ladera Linda Comm. basketball courts	LA-LAS-SD-CB0228-OS0227	MH2689 to CB0509	458.6	459	12/5/2015	Hard deposits at the beginning of the pipe from MH2689 to 10' approx. 20%. The rest of the line looks clean and in good condition.
387	13	928	111	12" RCP	Line starts at CB in front of property to OS behind property	LA-LAS-SD-CB0028-OS0227	CB0228 to OS0227	60	1580	12/19/2015	Multiple cracks at 31'. Severe cracks from 41' to 44'. Rebar intrusion at 52'. Inspection abandoned at 60' due to settled deposits approx. 50%.
388	14	922	111	12" RCP	Line runs from CB across from property to OS down the canyon	LA-LAS-SD-CB0051-OS0052	CB0051 to OS0052	5	65	12/8/2015	Broken pipe; soil is visible at 1'. Inspection abandoned due to debris blockage at 5'.
389	15	921	112	12" CMP	Line runs from CB in front of property to CB in front of 6512 Via Colmita	LA-LAS-SD-CB0250-CB0249	CB0250 to CB0249	39	165	12/8/2015	Heavy corrosion from 0' to 36'. Pipe material changes after 36' to RCP; pipe is severely broken and blocked 95% by debris (mainly rocks).
390	16	799	116	18" CMP	Line runs from CB in front of property to CB behind property	LA-LAS-SD-CB0293-CB0292, LA-LAS-SD-CB0292-CB1905, LA-LAS-SD-CB1905-CB42524, LA-LAS-SD-CB42524-CB2608	CB0293 to CB2608	238	260	12/4/2014	Heavy corrosion throughout the pipe. Debris and rock deposits from CB0293 to 33' approx. 10%. Missing a portion of CMP along the pipe on both side approx. 2" to 3". Missing invert starting at 238' to 77'. Inspection abandoned due to void.
391	17	440	86	36" CMP	Line runs from MH approx. 160' east of property to MH in the middle of golf course	SM-OWW-SD-MH0629-MH0628	MH0628 to MH0629	330			This line was not able to be inspected due to inaccessibility. I assumed the line is in the condition as line no. 500.
392	18	590	86	30" CMP	Line runs from MH in the middle of the golf course to ?? DNE		MH0629 to CB0630	??			Inspection abandoned at the beginning of the line starting from CB0630 due to large void and heavy corrosion in pipe.
393	19	502	86	15" CMP	Line starts at CB on Los Verdes Dr. (approx. 130' north of golf course parking entrance) to ??	DNE	CB0631 to IS ??	31		10/30/2014	Light corrosion throughout the pipe. Debris starting at 15' to IS - 50%
394	20	538	89	36" RCP	Line starts at IS on Via Del Cielo northbound to MH in the middle of the street	SM-OWW-SD-IS1683-CB1682	IS1683 to CB1682	16		10/23/2014	Hard deposits throughout the pipe - 40%.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
395	628	98	18" RCP	Line starts at CB on Hawthorne median (approx. 200' north of Vallon Dr.) to CB on Hawthorne southbound	SM-OSW-SD-CB0725-CB0728	CB0725 to CB0728	50		11/4/2014	Surface missing wall (exposed rebar) from 10 to 2 o'clock (approx. 2' to 3' in length). The rest of the pipe is clean and in good condition.
396	671	104	18" RCP	Line runs from MH in front of 32 Seacove to MH in front of 36 Seacove	SM-OSW-SD-MH3532-JS3535, SM-OSW-SD-JS3538-JS3539, SM-OSW-SD-JS3533-MH3528	MH3532 to MH3528	242		10/21/2014	Plastic sheeling blocking pipe -40% at 212' from MH3532; this seems to be at JS3538 where line is full of debris per video CB0679 to JS3538 (line no. 675). Overall line is clean and in good condition. The first 187' from MH0160 have been lined; thereafter is RCP. Joint separation at 285'; sand bags hanging from open joint. Hole at 281' from 5 to 7 o'clock.
397	603	124	30" CMP	Line runs from MH in front of property to CB on Western Dr	LA-LAE-SD-MH0160-GB0161, LA-LAE-SD-GB0161-	MH0160 to CB1908	296		10/6/2014	Inspection abandoned at 20' due to soil in pipe -50%. Overall pipe in good condition.
398	638	134	18" RCP	Line runs from IS adjacent to CalWater's driveway to CB		IS3121 to CB3122	22		10/13/2014	
399	379	67	18" RCP	Line runs from CB in front of property to PC behind same property	SM-PVW-SD-CB1251-PC1250	CB1251 to PC1250	169		11/7/2014	Hard deposits from the beginning of the pipe to 17' (approx. 10%). Hard deposits from 33' to 60' (approx. 15%). The rest of the pipe is clean and in good condition.
400	383	68	18" RCP	Line starts at CB in front of property to MH on Dorrville Dr.	SM-PVW-SD-CB1424-GB2483, SM-PVW-SD-GB2483-MH2522	CB1424 to MH2522	187		11/10/2014	Top portion of pipe is broken at 5.7' from CB. Hard deposits at 153' to 165' (approx. 10%). The rest of the line looks clean and in good condition.
401	423	74	24" RCP	Lines runs from MH in front of property to MH around the corner of same property on PVDW	SM-OWW-SD-MH3129-MH3131	MH3129 to MH3131	122		11/4/2014	Fine deposits settled starting at 30' to 65' (approx. 5% to 10%) and at 108' to 122' (approx. 10%). The rest of the pipe is clean and in good condition.
402	431	76	21" RCP	Line starts at CB in front of property to CB in front of 30405 Via Victoria	SM-OWW-SD-CB1133-GB2315, SM-OWW-SD-GB2315-CB1134	CB1133 to CB1134	72		11/3/2014	Fine deposits settled for the first 37' of the line starting at CB1133 (approx. 10%). Fine deposits settled at 75' to CB1134 (approx. 20%); inspection abandoned due to fine deposits and cobbles.
403	435	76	30" CMP	Line runs from CB in front of property to JS on open channel behind property	SM-OWW-SD-CB3302-GB3304, SM-OWW-SD-GB3304-IS3307, SM-OWW-SD-IS3307-GB3308, SM-OWW-SD-GB3308-GB3309, SM-OWW-SD-GB3310-IS3303	CB3302 to JS3303	263		12/10/2014	Heavy corrosion for the first 50' from CB. Pipe has been panned recently, partially cleaned, but still has some areas showing the metal pipe (heavily corroded). Inspection abandoned at 263' due to large void.
404	489	84	18" RCP	Line starts at CB on PVDW median (approx. 1800' north of Hawthorne Blvd.) to CB across PVDW southbound	SM-OWW-SD-CB1628-CB0613	CB1628 to CB1613	25		11/25/2014	Soil deposits settled throughout the pipe from 5% to 40%. Overall pipe is in good condition.
405	504	95	18" RCP	Line starts at IS on property to MH	SM-OWW-SD-IS2843-MH2845	IS2843 to MH2845	14		10/27/2014	Approx. 50% of the inlet is covered by soil, rocks and plants. The pipe itself is clean and in good condition.
406	501	95	18" RCP & UNKNW	Line starts at CB adjacent to property to MH in front of 7060 Via Del Mar	SM-OWW-SD-CB2837-GB2838, SM-OWW-SD-GB2838-MH2835	CB2837 to MH2835	46.5		11/20/2014	Deposits settled starting at 46' to 72' -40%.
407	728	112	12" RCP	Line runs from CB in front of property to OS behind 6516 Via Colmita	LA-LAS-SD-CB0249-OS0248	CB0249 to OS0248	229		10/14/2014	Severely fractured pipe at 6'. Multiple longitudinal cracks in the pipe starting at 14' to 16'. Pipe is misaligned at pipe connectors throughout its length. Major cracks at 123'; longitudinal crack starting at 125' to 145'. Longitudinal crack starting at 153' to 165'. Pipe is clean.
408	729	112	12" RCP & CMP	Line runs from CB in front of property to CB in front of 6460 Via Colmita	LA-LAS-SD-CB0254-CB0253	CB0254 to CB0253	157.5		10/14/2014	The first 130' are RCP; longitudinal crack starting almost throughout the entire pipe length. CMP starts after 130' from CB0254; pipe has some average corrosion and settled sand starting at 146' to 157' (approx. 20%).
409	730	112	12" RCP	Line runs from CB in front of property to CB in front of 4604 Bearcats	LA-LAS-SD-CB0253-CB0252	CB0253 to CB0252	30.5'		10/14/2014	Multiple cracks at the beginning of CB0253; longitudinal crack starting at 8' to 15'. Severe pipe cracks at 28'. Inspection abandoned due camera's inability to make turns.
410	732	112	12" RCP & CMP	Line starts at CB at northwest corner of intersection to OS behind 6304 Via Ciega down the canyon	LA-LAS-SD-CB0257-OS0258	CB0257 to OS0258	142		10/14/2014	The first 83' from CB are RCP; multiple cracks at 12.5'; 22.7'; 77'. CMP starts at 83'; light to moderate corrosion.
375	351	62	24" RCP	Line starts at CB in front of property to CB across Montemalaga westbound	ML-PVW-SD-CB1552-CB1559	CB1552 to CB1559	64.5	65	11/24/2014	Exposed rebar around active tap break-in at 39.5'. Overall pipe looks clean and in good condition.
376	405	81	21" RCP	Line starts at CB in front of property to OS on Crest Rd. behind 5832 Summit property	SM-OSW-SD-CB1059-OS1058	CB1059 to OS1058	125.7	126	12/22/2015	Hard deposits at the beginning of the pipe to 11' approx. 10%. The rest of the pipe looks clean and in good condition.
377	526	86	36" CMP	Line runs from CB on Hawthorne Blvd. northbound (approx. 260' north of Los Varas Dr.) to CB across Hawthorne Blvd.	SM-OWW-SD-CB1115-CB1154	CB1115 to CB1154	79	79	8/21/2014	Heavy corrosion throughout the pipe. Pipe is good candidate for lining.
378	507	87	18" RCP	Line starts at CB in front of property to CB in front of 6915 Alta Vista Dr.	SM-OSW-SD-CB0740-CB0739	CB0740 to CB0739	13	30	11/21/2014	Hard deposits (approx. 20%) at the beginning and starting from 13' to end of line.
379	525	88	36" CMP	Line starts at CB on Hawthorne Blvd. (approx. 110' north of Dupre Dr.) to CB next to median.	SM-OSW-SD-CB0745-JS0742	CB0745 to JS0742	33	75	12/18/2015	Water level and debris is at approx. 25% throughout the pipe.
380	614	96	8" Pottery & Clay	Line starts at CB to CB on property	SM-OSW-SD-CB2823-CB2824	CB2823 to CB2824	34	34	12/17/2015	Debris from 32' to 34' approx. 60%.
381	619	96	30" RCP	Line runs from MH on City Hall yard by driveway entrance to OS	SM-OSW-SD-MH2823-GB2854, SM-OSW-SD-GB2854-OS2855	MH2823 to OS2855	180	200	10/30/2014	Inspection abandoned at 180' due to debris and standing water (approx. 15%).
382	406	82	18" RCP	Line starts at CB on Crenshaw Blvd. southbound (approx. 180' south of San Clemente Pl.) to MH 65'	SM-OSS-SD-CB0090-GB02204, SM-OSS-SD-GB02204-MH00996	CB0090 to MH0096	64	64	12/23/2014	Exposed rebar at 24' and broken concrete around the pipe. The rest of the pipe is clean and in good condition.
383	703	108	30" RCP	Line runs from MH to MH west of Forestal Dr.	SM-OSE-SD-MH3521-MH3467	MH3521 to MH3467	200	210	1/6/2015	Sand and rock deposits starting at 194' to MH3467 from 5% to 40%. Inspection abandoned at 200' due to debris blockage. Pipe seems to be in good condition.
384	436	77	36" RCP	Line runs from CB behind 30322 Camino Povernit property to MH behind 30165 Ave. Tranquila	SM-OWW-SD-GB1179-CB2216, SM-OWW-SD-MH141-GB1179	CB2216 to MH141	1213		10/31/2014	Exposed rebar at 911' (9 to 3 o'clock) from MH1180. The rest of the pipe is clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13-17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
385	2	498.2	96	18" RCP	Line runs from MH at corner to IS 7?	SM-OWW-SD-IS1156-MH1157	MH1157 to IS1156 (LACO)	132		10/30/2014	Settled stones from MH to 10' -10%. Exposed rebar and hole at 120'. CMP starts at 132'. It is light to medium rust.
386	3	508	87	24" RCP	Line starts at CB in front of property to CB in front of 6933 Alta Vista Dr.	SM-OSW-SD-CB0739-MH0741	CB0739 to MH0741	210		11/5/2014	Hard deposits throughout the pipe; they vary from ~5% to 15%. Sand bags inside the catch basin ~80%. Pipe is clean and in good condition.
387	4	639	102	18" RCP	Line runs from CB on PVDS and church driveway to MH in church parking lot.	SM-OSW-SD-CB3552-MH3550	CB3552 to MH3550	15		10/20/2014	Invert has been paved with concrete previously. Exposed corroded rebar missing concrete pavement in the middle of the pipe starting at 104' to 105'. Line is clean and in good condition. Pipe has been lined previously. Line looks clean and in good condition except for the last ~15' of the line that has been collapsed (top portion).
388	5	667	103	54" CMP	Line runs from MH in between 11 Barkentine & 12 Packet to MH in between 18 Barkentine & 22 Packet	SM-OSW-SD-MH0680-MH0689	MH0680 to MH0689	347.5		10/17/2014	Multiple cracks starting from CB0158 to 7'. The first 7' from CB0620 are CMP (medium corrosion). The rest of the RCP line is clean and in good condition.
389	6	680	105	31" CBP	Line runs from CB on Seagate to OS down the cliff	SM-OSW-SD-CB0657-OS0659	CB0657 to OS0659	131.5		10/29/2014	Medium to heavy corrosion throughout the pipe.
390	7	603	124	18" RCP	Line runs from MH in front of property to CB across the street	LA-LAE-SD-CB0158-CB0158	CB0158 to CB0158	27		10/6/2014	Pipe has been lined previously. Gravel deposits starting at 61' to 80' (approx. 15%). The rest of the line is clean and in good condition.
391	8	657	133	24" CBP & 24" RCP	Line runs from CB in front of property to CB across the road	LA-LAS-SD-CB0820-CB0818	CB0820 to CB0818	32.5		10/13/2014	Top portion of pipe is broken (rebar and soil exposed) from 9 to 3 o'clock at 24.2' from CB0587. Overall line looks clean and in good condition.
392	9	382	68	36" CMP	Line runs from on Hawthorne southbound approx. 265' north of intersection to MH on median	SM-PVW-SD-CB1339-GB2446, SM-PVW-SD-MH1345-GB2446	CB1339 to MH1345	59		11/10/2014	Multiple cracks at the beginning or U-turn to S. Pipe misaligned in various locations. Longitudinal cracks starting at 14' to 19'. Debris (mainly foliage) starting at 15' to CB0250 (approx. 10% to 40%).
393	10	522	88	30" CMP	Line starts at CB in front of property to MH on Carlier Dr at Duane Dr.	SM-OSW-SD-CB0747-MH0759	CB0747 to MH0759	82		11/5/2014	Roots at joint 6.5' and 23'. Broken concrete at tap break-in 56'. Overall line is clean and in good condition.
394	11	623	97	30" RCP	Line starts at CB on Hawthorne northbound	SM-OSW-SD-CB0592-CB0587	CB0592 to CB0587	75.5		11/25/2014	The first 26' are RCP. CMP thereafter; medium to heavy corrosion inspection abandoned due to pipe inclination.
395	12	726	112	18" RCP	Line starts at CB in front of property to CB in front of 6453 Via Colinita	LA-LAS-SD-CB0247-CB0250	CB0247 to CB0250	30		10/14/2014	Settled debris at 25' (approx. 20%) to 65.7'.
396	13	397	70	18" RCP	Line starts at CB in front of property to OS on Highway	SM-PVW-SD-CB2713-TS2714, SM-PVW-SD-TS2714-OS2715	CB02713 to OS2715	60		11/21/2014	Survey abandoned at 149' due to water level and no downstream access. Overall line is clean and in good condition.
397	14	414	73	30" RCP & CMP	Line runs from MH on Ulenishaw Blvd. northbound approx. 830' north of Crest Rd.) to MH in front of 28705 ML-RHE-SD-JS48534-MH1006, ML-RHE-SD-JS3399-JS48534	SM-PVW-SD-CB02713-TS2714, SM-PVW-SD-TS2714-OS2715	MH3399 to MH1006	90		12/1/2014	Inspection abandoned at 73' due to water level. Overall line looks clean and in good condition.
398	15	611	96	30" RCP	Line starts at CB in front of property to JS	SM-OSW-SD-CB2819-JS2820	CB2819 to JS2810	66		12/17/2015	Settled hard deposits from 6.5' to 9' approx. 10%. Overall the line looks clean and in good condition.
399	16	579	137	30" RCP	Line runs from MH at intersection to OS across Western ML-LAN-SD-MH0223-TS14135, ML-LAN-SD-TS14135-TS0222, ML-LAN-SD-TS0222-OS0221	ML-LAN-SD-MH0223-TS14135, ML-LAN-SD-TS14135-TS0222, ML-LAN-SD-TS0222-OS0221	MH0223 to OS0221	149		12/18/2015	Moderate root intrusion at joint 5'. Overall the line looks clean and in good condition.
400	17	881	139	96" RCP	Line runs from MH on Western at Redondella Dr. to OS LA-LAN-SD-MH0190-CB1956, LA-LAN-SD-CB1956-OS0198	LA-LAN-SD-MH0190-CB1956, LA-LAN-SD-CB1956-OS0198	MH0190 to OS0189	73.3		12/18/2015	Sand and rock deposits ~10% from beginning of pipe to 52'. The pipe seems to be in good condition.
401	18	213	110	18" RCP	Line starts at CB in front of property to OS in front of 3407 Newridge Dr.	LA-LAS-SD-MH5565-OS0098, LA-LAS-SD-CB0099-MH5565	CB0099 to OS0098	81		12/4/2015	Pipe from CB0296 to 304' has been lined previously; it is clean and in good condition. CMP starts after 304'; pipe has light to moderate corrosion.
402	19	214	110	18" RCP	Line starts at CB in front of property to CB across De Luna Rd.	LA-LAS-SD-CB0124-CB0123	CB0124 to CB0123	31.7		12/4/2015	Circumferential crack at 9', 12', 53'.
403	20	700	108	30" RCP	Line starts at IS on Fomental northbound to MH west of the road	SM-OSW-SD-IS0519-TS3468, SM-OSW-SD-TS3468-JS2434, SM-OSW-SD-JS2434-JS2435, SM-OSW-SD-JS2435-MH3467	IS0519 to MH3467	144		1/6/2015	Hard deposits throughout the pipe ~20%.
404	21	709	116	24" CMP	Line runs from CB in front of the property to OS down the canyon	SM-OSW-SD-CB0296-GB0297, SM-OSW-SD-GB0297-GB1906, SM-OSW-SD-GB1906-OS0296	CB0296 to OS0298	397		12/4/2014	Pipe has been lined previously. Debris in the last portion of the line approx. 15' in length ~40%. Overall line looks clean and in good condition.
405	22	820	135	12" Concrete	Line runs from CB on Miraflores southbound to CB across median on Miraflores northbound	LA-LAE-SD-CB0839-CB0837	CB0839 to CB0837	68.7		12/9/2014	Fine deposits settled starting at 9' to 20' (approx. 5%) and debris & fine deposits settled at 29' to 34' (approx. 10%).
406	1	821	126	18" RCP	Line starts at CB in front of property to CB across the road	LA-LAE-SD-CB0015-CB0014	CB0015 to CB0014	32		10/9/2014	Fine deposits settled throughout the pipe.
407	2	649	132	18" CBP	Line runs from CB in front of property to OS down the canyon	LA-LAE-SD-CB0787-GB3118, LA-LAE-SD-GB3118-GB3120, LA-LAE-SD-GB3120-GB3119, LA-LAE-SD-GB3119-OS0788	CB0787 to OS0788	180		10/10/2014	Deposits and debris starting at 40' to 49'. The rest of the line is clean and in good condition.
408	3	420	74	18" RCP	Line starts at CB in front of 7455 Alida to CB in front of 7460 Alida	SM-OWW-SD-CB3125-CB1245	CB3125 to CB1245	35.5		11/4/2014	Deposits and debris starting at 140' approx. 5%. Rocks and sand deposits starting at 170' to OS (approx. 20%).
409	4	431	75	18" RCP	Line starts at CB in front of 30150 Via Lorado to CB in front of 7442 Via Lorado	SM-OWW-SD-CB1245-CB1248	CB1245 to CB1248	35		10/31/2014	Big rocks at 7' and 24'. Inspection abandoned at 24' due to obstacles.
410	5	430	75	18" RCP	Line runs from MH on PVOW median by Via Lorado to CB on PVOW median (approx. 200' south)	SM-OWW-SD-MH1247-CB3076	MH1247 to CB3076	200		10/31/2014	Deposits settled starting at 23' to 37' (approx. 10%).
411	6	805	96	18" RCP	Line runs from CB on Hawthorne southbound (approx. 815' northwest of City Hall driveway) to CB on Hawthorne median	SM-OWW-SD-CB0585-CB0584	CB0585 to CB0584	45		10/30/2014	Hard deposits at starting at 9' to 13' (approx. 15% and from 32' to 39' approx. 15%). Also a concrete deposit stuck in the middle of the pipe at 48' approx. 10%.
412	7	947	101	18" RCP	Line runs from CB at the west end of road to OS on Via Palacio	SM-OSW-SD-CB2863-GB2864, SM-OSW-SD-GB2864-OS2865	CB2863 to OS2865	205		10/21/2014	Deposits settled starting at 23' to 37' (approx. 10%).
413	8	450	101	18" RCP	Line runs from JS in front of 6508 Via Baron to OS on Seacove Dr.	SM-OSW-SD-JS2868-GB2870, SM-OSW-SD-GB2870-OS2869	JS2868 to OS2869	125		11/21/2014	Hard deposits at starting at 9' to 13' (approx. 15% and from 32' to 39' approx. 15%). Also a concrete deposit stuck in the middle of the pipe at 48' approx. 10%.
414	9	694	107	24" RCP	Line runs from CB to CB at end of Inglefield cul-de-sac	SM-OSE-SD-CB3198-CB3199	CB3198 to CB3199	37		11/20/2014	Deposits settled starting at 23' to 37' (approx. 10%).
415	10	737	114	18" RCP	Line runs from CB in front of property to CB across the cul-de-sac	SM-OSE-SD-CB0095-CB0094	CB0095 to CB0094	46		10/13/2014	Deposits settled starting at 23' to 37' (approx. 10%).

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
416	341	114	18" RCP	Line runs from CB in front of property to MH in front of 3224 Deluna	SM-OSF-SD-CB0079-MH0082	CB0079 to MH0082	140	26	2/21/2000	Deposits and debris in the pipe (approx. 5%). Line is in good condition.
417	368	65	24" RCP	Line starts at CB on southwest corner to CB on northwest corner	SM-PVN-SD-CB2751-CB2750	CB2751 to 2750	26	26	11/18/2014	Hard deposits at 16' to 19' (approx. 10%). Overall line is clean and in good condition.
418	370	65	24" RCP	Line starts at CB on southeast corner to CB on northeast corner	SM-PVN-SD-CB2754-CB2755	CB2754 to CB2755	24.5	25	11/18/2014	Hard deposits from 6' to 15' (approx. 10%). Overall line is clean and in good condition.
419	396	70	24" RCP	Line starts at CB in front of property to JS	SM-PVN-SD-CB2728-JS2730	CB2728 to JS2730	43	43	11/17/2014	Hard deposits at the beginning and end of line. Large rocks from 7' to 10'. Overall line is in good condition.
420	405	72	18" CMP	Line starts at CB on Hawthorne southbound to mainline	SM-PVN-SD-CB1431-JS2815	CB1431 to mainline	15.5	16	8/25/2014	This line is the same as line 149. Medium corrosion. Overall line is clean and in good condition.
421	810	96	18" RCP	Line starts at CB in front of property to JS	SM-OSW-SD-CB2817-JS2816	CB2817 to JS2816	53.6	54	12/17/2015	Water infiltration at 2.5' from 3 to 9 o'clock; hard deposits starting at 24' to 29' approx. 5%. Overall line is clean and in good condition.
422	530	128	24" CMP	Line runs from CB on Marlingale southbound to OS down the canyon	LA-LAN-SD-CB0082-OS3202	CB0082 to OS3202	187	187	12/10/2014	Pipe is deformed starting at 42' to 47' from 7 to 12 o'clock. Pipe has been lined previously. Line is clean and in good condition.
423	849	135	24" Concrete	Line starts at CB in front of 6617 Via Siena to CB across Marlene Dr.	LA-LAE-SD-CB0039-CB0038	CB0039 to CB0038	62	62	12/9/2014	Hard deposits at the beginning of the line 10%. Broken pipe at 27' to 28' (replaced previously with RCP). Circumferential fracture at 46' and 58'. Exposed near at CB0038.
424	830	96	18" RCP	Line runs from JS on Hawthorne southbound to MH on City Hall yard by driveway entrance	SM-OSW-SD-IS2805-CB2804	IS2805 to CB2804	10	10	1/5/2015	Mud and debris on pipe -15%. Overall the pipe looks in good condition.
425	756	116	24" CMP	Line runs from CB in front of property to OS down the canyon	SM-OSF-SD-CB0000-MH0091, SM-OSF-SD-MH0091-GB3429, SM-OSF-SD-GB3429-OS0302	CB0000 to OS0302	131	350	12/5/2014	Line runs from CB on Hawthorne southbound to OS down the canyon. Line runs from MH on property to MH in front of 45 Via Malona property. Hard deposits at JS 2725 from 5 to 7 o'clock. Overall pipe looks clean and in good condition.
426	383	70	24" RCP	Line runs from MH in front of property to JS close to 43 Via Porto Grande	SM-PVN-SD-MH2731-MH2733, SM-PVN-SD-GB2732-MH2731, SM-PVN-SD-JS2730-GB2732	MH2733 to JS2730	299	117/2014	11/7/2014	Hard deposits (-5%) for the first 7' from JS2730. Overall line is clean and in good condition.
427	364	70	24" RCP	Line starts at CB on Hawthorne southbound (approx. 520' south of intersection) to JS	SM-PVN-SD-CB2729-JS2730	CB2729 to JS2730	7	11/7/2014	11/7/2014	Sediment and rocks in the pipe -10%. Overall line is in good condition.
428	368	78	18" RCP	Line runs from MH in front of property to OS	SM-OWW-SD-CB1096-JS48132	CB1096 to JS2679	17	11/11/2014	11/11/2014	Light corrosion throughout the pipe.
429	441	80	30" RCP	Line runs from MH in front of property to OS	SM-OWW-SD-MH2632-GB2634, SM-OWW-SD-GB2634-TS2635, SM-OWW-SD-TS2635-GB2636, SM-OWW-SD-GB2636-OS2633	MH2632 to OS2633	170	11/14/2014	11/14/2014	Water infiltration at 162' close to the OS from 10 to 2 o'clock. Overall pipe looks clean and in good condition.
430	444	90	18" RCP	Line runs from CB on Via Vicente adjacent to 78 Via Del Sol to MH in the middle of Via Vicente	SM-OWW-SD-CB1695-MH1694	CB1695 to MH1694	19	10/28/2014	10/28/2014	Hard deposits starting at 12' from 5 to 7 o'clock -5%. Overall line is clean and in good condition.
431	531	92	18" RCP	Line runs from CB on northwest corner of intersection to JS	SM-OWW-SD-CB0724-JS0727	CB0724 to JS0727	35	10/31/2014	10/31/2014	Line has sediment from beginning of CB1711.1 to 12' approx. -5%. Pipe is in good condition.
432	562	98	18" RCP	Line starts at CB on northeast corner of intersection to JS	SM-OWW-SD-CB0724-JS0727	CB0724 to JS0727	35	11/4/2014	11/4/2014	Hard deposits from the beginning of the pipe at CB to 18' (approx. 5% to 10%). Overall line is clean and in good condition.
433	633	98	18" RCP	Line runs from CB on southwest corner to OS in canyon	SM-OWW-SD-CB0721-OS0726	CB0721 to OS0726	130	11/4/2014	11/4/2014	Pipe has been lined previously. Lining is wrinkled throughout the pipe. Overall line is clean and in good condition.
434	633	99	24" CMP	Line starts from IS to MH in front of P/V/C parking area	SM-OWW-SD-IS3601-MH3600	IS3601 to MH3600	28	10/16/2014	10/16/2014	Line has debris (small tree sticks) throughout its length -10%; overall line is clean and in good condition.
435	644	105	18" RCP	Line runs from CB to MH on Sea Gale	SM-OWW-SD-CB3541-MH3539	CB3541 to MH3539	17.5	10/24/2014	10/24/2014	Hard deposits at 17' from 3 to 6 o'clock -15%.
436	644	126	24" RCP	Line starts at CB in property's corner to CB in front of 29444 Bayand Dr.	LA-LAE-SD-CB0021-CB0022	CB0021 to CB0022	68	10/6/2014	10/6/2014	Hard deposits at the end of the line CB0021 -5%. Overall pipe is clean and in good condition.
437	611	126	24" RCP	Line starts at CB in front of property on Noble View Dr. to CB in front of 29444 Bayand Dr.	LA-LAE-SD-CB0020-CB0022	CB0020 to CB0022	82	10/6/2014	10/6/2014	Hard deposits from 29' to 41' -5%. Overall pipe is clean and in good condition.
438	613	126	18" RCP	Line runs from CB in front of property to MH behind the same property	LA-LAE-SD-CB3420-CB14907	CB3420 to MH0018	199	10/9/2014	10/9/2014	Hard deposits at 21' from 5 to 7 -10%. Overall pipe looks clean and in good condition.
439	617	126	18" RCP	Line runs from CB in front of property to MH in 1903 Summerland St. Community Christian Church backyard	LA-LAE-SD-CB0005-GB0004, LA-LAE-SD-GB0004-JS1927-MH1926	CB0005 to MH1926	427	10/9/2014	10/9/2014	Small longitudinal crack from 122' to 128'. Circumferential crack from 8 to 4. Overall pipe is clean and in good condition.
440	623	127	30" RCP	Line runs from MH in property's backyard to MH on 25641 Western Ave.	LA-LAE-SD-MH1926-GB0001, LA-LAE-SD-GB0001-MH1928	MH1926 to MH1928	413	10/9/2014	10/9/2014	Rebar exposure at 141' (position 11 o'clock); Overall pipe looks clean and in good condition.
441	624	133	18" RCP	Line runs from CB in front of property to CB across the road	LA-LAE-SD-CB0022-CB0021	CB0022 to CB0021	29	10/13/2014	10/13/2014	Small circumferential crack at 0.5' and 24'. Overall pipe is clean and in good condition.
442	624	136	18" RCP	PVDE at Cal Water Reservoir property	LA-LAE-SD-CB0022-CB0021	CB0022 to CB0021	178	10/13/2014	10/13/2014	Deformed pipe at 39' (oval shape). Overall pipe is clean and in good condition.
443	623	68	18" RCP	Line starts at CB in front of property to OS in front of 28719 Plainfield Dr.	SM-PVN-SD-CB1372-OS1373	CB1372 to OS1373	93	11/10/2014	11/10/2014	Deposits settled compacted at the beginning of the pipe from CB to 3' (approx. 5%).
444	365	97	30" CMP	Line starts at CB on Hawthorne northbound (approx. 665' east of City Hall driveway entrance) to OS	SM-OSW-SD-CB0038-OS0591	CB0038 to OS0591	172	11/25/2014	11/25/2014	The first 27' from CB0038 have been lined previously. The rest of the pipe is unlined CMP with light to moderate corrosion throughout the pipe. Top portion of pipe has an open dent at 132.5'
445	624	114	18" RCP	Line starts at CB in front of property to CB across Deluna Dr.	SM-OSF-SD-CB0080-CB0079	CB0080 to CB0079	36	10/13/2014	10/13/2014	Little debris in the pipe. CB0080 needs cleaning; hard deposits at the beginning of the pipe. Overall pipe is clean and in good condition.
446	740	137	18" RCP	Line starts at CB in front of property on Western Ave. side to IS in the cemetery side	ML-LAN-SD-IS0214-CB0215	CB0215 to IS0214	62.5	10/15/2014	10/15/2014	Deposits settled at the beginning of the CB to 5' approx. 5%. Overall line is in good condition.

Storm Drain Video Inspection & Cleaning Services FY 20-21

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
448	12	348	71	24" RCP	Line runs from CB in front of property to OS of 4518 Elbridge Dr.	ML-RHE-SD-CB1463-MH3473-GB3474, ML-RHE-SD-GB3474-OS1464	CB1463 to OS1464	439.7	440	12/22/2015	Hard deposits at 6.5' to 10' approx. 5%. The rest of the pipe is clean and in good condition.
449	24	462	72	24" CMP	Line starts at CB on Hawthorne next to 29437 Indian Valley Rd. to 77	SM-PVN-SD-CB1430-MH1434	CB1430 to MH1434	19	19	8/25/2014	Light to medium corrosion throughout the pipe. Overall the pipe is clean and in good condition.
450	25	517	88	18" CMP	Line starts at CB on Hawthorne Blvd (approx. 145' north of Duane Dr.) to CB 35' south	SM-OSW-SD-CB0746-CB0745	CB0746 to CB0745	35	35	11/26/2014	Black coating is peeling off; light corrosion throughout out the pipe. Overall line looks clean and in good condition.
451	28	711	110	18" RCP	Line runs from CB on Crest northbound (approx. 140' south of Ganado Dr.) to CB 25' south	SM-OSW-SD-CB0746-CB0745	CB0746 to CB0745	27	27	12/15/2014	Circumferential crack at 24'. Overall line looks clean and in good condition.
452	27	764	115	24" Vitrified Clay & RCP	Line runs from IS in property to CB across PVDE in front of 30076 PVDE	SM-OSSE-SD-IS43324-IS43324, SM-OSSE-SD-IS43324-IS43324, SM-OSSE-SD-MH0066-JS34137, SM-OSSE-SD-JS34137-CB34138, SM-OSSE-SD-CB34138-IS0065	IS0066 to CB0065	413	413	12/11/2014	The first 215' are Vitrified Clay pipe. Infiltration stain around the pipe at 18'. Circumferential crack at 54'. Pipe material changes at 215' to RCP. Line is clean and in good condition.
453	28	768	109	30" RCP	Line runs from CB in the grass area next to the Luders Linda Comm. basketball courts	ML-RHE-SD-CB1459-MH1459, ML-RHE-SD-CB1459-MH1459, ML-RHE-SD-CB1459-MH1459, ML-RHE-SD-CB1459-MH1459	CB0509 to MH0507	754.7	758	12/6/2015	Minimal roots at joint 57.9'. Overall the line looks clean and in good condition.
454	29	711	111	12" RCP	Line starts at CB on PVDE northbound (approx. 35' north of Via Frascatti) to OS down the canyon	LA-LAS-SD-CB0111-OS0112	CB0111 to OS0112	48	48	12/4/2015	Moderate joint offset at 41'. Overall the line looks clean and in good condition.
455	30	468	71	18" RCP	Line starts at CB in front of property to CB in front of 4926 Golden Arrow Dr.	ML-RHE-SD-CB1459-MH1459, ML-RHE-SD-CB1459-MH1459, ML-RHE-SD-CB1459-MH1459, ML-RHE-SD-CB1459-MH1459	CB1459 to CB1458	35	35	12/23/2014	A little debris in pipe. Overall line is in good condition.
456	31	461	71	18" RCP	Line runs from CB in front of property to OS on Beechgate Dr. (behind same property)	GB3471, ML-RHE-SD-GB3471-GB3472, ML-RHE-SD-GB3472-OS1457	CB1458 to OS1457	225.8	226	12/23/2014	Hard deposits at from 20' to 27' -5%. Circumferential crack at 9'. Overall line is clean and in good condition.
457	22	468	73	24" RCP	Line starts at CB to MH in front of 28762 Crestbridge Rd.	ML-RHE-SD-CB1017-MH3489	CB1017 to MH3489	5	10	1/7/2015	
458	25	466	107	24" RCP	Line runs from CB at end of Intrepid cut-de-sac to JS	SM-OSSE-SD-CB1389-JS3200	CB1389 to JS3200	81	81	1/6/2015	Sand and rock deposits throughout the pipe -5%.
459	24	471	135	12" Concrete	Line runs from CB on median to CB in front of property	LA-LAE-SD-CB0837-CB0836	CB0837 to CB0836	35	35	12/9/2014	Hard deposits starting at 25' to 30' approx. 5%. Overall the pipe looks clean and in good condition.
460	1	493	85	30" RCP	Line runs from CB in front of property to MH in front of 30643 Rue Valois	SM-OWW-SD-CB0617-MH3374	CB0617 to MH3374	24	24	10/24/2015	Pipe looks clean and in good condition.
461	2	543	90	42" RCP	Line runs from MH in front of property to CB in front of 30 Pacifica Del Mar	SM-OWW-SD-CB1687-MH1686, SM-OWW-SD-CB1687-MH1686, SM-OWW-SD-CB1687-MH1686, SM-OWW-SD-CB1687-MH1686	MH1559 to CB1445, MH1685	340	340	10/24/2015	Pipe looks clean and in good condition.
462	3	715	110	18" CMP	Line runs from CB in front of property to OS on 30321 Diamond Ln. backyard	LA-LAS-SD-GB3413-GB3413, LA-LAS-SD-GB3413-GB3413, LA-LAS-SD-GB3413-GB3413, LA-LAS-SD-GB3413-GB3413	CB0123 to OS0125	75.6	75.5	12/4/2015	Pipe looks clean and in good condition.
463	4	716	111	30" CMP	Line runs from IS on west side of PVDE to OS across the road	LA-LAS-SD-IS0113-OS0114	IS0113 to OS0114	176.5	176.5	12/4/2015	Pipe looks clean and in good condition.
464	5	721	111	18" RCP	Line starts at CB in front of property to CB across the road	LA-LAS-SD-CB4537-CB0051	CB0050 to CB0051	33	33	12/9/2015	Pipe looks clean and in good condition.
465	6	735	113	18" RCP	Line starts at CB in front of property to CB across the road	LA-LAS-SD-CB0053-CB0054	CB0053 to CB0054	30	30	12/9/2015	Pipe has been lined previously. Line looks clean and in good condition.
466	7	772	119	34" RCP	Line runs from IS east of Paseo Del Mar (approx. 290' south of PVDS) to OS across Paseo Del Mar	LA-LAE-SD-CB0016-MH0013, LA-LAE-SD-MH0013-CB0016, LA-LAE-SD-MH0013-CB0016, LA-LAE-SD-MH0013-CB0016	CB0034 to CB0033	100	100	12/21/2015	All three videos show a clean pipe in good condition.
467	8	808	125	42" RCP	Line starts at CB in front of property to CB in front of 29403 Western (HOP Restaurant)	LA-LAE-SD-CB1559-TS2673, ML-PVN-SD-TS2673-MH1553	CB1559 to MH1553	295	295	10/6/2015	Pipe looks clean and in good condition.
468	9	352	62	24" RCP	Line runs from CB on Montalaga (behind 5412 Ironwood) to MH in front of 5412 Ironwood property	ML-PVN-SD-CB1559-TS2673, ML-PVN-SD-TS2673-MH1553	CB1559 to MH1553	168	168	11/24/2014	Pipe looks clean and in good condition.
469	10	353	62	24" RCP	From MH in front of property to MH in front of 26446 Birchfield Ave./Ironwood St.	ML-PVN-SD-MH1553-MH1558	MH1553 to MH1558	241	241	11/24/2014	Pipe looks clean and in good condition.
470	11	354	62	18" RCP	Line starts at CB on Ironwood to MH on Ironwood westbound	ML-PVN-SD-CB1555-MH1558	CB1555 to MH1558	6	6	11/24/2014	Pipe looks clean and in good condition.
471	12	355	62	18" RCP	Line starts at CB in front of property to MH on Ironwood westbound	ML-PVN-SD-CB1554-MH1558	CB1554 to MH1558	27	27	11/24/2014	Pipe looks clean and in good condition.
472	13	356	62	24" RCP	Line runs from MH on Ironwood st. to OS behind 5321 Ironwood St. property	ML-PVN-SD-MH1558-TS1557, ML-PVN-SD-TS1557-OS1556	MH1558 to OS1556	603	603	11/24/2014	Uninspected 150' of 24" Ironwood VCL. Pipe looks clean and in good condition.
473	14	357	62	3" RCP	Line starts at CB on property corner to PC on Silver Spur Rd.	ML-PVN-SD-CB1549-PC1548	CB1549 to PC1548	21	21	11/16/2014	Line looks clean and in good condition.
474	15	365	64	45" RCP	Line starts in front of property to MH in front of 26850 Basswood Ave.	SM-PVN-SD-MH2757-MH2762	MH2762 to MH2757	532	532	11/19/2014	Pipe looks clean and in good condition.
475	16	366	65	45" RCP	Line runs from MH in front of property to on northeast corner of Basswood and Indian Peak	SM-PVN-SD-JS2768-MH2757, SM-PVN-SD-MH2761-JS2768, SM-PVN-SD-MH2760-MH2761	MH2757 to MH2760	530	530	11/19/2014	Pipe looks clean and in good condition.
476	17	369	65	24" RCP	Line starts at CB on northeast corner to MH on northeast corner	SM-PVN-SD-CB2750-MH2761	CB2750 to MH2761	60	60	11/19/2014	Pipe looks clean and in good condition.
477	18	371	65	24" RCP	Line runs from CB to MH on northeast corner	SM-PVN-SD-CB2755-MH2761	CB2755 to MH2761	46	46	11/19/2014	Pipe looks clean and in good condition.
478	19	372	65	39" RCP	Line runs from CB on southeast corner to MH on northeast corner	SM-PVN-SD-MH2760-MH2761	MH2760 to MH2761	46	46	11/19/2014	Pipe looks clean and in good condition.
479	20	373	65	30" RCP	Line starts at CB in front of 26937 Basswood to MH in southeast corner of intersection	SM-PVN-SD-CB2752-MH2760	CB2752 to MH2760	32.5	33	11/19/2014	Pipe looks clean and in good condition.
480	21	374	65	30" RCP	Line starts at CB in front of 26940 Basswood to MH in southeast corner of intersection	SM-PVN-SD-CB2753-MH2760	CB2753 to MH2760	36	36	11/19/2014	Pipe looks clean and in good condition.
481	22	398	71	24" RCP	Line starts at CB in front of property to CB in front of 27866 Longleaf Dr.	ML-RHE-SD-CB1462-CB1463	CB1462 to CB1463	38	38	12/22/2015	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
482	479	84	36" RCP	Line runs from JS on PYDOW northbound (approx. 850' north of Rue Beaupre) to MH across PYDOW southbound (GB1625, SM-OWW-SD-GB1625-MH1624) Line runs from CB in front of property to MH in front of 30625 Rue Langlois Line starts at CB in front of property to CB across Rue Langlois Line runs from CB in front of property on Rue Valois northbound to CB on southbound Line starts at CB on Los Verdes Dr. northbound to JS or mainline Line starts at CB on Hawthorne Blvd. to approx. 510' south of Duane Dr. to CB 30' south Line starts at CB on Hawthorne Blvd. to approx. 540' south of Duane Dr. to CB across Hawthorne Blvd. on southbound Line runs from MH on Calle Viento to MH at intersection of Seavore cul-de-sac Line starts at CB on Calle Viento (adjacent to 30 Pacific Del Mar) to MH in the middle of Calle Viento Line starts at CB in front of property to MH in the middle of the street Line runs from CB on PYDOW northbound (approx. 260' north of Hawthorne) to MH across PYDOW in open space Line starts at CB in front yard of property to MH at Via La Cresta cul-de-sac Line starts at CB between 30960 & 30970 Via La Cresta to MH on hill behind 20950 Via La Cresta Line starts at CB to JS on backyard property Line runs from MH in front of property to CB at the end of Seavore cul-de-sac Line runs from MH on grass area of apartment complex to OS down the cliff Line runs from CB in front of property to MH down the canyon Line runs from MH to OS down the canyon Line starts at CB on PYDOW southbound to OS0321 Line runs from CB on Ganado at Floweridge to OS in front of 31211 Floweridge Line starts at IS to MH at end of cul-de-sac Line runs from MH at end of cul-de-sac to OS in Golf Course Line runs from CB at end of the cul-de-sac to MH at end of cul-de-sac Line runs from CB to MH on La Rotonda westbound Line runs from CB to MH on La Rotonda eastbound	SM-OWW-SD-JS1627-JS1626, SM-OWW-SD-JS1626-north of Rue Beaupre) to MH across PYDOW southbound (GB1625, SM-OWW-SD-GB1625-MH1624)	JS1627 to MH1624 to MH1624	105	118	10/24/2014	Pipe looks clean and in good condition.
483	491	85	18" RCP		SM-OWW-SD-CB3373-MH0616	CB3373 to MH0616	17	20	12/8/2014	Pipe looks clean and in good condition.
484	492	85	18" RCP		SM-OWW-SD-CB3373-MH0616	CB3373 to CB0615	39	39	12/8/2014	Pipe looks clean and in good condition.
485	494	85	36" RCP		SM-OWW-SD-CB0615-CB3373	CB0618 to CB0617	23.5	23.5	10/24/2014	Pipe looks clean and in good condition.
486	504	86	18" RCP		Repeat? (Line No. 447)	CB1118 to JS3519	34	34	11/5/2014	Pipe looks clean and in good condition. Line looks clean and in good condition.
487	530	88	24" CIP		SM-OWW-SD-CB0760-CB0761	CB0760 to CB0761	25	25	11/26/2014	Pipe has been lined previously. Line looks clean and in good condition.
488	531	88	24" CIP		SM-OWW-SD-CB0761-CB0762	CB0761 to CB0762	77	77	11/26/2014	Pipe has been lined previously. Line looks clean and in good condition.
489	546	90	24" RCP		SM-OWW-SD-MH1688-JS1691, SM-OWW-SD-JS1691-MH1685	MH1688 to MH1685	78	78	10/24/2014	Pipe looks clean and in good condition.
490	547	90	24" RCP		SM-OWW-SD-CB1689-MH1688	CB1689 to MH1688	33.5	33.5	10/24/2014	Pipe looks clean and in good condition.
491	548	90	18" RCP		SM-OWW-SD-CB1690-MH1688	CB1690 to MH1688	31	31	10/24/2014	Pipe looks clean and in good condition.
492	563	92	36" RCP	SM-OWW-SD-MH4527-IS0065 SM-OWW-SD-IS0065-OS0126	MB1702 to MB1707	597	19-Aug	11/3/2014	Pipe looks clean and in good condition.	
493	607	96	18" Polypropylene Chloride		CB2813 to MH2814- JS2811	110	110	12/17/2015	Pipe looks clean and in good condition.	
494	613	96	18" Polypropylene Chloride	SM-OWW-SD-CB2826-MH2825	CB2826 to MH2825	194.4	194.5	12/18/2015	Pipe looks clean and in good condition.	
495	615	96	18" RCP	SM-OWW-SD-CB2824-JS2822	CB2824 to JS2822	94	94	12/17/2015	Pipe looks clean and in good condition.	
496	681	105	54" RCP	SM-OWW-SD-MH3526-CB3524	MH3526 to CB3524	107	107	10/21/2014	Pipe looks clean and in good condition.	
497	687	105	65" STL	SM-OWW-SD-MH3539-OS3542	MH3539 to OS3542	291	291	10/20/2014	Pipe looks clean and in good condition.	
498	753	115	36" RCP	SM-OWW-SD-MH0065	CB0065 to MH0064	94	94	12/11/2014	Pipe looks clean and in good condition.	
499	754	115	36" Other	SM-OWW-SD-IS0065-OS0126	MH0064 to OS0126	464	464	12/11/2014	Pipe looks clean and in good condition.	
500	760	117	18" CIP	SM-OWW-SD-CB0321-OS0321	CB0321 to OS0321	21	21	12/15/2014	Pipe has been lined previously. Line looks clean and in good condition.	
501	764	121	18" RCP	SM-OWW-SD-CB0342-OS0341	CB0342 to OS0344	121.6	121	12/22/2015	Pipe looks clean and in good condition.	
502	785	122	36" RCP	SM-OWW-SD-IS0311-GB6522, SM-OWW-SD-GB6522-GB6523, SM-OWW-SD-GB6523-MH0307	IS0311 to MH0307	331	340	12/5/2014	Pipe looks clean and in good condition.	
503	786	122	36" RCP	SM-OWW-SD-MH0307-JS28116, SM-OWW-SD-JS28116-MC0310	MH0307 to OS0310	204	204	12/5/2014	Pipe looks clean and in good condition.	
504	788	122	18" RCP	SM-OWW-SD-CB0309-MH0307	CB0309 to MH0307	29	29	12/5/2014	Pipe looks clean and in good condition.	
505	789	122	18" RCP	SM-OWW-SD-CB0304-JS2697	CB0304 to MB1874 to JS2697	11	11	12/5/2014	Pipe looks clean and in good condition. Circumferential crack at the beginning of the pipe. Overall the line looks clean and in good condition.	
506	790	122	36" RCP	SM-OWW-SD-CB0303-JS2698	CB0303 to MH1874 to JS2698	9	9	12/5/2014		
507	791	122	36" RCP	SM-OWW-SD-MH0306-JS2697, SM-OWW-SD-JS2697-GB6524, SM-OWW-SD-GB6524-JS2698, SM-OWW-SD-JS2698-GB6525, SM-OWW-SD-GB6525-GB6526, SM-OWW-SD-GB6526-GB6527, SM-OWW-SD-GB6527-JS4890, SM-OWW-SD-JS4890-JS4891, SM-OWW-SD-JS4891-MH0307, SM-OWW-SD-MH0307-GB6531, SM-OWW-SD-GB6531-GB6532, SM-OWW-SD-GB6532-JS4893, SM-OWW-SD-JS4893-MH0307, SM-OWW-SD-MH0307-TS4896, SM-OWW-SD-TS4896-MH0305, SM-OWW-SD-MH0305-MH4895, SM-OWW-SD-MH4895-MH1874	JS MH0306 to MH0367-MH1874	813	813	12/4/2014	Pipe looks clean and in good condition. Inspection abandoned due to pipe inclination. Pipe looks clean and in good condition.	
508	794	122	18" RCP		IS1870 to MH1874	168	7	12/5/2014		
509	795	122	36" RCP		MH1874 to MH1871	415	415	12/5/2014	Pipe looks clean and in good condition.	
510	796	122	36" RCP		SM-OWW-SD-MH1871-MC1872, SM-OWW-SD-MC1872-JS1876, SM-OWW-SD-JS1876-MC1873, SM-OWW-SD-MC1873-OS1877	MH1871 to OS1877	367	400	12/5/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
511	797	123	18" CIP	Line runs from CB at end of cul-de-sac to OS behind property	LA-LAN-SD-CB0930-OS0931	CB0930 to OS0931	157	157	10/7/2014	Pipe has been lined previously. Line looks clean and in good condition.
512	818	126	36" RCP	Line runs from MH in property's backyard to CB in front of 1943 MacArthur St.	LA-LAE-SD-MH0018-CB3422, LA-LAE-SD-GB3422-MH3423	MH10018 to CB0014	659	659	12/19/2015	Pipe looks clean and in good condition.
513	829	128	24" CMP	Line starts at CB in front of property to CB across the road	LA-LAN-SD-CB0883-CB0882	CB0883 to CB0882	33	33	12/10/2014	Pipe looks clean and in good condition.
514	831	129	30" CMP	Line runs from JS in property's backyard adjacent to Marlin Dr. to OS down the canyon across PYDE	LA-LAE-SD-OS0787-OS0789	OS0787 to OS0789	330	330	12/11/2014	Pipe has been lined previously. Line is clean and in good condition.
515	832	129	18" CMP	Line runs from CB at end of the cul-de-sac to OS behind property	LA-LAE-SD-CB0838-OS0860	CB0838 to OS0860	125	125	12/10/2014	Pipe has been lined previously. Line is clean and in good condition.
516	834	129	18" CIP	Line runs from IS on driveway adjacent to Miraleste Library to CB across driveway	LA-LAE-SD-CB0877-CB0875	CB0877 to CB0875	14	14	12/15/2014	Pipe has been lined previously. Line is clean and in good condition.
517	835	129	18" RCP	Line runs from CB on driveway adjacent to Miraleste Library to OS down the canyon across PYDE	LA-LAE-SD-CB0875-OS0872	CB0875 to OS0872	26	26	12/15/2014	Circumferential crack at 1'. Overall line is clean and in good condition.
518	836	129	18" CIP	Line runs from CB on PYDE northbound (approx. 360' north of Cort Rd.) to OS down the canyon	LA-LAE-SD-CB0874-OS0873	CB0874 to OS0873	20.5	21	12/15/2014	Pipe has been lined previously. Line is clean and in good condition.
519	837	129	21" CMP	Line runs from CB on PYDE southbound (approx. 425' south of Cort Rd.) to CB across PYDE	LA-LAE-SD-CB0869-CB0870, LA-LAE-SD-CB0870-OS0871	CB0869 to CB0870, OS0871	139	139	12/10/2014	Pipe has been lined previously. Line is clean and in good condition.
520	838	129	UNKWN	Same as Line 837. Line runs from CB on PYDE northbound (approx. 425' south of Cort Rd.) to OS	LA-LAE-SD-CB0870-OS0871	CB0870 to OS0871	40	Same as line 837		
521	868	135	18" CMP	Line runs from IS behind property to OS/141 Noble View Dr.	LA-LAE-SD-OS0029-GB3414, LA-LAE-SD-GB3414-JS413	OS0029 to MH3413	98	98	12/9/2014	Pipe has been lined previously. Line is clean and in good condition.
522	876	137	18" RCP	Line starts at CB in front of property on Western Ave. side to mainline	ML-LAN-SD-CB0218-TS14135	CB0218 to Mainline	44.6	44.6	12/18/2015	Pipe looks clean and in good condition.
523	877	137	18" RCP	Line starts at CB in front of property on Western Ave. side to mainline	SM-PVW-SD-CB3351-GB3356, SM-PVW-SD-GB3356-MH3357, SM-PVW-SD-MH3357-OS3358	CB0215 to Mainline	75.7	76	12/18/2015	Pipe looks clean and in good condition.
523	358	63	24" RCP	Line starts at CB in front of property to OS in front of 6910 Maycroft Dr.	ML-LAN-SD-CB0215-TS14135	CB3351 to OS3358	161	161	11/7/2014	Pipe looks clean and in good condition.
524	359	63	24" RCP	Line starts at CB in front of property to OS on southwest corner of Brookford Dr./Arboret Dr.	SM-PVW-SD-CB3350-OS3361, SM-PVW-SD-JS3361-MH3360, SM-PVW-SD-MH3360-OS3362	CB3350 to OS3362	115	115	11/7/2014	Pipe looks clean and in good condition.
525	360	64	30" RCP	Line starts at CB on property (Mossbank Dr. side) to MH on Mossbank	SM-PVW-SD-CB2759-MH2763	CB2759 to MH2763	6	6	11/19/2014	Pipe looks clean and in good condition.
526	361	64	30" RCP	Line starts at CB on property (Mossbank Dr. side) to MH on Mossbank	SM-PVW-SD-CB2758-MH2763	CB2758 to MH2763	26	26	11/19/2014	Pipe looks clean and in good condition.
527	362	64	45" RCP	Line starts at MH at end of Mossbank cul-de-sac to MH in front of 26804 Basswood Ave.	SM-PVW-SD-MH2762-MH2763	MH2763 to MH2762	189	189	11/19/2014	Pipe looks clean and in good condition.
528	364	64	18" RCP	Line starts at CB in front of property to MH on Basswood northbound	SM-PVW-SD-CB2774-MH2762	CB2774 to MH2762	27	27	11/19/2014	Pipe looks clean and in good condition.
529	367	65	18" RCP	Line starts at CB on 27002 Shorewood (Basswood Ave. side) to JS in front of 26900 Basswood Ave.	SM-PVW-SD-CB2756-JS2768	CB2756 to JS2768	27	27	11/19/2014	Pipe looks clean and in good condition.
530	375	66	21" RCP	Line starts at MH in front of property to CB in front of 5108 Elkmont Dr.	ML-RHE-SD-MH1543-CB1542	MH1543 to CB1542	365	365	11/10/2014	Pipe looks clean and in good condition.
531	376	66	18" RCP	Line runs from CB in front of property to CB in front of 5108 Elkmont Dr.	ML-RHE-SD-CB1541-CB1542	CB1541 to CB1542	30	30	11/10/2014	Pipe looks clean and in good condition.
532	377	67	27" RCP	Line runs from MH in front of property to JS in front of 6762 Birchman Dr.	SM-PVW-SD-MH1282-JS1622	MH1282 to JS1622	411	411	11/7/2014	Pipe looks clean and in good condition.
533	378	67	18" RCP	Line starts at CB in front of property to CB in front of 28349 Plainfield Dr.	SM-PVW-SD-CB1252-CB1251	CB1252 to CB1251	32	32	11/7/2014	Pipe looks clean and in good condition.
534	384	69	15" RCP	Line starts at CB in front of property to CB across Elmbridge road	ML-RHE-SD-CB1480-CB1479	CB1480 to CB1479	37	37	11/10/2014	Pipe looks clean and in good condition.
535	385	69	18" RCP	Line runs from CB in front of property on Elmbridge Dr. side to JS on Browder Ln.	ML-RHE-SD-CB1479-JS2685	CB1479 to JS2685	52	52	11/10/2014	Pipe looks clean and in good condition.
536	418	74	18" RCP	Line starts at CB on PVDW northbound to CB on center median	SM-OWW-SD-CB1243-JS3197, SM-OWW-SD-JS3197-CB1244	CB1243 to CB1244	293	293	11/3/2014	Pipe looks clean and in good condition.
537	419	74	24" RCP	Line runs from CB on PVDW median (200' north of Marguerite Dr.) to MH on median 35' north	SM-OWW-SD-CB1244-MH3462	CB1244 to MH3462	38	38	11/25/2014	Pipe looks clean and in good condition.
538	421	74	24" RCP	Line runs from CB in front of property to MH 40' west	SM-OWW-SD-CB1245-MH3129	CB1245 to MH3129	41	41	11/4/2014	Pipe looks clean and in good condition.
539	423	74	24" RCP	Line runs from MH on PVDW northbound (approx. 95' north of Alida Pl.) to CB on PVDW median	SM-OWW-SD-MH3131-MH3462, SM-OWW-SD-CB1244-MH3462	MH3131 to CB1244	68	68	11/3/2014	Pipe looks clean and in good condition.
540	424	74	24" RCP	Line runs from MH on PVDW northbound (approx. 95' north of Alida Pl.) to IS	SM-OWW-SD-JS3130-JS3133, SM-OWW-SD-JS3133-MH3131	MH3131 to JS3130	20	20	11/11/1900	Pipe looks clean and in good condition.
541	427	74	24" RCP	Line runs from MH on PVDW median (approx. 230' north of Marguerite Dr.) to OS	GB3463-GB3464, SM-OWW-SD-GB3464-GB3465, SM-OWW-SD-GB3465-OS1246	MH3463 to OS1246	1067	1067	11/3/2014	Pipe looks clean and in good condition.
542	429	75	18" RCP	Line runs from CB in front of 7442 Via Lorado to MH on PVDW median	SM-OWW-SD-CB1248-MH1247	CB1248 to MH1247	123	123	10/31/2014	Pipe looks clean and in good condition.
543	432	76	18" RCP	Line starts at CB on Rue De La Pierre to CB in front of 30507 Rue De La Pierre	SM-OWW-SD-CB3300-CB3299	CB3300 to CB3299	27	27	11/7/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
544	86	433	24" RCP	Line starts at CB in front of property to CB in front of 30502 Rue Langlois	SM-OWW-SD-CB3399-CB3302	CB3399 to CB3302	79		11/3/2014	Pipe looks clean and in good condition.
545	87	434	16" RCP	Line starts at CB on Rue Langlois to CB in front of 30503 Rue Langlois	SM-OWW-SD-CB3301-CB3302	CB3301 to CB3302	43		11/3/2014	Pipe looks clean and in good condition.
546	88	469	18" RCP	Line starts at CB behind 11 Via Del Cielo property to CB SM-OWW-SD-CB1733-GB1734. SM-OWW-SD-GB1734-CB1735	SM-OWW-SD-CB3301-CB3302	CB1733 to CB1735	27.5		10/20/2014	Pipe looks clean and in good condition.
547	89	470	24" RCP	Line runs from CB adjacent to the south entrance of parking area to MH in parking area	SM-OWW-SD-CB1735-MH1736	CB1735 to MH1736	62.5		10/20/2014	Pipe looks clean and in good condition.
548	90	471	18" RCP	Line runs from CB in parking area south corner to MH in the middle of parking driveway	SM-OWW-SD-CB1737-MH1736	CB1737 to MH1736	28.5		10/20/2014	Pipe looks clean and in good condition.
549	91	472	24" RCP	Line runs from MH on parking area to JS	SM-OWW-SD-MH1736-JS1731	MH1736 to JS1731	392		10/20/2014	Pipe looks clean and in good condition.
550	92	473	30" RCP	Line runs from CB in front of property to MH in the middle of the street	SM-OWW-SD-CB1739-MH1738	CB1739 to MH1738	20		10/20/2014	Pipe looks clean and in good condition.
551	93	474	24" RCP	Line runs from CB in front of property to MH in the middle of the street	SM-OWW-SD-CB1740-MH1738	CB1740 to MH1738	30		10/20/2014	Pipe looks clean and in good condition.
552	94	475	30" RCP	Line runs from MH in front of property to MH on front yard of 5 Via Del Cielo	SM-OWW-SD-MH1738-MH1726	MH1738 to MH1726	166		10/20/2014	Pipe looks clean and in good condition.
553	95	476	18" RCP	Line runs from CB on PVDW northbound (approx. 850' north of Rue Beaupre) to JS	SM-OWW-SD-CB0614-JS1627	CB0614 to JS1627	8		11/25/2014	JS is a MH1627. Pipe looks clean and in good condition.
554	96	481	24" RCP	Line runs from CB on PVDW southbound (approx. 1800' north of Hawthorne Blvd. to MH 70' south	SM-OWW-SD-CB0613-MH1624	CB0613 to MH1624	66		11/25/2014	Pipe looks clean and in good condition.
555	97	482	40" RCP	Line runs from MH on PVDW southbound (approx. 1750' north of Hawthorne Blvd.)	TS0632-GB1629. SM-OWW-SD-GB1629-MH1630	MH1624 to MH1630	270		10/20/2014	Inspection abandoned due to camera inability to make a turn. Pipe looks clean and in good condition.
556	98	483	40" RCP	Line runs from MH in front of property to MH on Calle Cortada @ Via Del Cielo	SM-OWW-SD-GB1629-MH1630. SM-OWW-SD-TS0632-GB1629	MH1630 to MH1632	244		10/20/2014	Pipe looks clean and in good condition.
557	99	520	24" CMP	Line starts at CB to CB in front of property	SM-OWW-SD-CB0749-CB0748	CB0749 to CB0748	32		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
558	100	521	24" CMP	Line runs from CB to MH on Cartier Dr. at Dupre Dr.	SM-OWW-SD-CB0748-MH0759	CB0748 to MH0759	56		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
559	101	523	30" CMP	Line runs from MH at intersection to MH on Dupre Dr. at Hawthorne Blvd.	SM-OWW-SD-MH0759-MH0758	MH0759 to MH0758	130		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
560	102	524	24" CMP	Line starts at CB on Dupre Dr. eastbound to MH in the middle of the road	SM-OWW-SD-CB0743-MH0758	CB0743 to MH0758	28		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
561	103	525	24" CMP	Line starts at CB on Dupre Dr. westbound to MH in the middle of the road	SM-OWW-SD-CB0744-MH0758	CB0744 to MH0758	9		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
562	104	526	42" CPSP	Line runs from MH at intersection to MH on Hawthorne Blvd. southbound	Repeat? (Line No. 509)	MH0758 to OS1904 ?? MH1801	497		11/5/2014	Pipe looks clean and in good condition.
563	105	576	40" RCP	Line runs from MH on PVDW by St. Paul's Lutheran Church corner with cul-de-sac to ??	SM-OWW-SD-MH2749-OS20928	MH2749 to OS20928	228		10/21/2014	Pipe looks clean and in good condition.
564	106	577	48" RCP	Line runs from MH at corner of St. Paul's Lutheran Church and cul-de-sac to MH on Via Capri	SM-OWW-SD-MH2749-JS46935. SM-OWW-SD-JS2747-GB2748. SM-OWW-SD-JS2745-JS2747. SM-OWW-SD-JS2743-JS2745. SM-OWW-SD-MH2741-JS2743	MH2741 to MH2749	488		10/28/2014	Pipe looks clean and in good condition.
565	107	581	42" RCP	Line runs from MH on Via Capri at Via San Remo to MH on Via Capri before (2nd curve from Villa Capri gated entrance)	SM-OWW-SD-MH2735-JS2738. SM-OWW-SD-JS2738-JS2740. SM-OWW-SD-JS2740-MH2741	MH2735 to MH2741	305		10/28/2014	Pipe looks clean and in good condition.
566	108	582	18" RCP	Line runs from CB on Via Capri at Via San Remo to MH in the middle of the street	SM-OWW-SD-CB2739-JS2740	CB2739 to JS2740	20		10/28/2014	Pipe looks clean and in good condition.
567	109	584	18" RCP	Line runs from CB on Via Capri at Via San Remo to MH in the middle of the street	SM-OWW-SD-CB2736-MH2735	CB2736 to MH2735	18		10/28/2014	Pipe looks clean and in good condition.
568	110	585	48" RCP	Line runs from MH on landscaped area by Villa Capri gate entrance to MH on Via Capri at Via San Remo	SM-OWW-SD-MH2734-MH2735	MH2734 to MH2735	385		10/28/2014	Pipe looks clean and in good condition.
569	111	587	18" RCP	Line runs from CB on Hawthorne northbound (approx. 365' south of Via Rivera) to JS	SM-OWW-SD-CB2809-JS2809	CB2809 to JS2809	18		10/28/2014	Pipe looks clean and in good condition.
570	112	588	42" RCP	Line runs from MH in the middle of Hawthorne southbound (approx. 540' South of Via Rivera) to MH on landscaped area by Villa Capri gate entrance	SM-OWW-SD-MH2810-JS2809. SM-OWW-SD-JS2809-MH2734	MH2810 to MH2734	96		10/27/2014	Pipe looks clean and in good condition.
571	113	589	42" RCP	Line runs from MH in front of property to MH on Hawthorne (approx. 175' of Via Rivera)	SM-OWW-SD-MH2852-MH2810	MH2852 to MH2810	47		10/27/2014	Pipe looks clean and in good condition.
572	114	590	42" RCP	Line runs from MH in front of property to MH on Hawthorne (approx. 175' of Via Rivera)	SM-OWW-SD-MH2845-JS2846. SM-OWW-SD-JS2846-JS2848. SM-OWW-SD-JS2848-JS2850. SM-OWW-SD-JS2850-MH2852	MH2845 to MH2852	173		10/27/2014	Pipe looks clean and in good condition.
573	115	592	18" RCP	Line starts at CB between 7100 & 7090 Via Del Mar to JS	SM-OWW-SD-CB2847-JS2846	CB2847 to JS2846	6		10/27/2014	Pipe looks clean and in good condition.
574	116	593	18" RCP	Line starts at CB in front of property to MH	SM-OWW-SD-CB2844-MH2845	CB2844 to MH2845	13.5		10/27/2014	Pipe looks clean and in good condition.
575	117	595	36" RCP	Line starts at MH between 7100 & 7090 Via Del Mar to MH on Hawthorne Blvd southbound	SM-OWW-SD-MH2836-JS2840. SM-OWW-SD-JS2840-JS2842. SM-OWW-SD-JS2842-MH2810	MH2836 to MH2810	155		10/27/2014	Pipe looks clean and in good condition.
576	118	598	18" RCP	Line starts at CB between 7070 & 7050 Via Del Mar to JS	SM-OWW-SD-JS2840-JS2842	CB2840 to JS2842	8		10/27/2014	Pipe looks clean and in good condition.
577	119	599	18" RCP	Line starts at CB between 7065 & 7055 Via Del Mar to JS	SM-OWW-SD-CB2832-JS2831	CB2832 to JS2831	5		11/7/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
578	120	600	95	24" RCP	Line starts from MH in front of property to CB between 7070 & 7060 Via Del Mar	SM-OWW-SD-MH2835-MH2836	MH2835 to MH2836	79		10/27/2014	Pipe looks clean and in good condition.
579	121	602	95	24" RCP	Line runs from MH at end of cul-de-sac to MH in front of 7060 Via Del Mar	SM-OWW-SD-MH2834-MH2835	MH2834 to MH2835	68		11/20/2014	Pipe looks clean and in good condition.
580	122	603	95	24" RCP	Line starts at CB in open space by cul-de-sac to MH at cul-de-sac	SM-OWW-SD-CB2833-MH2834	CB2833 to MH2834	63		11/20/2014	Pipe looks clean and in good condition.
581	123	606	96	18" CIPP	Line runs from CB on Hawthorne southbound (approx. 615 northward of City Hall driveway) to PC	SM-OWW-SD-CB0584-PC0585	CB0584 to PC0585	110.5		10/30/2014	Pipe looks clean and in good condition.
582	124	608	96	24" RCP	Line starts at IS between 30959 & 30963 Via La Cresta to JS	SM-OWW-SD-IS2811-IS2812	IS2811 to JS2812	44		10/30/2014	Pipe looks clean and in good condition.
583	125	609	96	24" RCP	Line starts at CB in front of property to MH in the middle of the road	SM-OWW-SD-CB2815-MH2814	CB2815 to MH2814	40		10/30/2014	Pipe looks clean and in good condition.
584	126	612	96	30" RCP	Line runs from MH in front of property to MH on hill behind property	SM-OWW-SD-MH2814-IS2816, SM-OWW-SD-JS2816-GB2818, SM-OWW-SD-JS2820-GB2821, SM-OWW-SD-JS2822-GB2823	MH2814 to MH2825	185.5		10/30/2014	Pipe looks clean and in good condition.
585	127	616	96	30" RCP	Line runs from MH on hill behind property to MH off of Hawthorne southbound	SM-OWW-SD-MH2825-MH2827	MH2825 to MH2827	252		10/30/2014	Pipe looks clean and in good condition.
586	128	617	96	30" RCP	Line runs from MH Hawthorne southbound to MH on City Hall yard by driveway entrance	SM-OWW-SD-MH2827-GB2853, SM-OWW-SD-GB2853-JS2828, SM-OWW-SD-JS2828-MH2829	MH2827 to MH2829	176		10/30/2014	Pipe looks clean and in good condition.
587	129	619	96	18" RCP	Line runs from CB on Hawthorne southbound to MH on City Hall yard by driveway entrance	SM-OWW-SD-CB2804-MH2829	CB2804 to MH2829	135.5		10/30/2014	Pipe looks clean and in good condition.
588	130	625	97	24" RCP	Line starts at CB on Hawthorne southbound (approx. 1300' south of Vallon Dr.) to CB on Hawthorne northbound	SM-OWW-SD-CB0599-CB0595	CB0599 to CB0595	83		11/25/2014	Pipe looks clean and in good condition.
589	131	626	97	24" CIPP	Line starts at CB on Hawthorne southbound (approx. 1300' south of Vallon Dr.) to OS	SM-OWW-SD-CB0595-OS0596	CB0595 to OS0596	50		11/25/2014	Pipe has been lined previously. Pipe looks clean and in good condition.
590	132	627	97	30" RCP	535' south of Vallon Dr.) to CB on Hawthorne northbound	SM-OWW-SD-CB0752-CB0751	CB0752 to CB0751	104		11/25/2014	Pipe looks clean and in good condition.
591	133	628	97	30" RCP	Line starts at CB on Hawthorne southbound (approx. 600' south of Vallon Dr.) to OS	SM-OWW-SD-CB0751-OS0750	CB0751 to OS0750	24		11/25/2014	Pipe looks clean and in good condition.
592	134	636	98	30" CMP	Line starts at CB in front of 31325 Maine Dr. to CB across Maine Dr.	SM-OWW-SD-CB1620-CB0719	CB1620 to CB0719	35		11/5/2014	Pipe looks clean and in good condition.
593	135	637	98	36" CMP	Line runs from CB in front of 31326 Maine Dr. to MH in front of 31311 Maine Dr.	SM-OWW-SD-CB0719-MH1619	CB0719 to MH1619	104		11/5/2014	Pipe looks clean and in good condition.
594	136	646	101	18" RCP	Line runs from CB at the east end of road to OS on Coast Site Dr.	SM-OWW-SD-CB2866-OS2867	CB2866 to OS2867	128		10/21/2014	Pipe looks clean and in good condition.
595	137	648	101	18" RCP	Line runs from CB behind 6508 Via Baron to JS in front of 6508 Via Baron	SM-OWW-SD-CB2872-JS2868	CB2872 to JS2868	42		10/21/2014	Pipe looks clean and in good condition.
596	138	649	101	24" RCP	Line runs from CB in front of 6508 Via Baron to JS	SM-OWW-SD-CB2871-JS2868	CB2871 to JS2868	8.5		10/27/2014	Pipe looks clean and in good condition.
597	139	690	106	36" RCP & 36" CMP	Line runs from MH in front of property to OS on vacant lot next to 6124 PVDS (Firehouse)	SM-OWW-SD-MH0675-GB0674, SM-OWW-SD-GB0674-OS0673	MH0675 to OS0673	316.5		10/21/2014	Pipe looks clean and in good condition.
598	140	704	109	30" RCP	Line runs from IS to JS in between Schooner and Valor properties	SM-OWW-SD-MH0518-JS0524, SM-OWW-SD-JS0524-GB1919, SM-OWW-SD-GB1919-GB0517, SM-OWW-SD-GB0517-JS1918	IS0518 to JS1918	432		11/19/2014	Inspection abandoned at 432' due to pipe inclination. Line is clean and in good condition.
599	141	738	114	18" CIPP	Line runs from CB in front of property to MH behind 3227 Deluna	SM-OWW-SD-CB0084-MH0083	CB0084 to MH0083	113		10/13/2014	Pipe looks clean and in good condition.
600	142	739	114	18" CIPP	Line runs from MH on property's backyard to MH in front of 3224 Deluna	SM-OWW-SD-MH0083-GB34118, SM-OWW-SD-GB34118-GB34119, SM-OWW-SD-GB34119-GB34120, SM-OWW-SD-GB34120-GB34121, SM-OWW-SD-GB34121-MH0082	MH0083 to MH0082	250		10/13/2014	Pipe looks clean and in good condition.
601	143	746	114	36" CIPP	Line runs from MH behind 3134 Corinna to OS across Crest Rd.	SM-OWW-SD-CB0067-MH0073, SM-OWW-SD-MH0073-OS0072	MH0073 to OS0072	116		10/14/2014	Pipe has been lined previously. Line looks clean and in good condition.
602	144	748	114	24" RCP	Line runs from CB to CB on Crest eastbound	SM-OWW-SD-CB34923-CB34924	CB0069 to CB0070	40		10/13/2014	Pipe looks clean and in good condition.
603	145	749	114	30" RCP	Line runs from CB to CB on Crest eastbound	SM-OWW-SD-CB34924-CB0071	CB0070 to CB0071	39.5		10/13/2014	Pipe looks clean and in good condition.
604	146	750	114	30" RCP	Line runs from CB to CB on Crest eastbound	SM-OWW-SD-CB0071-MH0073	CB0071 to MH0073	38		10/13/2014	Pipe looks clean and in good condition.
605	147	874	137	18" RCP	Line starts at CB in front of property to MH on Peninsula Verde Dr. at Western Ave.	ML-LAN-SD-CB0217-MH0223	CB0217 to MH0223	32.5		10/15/2014	Pipe looks clean and in good condition.
606	148	875	137	18" RCP	Line starts at CB in front of property to MH on Peninsula Verde Dr. at Western Ave.	ML-LAN-SD-CB0216-MH0223	CB0216 to MH0223	10		10/15/2014	Pipe looks clean and in good condition.
607	149	883	140	78" RCP	Line runs from JS on Toscanini (approx. 135' east of Western Ave.) to JS on Western Ave. at Toscanini	LA-LAE-SD-JS0149-JS2711	JS2711 to JS0149	229		10/15/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
608	386	70	24" RCP	Line starts at CB in front of property to MH in front of 8 Via Malona	SM-PVW-SD-CB2720-MH2722	CB2720 to MH2722	240		11/10/2014	Pipe looks clean and in good condition.
609	387	70	18" RCP	Line starts at CB to MH in front of property	SM-PVW-SD-CB2721-MH2722	CB2721 to MH2722	18		11/10/2014	Pipe looks clean and in good condition.
610	388	70	24" RCP	Line runs from MH in front of property to MH in front of 19 Via Malona	SM-PVW-SD-MH2722-MH2727	MH2722 to MH2727	266		11/10/2014	Pipe looks clean and in good condition.
611	389	70	24" RCP	Line runs from MH in front of property to MH in front of 29 Via Malona	SM-PVW-SD-MH2727-MH2726	MH2727 to MH2726	180		11/10/2014	Pipe looks clean and in good condition.
612	390	70	18" RCP	Line starts at CB in front of property to CB in front of 29 Via Malona	SM-PVW-SD-CB2724-CB2723	CB2724 to CB2723	38		11/17/2014	Pipe looks clean and in good condition.
613	391	70	18" RCP	Line runs from CB in front of property to JS	SM-PVW-SD-CB2723-JS2725	CB2723 to JS2725	14		11/17/2014	Pipe looks clean and in good condition.
614	392	70	30" RCP	Line runs from MH on property to MH on 28826 King Arthur Ct. backyard	SM-PVW-SD-MH2726-MH2719	MH2726 to MH2719	115		11/17/2014	Pipe looks clean and in good condition.
615	407	73	36" RCP	Line runs from MH in front of property to JS in the middle of the street	ML-RHE-SD-US3488-MH3489	MH3489 to JS3488	13		11/16/2014	Pipe looks clean and in good condition.
616	409	73	39" RCP	Line runs from MH in front of property to JS approx. 305 ML-RHE-SD-GB3487-JS3488, ML-RHE-SD-MH1007-GB3487	ML-RHE-SD-GB3487-JS3488, ML-RHE-SD-MH1007-GB3487	MH1007 to JS3488	317		11/16/2014	Pipe looks clean and in good condition.
617	410	73	18" RCP	Line starts at CB to MH in front of property	ML-RHE-SD-CB1008-MH1007	CB1008 to MH1007	27		11/16/2014	Pipe looks clean and in good condition.
618	411	73	18" RCP	Line starts at CB to MH in front of property	ML-RHE-SD-CB1009-MH1007	CB1009 to MH1007	10		11/16/2014	Pipe looks clean and in good condition.
619	412	73	36" RCP	Line runs from MH in front of property to MH in front of 28733 Creanridge Rd.	ML-RHE-SD-MH1006-MH1007	MH1006 to MH1007	297		11/20/2014	Pipe looks clean and in good condition.
620	413	73	30" RCP	Line runs from MH in front of property to MH in front of 28733 Creanridge Rd.	ML-RHE-SD-GB3486-MH1006, ML-RHE-SD-MH1003-GB3486	MH1003 to MH1006	315		11/16/2014	Pipe looks clean and in good condition.
621	416	73	18" Lined	Line starts at CB on Crest Rd. eastbound (approx. 580' from Greenlane Blvd.) to CB across Crest Rd.	ML-RHE-SD-CB0997-CB0998	CB0997 to CB0998	240		11/11/2014	Pipe has been lined previously. Line is clean and in good condition.
622	425	74	18" RCP	Line runs from CB on PVDW northbound (approx. 115' north of Alida Pl.) to JS 20' south	SM-OWW-SD-CB3132-JS3133	CB3132 to JS3133	10		11/14/2014	Pipe looks clean and in good condition.
623	437	78	18" RCP	Line starts at CB in front of 30026 Cactian Pl in front of 30023 Cactian Pl	SM-OWW-SD-CB1098-CB1099	CB1098 to CB1099	31		11/15/2014	Pipe looks clean and in good condition.
624	438	78	18" CMP	Line runs from CB in front of property to CB on Hawthorne Blvd. behind same property	SM-OWW-SD-CB1888-GB1888, SM-OWW-SD-GB1888-GB1888, SM-OWW-SD-GB1888-GB1888	CB1888 to GB1888	145		11/13/2014	Pipe has been lined previously. Pipe is clean and in good condition.
625	439.1	78	18" Lined	Line runs from CB on Hawthorne (approx. 445' south from intersection) to MH on vacant lot behind Ralph's	SM-OWW-SD-CB1100-MH2679, SM-OWW-SD-JS48132-MH1101	CB1100 to MH1101	91		11/13/2014	Pipe has been lined previously. Pipe is clean and in good condition.
626	441	78	36" RCP	Line runs from MH on vacant lot behind Ralph's to MH in front of 30135 Ave. Calistral	SM-OWW-SD-MH1101-GB3160, SM-OWW-SD-GB3160-GB3161, SM-OWW-SD-GB3161-MH3162	MH1101 to MH3162	408		11/13/2014	Pipe looks clean and in good condition.
627	442	78	36" RCP	Line runs from MH in front of property to MH in front of 30107 Ave. Calistral	SM-OWW-SD-MH3162-JS3163, SM-OWW-SD-JS3163-MH3166	MH3162 to MH3166	238		11/14/2014	Pipe looks clean and in good condition.
628	443	78	24" RCP	Line starts at CB in front of property to JS	SM-OWW-SD-CB3164-JS3163	CB3164 to JS3163	23		11/15/2014	Pipe looks clean and in good condition.
629	444	78	18" RCP	Line starts at CB in front of property to MH	SM-OWW-SD-CB3165-MH3166	CB3165 to MH3166	12		11/14/2014	Pipe looks clean and in good condition.
630	446	78	36" RCP	Line runs from MH in front of property to MH in front of 30134 Ave. Explendda	SM-OWW-SD-JS3169, SM-OWW-SD-JS3169-GB3170, SM-OWW-SD-GB3170-MH2627	MH3166 to MH2627	400		11/14/2014	Hard deposits starting from 300' to 345' ->5%. Pipe looks clean and in good condition.
631	447	78	18" RCP	Line runs from CB on Los Verdes (301'96 Ave. Explendda) to JS	PIPE FOUND	CB1118 to JS3519	34		11/15/2014	Pipe looks clean and in good condition.
632	448	78	18" RCP	Line starts at CB on Sea Terrace adjacent to 65 Seabreeze	SM-OWW-SD-CB2637-JS2639	CB2637 to JS2639	65		11/14/2014	Pipe looks clean and in good condition.
633	449	79	24" RCP	Line starts at CB in front of property to MH (approx. 300' SM-OWW-SD-CB2638-JS2639, SM-OWW-SD-JS2639-JS2640, SM-OWW-SD-JS2640-MH1080)	SM-OWW-SD-CB2638-JS2639, SM-OWW-SD-JS2639-JS2640, SM-OWW-SD-JS2640-MH1080	CB2638 to MH1080	297		11/14/2014	Pipe looks clean and in good condition.
634	450	79	18" RCP	Line starts at CB adjacent to 70 Seabreeze to JS	SM-OWW-SD-CB2642-JS2640	CB2642 to JS2640	20		11/14/2014	Pipe looks clean and in good condition.
635	451	79	30" RCP	Line runs from MH on Crest Rd. eastbound (approx. 240' west of intersection) to MH adjacent to 70 Seabreeze	SM-OWW-SD-MH2645-GB2646, SM-OWW-SD-GB2646-MH1080	MH2645 to MH1080	118		11/14/2014	Pipe looks clean and in good condition.
636	452	79	18" RCP	Line starts at CB on Seabreeze (approx. 210' west of Sea Terrace) to MH across the road	SM-OWW-SD-CB2641-MH1080	CB2641 to MH1080	30		11/14/2014	Pipe looks clean and in good condition.
637	453	79	36" RCP	Line runs from MH adjacent to 70 Seabreeze to OS	SM-OWW-SD-MH1080-GB2647, SM-OWW-SD-GB2647-OS2643	MH1080 to OS2643	75		11/14/2014	Pipe looks clean and in good condition.
638	455	80	18" RCP	Line starts at CB in front of property to JS	SM-OWW-SD-CB2626-JS2624	CB2626 to JS2624	36		11/10/2014	Pipe looks clean and in good condition.
639	456	80	24" RCP	Line runs from JS (approx. in front of 20 Seabreeze) to MH in front of 28 Seabreeze	SM-OWW-SD-JS2624-GB2623, SM-OWW-SD-GB2623-JS2622, SM-OWW-SD-JS2622-MH2621	JS2624 to MH2621	203		11/11/2014	Pipe looks clean and in good condition.
640	457	80	18" RCP	Line starts at CB in front of property to JS	SM-OWW-SD-CB2620-JS2622	CB2620 to JS2622	26		11/14/2014	Pipe looks clean and in good condition.
641	458	80	18" RCP	Line starts at CB on Canal Ave. adjacent to 27 Sea View to MH in front of 28 Sea View	SM-OWW-SD-CB2619-MH2621	CB2619 to MH2621	67		11/11/2014	Pipe looks clean and in good condition.
642	459	80	24" RCP	Line runs from MH in front of 28 Sea View to MH in front of 34 Sea View	SM-OWW-SD-MH2621-MH2627	MH2621 to MH2627	278		11/11/2014	Pipe looks clean and in good condition.
643	460	80	24" RCP	Line starts at CB in front of property to MH in the middle of the street	SM-OWW-SD-CB2628-MH2627	CB2628 to MH2627	21		11/14/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
644	186	461	80	24" RCP	Line runs from MH in front of property to MH in front of 40 Sea View	SM-OSW-SD-MH2627-MH2629	MH2627 to MH2629	300		11/14/2014	Pipe looks clean and in good condition.
645	187	462	80	18" RCP	Line starts at CB in front of property to TS	SM-OSW-SD-CB2631-TS2630	CB2631 to TS2630	5		11/14/2014	Pipe looks clean and in good condition.
646	188	463	80	30" RCP	Line runs from MH in front of property to MH on easement	SM-OSW-SD-MH2629-TS2630, SM-OSW-SD-TS2630-MH2632	MH2629 to MH2632	127		11/14/2014	Pipe looks clean and in good condition.
647	189	476	83	30" RCP	Line runs from MH in front of property to MH in front of 5 Via Del Cielo property	SM-OSW-SD-MH1725-GB1726, SM-OSW-SD-GB1725-MH1726	MH1725 to MH1726	464		10/22/2014	Pipe looks clean and in good condition.
648	190	477	83	18" RCP	Line runs from MH in front yard of property to OS down the cliff	SM-OSW-SD-MH1725-GB1727, SM-OSW-SD-GB1727-MH1728, SM-OSW-SD-GB1728-TS1730, SM-OSW-SD-TS1730-TS1729, SM-OSW-SD-TS1729-JS1731, SM-OSW-SD-JS1731-JS1732, SM-OSW-SD-JS1732-OS3103	MH1726 to OS3103	555		10/22/2014	Pipe looks clean and in good condition.
649	191	484	84	18" RCP	Line starts at CB on Calle Cortada next to 30 Via Del Cielo to MH in the middle of the street of Calle Cortada	SM-OSW-SD-CB1633-MH1632	CB1633 to MH1632	18		10/23/2014	Pipe looks clean and in good condition.
650	192	485	84	18" RCP	Line starts at CB on Calle Cortada next to 32 Via Del Cielo to MH in the middle of the street of Calle Cortada	SM-OSW-SD-CB1634-MH1632	CB1634 to MH1632	18		10/23/2014	Pipe looks clean and in good condition.
651	193	486	84	48" RCP	Line runs from MH on Calle Cortada to MH in front of 33 Via Del Cielo	SM-OSW-SD-MH1632-GB1635, SM-OSW-SD-GB1635-GB1636, SM-OSW-SD-GB1636-MH1637	MH1632 to MH1637	77.5		10/23/2014	Pipe looks clean and in good condition.
652	194	487	84	48" RCP	Line runs from MH in front of property to MH on Calle Entradero behind 35 Via Del Cielo	SM-OSW-SD-MH1637-GB1638, SM-OSW-SD-GB1638-GB1639, SM-OSW-SD-GB1639-GB1640, SM-OSW-SD-GB1640-GB1641, SM-OSW-SD-GB1641-MH1642	MH1637 to MH1642	366		10/23/2014	Pipe looks clean and in good condition.
653	195	488	84	48" RCP	Line runs from MH on Calle Entradero to MH behind 37 Via Del Cielo on Calle Entradero	SM-OSW-SD-MH1642-MH1643	MH1642 to MH1643	123.5		10/22/2014	Pipe looks clean and in good condition.
654	196	489	84	18" RCP	Line starts at CB on Calle Entradero behind 37 Via Del Cielo to MH in the middle of Calle Entradero	SM-OSW-SD-CB1645-MH1643	CB1645 to MH1643	12		10/22/2014	Pipe looks clean and in good condition.
655	197	490	84	18" RCP	Line starts at CB on Calle Entradero southbound to MH in the middle of Calle Entradero	SM-OSW-SD-CB1644-MH1643	CB1644 to MH1643	14		10/22/2014	Pipe looks clean and in good condition.
656	198	495	85	30" RCP	Line runs from MH in front of property to MH in front of 30706 Via Rivera	SM-OSW-SD-MH3387-GB3388, SM-OSW-SD-GB3388-MH3389, SM-OSW-SD-MH3389-JS1976, SM-OSW-SD-JS1976-MH3377, SM-OSW-SD-GB3377-MH3376, SM-OSW-SD-GB3376-MH3374	MH3387 to MH3376	572.5'		10/23/2014	Pipe looks clean and in good condition.
657	199	495.1	85	30" RCP	Line runs from MH on Via Rivera at Rue de la Pierre to MH in front of 30653 Rue Valois	SM-OSW-SD-MH0635-JS1976, SM-OSW-SD-JS1976-MH0619, SM-OSW-SD-MH0619-JS0634, SM-OSW-SD-JS0634-GB3377, SM-OSW-SD-GB3377-MH0635, SM-OSW-SD-GB3376-MH3374	MH0635 to MH3374	305		10/23/2014	Pipe looks clean and in good condition.
658	200	498.1	86	30" RCP	Line runs from MH at corner of intersection to MH adjacent to Los Verdes northbound	SM-OSW-SD-MH1157-MH1158, SM-OSW-SD-MH1158-JS3519, SM-OSW-SD-JS3519-JS3520, SM-OSW-SD-JS3520-MH31716, SM-OSW-SD-MH31716-GB31722, SM-OSW-SD-GB31722-GB31719, SM-OSW-SD-GB31719-MH31720	MH1157 to MH1120	711		10/30/2014	Unmapped MH at 120', 343' and 572'. Pipe is clean and in good condition.
659	201	505	86	18" RCP	Line starts at CB in front of 30196 Ave. Esplanada to MH	SM-OSW-SD-CB1117-MH1158	CB1117 to MH1158	14.5		11/5/2014	Pipe looks clean and in good condition.
660	202	506.1	86	27" RCP	Line runs from MH at corner to MH in front of 30235 Ave. Selecta	SM-OSW-SD-MH1115-MH1157	MH1115 to MH1157 (IACO)	310		10/30/2014	Pipe looks clean and in good condition.
661	203	506.2	86	27" RCP	Line runs from MH in front of 30235 Ave. Selecta to MH between 30232 & 30242 Ave. Selecta homes	SM-OSW-SD-MH1155-GB2530, SM-OSW-SD-GB2530-MH1116	MH1155 to MH1116 (IACO)	187		10/30/2014	Pipe looks clean and in good condition.
662	204	510	87	42" RCP	Line runs from MH in front of property to MH in the middle of the golf course	SM-OSW-SD-MH0741-JS13717, SM-OSW-SD-JS13717-MH0734	MH0741 to MH0734	316		11/5/2014	Pipe looks clean and in good condition.
663	205	511	87	42" RCP	Line runs from MH in the middle of the golf course to MH behind 6767 Vallon Dr. (approx. 90' north of property)	SM-OSW-SD-MH0734-MH0733	CB0734 to MH0733	290		11/5/2014	Pipe looks clean and in good condition.
664	206	512	87	27" RCP	Line runs from MH behind 6767 Vallon Dr. (approx. 90' north of property) to TS adjacent to back property of 6767 Vallons Dr.	SM-OSW-SD-MH0733-JS0756, SM-OSW-SD-JS0756-TS2416	MH0733 to TS2416	455		11/5/2014	Pipe looks clean and in good condition.
665	207	516	87	18" RCP	Line runs from MH in front of property to CB in front of 6823 Alta Vista	SM-OSW-SD-CB0735-CB0736	CB0736 to CB0735	35		11/6/2014	Pipe looks clean and in good condition.
666	208	517	87	18" RCP	Line runs from IS behind property to CB in front of 6823 Alta Vista Dr.	SM-OSW-SD-IS0732-CB0735	CB0735 to IS0732	814		11/6/2014	Pipe looks clean and in good condition. This line does not end at an OS; it is a manhole.
667	209	532	141	18" RCP	Line starts at CB in front of property to OS in canyon behind property	SM-OSW-SD-CB0572-OS0573	CB0572 to OS0573	168		10/31/2014	Line does not end at an OS; it ties into a bigger unmapped line. Pipe is clean and in good condition.
668	210	532.1	141	48" RCP	Line starts, IS in canyon behind property to MH??	SM-OSW-SD-CB0572-OS0573	OS0573 to MH0570	282		11/3/2014	Pipe looks clean and in good condition.
669	211	533	89	48" RCP	Line runs from MH on Calle Entradero (behind 37 Via Del Cielo) to MH on Calle Entradero (behind 55 Via Del Cielo)	SM-OSW-SD-MH1643-MH1646	MH1643 to MH1646	416.5		10/24/2014	Pipe looks clean and in good condition.
670	212	534	89	48" RCP	Line runs from MH on Calle Entradero (behind 55 Via Del Cielo) to MH on Calle Entradero (behind 61 Via Del Cielo)	SM-OSW-SD-MH1646-GB1647, SM-OSW-SD-GB1647-MH1648, SM-OSW-SD-GB1648-MH1649	MH1646 to MH1649	428.5		10/24/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
671	213	89	18" RCP	Line runs from CB on Calle Entradero southbound (behind 61 Via Del Cielo) to MH in the middle of the road SM-OWW-SD-CB1651-MH1649	SM-OWW-SD-CB1651-MH1649	CB1651 to MH1649	13		10/27/2014	Pipe looks clean and in good condition.
672	214	89	18" RCP	Line runs from CB on Calle Entradero northbound (behind 61 Via Del Cielo) to MH in the middle of the road SM-OWW-SD-CB1650-MH1649	SM-OWW-SD-CB1650-MH1649	CB1650 to MH1649	21		10/27/2014	Pipe looks clean and in good condition.
673	215	89	36" RCP	Line runs from MH on Calle Entradero (behind 61 Via Del Cielo) to MH on Calle Entradero (behind 65 Via Del Cielo)	SM-OWW-SD-MH1649-MH1652	MH1649 to MH1652	61		10/24/2014	Pipe looks clean and in good condition.
674	216	89	18" RCP	Line starts at CB in front of property to MH in the middle of the street	SM-OWW-SD-CB1684-MH1681	CB1684 to MH1681	33		10/23/2014	Pipe looks clean and in good condition.
675	217	89	30" RCP	Line starts at IS on Via Del Cielo northbound to MH in the middle of the street	SM-OWW-SD-CB1682-MH1681	CB1682 to MH1681	31		10/23/2014	Pipe looks clean and in good condition.
676	218	89	30" RCP	Line runs from MH in front of property to MH on Calle Entradero	SM-OWW-SD-MH1681-GB1676 SM-OWW-SD-GB1676-MH1681	CB1682 to MH1681	283.5		10/23/2014	Pipe looks clean and in good condition.
677	219	90	48" RCP	Line runs from MH on Calle Entradero (behind 65 Via Del Cielo) to MH on open space (approx. 265' south)	SM-OWW-SD-MH1652-GB1655 SM-OWW-SD-GB1655-MH1653	MH1652 to MH1653	267		10/27/2014	Pipe looks clean and in good condition.
678	220	90	48" RCP	Line runs from MH on open space to MH in front of 36 Pacifica Del Mar	SM-OWW-SD-MH1653-MH1656	MH1653 to MH1656	476		10/27/2014	Pipe looks clean and in good condition.
679	221	90	42" RCP	Line runs from MH on Via Vicente by Calle Viento to MH on Pacifica Del Mar by Calle Viento	SM-OWW-SD-CB1699-GB1699 SM-OWW-SD-GB1699-MH1697	CB1699 to MH1697	319		10/28/2014	Pipe looks clean and in good condition.
680	222	90	42" RCP	Line runs from MH on Via Vicente adjacent to 78 Via Del Cielo to MH on Via Vicente by Calle Viento	SM-OWW-SD-MH1694-MH1697	MH1694 to MH1697	423		10/28/2014	Pipe looks clean and in good condition.
681	223	91	48" RCP	Line runs from MH in front of property to MH on driveway off of end of cul-de-sac	SM-OWW-SD-MH1656-GB1657 SM-OWW-SD-GB1657-MH1658 SM-OWW-SD-GB1658-MH1659	MH1656 to MH1659	320		10/27/2014	Pipe looks clean and in good condition.
682	224	91	18" RCP	Line starts at CB at end of the cul-de-sac to JS on driveway off of end of cul-de-sac	SM-OWW-SD-CB1659-JS1662 SM-OWW-SD-JS1662-MH1663	CB1659 to JS1662	47		10/28/2014	Pipe looks clean and in good condition.
683	225	91	48" RCP	Line runs from MH on driveway off of cul-de-sac to MH on open space	SM-OWW-SD-CB1662-GB1661 SM-OWW-SD-GB1661-MH1666	CB1662 to MH1666	242		10/27/2014	Pipe looks clean and in good condition.
684	226	91	48" RCP	Line runs from MH on open space to OS at the bottom of the cliff	SM-OWW-SD-MH1666-GB1667 SM-OWW-SD-GB1667-MH1670	MH1666 to OS1670	145		10/27/2014	Pipe looks clean and in good condition.
685	227	92	42" RCP	Line runs from MH on PVDW approx. 260' north of Via Vicente to MH Via Vicente by Via Del Cielo	SM-OWW-SD-MH1707-JS1708 SM-OWW-SD-JS1708-MH1694	MH1707 to MH1694	475		10/28/2014	Pipe looks clean and in good condition.
686	228	92	18" RCP	Line runs from CB on northwest corner of intersection to JS on Via Vicente	SM-OWW-SD-MH1707-JS1708	MH1707 to JS1708	184		10/31/2014	Pipe looks clean and in good condition.
687	229	92	36" RCP	Line runs from CB on Hawthorne southbound (approx. 225' north of Valen Dr.) to CB on Hawthorne southbound	SM-OWW-SD-CB0728-JS2401 SM-OWW-SD-JS2401-JS0727 SM-OWW-SD-JS0727-CB0721	CB0728 to CB0721	619		11/3/2014	Pipe looks clean and in good condition.
688	230	98	36" RCP	Line starts at CB on southeast corner to CB on southwest corner	SM-OWW-SD-CB2908-CB0721	CB2908 to CB0721	345		11/4/2014	Pipe looks clean and in good condition.
689	231	98	18" CMP				128		11/4/2014	Pipe has been lined previously. Pipe looks clean and in good condition.
690	232	99	36" RCP	Line starts at IS PVC entrance/exit island to MH in front of PVC parking area	SM-OWW-SD-MH1619-GB1900 SM-OWW-SD-GB1900-MH1699 SM-OWW-SD-GB1699-GB1897 SM-OWW-SD-GB1897-GB1898 SM-OWW-SD-GB1898-GB1896 SM-OWW-SD-GB1896-OS0720	IS0562 to MH3600	469		10/16/2014	Pipe looks clean and in good condition.
691	233	99	36" RCP	Line starts at MH in front of PVC parking area to MH	SM-OWW-SD-MH3600-MH3602	MH3600 to MH3602	194		10/16/2014	Pipe looks clean and in good condition.
692	234	99	36" RCP	Line starts at MH adjacent to gravel parking lot to MH by SM-OWW-SD-MH3602-JS3604 SM-OWW-SD-JS3604-MH3606	SM-OWW-SD-MH3602-JS3604 SM-OWW-SD-JS3604-MH3606	MH3602 to MH3606	506		10/16/2014	Pipe looks clean and in good condition.
693	235	99	36" RCP & 36" CMP	Line runs from MH by PVC trail to MH1669	SM-OWW-SD-MH1669	MH1669 to MH1669	483		10/29/2014	Pipe looks clean and in good condition.
694	236	102	48" RCP & CMP	Line runs from CB approx. 560' west of Barkentine Rd. to CB on PVDW eastbound	SM-OWW-SD-CB3556-GB3556 SM-OWW-SD-GB3556-JS3557 SM-OWW-SD-JS3557-CB3426	CB3556 to CB3426	256		10/29/2014	Pipe looks clean and in good condition.
695	237	102	42" RCP	Line runs from MH on PVDW approx. 150' east of Packer Rd.) to MH on PVDW approx. 150' east of Packer Rd.)	SM-OWW-SD-MH0691-JS0690 SM-OWW-SD-JS0690-MH0692	MH0691 to MH0692	300		10/17/2014	Pipe looks clean and in good condition.
696	238	102	24" RCP	Line runs from MH on PVDW eastbound (approx. 80' west of intersection) to MH on PVDW (approx. 140' west of Barkentine Rd.)	SM-OWW-SD-MH0681-JS13321 SM-OWW-SD-JS13321-MH0692	MH0681 to MH0692	210		10/17/2014	Pipe looks clean and in good condition.
697	239	102	66" STL	Line runs from IS approx. 560' west of Barkentine Rd. to MH on PVDW westbound	SM-OWW-SD-IS3554-MH3553	IS3554 to MH3553	299		10/20/2014	Pipe looks clean and in good condition.
698	240	102	66" STL	Line runs from MH on PVDW westbound (approx. 560' west of Barkentine Rd.) to MH in church parking lot	SM-OWW-SD-MH3553-MH3550	MH3553 to MH3550	204		10/20/2014	Pipe looks clean and in good condition.
699	241	102	18" RCP	Line starts at CB to MH in church parking lot	SM-OWW-SD-CB3551-MH3550	CB3551 to MH3550	31		10/20/2014	Pipe looks clean and in good condition.
700	242	103	66" STL	Line runs from MH by the church driveway to MH in the southeast corner of church property	SM-OWW-SD-MH3550-GB3549 SM-OWW-SD-GB3549-MH3547	MH3550 to MH3547	291.5		10/20/2014	Pipe looks clean and in good condition.
701	243	103	18" RCP	Line runs from CB to MH in the southeast corner of church property	SM-OWW-SD-CB3548-MH3547	CB3548 to MH3547	18		10/17/2014	Pipe looks clean and in good condition.
702	244	103	66" STL	Line runs from MH in the southeast corner of church property to MH on Sea Gate Dr.	SM-OWW-SD-MH3547-MH3544	MH3547 to MH3544	404		10/20/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
703	245	103	18" RCP	Line runs from CB on Sea Gate southbound to MH on the road	SM-OSW-SD-CB3546-MH3544	CB3546 to MH3544	29		10/17/2014	Pipe looks clean and in good condition.
704	246	103	18" RCP	Line runs from CB on Sea Gate northbound to MH on the road	SM-OSW-SD-CB3545-MH3544	CB3545 to MH3544	11		10/17/2014	Pipe looks clean and in good condition.
705	247	103	66" STL	Line runs from MH to MH on Sea Gate northbound	SM-OSW-SD-MH3544-MH3543	MH3544 to MH3543	371		10/20/2014	Pipe looks clean and in good condition
706	248	103	54" CMP	Line runs from MH on PVDs between Packet & Barkentine to MH in between 11 Barkentine & 12 Packet	SM-OSW-SD-MH0689-JS3530, SM-OSW-SD-MH0692-MH0680	MH0692 to MH0680	344		10/17/2014	Invert has been paved with concrete previously. Line is clean and in good condition.
707	249	103	54" CMP	Line runs from MH in between 19 Barkentine & 22 Packet to MH on Seacove Dr. off of Packet	SM-OSW-SD-MH0688-JS3530, SM-OSW-SD-JS3530-MH3528	MH0688 to MH3528	314.5		10/17/2014	Invert has been paved with concrete previously. Line is clean and in good condition.
708	250	104	18" RCP	Line runs from CB to CB in corner of street intersection front of 32 Seacove Dr.	SM-OSW-SD-CB3531-MH3532	CB3531 to CB3531	6.5		10/21/2014	Pipe looks clean and in good condition.
709	251	104	18" RCP	Line runs from CB to CB in front of property	SM-OSW-SD-CB3537-CB3536	CB3537 to CB3536	23		10/21/2014	Pipe looks clean and in good condition.
710	252	104	18" RCP	Line runs from CB to CB in front of property to JS	SM-OSW-SD-CB3536-JS3535	CB3536 to JS3535	23		10/21/2014	Pipe looks clean and in good condition.
711	253	104	18" RCP	Line runs from CB to CB in front of property	SM-OSW-SD-CB0678-CB3530	CB0678 to CB3530	5		10/21/2014	Pipe looks clean and in good condition.
712	254	104	18" RCP	Line runs from CB to CB in front of property	SM-OSW-SD-CB3530-MH3528	CB3530 to MH3528	26		10/21/2014	Pipe looks clean and in good condition.
713	255	104	18" RCP	Line runs from MH in front of property to MH in front of 42 Seacove	SM-OSW-SD-MH3528-MH3526	MH3528 to MH3526	255.5		10/21/2014	Pipe looks clean and in good condition.
714	256	105	54" RCP	Line runs from CB to MH in front of property	SM-OSW-SD-CB3529-MH3526	CB3529 to MH3526	14		10/29/2014	Pipe looks clean and in good condition.
715	257	105	54" RCP	Line runs from CB at the end of Seacove cul-de-sac to MH on Sea Gate Dr.	SM-OSW-SD-CB3529-MH3526	MH3526 to Mainline	13		10/21/2014	Pipe looks clean and in good condition.
716	258	105	54" RCP	Line runs from CB at the end of Seacove cul-de-sac to MH on Sea Gate Dr.	SM-OSW-SD-CB3524-MH3525	CB3524 to MH3525	78.5		10/21/2014	Pipe looks clean and in good condition.
717	259	105	54" RCP	Line runs from MH to MH on Sea Gate northbound	SM-OSW-SD-MH3543-MH3525	MH3543 to MH3525	240		10/20/2014	Pipe looks clean and in good condition.
718	260	105	66" STL	Line runs from MH on Sea Gate northbound to MH on apartment complex grass area	SM-OSW-SD-MH3525-MH3539	MH3525 to MH3539	133.5		10/20/2014	Pipe looks clean and in good condition.
719	261	105	66" STL	Line runs from MH on Sea Gate next to 44 Seacove to CB across road	SM-OSW-SD-CB3540-CB3541	CB3540 to CB3541	38.5		10/24/2014	Pipe looks clean and in good condition.
720	262	105	18" RCP	Line runs from CB to CB on Seagate	SM-OSW-SD-CB0658-CB0657	CB0658 to CB0657	35		10/29/2014	Pipe looks clean and in good condition.
721	263	105	18" RCP	Line starts at JS behind property to MH in front of 30121 Miraleste	LA-LAS-SD-S0240-MH3454	S0240 to MH3454	201		10/14/2014	Pipe looks clean and in good condition.
722	264	112	48" RCP	Line runs from MH in front of property to OS across Miraleste Dr. down the canyon	LA-LAS-SD-MH0494-GB0238	MH0494 to OS0237	246		10/14/2014	Pipe looks clean and in good condition.
723	265	112	48" RCP	Line starts at CB in front of property to OS across the road	LA-LAS-SD-CB3453-OS3452	CB3453 to OS3452	133		10/14/2014	Pipe looks clean and in good condition.
724	266	112	21" RCP	Line runs from MH in front of property to MH in front of 3134 Corrina	SM-OSW-SD-MH0082-MH34122, SM-OSW-SD-MH34122-MH0081, SM-OSW-SD-MH0081-MH3562, SM-OSW-SD-MH3562-MH34123, SM-OSW-SD-MH34123-MH0075	MH0082 to MH3562, MH0075 to MH3562	370		10/14/2014	Pipe has been lined previously. Line looks clean and in good condition.
725	267	114	24" CMP	Line starts at CB in front of property to JS	SM-OSW-SD-CB0078-MH0075	CB0078 to MH0075	30		10/14/2014	Pipe looks clean and in good condition.
726	268	114	18" RCP	Line runs from CB in front of property to MH in front of 3134 Corrina	SM-OSW-SD-CB0077-JS0076	CB0077 to MH0076	30		10/14/2014	Pipe looks clean and in good condition.
727	269	114	18" RCP	Line starts at JS behind 27925 Alafara property to MH on Calzada Dr.	SM-OSW-SD-MH0075-JS0076, SM-OSW-SD-MH0076-MH0074, SM-OSW-SD-MH0074-MH0182, SM-OSW-SD-MH0182-MH0181, SM-OSW-SD-MH0181-MH0180	MH0075 to MH0076, MH0076 to MH0182, MH0182 to MH0181, MH0181 to MH0180	218		10/14/2014	Pipe has been lined previously. Line looks clean and in good condition.
728	270	114	24" RCP & 24" CMP	Line starts at MH in front of property to MN on Crest Rd behind same property	SM-OSW-SD-MH0075-JS0076, SM-OSW-SD-MH0076-MH0074, SM-OSW-SD-MH0074-MH0182, SM-OSW-SD-MH0182-MH0181, SM-OSW-SD-MH0181-MH0180	JS0076 to MH0076, MH0076 to MH0182, MH0182 to MH0181, MH0181 to MH0180	378.5		10/7/2014	Pipe looks clean and in good condition.
729	271	123	36" RCP	Line runs from MH in front of property to MH in front of 28102 Monterena Dr.	LA-LAN-SD-S0323-MC1943, LA-LAN-SD-MC1949-MC1950, LA-LAN-SD-MC1950-MH0182	JS0323 to MC1943, MC1943 to MC1949, MC1949 to MC1950, MC1950 to MH0182	339		10/7/2014	Pipe looks clean and in good condition.
730	272	123	36" RCP	Line runs from CB in property corner to CB across Velez Dr.	LA-LAE-SD-CB0157-CB0159	CB0157 to CB0159	25.5		10/6/2014	Pipe looks clean and in good condition.
731	273	124	18" RCP	Line runs from CB in property corner to MH in front of 28402 Pontevedra	LA-LAE-SD-CB0159-MH0160	CB0159 to MH0160	98		10/6/2014	Pipe looks clean and in good condition.
732	274	124	31" RCP	Line runs from CB in front of property to MH in front of 28402 Pontevedra	LA-LAE-SD-CB0045-MH0172, LA-LAE-SD-MH0172-MH0171, LA-LAE-SD-MH0171-MH0170	CB0045 to MH0172, MH0172 to MH0171, MH0171 to MH0170	228		10/6/2014	Pipe looks clean and in good condition.
733	275	124	31" RCP	Line runs from CB at end of cul-de-sac to OS behind property	LA-LAE-SD-CB0172-MH0172, LA-LAE-SD-MH0172-MH0171, LA-LAE-SD-MH0171-MH0170	CB0172 to MH0172, MH0172 to MH0171, MH0171 to MH0170	210		10/6/2014	Pipe has been lined previously. Overall line is in good condition.
734	276	125	18" RCP	Line runs from MH at end of cul-de-sac to OS behind property	LA-LAE-SD-CB0007-MH0172, LA-LAE-SD-MH0172-MH0171, LA-LAE-SD-MH0171-MH0170	CB0007 to MH0172, MH0172 to MH0171, MH0171 to MH0170	152		10/6/2014	Pipe has been lined previously. Line looks clean and in good condition.
735	277	125	18" RCP	Line runs from CB at cul-de-sac to OS behind 39302 Highmore Ave.	LA-LAE-SD-CB0011-OS0009	CB0011 to OS0009	147		10/6/2014	Pipe looks clean and in good condition.
736	278	125	18" RCP	Line runs from CB in southeast corner of Western Ave. & Park Western Dr. to OS on Park Western Dr.	LA-LAE-SD-CB4173-MH0010	CB4173 to MH0010	80		10/6/2014	Pipe looks clean and in good condition.
737	279	125	18" RCP	Line starts at CB in front of property on Bayend Dr. to CB in front of 28444 Bayend Dr.	LA-LAE-SD-CB0019-CB0022	CB0019 to CB0022	68		10/6/2014	Pipe looks clean and in good condition.
738	280	126	18" RCP							

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
739	814	126	36" RCP & 36" CMP Line	Line runs from CB in front of property to JS	LA-LAE-SD-CB0022-CB0023, LA-LAE-SD-CB0023-JS3416	CB0022 to JS3416	106		10/9/2014	Pipe looks clean and in good condition.
740	815	126	36" RCP	Line runs from JS in the canyon to CB in front of 1921 Upland St.	PIPE FOUND	JS3416 to CB3420	45		11/17/2014	Pipe has been lined previously. Line looks clean and in good condition.
741	816	126	18" RCP	Line starts at CB in front of property on Upland St. side to CB across the road	LA-LAE-SD-CB0017-CB3420	CB0017 to CB3420	38		10/9/2014	Pipe looks clean and in good condition.
742	819	126	36" RCP	Line runs from CB in front of property to MH in property's backyard	LA-LAE-SD-CB0014-CB3421, LA-LAE-SD-CB3421-MH3423	CB0014 to MH3423	66		10/9/2014	Pipe looks clean and in good condition.
743	822	127	24" RCP	Line starts at CB on General southbound (approx. 120' west of Benice Dr.) to CB across General St.	LA-LAE-SD-CB0006-CB0005	CB0006 to CB0005	37		10/9/2014	Pipe looks clean and in good condition.
744	825	127	18" RCP	Line starts at CB in front of property to MH on Summerland St.	LA-LAE-SD-CB0002-CB0003, LA-LAE-SD-CB0003-MH1924	CB0002 to MH1924	225.5		10/9/2014	Pipe looks clean and in good condition.
745	826	127	18" RCP	Line runs from MH by property's driveway to CB in property's parking lot	LA-LAE-SD-MH1924-CB1925, LA-LAE-SD-CB1925-CB1923	MH1924 to CB1923	88		10/9/2014	Pipe looks clean and in good condition.
746	827	127	18" RCP	Line runs from CB in property's parking lot to MH on backyard	LA-LAE-SD-CB1923-JS1927	CB1923 to JS1927	100		10/9/2014	Pipe looks clean and in good condition.
747	827.1	127	36" RCP	Line runs from MH1928 in front of Eastview Townhouse Building to MH across Western Ave.		MH29128 to MH	200		10/9/2014	Pipe looks clean and in good condition.
748	848	132	18" RCP	Line runs from CB in front of property to CB in front of 3249 Crownview Dr.	LA-LAE-SD-CB0786-CB0787	CB0786 to CB0787	74		10/10/2014	Pipe looks clean and in good condition.
749	850	132	18" RCP	Line runs from CB in front of property to JS across Grandpoint	LA-LAS-SD-CB0784-JS2704	CB0784 to JS2704	78.5		10/10/2014	Pipe looks clean and in good condition.
750	851	132	24" RCP	Line runs from CB in front of property to OS in front of 29624 Grandpoint Ln.	LA-LAS-SD-CB0785-JS2704	CB0785 to JS2704	85.5		10/10/2014	Pipe looks clean and in good condition.
751	851.1	132	24" RCP	Line runs from CB in front of property to OS behind 29100 Knoll View Dr. property	LA-LAS-SD-JS2704-OS0783	JS2704 to OS0783	111		10/10/2014	Pipe looks clean and in good condition.
752	852	133	18" RCP	Line runs from CB in front of property to CB across Crownview Dr.	LA-LAS-SD-CB0814-CB0815	CB0814 to CB0815	30.5		10/10/2014	Pipe looks clean and in good condition.
753	853	133	18" RCP	Line runs from CB in front of property to OS behind property down the canyon	LA-LAS-SD-CB0815-CB3110, LA-LAS-SD-CB3110-CB3111, LA-LAS-SD-CB3111-CB3113, LA-LAS-SD-CB3113-CB3112, LA-LAS-SD-CB3112-OS0816	CB0815 to OS0816	553		10/10/2014	Pipe looks clean and in good condition.
754	855	133	24" RCP	Line runs from CB in front of property to MH in property	LA-LAS-SD-CB0821-CB3114, LA-LAS-SD-CB3114-CB3117, LA-LAS-SD-CB3117-MH3115, LA-LAS-SD-MH3115-CB3116, LA-LAS-SD-CB3116-CB0819, LA-LAS-SD-CB0819-CB0820	CB0821 to MH3115, CB0821 to CB0820	341		10/13/2014	Pipe has been lined previously. Line looks clean and in good condition.
755	858	133	30" RCP	Line runs from CB in front of property to OS behind 29100 Knoll View Dr. property	LA-LAS-SD-CB0819-CB0817	CB0819 to OS0817	431		10/13/2014	Pipe has been lined previously. Line looks clean and in good condition.
756	860	134	18" RCP	Line runs from CB adjacent to Calwater's driveway to CB on the other side of same driveway	LA-LAE-SD-CB3122-CB3123	CB3122 to CB3123	44		10/13/2014	Pipe looks clean and in good condition.
757	861	134	18" RCP & 18" CMP	Line runs from CB to OS in southwest corner of PVDE & Via Canada		CB3123 to OS3127	101		10/13/2014	Pipe looks clean and in good condition.
758	862	134	18" RCP	Line runs from CB in southwest corner of PVDE & Via Canada to CB in northwest corner of same intersection		CB3123 to OS3127	27		10/13/2014	Pipe looks clean and in good condition.
759	863	134	24" RCP	Line runs from CB in southwest corner of intersection to JS across PVDE	LA-LAE-SD-CB0798-JS46535	CB0798 to JS0799	101		10/13/2014	Pipe looks clean and in good condition.
760	867	134	18" RCP	Line runs from CB on PVDE southbound (approx. 400' south of Crownview Dr.) to OS across PVDE in the canyon	LA-LAE-SD-CB0804-OS0803	CB0804 to OS0803	69		10/16/2014	Pipe looks clean and in good condition.
761	873.1	136	24" RCP	PVDE at Cal Water Reservoir property		IS to CB0793	1006			Unmapped structure at 824'. Overall pipe looks clean and in good condition.
762	873.2	136	48" CMP	PVDE at Crownview Dr. by Cal Water Reservoir property		IS to CB0793	170			Pipe looks clean and in good condition.
763	882	140	24" RCP	Line starts at CB southeast corner of intersection to JS	LA-LAE-SD-CB0141-JS0149	CB0141 to JS0149	56		11/17/2014	Pipe looks clean and in good condition.
764	633	98	48" CMP	Line runs from CB on Hawthorne southbound (approx. 95' north of Vallon Dr.) to CB across Hawthorne on northbound	SM-OSW-SD-CB0723-CB0721	CB0722 to CB0721	75		11/4/2014	
765	1	363	18" RCP	Line starts at CB in front of property to MH on Basswood northbound	SM-PVN-SD-CB2775-MH2762	CB2773 to MH2762	5.5	6	1/7/2015	Pipe looks clean and in good condition.
766	7	408	24" RCP	Line starts at CB in front of property to JS in the middle of the street	ML-RHE-SD-CB1010-JS3488	CB3010 to JS3488	22	22	1/7/2015	Pipe looks clean and in good condition.
767	13	467	24" RCP	Line starts at CB on Crenshaw Blvd. northbound (approx. 165' south of Valley View Rd.) to JS	SM-OSW-SD-CB03290-JS03292	CB3290 to JS3292	38	38	12/23/2014	Pipe looks clean and in good condition.
768	14	486	27" RCP	Line runs from MH in front of property to IS on 30602 Via Rivera backyard	SM-OWW-SD-TS3389-MH3387, SM-OWW-SD-TS3394-TS3389, SM-OWW-SD-TS3395-TS3384, SM-OWW-SD-TS3392-JS3395	MH3387 to IS3382	210	245	12/23/2014	Pipe looks clean and in good condition.
769	15	509	42" CMP	Line runs from MH in front of property to ??	SM-OSW-SD-MH0758-MH0757, SM-OSW-SD-MH0757-JS1901	MH0758 to JS1901	497	497	11/5/2014	Pipe looks clean and in good condition.
770	21	566	36" RCP	Line runs from OS adjacent to PVDE (approx. 640' south of Hawthorne) to structure north of OS0576		MH0576.1 to MH0576	479.5	479	12/8/2014	Pipe looks clean and in good condition.
771	24	622	18" RCP	Line starts at IS on median in front of City Hall bus stop to MH by City Hall driveway entrance	SM-OSW-SD-IS2805-CB2804, SM-OSW-SD-CB2804-MH2829	IS2805 to MH2829	200	200	1/5/2015	Pipe looks clean and in good condition.
772	696	107	18" RCP	Line runs from CB to JS on Intrepid Dr.	SM-OSW-SD-CB3201-JS3200	CB3201 to JS3200	3	3	1/5/2015	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
773	30	698	108	18" RCP	Line runs from CB on Forestal northbound to JS	SM-OSE-SD-CB0520-JS2434	CB0520 to JS2434	12	12	1/6/2015	Pipe looks clean and in good condition.
774	31	699	108	18" RCP	Line runs from CB on Forestal southbound to JS	SM-OSE-SD-MH3521-MH3467, SM-OSE-SD-JS2435-MH3467	CB0521 to JS2435	3	3	1/6/2015	Pipe looks clean and in good condition.
775	36	736	113	18" CMP	Line runs from CB in front of property to OS behind the property	LA-LAS-SD-CB0054-CB1904, LA-LAS-SD-CB1904-CB1902, LA-LAS-SD-CB1902-CB1903, LA-LAS-SD-CB1903-OS0055	CB0054 to OS0055	176	190	12/8/2014	Pipe looks clean and in good condition.
776	39	755	116	18" RCP	Line starts at CB in front of property to CB across the road	LA-LAS-SD-CB0294-CB0293	CB0294 to CB0293	23	23	12/4/2014	Pipe looks clean and in good condition.
777	41	757	116	24" RCP	Line runs from CB in front of property to OS behind de-sac	SM-OSE-SD-CB0299-CB0300	CB0299 to CB0300	56	56	12/5/2014	Pipe looks clean and in good condition.
778	55	872	135	12" C/Sew	Line starts at IS behind property to OS in front of 2166 same property	LA-LAE-SD-CB0836-OS0835	CB0836 to OS0835	220	220	12/9/2014	Pipe looks clean and in good condition. Inspection abandoned at IS due to pipe inclination; pipe seems to be clean and in good condition at the IS.
779	56	873	135	12" C/Sew	Line starts at CB in southeast corner to JS across Indian General St.	LA-LAE-SD-IS0025-IS3411	IS0025 to OS0024-MH3411	195	195	12/9/2014	Pipe looks clean and in good condition at the IS.
780	4	403	72	18" RCP	Line starts at CB in front of property to JS	SM-PWV-SD-CB1428-JS2096	CB1428 to JS2096	30	30		
781	11	454	80	18" RCP	Line runs from MH in property's backyard to OS on 22912 Highway Ave backyard	SM-OSW-SD-CB2625-JS2624	CB2625 to JS2624	30	30		
782	40	820	126	36" RCP	Line runs from CB on property's backyard to JS	LA-LAE-SD-MH3423-IS3419	MH3423 to OS3419	50	50	12/19/2014	Line 457 named incorrectly 7777
783	16	444	78	18" CMP	Line starts at IS behind property to PC in front of 4343	SM-OWW-SD-CB3168-JS3169	CB3168 to JS3169	15	15		No access
784	39	487	107	UNKWN	Line starts at IS adjacent to 9 Calle Viento to MH at intersection	SM-OSE-SD-IS0528-PC0527	IS0528 to PC0527	255	255		No US access & D/S curb outlet
785	1	549	90	UNKWN	Line runs from IS in open space between driveway extension and trail to JS	SM-OWW-SD-IS1685	IS1685 to MH1685	60	60		No access
786	3	585	91	UNKWN	Line runs from MH to MH on open space	SM-OWW-SD-IS1687-JS1688	IS1687 to JS1688	90	90		Cannot locate
787	3	587	91	UNKWN	Line starts at IS at end of the open channel behind 52 Pacifica Del Mar to MH in open space	SM-OWW-SD-MH1674-MH1674	MH1669 to MH1674	145	145		Cannot locate
788	4	588	91	UNKWN	Line starts at IS adjacent to the open channel behind 52 Pacifica Del Mar to MH in open space	SM-OWW-SD-IS1675-MH1674	IS1675 to MH1674	80	80		Cannot locate
789	3	589	91	UNKWN	Line runs from CB on PVDS median westbound to CB across PVDS		CB0557 to CB0555	60	60		Cannot locate
790	3	590	100	UNKWN	Line runs from CB on PVDS median eastbound to OS down on the bluff		CB0555 to OS0556	40	40		Cannot locate
791	7	591	100	UNKWN	Line starts at inlet on PVDS median eastbound (approx. 260' west of intersection) to JS on PVDS at Packet Rd. in S Seacove		IS3427 to JS0690	90	90		Cannot locate
792	3	594	102	18" CMP	Line runs from CB in the canyon west of Intrepid Dr. to ??	SM-OSW-SD-IS0670-OS0669	IS0670 to OS0669	100	100		No access
793	3	597	106	UNKWN	Line runs from CB in the canyon west of Intrepid Dr. to ??		CB0523 to ??				Cannot locate
794	10	597	107	UNKWN	Line starts at IS between Ladera Linda Community Center and Dauntless Dr.		CB0522 to ??				Cannot locate
795	10	598	107	UNKWN	Line runs from CB in front of property to OS behind same property		IS0508 to Mainline	55	55		Cannot locate
796	12	107	109	UNKWN	Line runs from CB in front of property to OS behind same property		CB0252 to OS0251	200	200		No access
797	13	731	112	UNKWN	Line runs from CB in front of property to JS across Via De Anzar	LA-LAS-SD-CB0252-OS0251	CB0252 to OS0251	200	200		Cannot locate
798	14	545	130	UNKWN	Line runs from CB on PVDS northbound (approx. 115' north of Alida Pl.) to MH on PVDS median		CB0851 to JS3404	200	200		Cannot locate
799	9	426	74	24" RCP	Line runs from MH adjacent to property to MH in front of 6838 Alta Vista Dr.		CB3132 to MH3462	80	80		
800	16	514	87	UNKWN	Line runs from MH to CB in front of property		MH0738 to MH0737	280	280		
801	17	515	87	UNKWN	Line runs from MH to CB in front of property		MH0737 to CB0736	120	120		
802	26	678	104	54" CMP	Line runs from MH in front of property to OS on bluff behind property	SM-OSW-SD-MH3528-JS1618, PIPE FOUND	MH3528 to OS0688	305	305		
803	37	747	114	UNKWN	Line starts at CB on Crest eastbound (approx. 1300' north of PVDE) to CB		CB0068 to CB0069	40	40		
804	38	751	114	UNKWN	Line runs from CB in front of property to ??	SM-OSE-SD-CB3492-CB3493	CB0067 to ??				
805	1	544- included in line 543	90	UNKWN	Line runs from CB in front of property to MH on Pacifica Del Mar at Calle Viento		CB1693 to MH1685	40	40		There is no CB1693; it is a continuous line from MH1656 to MH1685
806	2	564	93	UNKWN	Line runs from IS adjacent to St. Paul's Lutheran Church cul-de-sac to OS across on PVDS		IS0580 to OS0581	625	625		Does not exist
807	3	567	93	UNKWN	Line runs from CB on PVDS (approx. 640' south of Hawthorne) to OS		CB0577 to OS0576	50	50		Does not exist
808	4	568	93	UNKWN	Line runs from CB on PVDS median (approx. 650' south of Hawthorne) to CB across PVDS southbound		CB0578 to CB0577	90	90		Does not exist

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
809	5	569	93	UNKWN	Line runs from MH on PVDW northbound (approx. 680' south of Hawthorne) to CB on median across PVDW south of Hawthorne) to OS on Crestridge Rd.	DNE	MH2857 to CB0578	35			Does not exist
810	6	570	93	UNKWN	Line runs from CB on PVDW northbound (approx. 680' south of Hawthorne) to MH	DNE	CB0579 to MH2857	10			Does not exist
811	7	571	93	48" RCP	Line runs from MH on PVDW northbound (approx. 680' south of Hawthorne) to JS	DNE	MH2857 to JS2856	55			Does not exist
812	8	572	93	48" RCP	Line runs from MH on PVDW northbound (approx. 680' south of Hawthorne) to OS	DNE	MH2857 to OS2859	155			Does not exist
813	9	621	96	UNKWN	Line runs from CB on Hawthorne northbound by City Hall bus stop to JS	DNE	CB2802 to JS2806	30			Does not exist
814	10	632	98	UNKWN	Line starts at CB on northwest corner of intersection to CB	DNE	CB0723 to CB0722	40			Does not exist
815	11	705	109	UNKWN	Line starts at IS in hill east of Forrestal to MH adjacent to the road	DNE	IS0511 to MH2689	390			Does not exist
816	12	513	87	UNKWN	Line runs from MH adjacent to property to ??	DNE	MH0738 to ??	??			Does not exist
817	22	501	86	UNKWN	Line starts at CB on Los Verdes Dr. (approx. 180' north of golf course parking entrance) to ??	DNE	CB0630 to ??	??			Does not exist
818	1	404	72	42" RCP	Line starts at CB in front of 29457 Indian Valley Dr. to JSSM-FVW-SD-CB1429-JS2096		CB1429 to JS2096	15			Same as line no. 149
819	2	417	73	UNKWN	Line starts at CB on Crest Rd. westbound (approx. 580' from Crestshaw Blvd.) to OS on Crestridge Rd.	ML-RHE-SD-CB0998-PC0999	CB0998 to PC0999				Combined with line no. 416
820	3	519	88	18" CMP	Line runs from MH in property's backyard to OS in front of 30936 Cartier Dr.	SM-OSW-SD-MH2910-GB2912, SM-OSW-SD-GB2912-OS2909	MH2910 to OS2909				Combined with line no. 518
821	4	529	88	26" CMP	Line runs from CB next to median to MH across Hawthorne Blvd. by Ryan Park driveway entrance	SM-OSW-SD-JS0742-MH0757	CB0742 to MH0757	100			Combined with line no. 528
822	5	565	93	UNKWN	Line runs from OS adjacent to PVDW (approx. 640' south of Hawthorne) to OS in open space	PIPE FOUND	OS0576 to OS0581	415			Included in line no. 188
823	6	575	93	30" CMP & 30" RCP	Line runs from CB on PVDW northbound (approx. 670' south of Hawthorne) to OS on PVDW southbound		CB2859 to OS2862	130			Same as line 572.1
824	7	652	102	48" CMP	Line starts CB on PVDW eastbound (approx. 460' west of Berkentine Rd.) to MH on PVDW at Packer Rd.	SM-OSW-SD-CB3426-MH0691	CB3426 to MH0691	60			Combined with line no. 651
825	8	718	111	UNKWN	Line runs from CB on PVDW at Packer Rd. to PVDW to CB on PVDW	LA-LAS-SD-CB0226-CB0224	CB0226 to CB0224	85			8" Riser
826	9	719	111	UNKWN	Line runs from CB on PVDW at Via Frascati to OS down the canyon	LA-LAS-SD-CB0224-OS0225	CB0224 to OS0335	50			8" Riser
827	10	763	118	UNKWN	Line runs from IS on PVDW (approx. 1800' east of PVDW) to OS across PVDW	SM-OSE-SD-IS0950-OS0949	IS0950 to OS0949	100			Curb outlet
828	11	764	118	UNKWN	Line runs from IS on PVDW (approx. 2200' east of PVDW) to OS across PVDW	SM-OSE-SD-IS0952-OS0951	IS0952 to OS0951	100			Curb outlet
829	12	787	122	UNKWN	Line runs from CB at end of the cul-de-sac to MH at end of cul-de-sac		CB0308 to MH0307	60			Capped line
830	13	792	122	UNKWN	Line runs from MH to MH across the road	SM-OSE-SD-GB6524-JS2698, SM-OSE-SD-JS2697-GB6524	MH2698 to MH1874	65			Combined with line no. 791
831	14	793	122	UNKWN	Line runs from MH adjacent to the road to MH in the Golf Course	LA-LAE-SD-CB0862-CB0863	CB0862 to CB0863	725			8" Riser
832	15	840	130	UNKWN	Line runs from CB in front of property to CB across the road in front of 6272 El Tesoro	LA-LAE-SD-CB0863-JS0865	CB0863 to JS0865	30			8" Riser
833	16	841	130	UNKWN	Line runs from CB in front of property to JS across Via De Anzar	LA-LAE-SD-CB0863-JS0865	CB0863 to JS0865	110			8" Riser
834	17	842	130	UNKWN	Line runs from CB in front of property to OS down the canyon	LA-LAE-SD-CB0865-OS0949	CB0865 to OS0949	150			8" Riser
835	18	497	86	UNKWN	Line runs from CB on property's backyard to MH1121 in the middle of the golf park	SM-OWW-SD-GB1159-CB2245, SM-OWW-SD-MH1121-GB1159	CB0650 to OS0849	345			
836	19	498	86	UNKWN	Line runs from MH on golf park adjacent to Los Verdes Dr. to MH in the middle of the golf course	SM-OWW-SD-CB1119-IS3520, SM-OWW-SD-JS3519-JS3520, SM-OWW-SD-MH1158-IS3519	MH1121 to CB2245	450			
837	23	503	86	30" RCP	Line starts at CB on Los Verdes Dr. southbound to mainline		MH1120 to MH1121	13		1/12/2015	Pipe looks clean and in good condition.
838	24	574	93	18" RCP	Line runs from CB on median (approx. 200' south from the north tip of median) to JS in median		CB2861 to JS2860	40			No inspection nor reports given. Might not exist.
839	25	578	94	24" RCP	Line runs from IS at the end of the cul-de-sac to JS	SM-OWW-SD-IS2746-JS2747	IS2746 to JS2747	55.4	55.5	1/5/2015	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
840	26	579	94	18" RCP	Line starts at CB on Via Capri (2nd curve from Villa Capri gated entrance) to JS	SM-OWW-SD-CB2744-JS2745	CB2744 to JS2745	33	33	1/5/2015	Pipe looks clean and in good condition.
841	27	580	94	18" RCP	Line starts at CB on Via Capri (2nd curve from Villa Capri gated entrance) to JS	SM-OWW-SD-CB2742-JS2743	CB2742 to JS2743	29	29	1/5/2015	Pipe looks clean and in good condition.
842	28	583	94	18" RCP	Line runs from CB on Via Capri at Via Venta to JS south of Via Rivera) to CB across Hawthorne northbound	SM-OWW-SD-CB2737-JS2738	CB2737 to JS2738	15			No inspection nor reports given. Might not exist.
843	29	586	95	18" RCP	Line runs from MH in front of property to MH on Hawthorne (approx. 115' of Via Rivera) to JS		CB2807 to CB2808	40	40	1/13/2015	Line pipe from CB2807 to JS2808. Video shows in good condition. Pipe looks clean and in good condition.
844	30	591	95	UNKWN	Line starts at CB behind property to JS	SM-OWW-SD-CB2841-JS2842	CB2851 to JS2860	10			No inspection nor reports given. Might not exist.
845	31	596	95	18" AGP	Line starts at IS between 7065 & 7055 Via Del Mar to MH in the middle of Via Del Mar	SM-OWW-SD-IS2830-JS2831, SM-OWW-SD-JS2831-MH2836	CB2841 to JS2842	25			No inspection nor reports given. Might not exist.
846	32	597	95	36" RCP	Line starts at IS off of Hawthorne southbound (approx. 815' northwest of City Hall driveway) to CB on Hawthorne southbound		IS2830 to MH2836	33	33	1/13/2015	Pipe looks clean and in good condition.
847	33	604	96	UNKWN		SM-OWW-SD-IS0582-CB0583	IS0582 to CB0583	40			No inspection nor reports given. Might not exist.
848	34	674									Inspection abandoned at 120' from IS due to debris (mainly sand) blocking ~90% of the pipe. Confirmed with Josh that line was clean afterwards.
849	35	701	108	30" RCP	Line starts at IS off of Forrester to MH adjacent to Forrester northbound	SM-OSE-SD-IS2436-TS3466, SM-OSE-SD-JS2437, SM-OSE-SD-JS2437-JS2438, SM-OSE-SD-JS2438-MH2439	IS2436 to MH2439	122.5	122.5	1/15/2015	
850	36	702	108	30" RCP	Line runs from MH adjacent to Forrester northbound to MH west of the road	SM-OSE-SD-MH2439-GB2440, SM-OSE-SD-GB2440-MH3521	MH2439 to MH3521	135			No inspection nor reports given. Might not exist.
851	37	709	109	48" RCP	Line runs from IS on property to TS on Dauntless	SM-OSE-SD-IS0612-MH1912	IS0512 to TS1912	95			No inspection nor reports given. Might not exist.
852	38	710	109	18" RCP	Line runs from IS behind property to MH in front of 3855 SM-OSE-SD-IS0479-GB2134, SM-OSE-SD-GB2134-Pirate	SM-OSE-SD-IS0479-GB2134, SM-OSE-SD-GB2134-MH0480	IS0479 to MH0480	176	176	1/7/2015	Pipe looks clean and in good condition.
853	39	733	112	UNKWN	Line starts at CB in front of 6345 Via Collinia to OS behind 6352 Via Collinia down the canyon and La Vista Verde	LA-LAS-SD-CB0255-OS0256	CB0255 to OS256	200			No inspection nor reports given. Might not exist.
854	40	734	113	18" RCP	Line starts at CB in front of property to OS across PVDE and La Vista Verde	LA-LAS-SD-CB0119-OS0120	CB0119 to OS0120	456.5	456.5	1/8/2015	Video shows a very different pipe path from GIS. Pipe looks clean and in good condition.
855	41	761	117	UNKWN	Line runs from IS on PVDE (approx. 670' east of PVDS) to OS across PVDE	SM-OSE-SD-IS0948-OS0947	IS0948 to OS0947	100			Lines were not inspected for they were lined recently. Inspection should be done soon!
856	42	762	117	UNKWN	Line runs from IS on PVDS (approx. 530' east of PVDS) to OS across PVDS	SM-OSE-SD-IS4887-JS4888, SM-OSE-SD-IS4886-JS4889	IS0946 to OS0944	100			Lines were not inspected for they were lined recently. Inspection should be done soon!

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
857	765	118	UNKWN	Line runs from CB on PVDs (approx. 700' east of La Rotonda) to MH	SM-OSE-SD-CB0936-GB6908, SM-OSE-SD-GB6908-MH2695	CB0936 to MH2695	30			Lines were not inspected for they were lined recently. Inspection should be done soon!
858	766	118	UNKWN	Line runs from IS on PVDs (approx. 730' east of La Rotonda) to MH	SM-OSE-SD-IS0938-MH2695	IS0938 to MH2695	40			Lines were not inspected for they were lined recently. Inspection should be done soon!
859	767	118	UNKWN	Line runs from MH on PVDs (approx. 730' east of La Rotonda) to OS across PVDs down the canyon	SM-OSE-SD-GB6912-GB6913, SM-OSE-SD-GB6913-GB6914, SM-OSE-SD-GB6914-OS0937	MH2695 to OS0937	125			Lines were not inspected for they were lined recently. Inspection should be done soon!
860	768	118	UNKWN	Line runs from CB on PVDs (approx. 760' east of La Rotonda) to ??		CB0936 to ??				Lines were not inspected for they were lined recently. Inspection should be done soon!
861	769	118	UNKWN	Line runs from CB on PVDs (approx. 950' east of La Rotonda) to OS across PVDs down the canyon	SM-OSE-SD-IS0940-OS0939	CB0940 to OS0939	150			Lines were not inspected for they were lined recently. Inspection should be done soon!
862	770	118	UNKWN	Line runs from IS on PVDs (approx. 1300' east of La Rotonda) to CB on PVDs westbound	SM-OSE-SD-IS0943-CB0941	IS0943 to CB0941	60			Lines were not inspected for they were lined recently. Inspection should be done soon!
863	771	118	UNKWN	Line runs from MH on PVDs (approx. 1300' east of La Rotonda) to OS across PVDs down the canyon	SM-OSE-SD-CB0941-CB1108, SM-OSE-SD-MH1107-OS0942	CB0941 to OS0942	100			Lines were not inspected for they were lined recently. Inspection should be done soon!
864	773	119	12" Polypropylene Channel	Line runs from MH on PVDs westbound (approx. 450' east of Forestal) to JS	SM-OSE-SD-CB1843-MH0350	MH2694 to JS0392	285	285	1/14/2015	Open channel
865	775	120	30" RCP	Line runs from CB on PVDs (approx. 1300' east of La Rotonda) to MH	SM-OSE-SD-MH0350-MH1842	CB1843 to MH0350	30	30-Jan	1/14/2015	Pipe looks clean and in good condition.
866	776	120	30" RCP	Line runs from MH to MH in Golf Course	SM-OSE-SD-GB1849-GB1848, SM-OSE-SD-GB1853-GB1852	MH0350 to MH1842	80.6	80.5	1/14/2015	Pipe looks clean and in good condition.
867	777	120	30" RCP	Line runs from MH to MH in Golf Course	SM-OSE-SD-MH1847-MH1856	MH1842 to MH1847	266.4	266.5	1/14/2015	Longitudinal crack at 35' to 36' from MH1842 at 12 o'clock. The rest of the line looks clean and in good condition.
868	778	120	30" RCP	Line runs from MH to MH in Golf Course	SM-OSE-SD-GB1856-GB1855, SM-OSE-SD-GB1855-GB1854, SM-OSE-SD-GB1854-GB1853	MH1847 to MH1856	148.6	148.5	1/14/2015	Light deposits at 134.7' and 143' from MH1847. Overall the line looks clean and in good condition.
869	779	120	30" RCP	Line runs from MH to MH in Golf Course	SM-OSE-SD-GB1852-MH1851	MH1856 to MH1851	224	224	1/14/2015	Light deposits at 160' from MH1856. Overall the line looks clean and in good condition.
870	780	120	18" RCP & 18" RCP	Line runs from MH to OS in Golf Course	SM-OSE-SD-MH1851-OS1864	MH1851 to OS1864	76.4	76.5	1/14/2015	Pipe looks clean and in good condition.
871	781	120	30" RCP	Line runs from MH to OS in Golf Course	SM-OSE-SD-OS1864-OS1857	MH1851 to OS1857	360	360	1/14/2015	Pipe looks clean and in good condition.
872	782	120	UNKWN	Line runs from CB to JS in Golf Course	SM-OSE-SD-CB1862-IS1861	CB1862 to JS1861	45			
873	783	120	UNKWN	Line runs from IS to JS in Golf Course	SM-OSE-SD-IS1861-OS1860	IS1861 to OS1860	200			
874	809	125	40" RCP	Line runs from CB in front of property to CB in southeast corner of Western Ave. & Park Western Dr.	LA-LAN-SD-CB0885-OS0884	CB0843 to CB0842	325			This line is included in line 808 from MH0016 to MH0012. CB0013 does not exist.
875	828	128	18" RCP	Line runs from CB in front of property to OS in property's backyard	LA-LAE-SD-IS0876-CB0877	CB0885 to OS0884	250			
876	833	129	UNKWN	Line runs from IS to CB on driveway adjacent to Miraleste Library	LA-LAE-SD-CB0864-OS0865, LA-LAE-SD-IS0865-OS0866	IS0876 to CB0877	35			
877	839	130	UNKWN	Line runs from CB in front of property to OS in 6405 Via de Arcaz backyard		CB0864 to OS0866	469			
878	844	131	UNKWN	Line runs from IS in Canada Park adjacent to 6700 Via Canada to MH in front of 2151 Dorado Dr.		IS0031 to MH1932	870			
879	845	131	UNKWN	Line runs from CB in front of property to JS		CB0032 to JS2706	25			
880	846	131	UNKWN	Line runs from CB in front of property to JS		CB0030 to JS2705	25			
881	847	131	UNKWN	Line runs from CB in front of property to JS		CB0033 to JS2707	30			
882	856	133	UNKWN	Line runs from MH in property's yard to CB in front of 29723 Knoll View Dr.	LA-LAS-SD-MH3115-GB3116, LA-LAS-SD-GB3116-GB0819, LA-LAS-SD-GB0819-CB0820	MH3115 to CB0820	250			

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
883	69	864	134	UNKWN	Line runs from JS in southwest corner of intersection to OS across PVDE in the canyon		IS0796 to OS0800	270			
884	70	865	134	UNKWN	Line starts at CB on Crownview Dr. (approx. 200' west of intersection to CB 70' north		CB0794 to CB0795	70			
885	71	866	134	UNKWN	Line starts at CB on Crownview Dr. (approx. 130' west of intersection to JS		CB0795 to JS0797	130			
								7,773			
					Inspected (video not						
					Line is in good condition						
					Light/minor defect condition						
					Moderate defect condition						
					Average defect condition						
					Heavy defect condition						
					Severe defect condition						
					field/Not able to inspect						
					Line does not exist						
					GIS update needed						
					needed						

CITY OF RANCHO PALOS VERDES MASTER PLAN OF DRAINAGE

Michael Baker
INTERNATIONAL

TECHNICAL APPENDIX C-2

**CCTV INSPECTIONS
2012**

S. ...rain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Pipe Line No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
1	145	1C	1955	18" CMP	Pipe runs along 5503 Graydon property from CB located at end of Graydon cul-de-sac to OS behind property	SM-PVN-SD-CB1608-GB2656, SM-PVN-SD-GB2656-GB2657, SM-PVN-SD-GB2657-GB2658, SM-PVN-SD-GB2658-GB2659, SM-PVN-SD-GB2659-JS1604	CB1609 to JS1604	189	189	6/4/14	Heavy corrosion throughout the pipe. CMP pipe deformed (~40%) at 93'
2	146	12C	26	18" RCP	Line starts at CB 210' north of La Cret to Mainline	DNE	CB3179 to Mainline	35			Per contractor, this line does not exist.
3	146	12C	28	18" RCP	Line starts at CB 415' south of Costa Verde to Mainline	DNE	CB3178 to Mainline	45			Per contractor, this line does not exist.
4	346	22B	36	UNKN	Verify that line runs through the middle of median		CB0539 to ??	??			Line does not exist.
5	347	22B	36	18" RCP	Line runs from CB on median west of Crestmont (approx. 850' west of Crestmont) to unmaped MH5646.1 south of PVDOS	SM-PVN-SD-CB1455-IS2684, SM-PVN-SD-CB1456-IS2688	CB0543 to MH5646.1	52		9/12/14	Pipe looks clean and in good condition.
6	348	22B	36	18" RCP	Line runs from unmaped MH5646.1 south of PVDOS (approx. 850' west of Crestmont) to unmaped MH5646.1 south of PVDOS	SM-PVN-SD-CB1455-IS2684, SM-PVN-SD-CB1456-IS2688	MH5646.1 to MH5646.1	25		9/12/14	Pipe looks clean and in good condition.
7	349	22B	36	18" RCP	Line starts at CB approx. 480' east of Fisherman's Trail parking on PVDOS in mainline south of PVDOS	SM-PVN-SD-CB1454-IS2687	CB0547 to Mainline	35		9/17/14	Pipe looks clean and in good condition.
8	350	5C	10	UNKN	Line runs from CB on Silver Spur Rd. (behind 28636 Ford Dr. Lac property) to CB across Silver Spur Rd. (behind 28636 Ford Dr. Lac property) to intersection of CB on Hawthorne southeast corner	PPE FOUND	CB1534 to CB1535	79'			These catch basins were not able to be located in the field.
9	351	8B	18	UNKN	Line runs from CB on Hawthorne southeast corner to intersection of CB on Hawthorne southwest corner	SM-PVN-SD-CB1455-IS2684, SM-PVN-SD-CB1456-IS2688	CB1456 to CB1456.1	240'		6/4/14	This line was not video inspected for the camera did not fit through any of the access points.
10	352	8B	18	UNKN	Line runs from CB on Hawthorne southwest corner to intersection of CB on Hawthorne southwest corner	SM-PVN-SD-CB1455-IS2684, SM-PVN-SD-CB1456-IS2688	CB1456 to CB1456.1	60'		6/4/14	This line was not video inspected for the camera did not fit through any of the access points.
11	353	8B	18	UNKN	Line runs from CB on Hawthorne southwest corner to intersection of CB on Hawthorne southwest corner	SM-PVN-SD-CB1455-IS2684, SM-PVN-SD-CB1456-IS2688	CB1456 to CB1456.1	150'		6/4/14	This line was not video inspected for the camera did not fit through any of the access points.
12	354	21B	48	18" CMP	Line runs from MH1865 towards east (line not shown on GIS)	SM-PVN-SD-CB1454-IS2687	MH1865 to East	17'		6/9/14	Overall pipe is in good condition.
13	355	4B	4	18" CMP	Line runs from CB in front of 6003 Lighton Pl	SM-PVN-SD-CB1671-CB1570	CB1571 to CB1570	147'		6/10/14	Pipe has been lined previously. Line looks in good condition.
14	356	4B	5	18" CMP	Pipe runs from CB in front of 26603 Monominee Pl to MH behind same property	SM-PVN-SD-CB1671-CB1570, SM-PVN-SD-CB1672-GB3326, SM-PVN-SD-CB1673-MH3283	CB1571 to MH3283	32		6/10/14	Overall pipe is in good condition. There are deposits at end of pipe.
15	357	5C	6	18" RCP	Line starts at CB in front of 5536 Montemalaga to 555' east of Hawthorne	SM-PVN-SD-CB1562-CB1563	CB1562 to CB1563	5	5		Inspection not needed for CBs are next in each other
16	358	5A	8	18" RCP	Line starts at CB on Hawthorne median (approx. 555' east of Hawthorne)	ML-RHE-SD-CB3175-CB3176	CB3175 to CB3176	320.7	321	9/4/14	Pipe looks clean and in good condition.
17	359	5A	8	30" RCP	Line runs from MH on Hawthorne southbound (approx. 270' southeast from MH3326)	ML-RHE-SD-CB3330-MH3326	MH3326 to IS3330	352		9/4/14	Pipe looks clean and in good condition.
18	360	5C	8	18" RCP	Line starts at CB on Hawthorne median (approx. 270' southeast from MH3326)	ML-RHE-SD-CB3175-CB3176	CB3175 to CB3176	362		9/4/14	Pipe looks clean and in good condition.
19	361	5C	8	18" RCP	Line runs from CB on Hawthorne median (approx. 499' Rockvalley approx.) to CB approx. 120'	ML-RHE-SD-CB3174-CB3173	CB3174 to CB3173	125		9/4/14	Pipe looks clean and in good condition.
20	362	5A & 5A	8	18" RCP	Line runs from MH on Hawthorne southbound (approx. 145' north of Hawthorne) to CB across Hawthorne southbound	ML-RHE-SD-CB3171-CB3327	CB3171 to CB3327	49		9/8/14	Pipe looks clean and in good condition.
21	363	5A	8	18" RCP	Line runs from MH on Hawthorne southbound (approx. 145' north of Hawthorne) to CB across Hawthorne southbound	ML-RHE-SD-CB3327-MH3326	CB3327 to MH3326	61		9/4/14	Pipe looks clean and in good condition.
22	364	5A	8	18" RCP	Line runs from MH on Hawthorne southbound (approx. 145' north of Hawthorne) to CB across Hawthorne southbound	ML-RHE-SD-CB3329-MH3326	MH3326 to CB3329	505		9/4/14	Pipe looks clean and in good condition.
23	365	5A	8	30" RCP	Line runs from MH on Hawthorne southbound (approx. 145' north of Hawthorne) to CB across Hawthorne southbound	ML-RHE-SD-MH3326-IS3331, ML-RHE-SD-JS3331-MH3328	MH3326 to MH3328	13		9/4/14	Pipe looks clean and in good condition.
24	366	5B	8	18" RCP	Line runs from MH on Hawthorne southbound (approx. 145' north of Hawthorne) to CB across Hawthorne southbound	ML-RHE-SD-CB3325-MH3328	MH3325 to CB3328	503		9/4/14	Pipe looks clean and in good condition.
25	367	5A & 5B	8	30" RCP	Line runs from MH on Hawthorne southbound (approx. 145' north of Hawthorne) to CB across Hawthorne southbound	ML-RHE-SD-MH1324-MH3332, SM-PVN-SD-MH3332-IS2775, SM-PVN-SD-IS2775-GB2765, SM-PVN-SD-GB2765-GB3326	MH3332 (RVE) to MH3332	160		6/11/14	Pipe has been lined previously. Line looks in good condition.
26	368	4D	11	42" CMP	Line runs from MH at end of Meadow cul-de-sac to OS behind 5536 Montemalaga	SM-PVN-SD-MH3332-IS2775, SM-PVN-SD-IS2775-GB2765, SM-PVN-SD-GB2765-GB3326	MH3332 to OS2766	305		6/12/14	Pipe has been paved previously. Line looks in good condition.
27	369	4C	12	36" CMP	Line runs from MH in front of 6542 Montero to MH in front of 6542 Montero	SM-PVN-SD-MH3031-GB3046, SM-PVN-SD-GB3046-JS3042, SM-PVN-SD-JS3042-MH3039	MH3031 to MH3039	163		6/12/14	Pipe has been paved previously. Line looks in good condition.
28	370	4C	12	36" CMP	Line runs from MH in front of 6542 Montero to MH in front of 6542 Montero	SM-PVN-SD-MH3031-GB3046, SM-PVN-SD-GB3046-JS3042, SM-PVN-SD-JS3042-MH3039	MH3031 to MH3039	17		6/12/14	Pipe has been paved previously. Overall pipe is in ok condition.
29	371	4C	12	24" CMP	Line starts at CB in front of 6542 Montero to CB in front of 6550 Montero	SM-PVN-SD-MH3031-GB3046, SM-PVN-SD-GB3046-JS3042, SM-PVN-SD-JS3042-MH3039	CB3034 to CB3035	19'		6/12/14	Pipe invert has been paved previously. Overall pipe is in ok condition.
30	372	4C	12	30" CMP	Line runs from CB in front of 6550 Montero to MH3326	SM-PVN-SD-CB3035-MH3326	CB3035 to MH3326	19'			

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
31	17	51	6549 Moreno Dr.	4C	12		18" CMP	Line runs from CB in front of 6549 to MH in front of 6550 Moreno Dr. Line runs north along Moreno from MH in front of 6550 Moreno to OS behind 6563 Moreno property.	SM-PVW-SD-CB3036-MH3040	CB3036 to MH3040	29		6/12/14	Pipe has been lined previously. Overall pipe is in good condition. The invert is approximately 1.5' below the RCP. The entire RCP line seems to be part of Palco Verde Estates.
32	18	52	6550 Moreno Dr.	4C	12		48" CMP & 48" RCP		SM-PVW-SD-MH3040-GB3048, SM-PVW-SD-GB3048, OS3041	MH3040 to OS3041	325'		6/12/14	Pipe has been lined previously. Overall pipe is in good condition. The invert is approximately 1.5' below the RCP. The entire RCP line seems to be part of Palco Verde Estates.
33	19	54	Moreno Dr. & Lomo Dr.	4C	12		18" CMP	Line is on the north side of 27904 Lomo Dr. to JS	SM-PVW-SD-CB3033-US3038	CB3033 to JS3038	13'		6/12/14	Pipe has been lined previously (moderate wrinkled). Overall pipe is in good condition.
34	20	56	Hawthorne Blvd.	8A	13		36" CMP	Line starts at CB on Hawthorne, approximately 450' southwest from Ridgegate Dr. to MH on Hawthorne (behind 28128 Lomo property).	SM-PVW-SD-CB1590-MH3023	CB1590 to MH3023	110'		6/19/14	CMP invert has been parged previously. Line looks in good condition. Might need a little clearing.
35	21	57	Hawthorne Blvd.	8A	13		36" CMP	Line runs from MH behind property 28128 Lomo Dr. to MH on Corner of Lomo & La Gaitia Dr.	SM-PVW-SD-MH3023-GB3043, SM-PVW-SD-GB3043-MH3030	MH3023 to MH3030	505		6/17/14	CMP invert has been parged previously. Line looks in good condition. Might need a little clearing.
36	22	58	Lomo Dr. & La Gaitia Dr.	4C & 8A	13		36" CMP	Lomo intersection to MH in front of 28003 Montero	SM-PVW-SD-MH3030-MH3031	MH3030 to MH3031	505		6/17/14	CMP invert has been parged previously. Line looks in good condition.
37	23	59	5544 La Gaitia Dr.	8A	14		24" RCP	Line starts at CB in front of 6544 La Gaitia to CE	SM-PVW-SD-CB3026-CB3027	CB3026 to CB3027	40'		6/17/14	Pipe is in good condition.
38	24	60	28084 Ella Rd.	8A	14		30" RCP	Line runs from CB in front of 28084 Ella Rd. to CB in front of 28087 Ella Rd.	SM-PVW-SD-CB3027-CB3028	CB3027 to CB3028	70'		6/17/14	Pipe is in good condition.
39	25	63	Hawthorne Blvd. / Hawthorne Rd.	5C	15		18" RCP	Line runs from MH on Hawthorne (southbound) (approx. 60' south of Hawthorne) to CB on Hawthorne median at Blackhorse.	ML-RHE-SD-CB1512MH1521	CB1512 to MH1521	15		9/8/14	Pipe looks clean and in good condition.
40	26	65	Hawthorne Blvd. / Blackhorse Rd.	5C	15		30" RCP	Line runs from CB on Hawthorne median at Blackhorse to JS on Hawthorne median at Blackhorse.	ML-RHE-SD-CB1510-MH1489, ML-RHE-SD-JS2686-MH1489	MH1489 to JS2686	512		9/5/14	Pipe looks clean and in good condition.
41	27	66	Hawthorne Blvd.	5C & 7A	15		18" RCP	Line runs from JS on Hawthorne median at Blackhorse to CB on Hawthorne intersection 175' south of Blackhorse intersection.	ML-RHE-SD-CB1508-JS2686	CB1508 to JS2686	18		9/5/14	Pipe looks clean and in good condition.
42	28	66.1	Hawthorne Blvd.	5C & 7A	15		18" RCP	Line runs across Hawthorne from CB on southbound to CB on northbound. Line is approx. 100' south of Blackhorse intersection.	ML-RHE-SD-CB1507-JS2686	CB1507 to JS2686	59.5		9/5/14	Pipe looks clean and in good condition.
43	29	67	Hawthorne Blvd.	7A	16		30" RCP	Line runs from JS on Hawthorne median to CB on northbound approx. 370' south of Blackhorse intersection.	ML-RHE-SD-CB1508-JS2686	CB1508 to JS2686	520		9/5/14	Pipe looks clean and in good condition.
44	30	68	Hawthorne Blvd.	7A	16		18" RCP	Line runs from CB on Hawthorne median northeast of Silver Spur to CB on Hawthorne median.	ML-RHE-SD-CB1489	CB1489 to MH1489	29		9/5/14	Pipe looks clean and in good condition.
45	31	70	Hawthorne Blvd.	7A	16		30" Cast & Place	Line runs from CB on northbound (approx. 700' northeast of Silver Spur) to CB in front of 5131 Silver Arrow Dr.	ML-RHE-SD-CB1489	CB1489 to CB1489	221		9/8/14	Pipe looks clean and in good condition.
46	32	71	5131 Silver Arrow Dr.	7A	16		18" RCP	Line runs from CB in front of 5131 Silver Arrow to 5134 Silver Arrow.	ML-RHE-SD-CB1487-CB1488	CB1487 to CB1488	39		6/21/14	Pipe looks clean and in good condition.

Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
47	33	175	Paseo De La Luz at Via Del Cielo	20A	18		RCP	Line starts at CB on Paseo De La Luz southbound approx. 115' south of Via Del Cielo and runs southbound to the intersection of the street.	LOWAN-SD-CB1724MH1722	CB1724 to MH1722	24		7/31/14	Pipe looks in good condition.
48	34	76	Crestshaw Blvd. at Indian Peak Rd.	13A & 13B	19		48" CMP	Crestshaw to MH approx. 130' east of Crestshaw Blvd. southbound to the intersection of Indian Peak Rd.	MC-RHE-SD-MH121813	CB1412 to MH1413	1220		7/29/14	Pipe looks in good condition.
49	35	79	Crestshaw Blvd. at Silver Spur Rd.	13A & 13B	19		18" RCP	Line starts at CB on Crestshaw northbound to CB at Silver Spur Rd.	MC-RHE-SD-MH121813	MH1413 to CB1414	35		8/21/14	Pipe looks clean and in good condition.
50	36	81	5225 Middlecrest Rd.	13A & 13B	19		18" CMP	Line starts at CB in front of property to JS approx. 50' south.	MC-RHE-SD-JS2884-JS2884	CB1012 to JS2884	25.5		9/23/14	Light to medium corrosion throughout the pipe.
51	37	82	5230 Middlecrest Rd.	13A & 13B	19		48" CMP	JS is on 5230 Middlecrest property to OS on 5219A. RHE-SD-JS1014-JS2884. MC-RHE-SD-JS2883-JS2884. MC-RHE-SD-JS2884-JS1013.		CB1014 to OS1013	138		7/30/14	Pipe line has been paved previously. Line is in good condition.
52	38	83	Crestridge Rd. at Crestshaw Blvd.	13A	20		24" RCP	Line starts at CB on northwest corner of intersection to CB on the same corner.	MC-RHE-SD-CB1030-CB1029	CB1030 to CB1029	27		8/20/14	Pipe looks clean and in good condition.
53	39	84	Crestridge Rd. at Crestshaw Blvd.	13A	20		24" RCP	Line starts from CB on southwest corner of intersection to CB on southwest corner.	MC-RHE-SD-CB1029-CB1027	CB1029 to CB1027	87		8/20/14	Pipe looks clean and in good condition.
54	40	85	Crestridge Rd. at Crestshaw Blvd.	13A	20		18" RCP	Line starts from CB on southwest corner of intersection to CB approx. 50' northwest.	MC-RHE-SD-CB1029-CB1027	CB1027 to CB1028	91		8/20/14	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
55	41	89	Crestview Blvd. at Crestridge Rd.	13A	20		30" RCP	Line runs from MH approx. 176' south of southeast corner of intersection to MH in front of 28641 Crestridge Rd. property	ML-RHE-SD-CB1021-MH1003, ML-RHE-SD-MH3518-CB1021	MH3518 to MH1003	237		8/5/14	Pipe looks clean and in good condition
56	42	91	Crestview Blvd. at Crestridge Rd.	13A	30		18" RCP	Line runs from CB 1046 south of southeast corner of intersection to MH 1010 north	ML-RHE-SD-CB1022-MH1010	CB1022 to MH1010	10		8/5/14	Pipe looks clean and in good condition
57	43	102	Whitley Collins Dr. at Sun Met Dr.	12D & 13C	23		15" RCP	Line starts at CB on Whitley Collins median to JS	SM-OSS-SD-CB01046-JS02090	CB1046 to JS2090	32		8/5/14	Pipe looks clean and in good condition
58	44	103	Whitley Collins Dr. at Sun Met Dr.	12D & 13C	23		18" RCP	Line starts at CB on northeast corner of intersection to JS	SM-OSS-SD-CB01047-JS02090	CB1047 to JS2090	30		8/5/14	Pipe looks clean and in good condition
59	45	104	Whitley Collins Dr. at Sun Met Dr.	12D & 13C	23		21" RCP	Line starts at CB on northeast corner of intersection to CB on southeast corner	SM-OSS-SD-CB01048-JS02090, SM-OSS-SD-JS02090-CB01046	CB1048 to CB1046	100.5		8/5/14	Pipe looks clean and in good condition
60	46	105	Whitley Collins Dr. at Sun Met Dr.	12D & 13C	23		27" RCP	Line starts at CB on southeast corner of intersection to CB on northeast corner of Whitley Collins Dr. & Crest Rd. turn right corner to intersection to CB on southeast corner of intersection	SM-OSS-SD-CB01046-CB01044, SM-OSS-SD-CB01044-MH10446, SM-OSS-SD-MH10446-MH1050	CB1046 to CB1044	72		8/5/14	Pipe looks clean and in good condition
61	47	106	Whitley Collins Dr. at Crest Rd.	12D & 13C	23		18" RCP	Line starts at CB on southeast corner of intersection to CB on southeast corner of intersection	SM-OSS-SD-CB01046-MH10446, SM-OSS-SD-MH10446-MH1050	CB1046 to MH1050	100.5		8/5/14	Pipe looks clean and in good condition
62	48	107	Whitley Collins Dr. at Crest Rd.	12D & 13C	23		18" RCP	Line runs from CB on southeast corner of intersection to CB 45' south	SM-OSS-SD-CB01039-CB01040	CB1040 to CB1039	47		8/5/14	Pipe looks clean and in good condition
63	49	108	Whitley Collins Dr. at Crest Rd.	12D & 13C	23		18" RCP	Line runs from CB on Crest southeast corner of intersection to median 75' west	SM-OSS-SD-CB01044-MH10446	CB1044 to Median	65.5		8/5/14	Pipe looks clean and in good condition
64	50	109	25711 Whitley Collins at Crest Rd.	12D & 13C	23		18" RCP	Line starts at CB in front of property to CB in front of 25711 Whitley Collins	SM-OSS-SD-CB01044-CB01043	CB1044 to CB1043	34		8/5/14	Pipe looks clean and in good condition

San Juan Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
65	51	110	Whitley Collins at Crest Rd.	12D & 13C	23		15" RCP	Line runs from CB in median to to CB in front of 29719 Whitley Collins.	SM-OSS-SD-CB1042-CB1043	CB1042 to CB1043	39		8/5/14	Pipe looks clean and in good condition.
66	52	111	29719 Whitley Collins at Crest Rd.	12D & 13C	23		21" RCP	Line runs from CB in front of property to JS on Crest westbound	SM-OSS-SD-CB1043-JS02081	CB1043 to JS02081	59		8/5/14	Pipe looks clean and in good condition.
67	53	112	Crest Rd. at Whitley Collins Dr.	12D & 13C	23		48" RCP & UNKNOWN	Line runs from MH on Crest westbound to MH JS02081-MH10151	SM-OSS-SD-MH1050-JS02081, SM-OSS-SD-JS02081-MH10151	MH1050 to MH1051	464		8/14/14	Pipe looks clean and in good condition.
68	54	113	Crest Rd. at Whitley Collins Dr.	12D & 13C	23		48" RCP	Line runs from MH in median approx. 480' west from intersection to OS in canyon south of Crest.	SM-OSS-SD-MH1051-JS01056, SM-OSS-SD-JS01056-CB02676, SM-OSS-SD-CB02676-OS01055	MH1051 to OS1055	612		8/14/14	Pipe looks clean and in good condition.
69	55	114	Crest Rd.	12D & 13C	23		18" RCP	Line runs from CB approx. 530' west of Whitley Collins Dr. to CB 30' west.	SM-OSS-SD-CB01052-CB01053	MH1052 to CB1053	30		8/14/14	Pipe looks clean and in good condition.
70	56	115	Crest Rd.	12D & 13C	23		30" RCP	Line runs from CB approx. 680' west of Whitley Collins Dr. to JS in median across Crest westbound	SM-OSS-SD-CB01053-CB02676	CB1053 to JS2676	16		8/14/14	Pipe looks clean and in good condition.
71	57	119	Crest Rd.	12D	25		27" RCP	Line turns at CB in May Acres Rd. RIE to MH on Crest westbound	SM-OSS-SD-TS3245-MH13246, SM-OSS-SD-CB3244-TS3245	CB3244 to MH3246	239		8/14/14	Pipe looks clean and in good condition.
72	58	120	Crest Rd.	12D	25		27" RCP	Line runs from MH approx. 680' from highridge to MH 200' west	SM-OSS-SD-MH13246-MH13247	MH3246 to MH3247	144		8/14/14	Pipe looks clean and in good condition.
73	59	134	Crest Rd.	12C	26		24" RCP	Line turns at CB 545' west of Sea Terrace to MH in median	SM-OSS-SD-CB3191-MH1190	CB3191 to MH1190	118		8/15/14	Pipe looks clean and in good condition.
74	60	135	Crest Rd.	12C	26		18" RCP	Line runs from MH approx. 230' west of east end of median to MH1190	SM-OSS-SD-CB3192-MH1190	CB3192 to MH1190	65		8/20/14	Pipe looks clean and in good condition.
75	61	136	Crest Rd.	12C	26		24" RCP	Line runs from MH approx. 570' west of east end of median to MH1167	SM-OSS-SD-MH1190-MH1167, SM-OSS-SD-MH1167-MH1167	MH1190 to MH1167	365		8/15/14	Pipe looks clean and in good condition.
76	62	137	Crest Rd.	12C	26		18" RCP	Line runs from MH approx. 570' west of east end of median to MH1167	SM-OSS-SD-CB3188-MH1167	CB3188 to MH1167	70		8/21/14	Pipe looks clean and in good condition.
77	63	138	Crest Rd.	12C	26		24" RCP	Line runs from MH 620' east of west end of median to MH 480' west	SM-OSS-SD-MH1167-MH1168, SM-OSS-SD-MH1168-MH1165	CB3187 to MH1165	485		8/15/14	Pipe looks clean and in good condition.
78	64	139	Crest Rd.	12C	26		18" RCP	Line turns at CB approx. 1000' west of Anacapa to MH 85' southwest in median	SM-OSS-SD-CB3182-MH1165	CB3182 to MH1165	80.5		8/21/14	Pipe looks clean and in good condition.
79	65	140	Crest Rd.	12C	26		24" RCP	Line runs from MH 135' east of west end of median to CB 115' west	SM-OSS-SD-MH1165-CB3163	MH1165 to CB3163	134		8/15/14	Pipe looks clean and in good condition.
80	66	141	Crest Rd. at La Cienega Dr.	12C	26		18" RCP	Line turns at CB 80' east of La Cienega Dr. to CB in median	SM-OSS-SD-CB3164-CB3163, SM-OSS-SD-CB3163-CB3163	CB3164 to CB3163	47		8/15/14	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments Per Grade (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
81	67	142 Crest Rd. at La Croix Dr.	12C	26	24" RCP	Line runs from CB 287 east of west end of median to MH 700 west of east end of median (west of La Croix Dr.)	SM-OWW-SD-CB3183-MH1081	CB3183 to MH1081	171		8/18/14	Pipe looks clean and in good condition.
82	68	143 Crest Rd. at La Croix Dr.	12C	26	18" RCP	Line starts at CB on westbound 25' west of La Croix to MH in median west of La Croix	SM-OWW-SD-CB3194-MH1081	CB3194 to MH1081	77.5		8/21/14	Pipe looks clean and in good condition.
83	69	144 Crest Rd. at La Croix Dr.	12C	26	24" RCP	Line runs from MH 75 west of east end of median to MH 195' north	SM-OWW-SD-MH1081-MH3195	MH1081 to MH3195	190		8/18/14	Pipe looks clean and in good condition.
84	70	147 Crest Rd.	12C	26	24" RCP	Line runs from MH 285' south of west end of median to MH 155' east of Cresta Verde at Crest	SM-OWW-SD-MH3195-CB3198, SM-OWW-SD-CB3198-MH1092	MH3195 to MH1092	200		8/18/14	Pipe looks clean and in good condition.
85	71	148 Crest Rd.	12C	26	24" RCP	Line runs from MH 180' south of Cresta Verde to MH 15' west	SM-OWW-SD-TS46932-MH1092, SM-OWW-SD-CB46931-TS46932	CB1091 to MH1092	27		8/21/14	Pipe looks clean and in good condition.
86	72	152 Hawthorne Blvd. at Crest Rd.	12A & 12C	27	36" RCP	canyon (east side of Hawthorne) to CB in canyon west side of Hawthorne)	SM-OWW-SD-J51100-J51102	J51102 to J51105	424		9/3/14	Light corrosion throughout the pipe. Overall pipe looks clean and in good condition.
87	73	154 Crest Rd. at Hawthorne Blvd.	12C	28	18" RCP	Line starts at CB 315' east of Hawthorne on Crest westbound to MH	SM-OWW-SD-CB1086-MH1093	CB1086 to MH1093	5		8/19/14	Pipe looks clean and in good condition.
88	155	Crest Rd. at Hawthorne Blvd.	12C	28	24" RCP	Line runs from MH 305' east of Hawthorne to MH 170' west	SM-OWW-SD-MH1093-MH1094	MH1093 to MH1094	180		8/19/14	Pipe looks clean and in good condition.

S. . . Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
89	75	156	Crest Rd. at Hawthorne Blvd.	12C	28		18" RCP	Line starts at CB 130' east of Hawthorne on Crest westbound to MH	SM-OWN-SD-CB 1087-MH1094	CB1087 to MH1094	6		8/19/14	Pipe looks clean and in good condition.
90	76	157	Crest Rd. at Hawthorne Blvd.	12C	28		30" RCP	Line runs from CB 80' east of Hawthorne on Crest westbound to the intersection of Crest and Hawthorne Blvd.	SM-OWN-SD-MH1094-CB1095	CB1095 to MH1094	97.5		8/19/14	Pipe looks clean and in good condition.
91	77	161	Hawthorne Blvd. at Crest Rd.	12C	28		24" RCP	Line starts at CB 130' east of Hawthorne southbound to JS in the middle of Hawthorne Boulevard.	SM-OWN-SD-CB1290-SD- CB2899-CB3300	CB2899 to JS2801	149		8/19/14	Pipe looks clean and in good condition.
92	78	163	Rue La Fleur at Rue De La Pierre	20A	29		18" RCP	Line starts at CB on southeast corner of intersection to CB in front of 30503 Rue Langlois.	SM-OWN-SD-CB3301-CB3302	CB3301 to CB3302	43		7/30/14	Pipe is in good condition.
93	79	164	Rue De La Pierre at Rue La Fleur	20A	29		18" RCP	Line starts at CB on Rue De La Pierre (southeast corner of intersection) to CB in front of 30507 Rue De La Pierre.	SM-OWN-SD-CB3300-CB3309	CB3300 to CB3309	32		7/30/14	Pipe is in good condition.
94	80	165	Rue De La Pierre at Rue Langlois	20A	29		24" RCP	Line starts at CB on southeast corner of intersection to CB in front of 30503 Rue Langlois.	SM-OWN-SD-CB3309-CB3302	CB3309 to CB3302	82		7/30/14	Pipe is in good condition.
95	81	174	Paseo De La Luz at Via Del Cielo	20A	30		18" RCP	Line starts at CB on Paseo De La Luz northbound to the intersection of Via Del Cielo to MH in the middle of the street.	SM-OWN-SD-CB1723-MH1722	CB1723 to MH1722	30	20	7/31/15	Pipe looks clean and in good condition.
96	82	167	PUDW at Calle Embarcadero	11C	30		27" RCP	Line runs from MH on median approx. 60' west of SM-OWN-SD-CB46043 to CB on northwest corner of MH1165-SD46043 intersection.	SM-OWN-SD-CB46043-CB1164, SM-OWN-SD- MH1165-SD46043	MH1165 to CB1164	171		8/17/14	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Please I)	Number of Pipe Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
97	83	167.1	PVDW at Calle Enriadero	11C	30		18" RCP	Line runs from CB on PVDW northbound to MH on median approx. 60' west of Calle Enriadero		CB1155.1 to MH1185	20		9/17/14	Pipe looks clean and in good condition.
98	84	168	PVDW at Calle Enriadero	20A	30		18" RCP	IS is at end of open channel outside of PVDW south of Calle Enriadero to CB 45' south west side of PVDW	PIPE FOUND	IS0567 to OS0569	427		9/17/14	Unobstructed MH is 172' west of 288' long IS. Pipe looks clean and in good condition.
99	85	169	PVDW at Calle Enriadero	11C	30		18" RCP	Line starts at CB at median (approx. 160' south of Calle Enriadero) to CB on PVDW eastbound	SM-OWN-SD-CB1715-CB1716	CB1715 to CB1716	34		9/15/14	Pipe looks clean and in good condition.
100	86	170	PVDW at Calle Enriadero	11C	30		18" RCP	Line starts at CB on PVDW eastbound (25' south of Calle Enriadero) to CB 45' south	SM-OWN-SD-CB1713-CB1716	CB1713 to CB1716	25		9/15/14	Pipe looks clean and in good condition.
101	87	171	PVDW at Calle Enriadero	11C	30		18" RCP	Line starts at CB on PVDW eastbound (200' south of Calle Enriadero) to CB 25' north	SM-OWN-SD-CB1714-CB1716	CB1714 to CB1716	25		9/15/14	Pipe looks clean and in good condition.
102	88	172	PVDW at Calle Enriadero	20A	30		18" RCP	Line starts at CB on PVDW eastbound (170' south of Calle Enriadero) to MH in southwest property of intersection	SM-OWN-SD-CB1717-CB1718, SM-OWN-SD-CB1717-MH1712	CB1716 to MH1712	202		9/15/14	Pipe looks clean and in good condition.
103	89	173	PVDW at Calle Enriadero	20A	30		18" RCP	Line runs from TS in southwest property approx. 330' from Calle Enriadero	SM-OWN-SD-CB1721-MH1722, SM-OWN-SD-CB1721-CB1722	MH1712 to MH1722	187		9/15/14	Pipe looks clean and in good condition.

San Jose Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
104	90	173.1 PWDW al Calle Encarnado	20A	30		30" RCP	Line runs from TS in southwest property approx. 330' from Calle Encarnado	SM-OWN-SD-CB1119-MH112	TS1719 to MH112	65.5		9/15/14	Pipe looks clean and in good condition.
105	91	176 Hawthorne Blvd. & Rhone Dr.	12C	31		27" RCP	Line runs from CB 130' north of Rhone Dr. to MH in the middle of Hawthorne northbound	SM-OWN-SD-CB1113-MH113	CB1153 to MH113	209	300	7/31/15	No video in the folder provided by Performance Pipeline
106	92	176 30095 Cavlier Dr.	12C & 10A	31		18" RCP	Line starts at CB in front of property to CB in front of 30095 Cavlier Dr.	SM-OWN-SD-CB1110-CB1152	CB1110 to CB1152	40		7/31/14	Pipe looks in good condition.
107	93	177 30095 Cavlier Dr.	12C	31		36" RCP	Line runs from CB in front of property to CB behind property on Hawthorne Blvd.	SM-OWN-SD-CB1152-CB342, SM-OWN-SD-CB342-CB343, SM-OWN-SD-CB343-CB344, SM-OWN-SD-CB344-CB345, SM-OWN-SD-CB345-CB346, SM-OWN-SD-CB346-CB1153	CB1152 to CB1153	258		7/31/14	Pipe has been lined previously. Pipe looks in good condition.
108	94	173 Hawthorne Blvd. & Rhone Dr.	12C	31		18" RCP	Line starts at CB on Hawthorne 60' south of Rhone Dr. to CB 30' south	SM-OWN-SD-CB1111-CB1112	CB1111 to CB1112	30		7/31/14	Pipe looks clean and in good condition.
109	95	160 Hawthorne Blvd. & Rhone Dr.	12C	31		18" RCP	Line runs from CB on Hawthorne 50' south of Rhone Dr. to MH 20' southwest on Hawthorne northbound	SM-OWN-SD-CB1112-MH113	CB1112 to MH113	15.6		7/31/14	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

	Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Map # No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point (Approx.)	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
110	96	181	Hawthorne Bys. & Rhone Dr	12C & 19A	31		30" RCP	Line runs from MH in the middle of Hawthorne northbound 30' south of Rhone to UNKNOWN south end		MH1133 to MH1135	257		7/31/14	Pipe looks clean and in good condition.
111	97	184	Hawthorne Dr. at Los Verdes Dr.	20B	31		36" RCP	Line runs from CB on Hawthorne southbound 255' north of Los Verdes Dr. to MH in the 30332 Avenida Selecta backyard	SM-OWW-SD-CB1154-082531 SM-OWW-SD-082531-MH1155	CB1154 to MH1155	75		8/21/14	Pipe looks clean and in good condition.
112	98	186	Hawthorne & PVDW	20C	33		18" RCP	Line starts at CB at the northeast corner of intersection to CB at southeast corner	SM-OWW-SD-CB3305-CB3306	CB3305 to CB3306	90		8/25/14	Pipe looks clean and in good condition.
113	99	188	Hawthorne & PVDW	20C	33		18" RCP	Line runs from MH at southwest corner to OS 245' south	SM-OWW-SD-MH3484-53485 PIPE FOUND	MH3484 to OS2575	858		8/25/14	OS 2575 runs into street from southbound. Pipe looks clean and in good condition.
114	100	191	PVDW at PVIC	22A	34		30" RCP	Line starts at CB by PVIC entrance on PVDW northbound to US in PVIC entrance island		CB3484 to PVIC2	80		9/9/14	Pipe looks clean and in good condition.
115	101	192	PVDW at PVIC	22A	34		30" RCP	Line starts at CB south of PVIC entrance on PVDW westbound to CB across PVIC eastbound	SM-OWW-SD-CB0558-CB0559	CB0558 to CB0559	95.5		9/9/14	Pipe has been lined previously. Line looks in good condition.
102	197.1				35		18" RCP	Line runs from CB to 30' RCP southbound 18' in parking lot eastbound to OS		MH0551 to BH0553	285.4	294	9/14/15	Pipe looks clean and in good condition.
103	197.2				35		18" RCP	Line runs from CB to PVIC southbound 18' in parking lot eastbound to OS		MH0551 to BH0553	285	294	9/14/15	Pipe looks clean and in good condition.
104	197.3				35		18" RCP	Line runs from MH to MH across the half of Hawthorne's lot		MH0551 to MH0553.1	187.3	187.6	9/14/15	Pipe looks clean and in good condition.

Page 125

5.000 Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe (Approx.)	Pipe Length	Video Date	Comments
105	137.4				35		18" RCP	Line from Drive Man to MH1 (down the SWLF by sidewalk) to 134		Manhole 3.1 to Manhole 3.2	187.8	187.8	10/18/18	Pipe looks clean and in good condition.
106	137.5				35		18" RCP	Line from Drive Man to MH1 (down the SWLF by sidewalk) to 135		Manhole 3.2 to Manhole 3.3	207.8	207.8	10/18/18	Pipe looks clean and in good condition.
107	137.7				35		18" RCP	Line from Drive Man to MH1 (down the SWLF by sidewalk) to 136		Manhole 3.3 to Manhole 3.4	48.3	48.3	10/18/18	Pipe looks clean and in good condition.
108	137.6				35		18" RCP	Line from Drive Man to MH1 (down the SWLF by sidewalk) to 137		Manhole 3.4 to Manhole 3.5	114.1	114.1	10/18/18	Pipe looks clean and in good condition.
109	137.9				35		18" RCP	Line from Drive Man to MH1 (down the SWLF by sidewalk) to 138		Manhole 3.5 to Manhole 3.6	71.3	71.3	10/18/18	Pipe looks clean and in good condition.
110	344	PVDS by Crestmont/Terranea Way		228	36		36" RCP	Line from Drive Man to MH1 (down the SWLF by sidewalk) to 139	3M-OBW-SD-CB0533-CB0540	CB0533 to CB0540	32		9/2/14	Pipe looks clean and in good condition.
111	345	PVDS by Crestmont/Terranea Way		228	36		36" RCP	Line from Drive Man to MH1 (down the SWLF by sidewalk) to 140		CB0540 to J55541	116		9/2/14	Pipe looks clean and in good condition.
112	340	PVDS by Crestmont/Terranea Way		228	37		36" RCP	Line from Drive Man to MH1 (down the SWLF by sidewalk) to 141		CB0541 to CB0542	16		8/28/14	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
4	113	340.1 PVIDS at Crestmont Ln/Terranea Way	228	37		30" RCP		SM-OSW-SD-MH1623-CB05035, SM-OSW-SD-CB0533-JS3157	MH1623 to JS3157	239			Stormwater flow in 10.5" hole MH1623. Pipe looks clean and in good condition.
5	114	341 PVIDS at Crestmont Ln/Terranea Way	228	37		18" RCP	Line starts at CB approx. 200' east of Terranea Way on PVIDS eastbound to MH	SM-OSW-SD-CB0533-MH1623	CB0533 to MH1623	22		8/29/14	Pipe looks clean and in good condition.
6	115	336 PVIDS at Tamono Dr/Squaliti Dr	23A	38		18" RCP	Line starts at CB on median east of Squaliti to CB on southeast corner of intersection	SM-OSW-SD-CB05035-JS44324, SM-OSW-SD-IS0654-CB0655	JS2654 to CB0655	16.5		8/29/14	Pipe looks clean and in good condition.
7	116	330.1 PVIDS at Abalone Cove Park	23B	39		24" RCP	Line starts at CB on PVIDS eastbound median to CB on PVIDS eastbound by Park exit		CB0653 to CB0655	51		9/12/14	Unmapped CB0653 is an PVIDS eastbound by Park exit. Pipe looks clean and in good condition.
8	117	330.2 PVIDS at Abalone Cove Park	23B	39		24" RCP	Line runs from CB on PVIDS eastbound by Park exit to OS adjacent to Abalone Cove Parking		CB0653 to CB0655	59		9/12/14	Pipe looks clean and in good condition.
9	118	334 PVIDS at Sascoe Dr.	23B	39		18" RCP	Line starts at CB on median west of Sascoe to JS	SM-OSW-SD-CB35318-JS2681	CB0655 to JS2680 / MH2680	199		9/12/14	Pipe looks clean and in good condition.
10	119	319 PVIDS at Narocssa	24A	40		120" CMP	Line starts at IS east of Narocssa to OS west of PVIDS	SM-OSS-SD-IS00637-GBM4503, SM-OSS-SD-GBM4504-JS00706, SM-OSS-SD-JS00706-IS02842, SM-OSS-SD-CB0655-JS00637	IS0637 to OS0659	679		8/29/14	Invert has been paved previously. Catch basin at JS00706. Line looks clean and in good condition.
11	320.1	PVIDS at Narocssa	24A	40		24" CMP			CB0705 to JS0706	191		9/31/14	Pipe looks clean and in good condition.

San Jose Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Plus 1)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
12	121	321	PVDS at Narcissa	24A	40		18" RCP	Line starts at CB on PVDS westbound 350' west of Narcissa to CB on PVDS eastbound 80' east from nursery school gate entrance		CB0700 to CB0699	43.5		9/3/14	Pipe looks clean and in good condition
13	122	323	PVDS at Narcissa	24A	40		36" CMP	Line runs from CB on median between Narcissa and nursery school gate to CB on median west of nursery school gate		CB0705 to CB0703	303		9/3/14	Pipe looks clean and in good condition
14	123	325	PVDS at Narcissa	24A	40		24" RCP	Line runs from CB on median west of nursery school gate (approx. 350' of east end of median) to CB 200' east		CB0703 to CB0703	200		9/3/14	Pipe looks clean and in good condition
15	124	326	PVDS at Narcissa	24A	40		24" RCP	Line runs from CB on median west of nursery school gate (approx. 500' of east end of median) to CB 200' east		CB0703 to CB0703	200		9/3/14	Pipe looks clean and in good condition
16	125	323	PVDS at Wayfarer's Chapel	24A	40		24" RCP	Line runs from CB on west side of Wayfarer's Chapel entrance to OS south of PVDS	SM-OS-SD-CB08510-OS00660, SM-OS-SD-CB00661-CB08510	CB0861 to OS0060	117		9/11/14	Pipe looks clean and in good condition
17	126	313.1	PVDS landslide area	24D	42		18" RCP	Line runs from CB on PVDS eastbound 1000' west of Schooner to CB on PVDS eastbound	SM-OS-SD-CB1409-CB0530	CB0530 to CB0530	62		9/11/14	Pipe looks clean and in good condition
18	127	313.2	4318 PVDS	24D	42		18" RCP	Line runs from CB in front of the property to CB or OS south of Schooner	SM-OS-SD-CB1409-CB0530	CB0530 to OS0531	42		9/11/14	Pipe looks clean and in good condition
19	128	312	PVDS at Schooner Dr.	28A	43		24" RCP	Line starts at CB on PVDS westbound (approx. 510' west of Schooner) to OS south of PVDS	SM-OS-SD-CB0532-OS0531	CB0532 to OS0531	35		8/27/14	Line has been lined previously. It is clean and in good condition.
20	129	312.1	PVDS at Schooner Dr.	28A	43		36" RCP	Line starts at CB on PVDS eastbound 330' west of Schooner to CB on PVDS eastbound	SM-OS-SD-CB14511-CB0532	CB0532 to OS0422	70		8/27/14	Pipe looks clean and in good condition
21	130	309	PVDS at Conqueror Dr.	28A	44		18" RCP	Line runs from CB on parking area island to OS north of intersection to MH on Trump National Dr.	SM-OS-SD-CB3407-OS3405	OS3405 to MH2793	6		8/11/14	Video was taken from CB3407 to MH2465. Pipe looks clean and in good condition.
22	131	304	PVDS at Trump National Dr.	28A	45		24" RCP	Line runs from MH west of Trump National to OS south of intersection to MH on Forestal Dr.	SM-OS-SD-OS2793-MH2794, SM-OS-SD-CB2794-OS2793	OS2793 to OS2797	365		8/6/14	Pipe looks clean and in good condition
23	132	306	PVDS at Trump National Dr.	28A	45		36" RCP	Line runs from MH west of Trump National to OS 275' west of Forestal	SM-OS-SD-OS2796-OS2797, SM-OS-SD-OS2796-OS2797	OS2796 to OS2796	208		8/6/14	Pipe looks clean and in good condition
24	133	299	Forestal Dr. at PVDS	28A	46		18" RCP	Line starts at CB on Forestal southbound 75' north of PVDS to OS on mainline	SM-OS-SD-CB2796-OS2795	UNKNOWN	9.6	10	8/6/14	Pipe looks clean and in good condition
25	134	293	Forestal Dr. at Kona Vista Dr.	28A	46		30" RCP	Line starts at CB on Forestal approx. 165' north of Kona Vista to CB 10' south	SM-OS-SD-CB2779-CB2777	CB2779 to CB2777	11		8/6/14	Pipe looks clean and in good condition

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Map No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
26	135	234 Forestal Dr. at Aqua Vista Dr.	23A	45		30" RCP	Line starts at CB on Forestal approx. 95' north of Aqua Vista to JS.	SM-OSE-SD-CB2776-52780	CB2776 to 52780	39.5		8/6/14	Pipe looks clean and in good condition.
27	136	235.1 Forestal Dr. at Aqua Vista Dr.	23A	45		30" RCP	Line runs from CB in Forestal/Aqua Vista corner to PVDOS.		CB2776 to 52780	40		8/6/14	Pipe looks clean and in good condition.
28	137	237 Forestal Dr. at PVDOS	23A	45		18" RCP	Line starts at CB on Forestal southbound 105' north of PVDOS to CB 15' south.	SM-OSE-SD-CB2782-52776	CB2782 to 52776	16.5		8/6/14	Pipe looks clean and in good condition.
29	138	238 Forestal Dr. at PVDOS	23A	45		30" RCP	Line starts at CB on Forestal southbound 90' north of PVDOS to JS on median.	SM-OSE-SD-CB2776-MH2784	CB2776 to 52780	37		8/6/14	Pipe looks clean and in good condition.
30	139	239.1 Forestal Dr. at PVDOS	23A	45		18" RCP	Line runs from CB on Forestal corner at intersection to 71' south of PVDOS.		CB2776 to 52780	25		8/6/14	Pipe looks clean and in good condition.
31	140	301 Forestal Dr. at PVDOS	23A	45		42" RCP	Line runs from MH on northwest corner to OS south of PVDOS.		CB2776 to 52780	516		8/7/14	Unmapped MH at 197' & 516'. Pipe looks clean and in good condition.
32	141	302 Aqua Vista/PVDOS median	23A	45		30" RCP	Line runs from CB on Aqua Vista median to CB or PVDOS median.	SM-OSE-SD-CB2791-52791	CB2791 to 52791	23		8/7/14	Pipe looks clean and in good condition.
33	142	303 Aqua Vista Dr. at Forestal	23A	45		24" RCP	Line runs from CB on Aqua Vista/PVDOS median to JS on median.	SM-OSE-SD-CB2790-52791, SM-OSE-SD-CB2790-52791	CB2791 to 52791	63.5		8/7/14	Pipe looks clean and in good condition.
34	143	289 PVDOS at Forestal Dr.	28B	47		30" RCP	Line starts at CB (partial above CB in median) might be on PVDOS westbound approx. 515' from intersection to MH.		CB2791 to 52791	16		8/26/14	all 1200' of pipe still good. Inspection limited in existing video inspection above 15' (could be verify in 1st hour). Pipe looks clean and in good condition.
35	144	290 PVDOS at Forestal Dr.	28B & 28A	47		30" RCP	Line runs from MH to OS west of PVDOS.		CB2791 to 52791	526		8/26/14	all 1200' of pipe still good. Inspection limited in existing video inspection above 15' (could be verify in 1st hour). Pipe looks clean and in good condition.
36	145	291 PVDOS at Seacrest Dr.	28B	48		18" RCP	Line starts at CB on PVDOS westbound (approx. 315' east of intersection) to CB 15' east.	SM-OSE-SD-CB1865-CB1867	CB1865 to CB1867	14		8/27/14	Pipe looks clean and in good condition.
37	146	292 PVDOS at Seacrest Dr.	28B	48		18" RCP	Line starts at CB on PVDOS westbound (approx. 335' east of intersection) to CB 15' east.	SM-OSE-SD-CB1867-MH1865	CB1867 to MH1865	31		8/27/14	Pipe looks clean and in good condition.

5... ..Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
38	147	283	PVDS at Seaciff Dr.	288	48		36" RCP	Line runs from MH in PVDS median (approx. 335' east of median west end) to MH at intersection south of PVDS	SM-OSE-SD-MH1865-JS1846, SM-OSE-SD-JS1846-CB1844, SM-OSE-SD-CB1844-MH0350	MH1865 to MH0350	372		8/27/14	MH1865 is buried. Pipe looks good and in good condition.
39	148	284	PVDS at Seaciff Dr.	288	48		18" RCP	Line starts at CB on PVDS eastbound to JS on median	SM-OSE-SD-CB1845-JS1846	CB1845 to JS1846	11		8/27/14	Pipe looks clean and in good condition.
40	149	285	PVDS at Seaciff Dr.	288	48		21" RCP	Line starts at CB on northwest corner of intersection to JS	SM-OSE-SD-CB0346-JS0351	CB0346 to JS0351	83.5		8/8/14	Pipe looks clean and in good condition.
41	150	286	PVDS at Seaciff Dr.	288	48		21" RCP	Line starts at CB on Seaciff westbound (approx. 20' north from intersection) to CB 25' south	SM-OSE-SD-CB0346-CB0347	CB0346 to CB0347	69		8/8/14	Hard deposits from 25' to 37' about 15%. Overall pipe is clean and in good condition.
42	151	287	PVDS at Seaciff Dr.	288	48		18" RCP	Line runs from CB on Seaciff Dr. to CB on PVDS (SM-OSE-SD-CB0347-JS0351, SM-OSE-SD-JS0351, SM-OSE-SD-CB0348-JS0351)	SM-OSE-SD-CB0347-JS0351, SM-OSE-SD-CB0348-JS0351	CB0347 to CB0348	78		8/8/14	Pipe looks clean and in good condition.
43	152	288	PVDS at Seaciff Dr.	288	48		21" RCP	Line runs from CB on Seaciff Dr. (northeast corner of intersection) to MH south of PVDS (JS0351, SM-OSE-SD-JS0351-MH0350)	SM-OSE-SD-CB0347-JS0351, SM-OSE-SD-JS0351-MH0350	CB0347 to MH0350	122		8/8/14	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
44	153	279 PVIDS at PVIDE	28B & 28D	49		24" RCP	Line starts at CB on PVIDE (southeast corner of intersection) to CB on PVIDE (northwest corner)		CB0314 to CB0315	179	179	8/8/14	Pipe looks clean and in good condition.
45	114	277 PVIDS at PVIDE	28B & 28D	49		42" RCP	Line starts at JS on northeast corner of intersection to OS south of PVIDS	SM-OSE-SD-050317-JS2096	JS2096 to OS0316	32		8/8/14	Pipe looks clean and in good condition.
46	155	277.1 PVIDS at PVIDE	28B & 28D	49		42" RCP	Line starts at JS on northeast corner of intersection to OS south of PVIDS	SM-OSE-SD-050317-JS2096	JS2096 to OS0316	448		8/8/14	Pipe looks clean and in good condition.
47	156	201 Western Ave @ De La Sorda Dr	33A	50		21" RCP	Line runs from CB on De La Sorda (at the southwest corner of intersection) to CB on De La Sorda (northwest corner of intersection)	LALAE-SD-CB0167-CB0168	CB0167 to CB0168	31.2		5/20/14	Line has been cleaned. Pipe looks in good condition.
48	157	202 Western Ave @ De La Sorda Dr	33A	50		24" RCP	Line runs from CB on De La Sorda (northwest corner of intersection) to MH on Western	LALAE-SD-CB0168-MH1907	CB0168 to MH1907	97.5		5/20/14	Line has been cleaned. Pipe looks in good condition.
49	158	204 Sunrise Ridge Rd. Cul-de-sac	15B	51		18" CMP	Line starts at CB at the end of the cul-de-sac to OS on 277.5 PVIDE property	LALAE-SD-CB0930-OS0931	CB0930 to OS0931	157	157	10/7/15	Pipe has been lined previously. Overall line is clean and in good condition.

5. Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments Per Grade (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
50	159	205 2522 Sunnyside Ridge Rd.	15B	51		18" CMP	Line starts at CB in front of 2522 Sunnyside Ridge to OS in front of 2507 Sunnyside Ridge	LALAN-SD-CB0933-CB0933	CB0933 to CB0933	51	51	5/29/15	Pipe has been lined previously. Overall line is clean and in good condition.
51	160	206 2507 Sunnyside Ridge Rd.	15B	51		18" CMP	Line runs from CB in front of 2507 Sunnyside Ridge to OS behind the same property	LALAN-SD-CB0933-OS0934	CB0933 to OS0934	194	194	5/29/15	Pipe has been lined previously. Overall line is clean and in good condition.
52	161	230 18 Station Rd.	15A	54		24" RCP	Line runs from CB behind 18 Station to MH behind 24 Station	LALAN-SD-CB0894-MH0463	CB0894 to MH0463	185.6		6/3/14	Pipe looks clean and in good condition.
53	162	231 24 Station Rd.	15A	54		24" RCP	Line runs from MH behind 24 Station to MH on PVDE at Bronco	LALAN-SD-MH0463-MH0491	MH0463 to MH0491	230		6/3/14	Pipe looks clean and in good condition.
54	163	235 28541 PVDE	15A	54		18" RCP	Line runs from CB on Bronco at PVDE to JS on Bronco	LALAN-SD-CB0890-JS3449	CB0890 to JS3449	24.7		6/2/14	Line has been cleaned. Pipe looks in good condition.
55	164	245 PVDE at Mustang Rd.	15C	55		18" RCP	Line starts at CB on PVDE northbound to OS on 2 Coast Rd.	LALAN-SD-CB0914-OS0913	CB0914 to OS0913	42	42	12/15/14	Pipe has been lined previously. Line is clean and in good condition.
56	165	248 PVDE at Rockinghorse Rd.	15C	55		18" RCP	Line starts at CB south of Rockinghorse to OS on 10 Rockinghorse Rd.	LALAE-SD-CB0909-OS0908	CB0909 to OS0909	30	30	12/15/14	Pipe has been lined previously. Line is clean and in good condition.
57	166	253 2312 Coit Rd.	15D	56		24" CMP	Line runs from CB in front of the property to OS in LALAE-SD-CB3371-OS3370, LALAE-SD-OS3370-OS3373, LALAE-SD-CB3369-OS3373	CB3371 to OS3373	CB3371 to OS3373	339		8/2/14	Pipe has been lined previously. Line looks in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Map # No.	Storm Drain Map No.	Year Built	Pipe Size	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
58	167	259 28500 Western Ave.	33C	57		78" RCP	Line runs from JS behind property to TS	LA-LAE-SD-MH1016-TS3207 LA-LAE-SD-JS3217- MH1030 LA-LAE-SD-JS3214-JS3217	JS3214 to TS3207	508	508	5/20/14	Pipe looks clean and in good condition.
59	168	254 18009 Toscanini Dr. at Western Ave.	33C	57		18" RCP	Line starts at CB in front of property to CB in rear of 18009 Toscanini	LA-LAE-SD-CB0146-CB0145	CB0146 to CB0145	33.8		5/20/14	Line has been cleaned. Pipe looks in good condition.
60	169	255 18003 Toscanini Dr. at Western Ave.	33C	57		24" RCP	Line runs at CB in front of property to CB across Toscanini Dr.	LA-LAE-SD-CB0145-CB0146	CB0145 to CB0146	35.6		5/20/14	Line has been cleaned. Pipe looks in good condition.
61	170	256 Toscanini Dr. at Western Ave.	33C	57		18" RCP	Line runs from CB at southwest corner to CB 40' east.	LA-LAE-SD-CB0147-CB0146	CB0146 to CB0147	32		5/20/14	Line has been cleaned. Pipe looks in good condition.
62	171	257 Toscanini Dr. at Western Ave.	33C	57		24" RCP	Line runs from CB at southwest corner to JS on Western (south of Toscanini Dr.)	LA-LAE-SD-CB0146-JS0140	CB0146 to JS0140	116.7		5/20/14	Line has been cleaned. Pipe looks in good condition.
63	172	262 Western Ave. at Caddington Dr.	33C	58		24" RCP	Line starts at CB on Western (northwest corner) to CB 85' north	LA-LAE-SD-CB0151-CB0152	CB0151 to CB0152	32		9/25/14	Pipe looks clean and in good condition.
64	173	263 Western Ave. at Caddington Dr.	33C	58		24" RCP	Line runs from CB on Western (northwest corner) to front structure		CB0152 to MH1016	87		9/25/14	Pipe looks clean and in good condition.
65	174	265a 28019 Gunter at Caddington	33C	58		18" RCP	Line runs from MH on parking lot behind Chromas to MH in front of property (ends on Western)	LA-LAE-SD-CB0044-JS1030 LA-LAE-SD-MH1016-MH1014	CB0044 to JS1030 MH1016 to MH1014	33.8 522		5/20/14 10/7/14	Line has been cleaned. Pipe looks in good condition. Pipe looks clean and in good condition.
66	175	265b The Terrace Shopping Plaza on Western	33C	58		48" RCP							

Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
67	176	265c The Terrace Shopping Plaza on Western	33C	58		48" RCP	Line runs from MH on parking to behind Crummas to 35 location (??)		MH1918 to IS1916	427		10/6/14	Pipe looks clean and in good condition.
68	177	267 Newridge Dr. LACO	26A	59		33" RCP	Line starts at CB in front of 3485 Newridge to MH in the middle of the road	LALAS-SD-CB0101-MH0102	CB0101 to MH0102	20.6	21	5/29/15	Pipe looks clean and in good condition.
69	178	268 Newridge Dr. LACO	26A	59		33" RCP	Line runs from MH in the middle of the road to 14 Diamonds property	LALAS-SD-CB0101-MH0102	MH0102 to CB0255	829		8/11/14	Line has been cleaned. Pipe looks in great condition. Outer inspection near last block.
70	179	271 2009 Chandelier Dr. at Miraleste Dr.	26D	61		18" RCP	Line starts at CB on Miraleste to CB in front of property on Chandelier Dr.		CB0263 to CB0264	202		9/23/14	Pipe looks clean and in good condition
71	180	272 2009 Chandelier Dr. at Miraleste Dr.	26D	61		18" RCP	Line runs from CB in front of property to CB on southwest corner of intersection		CB0264 to CB0265	30		9/23/14	Pipe looks clean and in good condition.
72	181	273 Chandelier Dr. at Miraleste Dr.	26D	61		30" RCP	Line runs from CB on southwest corner to MH on Miraleste northbound		CB0265 to MH0265	130		9/23/14	Buffed JS at 130'. Pipe looks clean and in good condition.
73	182	273.1 Chandelier Dr. at Miraleste Dr.	26D	61		30" RCP	Line runs from CB on southwest corner to MH on Miraleste northbound		CB0265 to MH0265	166		9/23/14	Inspection 180 to 111'. Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Pipe Size	Storm Drain Map No.	Year Built	Location Description	GIS Storm Drain Grid #	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
74	193	274	18" RCP	61		Chandeur Dr. at Moles Dr.	26D	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
75	194	275	18" RCP	8		Hawthorne Blvd.	5A	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
76	195	276	18" RCP	15		Hawthorne Blvd. / Hawthorne Rd.	5C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
77	196	277	18" RCP	15		Hawthorne Blvd. / Hawthorne Rd.	5C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
78	197	278	18" RCP	15		Hawthorne Blvd. / Hawthorne Rd.	5D	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
79	198	279	18" RCP	16		Hawthorne Blvd.	7A	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
80	199	280	18" RCP	25		Crest Rd.	12D	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
81	200	281	18" RCP	25		Crest Rd. at Sea Terrace	12D	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
82	201	282	18" RCP	27		Hawthorne Blvd. at Indian Valley Rd.	12A & 12C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
83	202	283	18" RCP	27		Hawthorne Blvd. at Crest Rd.	12A & 12C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
84	203	284	18" RCP	34		PVDW at PVC	22A	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
85	204	285	18" RCP	36		PVDW by Crestmont Terrace Way	22B	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
86	205	286	18" RCP	39		PVDW at Abilene Cove Park	23B	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
87	206	287	18" RCP	40		PVDW at Narcissa	24A	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
88	207	288	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
89	208	289	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
90	209	290	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
91	210	291	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
92	211	292	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
93	212	293	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
94	213	294	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
95	214	295	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
96	215	296	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
97	216	297	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
98	217	298	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
99	218	299	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.
100	219	300	18" RCP	41		PVDW at Poppyvine	24C	Line runs from MH on Marquette northbound to CR on eastside of Moles Dr. approx. 300' south of Hwy 101.	ML-RHE-SD-CB1175-CB3171	MH0262 to OS0266	96		9/23/14	Inspected MH at 27. Pipe looks clean and in good condition.

Summary Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Line Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
89	34	PVOS landscape area	24D	42		18" RCP	Line starts at CB on PVOS eastbound approach 1000' west of 500corner to US west of PVOS	SM-OSE-SD-CB3535-OS5529	CB5530 to OS5529	955	955	9/11/14	(Unresponsive City at 150' and 402' No block seen when staff depth is moderate condition)
90	19	PVOS at Corner Dr.	28A	44		18" RCP	Line starts at CB on median east of corner to CB on parking area island		CB5408 to CB5407	73	73	8/11/14	Hard deposits at 54' and 62' from 4 to 6 -10%. Overall pipe is clean and in good condition
91	19	Ferrisall Dr at PVOS	28A	46		18" RCP	Line starts at CB on Ferrisall southbound 115' north of PVOS to US on mainline	SM-OSE-SD-CB2781-JS2783	CB2781 to JS2783	30	30	8/6/14	Concrete lump at 20' from 4 to 5. Exposed rebar at 20'. Overall pipe is clean and in good condition.
92	18	2319 Coll Rd	15D	56		18" CMP	Line starts at CB in front of the property to CB in front of 2312 Coll Rd.	LA-LAE-SD-CB3272-CB3271	CB3272 to CB3271	35	35	6/2/14	Light corrosion. Overall pipe looks in good condition.
93	34	28560 Western Ave	33C	57		30" RCP	Line runs from JS on south side of property to JS LA-LAE-SD-1945734-JS3214, LA-LAE-SD-JS0155-JS45734		JS3214 to JS0155	308.7	309	5/20/14	Grafts at 195
94	13	Newsbridge Dr. LACS	26A	59		30" RCP	Line starts at CB in front of 3482 Newsbridge to Mid in the middle of the road	LA-LAE-SD-CB0105-MH0102	CB0105 to MH0102	31	31	5/20/15	Hard deposits starting at 8' to 18' approx. 5%. Overall line looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
95	15	30444 Cavallera Dr.	26C	60		30" CMP	Line runs in CB in front of property to CB in front of 30443 Cavallera Dr.	SM-OSE-SD-CB0389-CB0411	CB0389 to CB0411	31	31	9/16/14	Hard deposits starting at 22' to 31' (~10%). Overall pipe looks clean and in good condition.
96	21	Montemalaga Dr. East of Grayslake Rd.	4B	6	1958	84" CMP	Pipe runs across Montemalaga Dr. from the North S.M.P.N-SD-633334 to the South S.M.P.N-SD-633335-OS3336	SM-OSE-SD-CB0389-CB0411	IS3333 to OS3336	473	473	6/11/14	Moderate corrosion throughout the pipe. Rocks accumulated - 10% from 200' to 210'. Deposit settled - 40% from 425' to 473' outlet.
97	3	26513 Basswood Ave.	4B	6	~1950	30" CMP	Line runs from CB in front of 26513 Basswood to S.M.P.N-SD-CB1563-CB04134. S.M.P.N-SD-CB04134-OS1564	SM-OSE-SD-CB0389-CB0411	CB1563 to OS1564	630	630	6/10/14	Invert repaired previously throughout the pipe.
98	3	Crest Rd.	12D	25		30" CMP	Line runs from MH (CB1069) approx. 820' from Country Meadows to MH on eastbound	SM-OSW-SD-IS3248-MH1078. S.M-OSW-SD-IS3248	MH1078 to MH1079	91	91	8/14/14	Light to medium corrosion throughout the pipe.
99	4	Crest Rd.	12D	25		30" CMP	Line runs from MH 335' east of Sea Terrace to MH 140' west	SM-OSW-SD-MH1078-MH1079	MH1078 to MH1079	121	121	8/15/14	Light to medium corrosion throughout the pipe.
100	8	Crest Rd.	12D	25		30" CMP	Line runs from MH 335' east of Sea Terrace to MH 140' west	SM-OSW-SD-MH1078-MH1079	MH1078 to MH1079	282	282	8/15/14	Light to medium corrosion throughout the pipe.

S... .. Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
101	8	133 Crest Rd at Sea Terrace	12D	25		18" CIP	Line runs from MH 110 east of Sea Terrace to MH 115 west of the road (Crest eastbound)	SM-OSW-SD-MH1072-MH1242	MH1072 to MH1242	178	178	9/15/14	Light to medium corrosion throughout the pipe
102	7	133 Crest Rd	12D	25		18" CIP	Line runs from MH in the middle of Crest eastbound to MH 110 west	SM-OSW-SD-MH1072-MH1245	MH1072 to MH1245	109	109	9/15/14	Light to medium corrosion throughout the pipe
103	9	146 Hawthorne Blvd at Indian Valley Rd.	13A & 13C	27		18" CIP	Line starts at CB 277 south of Lodienna to Machine	SM-PWV-SD-CB1431-J23815	CB1431 to Machine	15.5	16	8/25/14	Moderate corrosion Overall pipe looks in good condition
104	9	933.5 PVDW at PVDG	22A	34		18" CIP	Line starts at CB by PVDG entrance on PVDW eastbound to 15 in PVDG entrance inline	SM-OWW-SD-US1561-CB36320, SM-OWW-SD-CB36320-OSM135	CB36320 to CB36320	71	71	9/9/14	Top portion of pipe is deformed at 63' (~20%). Light to medium corrosion throughout the pipe
105	18	973 PVDW at PVDG	22A	34		34" RCP	Line runs from CB south of PVDG eastbound to 15 in PVDG entrance inline	SM-OSW-SD-CB5568-CB5569	CB5568 to CB5569	70	70	9/9/14	Deposits settle gravel from 17' to end of pipe (~15%). Pipe has been well previously.
11	1074			35		18" RCP	Line runs from MH in RBF lower the south to Machine's line	SM-OSW-SD-MH2053-J	MH2053 to Machine	208	208	11/18/13	Broken concrete; reinforcement visible at 10 o'clock
1	200	PVDW at Trump National Dr.	26A	45		18" RCP	Line starts at CB southeast corner of intersection to JS on machine	SM-OSW-SD-CB2788-J52789	CB2788 to J52789	85	85	8/7/14	Exposed repair in two areas at 6' (approx. Ø 8"). Overall pipe is clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
2	13	201	13424 Aquia Vista Dr. at Forestal	20B	47		18" RCP	Line starts at CB on Aquia Vista eastbound to CB on westbound	SM-OSE-SD-CB0367-CB0368	CB0367 to CB0368	33	33	8/7/14	Circular/elliptical bulges at 5' (1.5' max). Hard deposits starting at 20' to 33' from 3 to 5.
3	14	201	16602 Monticorns Dr. at Van Kuraan Dr.	33C	57		18" RCP	Line starts at CB in front of property to CB across Monticorns	LALAE-SD-CB0137-CB0138	CB0137 to CB0138	47.5	48	5/20/14	Hard deposits from 28' to 39'. Moderate approx. 10%. Overall the line is clean and in good condition.
4	1	16	Hyile Rd. & Lightfoot Pl	4B	4	1982	24" CMP & 36" RCP	Pipe runs from CB in front of 6003 Lightfoot Pl to MH behind 6007 Via Sonoma property	SM-PVN-SD-CB1070-MH1566, SM-PVN-SD-MH1566-MH1572	CB1070 to MH1572	545	545	6/9/14	Moderate corrosion throughout the pipe
5	3	17	6007 Via Sonoma	4B	4	1982	18" CMP	Pipe runs along 6007 Via Sonoma property from CB at end of cul-de-sac to MH behind property	SM-PVN-SD-CB1067-MH1566	CB1067 to MH1566	100	100	6/9/14	Existing lining is wearing off. Visible corrosion through the pipe
6	3	46	Flumbeau East of Graylake	4D	11	HAVE PLANS 24570	36" RCP & 36" CMP	RCP Pipe runs along center of roadway then transitions to CMP before running along prop line and into canyon drainage	SM-PVN-SD-533396-CB3397, SM-PVN-SD-CB3397-CB1574, SM-PVN-SD-CB1574-CB1574, SM-PVN-SD-CB1574-CB3398, SM-PVN-SD-CB3398-CB1573	CB3397 to CB1573	583	584	6/11/14	RCP line from 0' to 280' (end of RCP line) looks in good condition. 36" CMP starts at 280' and ends at 563.6'. Moderate corrosion throughout.
7	4	66.3	Hawthorne Blvd. / Blackhorse Rd.	5C	15		36" RCP	Line runs from CB on Hawthorne median at Blackhorse to MH on Hawthorne median	ML-RHE-SD-CB1510-MH1489, ML-RHE-SD-MH1489-JS48136, ML-RHE-SD-JS48136-MH1521	CB1510 to MH1521	511	511	9/5/14	Longitudinal crack on both sides of the pipe at 0' to 5'. Joint offset medium at 225'.
8	80	5/200	Modicreses Rd.	73A & 13B	19		18" CMP	Line starts at CB in front of property to CB across ML-RHE SD-JS2664	ML-RHE-SD-JS2663, ML-RHE-SD-JS2683-JS2664	CB1011 to CB1012	26	26	7/30/14	Medium to heavy corrosion throughout the pipe

San Juan Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
9	6	Crestridge Rd. at Crestshaw Blvd	13A	20		30" RCP	Line runs from CB on southwest corner of intersection to MH approx. 245' south of intersection to CB across Crestshaw	ML-RHE-SD-CB1027-MH1001	CB1027 to MH1001	240	240	8/20/14	Hard deposits (minimum) from 216' to 228' Overall pipe looks clean and in good condition.
10	7	Crestshaw Blvd. at Crestridge Rd	13A	20		30" RCP	Line runs from MH approx. 245' south of intersection to MH across Crestshaw northbound	ML-RHE-SD-MH1001-JS21820 ML-RHE-SD-JS21820-MH1001	MH1001 to MH3518	83	83	8/20/14	The RCP lin is clean and in good condition. Line has a small Cdp section from 84' to 97' this section has medium corrosion.
11	8	Crestshaw Blvd. at Crestridge Rd	13A	20		18" RCP	Line runs from CB in the median approx. 212' south of intersection to CB across Crestshaw northbound	ML-RHE-SD-CB1002-CB1022	CB1002 to CB1022	47.5	48	8/21/14	Pipe has a fracture around its circumference at 2' Broken pipe at 1' from 9 to 9 o'clock.
12	9	Del Canto Park on Crestshaw Blvd/Park Pl	13C	22		18" RCP	Line starts at CB in parking lot to CB across Park Pl	SM-OSS-SD-CB00979-CB00979	CB00979 to CB00979	25	25	7/28/14	Circumferential crack at the beginning of the pipe. Overall pipe is in good condition.
13	10	Del Canto Park on Crestshaw Blvd/Park Pl	13C	22		24" RCP	Line runs from CB in parking lot to OS in canyon	SM-OSS-SD-CB00979-CB00980	CB00979 to CB00980	172	7	7/28/14	Overall pipe is in good condition. Standing water at 172 approx. 95' (inspection abandoned).
14	11	Crest Rd. at Highridge Rd	12D	24		30" CSM	Line starts at CB approx. 90' east of intersection to CB approx. 30' west	SM-OSW-SD-CB1061-CB1062	CB1061 to CB1062	27	27	8/18/14	Medium corrosion throughout the pipe
15	12	Crest Rd. at Highridge Rd	12D	24		30" CSM	Line starts at CB intersection to TS on southeast corner of intersection	SM-OSW-SD-CB1062-JS28177	CB1062 to JS28177	183	123	8/18/14	Medium corrosion throughout the pipe

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
16	13	Crest Rte. at Sea Terrace	120	25		30" RCP	Line runs from 181' to the middle of the road (CB eastbound) to MH 130' west in middle of road	SM-OSW-SD-MH3242-MH1079	MH3242 to MH1079	119	119	8/15/14	Medium corrosion throughout the pipe
17	14	Hawthorne Dr. at Los Verdes Dr.	19A	31		24" RCP	Line starts at CB on Hawthorne northbound 295' north of Los Verdes Dr. to CB 30' south	SM-QWW-SD-CB1114-CB1115	CB1114 to CB1115	29	29	8/21/14	Medium to heavy corrosion throughout the pipe
18	15	PVDS at Toronto Dr/Sashill Dr	23A	38		18" RCP	Line runs from CB on southeast corner to IS	SM-OSW-SD-CB6653-J544524	CB6653 to IS6653	32.5	33	9/29/14	Broken pipe at 1' from 10 to 12. Overall pipe is clean and in good condition
19	18	PVDS at Tramonio Dr/Sashill Dr	23A	38		18" RCP	Line runs from IS on southeast corner to CB on Sashill	SM-OSW-SD-J544524-OS6656	IS6653 to OS6656	208	208	8/29/14	Cracked/broken pipe at 175'. Overall pipe is clean and in good condition
20	17	PVDS at Narcissa	24A	40		18" RCP	Line runs from CB across PVDS southbound to CB on median west of runway southbound gate	SM-QSS-SD-CB0702-CB0703	CB0702 to CB0703	44	44	9/8/14	Hard deposits (rocks) from 0' to 16' about -15%
21	18	PVDS at Narcissa	24A	40		24" RCP	Line starts at CB on PVDS southbound (opposite 965' west of runway) to CB on median	CB0703 to CB0703.2	CB0703 to CB0703.2	52	52	9/8/14	Trip breakage including at the beginning of the line. Overall the line looks clean and in good condition
22	19	32423 Aqua Vista Dr. at Forrester	26B & 28A	47		24" RCP	Line runs from CB in front of 32423 Aqua Vista to OS west of PVDS	CB0365 to OS0365 MH	CB0365 to OS0365 MH	436	77	8/7/14	Significant scale and debris at 42.0' from 32.0' to 42.0' inspection. 100' scale. Hard deposits at 42' with 100' inspection. 100' scale. Hard deposits at 42' with 100' inspection. 100' scale. Hard deposits at 42' with 100' inspection. 100' scale.
23	20	Western Ave. @ De La Sonora Dr	33A	50		18" RCP	Line runs from CB on De La Sonora southbound corner of intersection	CB0166 to CB0167	CB0166 to CB0167	63.4	64	5/20/14	Hard deposits from 8' to 9' - Moderate

San Juan Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
24	31	242 River Rd. at cul-de-sac end	15C	55		18" CMP	Line starts at CB at the end of the cul-de-sac to OS behind 26554 River Rd. property	LALAN-SD-CB0997-JS3561-LALAN-SD-JS3561-OS0038	CB0997 to OS0938	220	220	6/2/14	Line from CB0997 to JS3561 at 73.1" has been lined previously (good condition), line from JS3561 to OS0938 is CMP moderate corrosion. Void at 201 ft. Last 15' of pipe has sediment and debris ~25%
25	23	244 28800 PVOE	11C	55		18" CMP	Line starts at CB north of 28800 PVOE to JS on PVOE	LALAN-SD-CB0901-US2709	CB0901 to JS2709	40.8	41	6/23/14	Line runs from CB0901 to OS0902 (medium corrosion)
26	23	246 Saddle Rd. at cul-de-sac end	15D	56		18" CMP	Line starts at CB on cul-de-sac end to OS on 30 Saddle Rd. property	LALAN-SD-CB0927-OS0928	CB0927 to OS0928	201	211	6/2/14	Pipe is lined up to 130.5 ft. Fractured pipe at 109 ft. & at 130 ft. No lining after 130.5 ft. (medium corrosion)
27	24	251 Brielle Ln. at cul-de-sac end	15D	56		18" CMP	Line starts at CB on cul-de-sac end to OS on 8 Brielle Ln. property	LALAE-SD-CB0920-OS0919	CB0920 to OS0919	18.5	180	6/2/14	Medium to heavy corrosion; inspection abandoned due to void at 154 ft.
28	25	253 Western Ave. at Castington Dr.	33C	58		18" CMP	Line starts at CB on Western neighborhood to mainline	LALAE-SD-CB0042-JS45733	CB0042 to Mainline	26	26	9/25/14	Medium corrosion throughout the pipe.
29	1	26307 Silver Spur	1C	1	1955	10" CMP	Pipe runs from CB in front of 26307 Silver Spur to OS in canyon	ML-PVN-SD-CB1800-OS1099	CB1800 to OS1099	125	125	6/4/14	Heavy corrosion throughout the pipe
30	3	OS10 toward SL	2D	3	1960	30" CMP	Pipe runs along center of road from MH in front of 5819 toward to MH in front of 5824 toward to 5824 toward to	ML-PVN-SD-MH1595-MH1592	MH1595 to MH1592	173	173	6/3/14	Heavy corrosion throughout the pipe

Sheet: Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
45	17	Crest Rd. at Hawthorne Blvd.	12C	28		30" CMP	Line runs from CB 1107 east of Hawthorne on Crest eastbound to CB 307 west.	SM-QWW-SD-CB1084-CB1095	CB1084 to CB1095	24	25	8/19/14	Heavy corrosion throughout the pipe.
46	18	Crest Rd. at Hawthorne Blvd.	12C	28		30" CMP	Line runs from CB 807 east of Hawthorne on Crest eastbound to CB 307 west.	SM-QWW-SD-CB1095-CB1089	CB1095 to CB1089	31	31	8/19/14	Heavy corrosion throughout the pipe.
47	18	Crest Rd. at Hawthorne Blvd.	12C	28		30" CMP	Line runs from CB 407 east of Hawthorne on Crest eastbound to JS 511 west of Hawthorne southbound.	SM-QWW-SD-CB1089-JS2001	CB1089 to JS2001	82	82	8/19/14	Heavy corrosion throughout the pipe.
48	18	Hawthorne Blvd. at Crest Rd.	12C	28		36" CMP	Line runs from JS on Hawthorne southbound to JS 505 south.	SM-QWW-SD-JS2001-MJC279	JS2001 to JS279	527	527	8/19/14	Medium to heavy corrosion throughout the pipe.
49	23	Hawthorne Dr. at Los Verdes Dr.	11A & 20B	31		36" CMP	Line runs from CB on Hawthorne northbound 255 north of Los Verdes Dr. to CB across Hawthorne on southbound 295.	SM-QWW-SD-CB1115-CB1154	CB1115 to CB1154	79	79	8/21/14	Heavy corrosion throughout the pipe.
50	23	Hawthorne & PCDW	20C	33		30" RCP & 30" CMP	Line runs from CB at southeast corner to MH at PCDW.	SM-QWW-SD-CB3305-MJC464	CB3305 to MJC464	161	161	8/25/14	The first 10' from CB are RCP; the rest of the pipe is CMP. Heavy corrosion throughout the pipe.
51	23	PVDOS by Parking Lot at Fisherman's Trail	22B	35		48" RCP	Line runs from US on PVDW westbound on at Japanese Garden entrance to CB across medium on PVDOS eastbound.	CB 141154 to CB 141154	CB 141154 to CB 141154	174.6	174.5	1/16/15	Heavy corrosion throughout the pipe.
52	24	PVDOS by Crestmont	22B	35		30" CMP	Line runs from CB 475 west of Crestmont to CB on medium west of Crestmont.	SM-QWW-SD-CB3038-CB3039	CB3038 to CB3039	83.5	84	9/2/14	Medium corrosion throughout the pipe. Hole on left side of pipe at 17'. Large joint offset at 81' (water standing). Medium corrosion throughout the pipe.
53	24	PVDOS at Poppenes	24C	41		24" CMP	Line runs from CB on northwest corner to OS across PVDOS.	SM-QSS-SD-CB0486-CB0489	CB 0486 to 77	111	111	8/20/14	Separated pipe at 111' soil is visible.
54	25	PVDOS at PVDCE	24B & 24D	49		48" RCP	Line starts at JS north of PVDOS (approx. 450' west of PVDOS) to OS south of PVDOS.	SM-QSE-SD-00000-CB2099, SM-QSE-SD-CB2099, TS2019, SM-QSE-SD-TS2019-CB2478	IS2020 to OS2019	363	363	8/11/14	Hole in pipe at 122' rebar is visible from 11 to 1. Joint separation at 168'. The rest of the pipe is in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Please)		Pipe Line No.	Number of Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RFP Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
55	23	28441 P/IDE	234		15A	54		18" RCP	Line runs from CB on P/IDE at Bronco to JS on Bronco at P/IDE	LA-LAN-SD-CB0081-CB3451, LA-LAN-SD-CB3451-US3450	CB0081 to JS3450	54	56	6/3/14	Debris at pipe junction (~50% obstruction); plastic blocking most of the pipe.
56	18	Western Ave. at Caddington Dr.	235		33C	56		30" CMP	Line starts at CB on Western southbound to mainline	LA-LAE-SD-CB0043-JS45732	CB0043 to Mainline	5	50	9/25/14	Inspection abandoned due to hole at the beginning of the pipe.
57	36	5417 Bayridge Rd.	36		1C	1	1955	30" RCP & 24" CMP	Pipe starts at CB in front of 5417 Bayridge to OS on 5507 Graylog St. property	ML-PVN-SD-CB1807-CB1808	CB1808 to OS1810	120	350	6/4/14	The first 85' of line is RCP; the rest is CMP. CMP is heavily corroded. Inspection abandoned due to void at 120'
58	36	5502 Bayridge Rd.	36		1C	1	1955	18" CMP	Pipe starts from CB at end of Bayridge cul-de-sac to OS in the canyon behind property	ML-PVN-SD-CB1803-CB2660, ML-PVN-SD-CB2660-CB2661, ML-PVN-SD-CB2661-OS1602	CB1803 to OS1602	379	379	7/9/14	Heavy corrosion throughout the pipe. Missing invert from 0' to 6'.
59	34	Blackstone Dr. North of Wildomar Dr.	34		3D	2	1960	36" & 48" CMP	Pipe starts at CB in front of 25103 Blackstone to OS in canyon behind property	SM-PVN-SD-CB1614-CB17707, SM-PVN-SD-CB17707-CB17708, SM-PVN-SD-CB17708-TS1597, SM-PVN-SD-TS1597-OS1612	CB1614 to OS1612	221	445	6/4/14	Heavy corrosion & voids throughout the pipe. Inspection abandoned due to hole at 221.5'
60	42	25101 Blackwood Ave.	42		1C	2	1955	18" CMP	Pipe runs along 25101 Blackwood property from OS in canyon behind property to OS in canyon behind property	SM-PVN-SD-CB1613-GB2655, SM-PVN-SD-GB2655-GB2666, SM-PVN-SD-GB2666-JS1598, SM-PVN-SD-JS1598-GB2667, SM-PVN-SD-GB2667-GB2668, SM-PVN-SD-GB2668-OS1611, SM-PVN-SD-OS1611-OS1612, SM-PVN-SD-OS1612-OS1613, SM-PVN-SD-OS1613-OS1614, SM-PVN-SD-OS1614-OS1615	CB1613 to OS1611	199	500	6/5/14	Heavy corrosion throughout the pipe. Regions of missing invert throughout. Inspection abandoned due to hole at 198.8'
61	2	5828 Montemalaga Dr.	2		2D	3	1962	30" CMP	Line runs from CB in front of 5828 Montemalaga Dr. to OS in canyon behind property	SM-PVN-SD-CB1508-CB1509	CB1508 to CB1509	49	75	6/3/14	Heavy corrosion throughout the pipe. Inspection abandoned missing invert from 48.9' to end of pipe.

San Jose Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
62	14	Montezuma Dr.	2D	3	1960	30" CMP	Line runs from CB on Montezuma westbound below S&D Ironwood St. to MH in front of S&D Ironwood St.	SM-PVN-SD-CB1588-MH1590	CB1589 to MH1590	125	125	6/9/14	Heavy corrosion throughout the pipe. Inspection abandoned due to missing invert from 122.8' to - end of pipe
63	15	5424 Ironwood	2D	3	1960	30" CMP	Line runs from MH in front of 5424 Ironwood to MH in corner of 5413 Ironwood property	SM-PVN-SD-MH1592-JB3558, SM-PVN-SD-JB3559-MH1592	MH1592 to MH1595	298	298	6/9/14	Heavy corrosion throughout the pipe. Invert is lifted up at 273'
64	16	26600 Lightfoot Pl	4B	5	1958	30" RCP & 30" CMP	Pipe runs along 26600 Lightfoot to OS in canyon. Line runs from OS to S&D removed St. to MH in front of S&D Ironwood St.	SM-PVN-SD-CB3276-GB3279, SM-PVN-SD-GB3279-MH1527, SM-PVN-SD-MH1527 to OS1565, SM-PVN-SD-OS1565 to S&D removed St. to MH in front of S&D Ironwood St.	CB3278 to OS1565	260	275	6/9/14	First 125' of pipe is RCP in good condition. CMP starts at 125'. Heavily corroded. Two metal trash lids at 176'. Hole on top of pipe at 186' (small not penetrating). Outlet hooking water back. Inspection abandoned at 260'.
65	17	25609 Graylake Rd.	4B	5	1958	24" CMP	MH in canyon behind 26603 Montezuma Pl property	SM-PVN-SD-TS3284-GB3285, SM-PVN-SD-GB3285-MH1527	CB3281 to MH3277	99	220	6/9/14	Heavy corrosion throughout the pipe. Video inspection abandoned due to missing invert after 99'
66	18	26504 Mazur	4B	6	1965	18" CMP	Pipe runs along properties 26504 Mazur & 26551 Basewood from CB at end of Mazur cul-de-sac to GB2770, OS in front of Basewood property	SM-PVN-SD-CB2767-GB2769, SM-PVN-SD-GB2769-GB2770, SM-PVN-SD-GB2770-TS2771, SM-PVN-SD-TS2771-OS2772	CB2767 to OS2772	122	150	6/10/14	Heavy corrosion throughout the pipe. Inspection abandoned due to holes at 122'
67	19	5349 Whittier Dr.	5A	7	1955	18" CMP	Line starts at CB in front of 5349 Whittier to CB in front of 5420 Montezuma	ML-PVN-SD-CB1551-GB3558, ML-PVN-SD-GB3558-CB1552	CB1551 to CB1552	221	221	6/10/14	Heavy corrosion and holes throughout the pipe. RCP ends at 235 ft. 30" CMP starts at 235' (missing invert); inspection abandoned
68	20	5108 Elmer Dr.	5C	9		30" RCP & 30" CMP	Line runs along Elmer and along 5103 & 5107 Elmer properties to the canyon. Line runs from OS to S&D removed St. to MH in front of S&D Ironwood St.	ML-PNE-SD-GB1540-MC3434, ML-PNE-SD-MC3434-GB3435, ML-PNE-SD-GB3435-OS1538	CB1542 to OS1538	215	390	6/20/14	

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

$\mathcal{H}^1$ $\mathcal{H}^2$ $\mathcal{H}^3$ $\mathcal{H}^4$ $\mathcal{H}^5$ $\mathcal{H}^6$ $\mathcal{H}^7$ $\mathcal{H}^8$ $\mathcal{H}^9$ $\mathcal{H}^{10}$ $\mathcal{H}^{11}$ $\mathcal{H}^{12}$ $\mathcal{H}^{13}$ $\mathcal{H}^{14}$ $\mathcal{H}^{15}$ $\mathcal{H}^{16}$ $\mathcal{H}^{17}$ $\mathcal{H}^{18}$ $\mathcal{H}^{19}$ $\mathcal{H}^{20}$ $\mathcal{H}^{21}$ $\mathcal{H}^{22}$ $\mathcal{H}^{23}$ $\mathcal{H}^{24}$ $\mathcal{H}^{25}$ $\mathcal{H}^{26}$ $\mathcal{H}^{27}$ $\mathcal{H}^{28}$ $\mathcal{H}^{29}$ $\mathcal{H}^{30}$ $\mathcal{H}^{31}$ $\mathcal{H}^{32}$ $\mathcal{H}^{33}$ $\mathcal{H}^{34}$ $\mathcal{H}^{35}$ $\mathcal{H}^{36}$ $\mathcal{H}^{37}$ $\mathcal{H}^{38}$ $\mathcal{H}^{39}$ $\mathcal{H}^{40}$ $\mathcal{H}^{41}$ $\mathcal{H}^{42}$ $\mathcal{H}^{43}$ $\mathcal{H}^{44}$ $\mathcal{H}^{45}$ $\mathcal{H}^{46}$ $\mathcal{H}^{47}$ $\mathcal{H}^{48}$ $\mathcal{H}^{49}$ $\mathcal{H}^{50}$ $\mathcal{H}^{51}$ $\mathcal{H}^{52}$ $\mathcal{H}^{53}$ $\mathcal{H}^{54}$ $\mathcal{H}^{55}$ $\mathcal{H}^{56}$ $\mathcal{H}^{57}$ $\mathcal{H}^{58}$ $\mathcal{H}^{59}$ $\mathcal{H}^{60}$ $\mathcal{H}^{61}$ $\mathcal{H}^{62}$ $\mathcal{H}^{63}$ $\mathcal{H}^{64}$ $\mathcal{H}^{65}$ $\mathcal{H}^{66}$ $\mathcal{H}^{67}$ $\mathcal{H}^{68}$ $\mathcal{H}^{69}$ $\mathcal{H}^{70}$ $\mathcal{H}^{71}$ $\mathcal{H}^{72}$ $\mathcal{H}^{73}$ $\mathcal{H}^{74}$ $\mathcal{H}^{75}$ $\mathcal{H}^{76}$ $\mathcal{H}^{77}$ $\mathcal{H}^{78}$ $\mathcal{H}^{79}$ $\mathcal{H}^{80}$ $\mathcal{H}^{81}$ $\mathcal{H}^{82}$ $\mathcal{H}^{83}$ $\mathcal{H}^{84}$ $\mathcal{H}^{85}$ $\mathcal{H}^{86}$ $\mathcal{H}^{87}$ $\mathcal{H}^{88}$ $\mathcal{H}^{89}$ $\mathcal{H}^{90}$ $\mathcal{H}^{91}$ $\mathcal{H}^{92}$ $\mathcal{H}^{93}$ $\mathcal{H}^{94}$ $\mathcal{H}^{95}$ $\mathcal{H}^{96}$ $\mathcal{H}^{97}$ $\mathcal{H}^{98}$ $\mathcal{H}^{99}$ $\mathcal{H}^{100}$

San Juan County Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
75	4	46	4 Amber Sky Dr.	13D	22		18" CMP	Line starts at CB in front of property to CS in front of 5 Amber Sky	SM-OSS-SD-CB00971-CB00972	CB00971 to CB00972	34	34	7/28/14	Heavy corrosion throughout the pipe. Invert is starting to stack after the pipe length at 6 and 8 o'clock.
76	2	37	5 Amber Sky Dr.	13C	22		18" CMP	Line runs from CB in front of property to MH on Crestview trail adjacent to 8 Burnell home	SM-OSS-SD-MH00971-MH00972, SM-OSS-SD-CB00972-MH00971	MH00971 to CB00972	162	250	7/28/14	Heavy corrosion throughout the pipe. There is an open catch basin that was not inspected. The video was taken from MH00971 towards CB00972 to complete the inspection for the whole segment. Inspection was abandoned before MH00971 due to hole in the pipe.
77	4	114	Burnell Ln. cul-de-sac	13C & 18 A	22		18" CMP	Line starts at CB at end of cul-de-sac to CS in canyon	SM-OSS-SD-CB00975-CB00974	CB00975 to CB00974	84.5	-370	7/28/14	Heavy corrosion through out the pipe. Hole on invert at 18.5'. Video inspection abandoned due to drop in pipe at 84.5'.
78	2	114	Crest Rd.	12D	25		30" CMP	Line starts at CB approx. 700' from Country Meadows to CB 40' west	SM-OSS-SD-CB1067-CB1068	CB1067 to CB1068	36	36	8/14/14	Severe corrosion throughout the pipe.
79	1	122	Crest Rd.	12D	25		30" CMP	Line runs from CB approx. 650' from Country Meadows to MH (CB1069) 40' west	SM-OSS-SD-CB1069-MH1069	CB1069 to CB1069	41	41	8/14/14	Severe corrosion throughout the pipe.
80	2	122	35003 Rue Langlois	20A & 11C	25		30" CMP	Line runs from CB in front of property to JS behind property	SM-OSS-SD-CB3302-CB3304, SM-OSS-SD-CB3304-CB3305, SM-OSS-SD-CB3305-CB3307, SM-OSS-SD-CB3307-CB3308, SM-OSS-SD-CB3308-CB3309, SM-OSS-SD-CB3309-CB3310, SM-OSS-SD-CB3310-CB3311, SM-OSS-SD-CB3311-CB3312	CB3302 to CB3303	264	265	7/23/14	Heavy corrosion throughout the pipe. Holes in pipe at 246'. Missing invert starting at 263' to JS. Inspection abandoned.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
81	83	186	ESOM Sales Dr	19A	32		30" CMP	Line runs from CB in front of property to OS in street	PIPE FOUND: SM-OSW-SD-GB1885-OS0783, SM-OSW-SD-GB0764-GB1885, SM-OSW-SD-GB1894-GB0764, SM-OSW-SD-GB1893-GB1894, SM-OSW-SD-GB1895-GB1894, SM-OSW-SD-GB1896-GB1894, SM-OSW-SD-GB1897-GB1894, SM-OSW-SD-GB1898-GB1894, SM-OSW-SD-GB1899-GB1894, SM-OSW-SD-GB1900-GB1894, SM-OSW-SD-GB1901-GB1894, SM-OSW-SD-GB1902-GB1894, SM-OSW-SD-GB1903-GB1894, SM-OSW-SD-GB1904-GB1894, SM-OSW-SD-GB1905-GB1894, SM-OSW-SD-GB1906-GB1894, SM-OSW-SD-GB1907-GB1894, SM-OSW-SD-GB1908-GB1894, SM-OSW-SD-GB1909-GB1894, SM-OSW-SD-GB1910-GB1894, SM-OSW-SD-GB1911-GB1894, SM-OSW-SD-GB1912-GB1894, SM-OSW-SD-GB1913-GB1894, SM-OSW-SD-GB1914-GB1894, SM-OSW-SD-GB1915-GB1894, SM-OSW-SD-GB1916-GB1894, SM-OSW-SD-GB1917-GB1894, SM-OSW-SD-GB1918-GB1894, SM-OSW-SD-GB1919-GB1894, SM-OSW-SD-GB1920-GB1894, SM-OSW-SD-GB1921-GB1894, SM-OSW-SD-GB1922-GB1894, SM-OSW-SD-GB1923-GB1894, SM-OSW-SD-GB1924-GB1894, SM-OSW-SD-GB1925-GB1894, SM-OSW-SD-GB1926-GB1894, SM-OSW-SD-GB1927-GB1894, SM-OSW-SD-GB1928-GB1894, SM-OSW-SD-GB1929-GB1894, SM-OSW-SD-GB1930-GB1894, SM-OSW-SD-GB1931-GB1894, SM-OSW-SD-GB1932-GB1894, SM-OSW-SD-GB1933-GB1894, SM-OSW-SD-GB1934-GB1894, SM-OSW-SD-GB1935-GB1894, SM-OSW-SD-GB1936-GB1894, SM-OSW-SD-GB1937-GB1894, SM-OSW-SD-GB1938-GB1894, SM-OSW-SD-GB1939-GB1894, SM-OSW-SD-GB1940-GB1894, SM-OSW-SD-GB1941-GB1894, SM-OSW-SD-GB1942-GB1894, SM-OSW-SD-GB1943-GB1894, SM-OSW-SD-GB1944-GB1894, SM-OSW-SD-GB1945-GB1894, SM-OSW-SD-GB1946-GB1894, SM-OSW-SD-GB1947-GB1894, SM-OSW-SD-GB1948-GB1894, SM-OSW-SD-GB1949-GB1894, SM-OSW-SD-GB1950-GB1894, SM-OSW-SD-GB1951-GB1894, SM-OSW-SD-GB1952-GB1894, SM-OSW-SD-GB1953-GB1894, SM-OSW-SD-GB1954-GB1894, SM-OSW-SD-GB1955-GB1894, SM-OSW-SD-GB1956-GB1894, SM-OSW-SD-GB1957-GB1894, SM-OSW-SD-GB1958-GB1894, SM-OSW-SD-GB1959-GB1894, SM-OSW-SD-GB1960-GB1894, SM-OSW-SD-GB1961-GB1894, SM-OSW-SD-GB1962-GB1894, SM-OSW-SD-GB1963-GB1894, SM-OSW-SD-GB1964-GB1894, SM-OSW-SD-GB1965-GB1894, SM-OSW-SD-GB1966-GB1894, SM-OSW-SD-GB1967-GB1894, SM-OSW-SD-GB1968-GB1894, SM-OSW-SD-GB1969-GB1894, SM-OSW-SD-GB1970-GB1894, SM-OSW-SD-GB1971-GB1894, SM-OSW-SD-GB1972-GB1894, SM-OSW-SD-GB1973-GB1894, SM-OSW-SD-GB1974-GB1894, SM-OSW-SD-GB1975-GB1894, SM-OSW-SD-GB1976-GB1894, SM-OSW-SD-GB1977-GB1894, SM-OSW-SD-GB1978-GB1894, SM-OSW-SD-GB1979-GB1894, SM-OSW-SD-GB1980-GB1894, SM-OSW-SD-GB1981-GB1894, SM-OSW-SD-GB1982-GB1894, SM-OSW-SD-GB1983-GB1894, SM-OSW-SD-GB1984-GB1894, SM-OSW-SD-GB1985-GB1894, SM-OSW-SD-GB1986-GB1894, SM-OSW-SD-GB1987-GB1894, SM-OSW-SD-GB1988-GB1894, SM-OSW-SD-GB1989-GB1894, SM-OSW-SD-GB1990-GB1894, SM-OSW-SD-GB1991-GB1894, SM-OSW-SD-GB1992-GB1894, SM-OSW-SD-GB1993-GB1894, SM-OSW-SD-GB1994-GB1894, SM-OSW-SD-GB1995-GB1894, SM-OSW-SD-GB1996-GB1894, SM-OSW-SD-GB1997-GB1894, SM-OSW-SD-GB1998-GB1894, SM-OSW-SD-GB1999-GB1894, SM-OSW-SD-GB2000-GB1894, SM-OSW-SD-GB2001-GB1894, SM-OSW-SD-GB2002-GB1894, SM-OSW-SD-GB2003-GB1894, SM-OSW-SD-GB2004-GB1894, SM-OSW-SD-GB2005-GB1894, SM-OSW-SD-GB2006-GB1894, SM-OSW-SD-GB2007-GB1894, SM-OSW-SD-GB2008-GB1894, SM-OSW-SD-GB2009-GB1894, SM-OSW-SD-GB2010-GB1894, SM-OSW-SD-GB2011-GB1894, SM-OSW-SD-GB2012-GB1894, SM-OSW-SD-GB2013-GB1894, SM-OSW-SD-GB2014-GB1894, SM-OSW-SD-GB2015-GB1894, SM-OSW-SD-GB2016-GB1894, SM-OSW-SD-GB2017-GB1894, SM-OSW-SD-GB2018-GB1894, SM-OSW-SD-GB2019-GB1894, SM-OSW-SD-GB2020-GB1894, SM-OSW-SD-GB2021-GB1894, SM-OSW-SD-GB2022-GB1894, SM-OSW-SD-GB2023-GB1894, SM-OSW-SD-GB2024-GB1894, SM-OSW-SD-GB2025-GB1894, SM-OSW-SD-GB2026-GB1894, SM-OSW-SD-GB2027-GB1894, SM-OSW-SD-GB2028-GB1894, SM-OSW-SD-GB2029-GB1894, SM-OSW-SD-GB2030-GB1894, SM-OSW-SD-GB2031-GB1894, SM-OSW-SD-GB2032-GB1894, SM-OSW-SD-GB2033-GB1894, SM-OSW-SD-GB2034-GB1894, SM-OSW-SD-GB2035-GB1894, SM-OSW-SD-GB2036-GB1894, SM-OSW-SD-GB2037-GB1894, SM-OSW-SD-GB2038-GB1894, SM-OSW-SD-GB2039-GB1894, SM-OSW-SD-GB2040-GB1894, SM-OSW-SD-GB2041-GB1894, SM-OSW-SD-GB2042-GB1894, SM-OSW-SD-GB2043-GB1894, SM-OSW-SD-GB2044-GB1894, SM-OSW-SD-GB2045-GB1894, SM-OSW-SD-GB2046-GB1894, SM-OSW-SD-GB2047-GB1894, SM-OSW-SD-GB2048-GB1894, SM-OSW-SD-GB2049-GB1894, SM-OSW-SD-GB2050-GB1894, SM-OSW-SD-GB2051-GB1894, SM-OSW-SD-GB2052-GB1894, SM-OSW-SD-GB2053-GB1894, SM-OSW-SD-GB2054-GB1894, SM-OSW-SD-GB2055-GB1894, SM-OSW-SD-GB2056-GB1894, SM-OSW-SD-GB2057-GB1894, SM-OSW-SD-GB2058-GB1894, SM-OSW-SD-GB2059-GB1894, SM-OSW-SD-GB2060-GB1894, SM-OSW-SD-GB2061-GB1894, SM-OSW-SD-GB2062-GB1894, SM-OSW-SD-GB2063-GB1894, SM-OSW-SD-GB2064-GB1894, SM-OSW-SD-GB2065-GB1894, SM-OSW-SD-GB2066-GB1894, SM-OSW-SD-GB2067-GB1894, SM-OSW-SD-GB2068-GB1894, SM-OSW-SD-GB2069-GB1894, SM-OSW-SD-GB2070-GB1894, SM-OSW-SD-GB2071-GB1894, SM-OSW-SD-GB2072-GB1894, SM-OSW-SD-GB2073-GB1894, SM-OSW-SD-GB2074-GB1894, SM-OSW-SD-GB2075-GB1894, SM-OSW-SD-GB2076-GB1894, SM-OSW-SD-GB2077-GB1894, SM-OSW-SD-GB2078-GB1894, SM-OSW-SD-GB2079-GB1894, SM-OSW-SD-GB2080-GB1894, SM-OSW-SD-GB2081-GB1894, SM-OSW-SD-GB2082-GB1894, SM-OSW-SD-GB2083-GB1894, SM-OSW-SD-GB2084-GB1894, SM-OSW-SD-GB2085-GB1894, SM-OSW-SD-GB2086-GB1894, SM-OSW-SD-GB2087-GB1894, SM-OSW-SD-GB2088-GB1894, SM-OSW-SD-GB2089-GB1894, SM-OSW-SD-GB2090-GB1894, SM-OSW-SD-GB2091-GB1894, SM-OSW-SD-GB2092-GB1894, SM-OSW-SD-GB2093-GB1894, SM-OSW-SD-GB2094-GB1894, SM-OSW-SD-GB2095-GB1894, SM-OSW-SD-GB2096-GB1894, SM-OSW-SD-GB2097-GB1894, SM-OSW-SD-GB2098-GB1894, SM-OSW-SD-GB2099-GB1894, SM-OSW-SD-GB2100-GB1894, SM-OSW-SD-GB2101-GB1894, SM-OSW-SD-GB2102-GB1894, SM-OSW-SD-GB2103-GB1894, SM-OSW-SD-GB2104-GB1894, SM-OSW-SD-GB2105-GB1894, SM-OSW-SD-GB2106-GB1894, SM-OSW-SD-GB2107-GB1894, SM-OSW-SD-GB2108-GB1894, SM-OSW-SD-GB2109-GB1894, SM-OSW-SD-GB2110-GB1894, SM-OSW-SD-GB2111-GB1894, SM-OSW-SD-GB2112-GB1894, SM-OSW-SD-GB2113-GB1894, SM-OSW-SD-GB2114-GB1894, SM-OSW-SD-GB2115-GB1894, SM-OSW-SD-GB2116-GB1894, SM-OSW-SD-GB2117-GB1894, SM-OSW-SD-GB2118-GB1894, SM-OSW-SD-GB2119-GB1894, SM-OSW-SD-GB2120-GB1894, SM-OSW-SD-GB2121-GB1894, SM-OSW-SD-GB2122-GB1894, SM-OSW-SD-GB2123-GB1894, SM-OSW-SD-GB2124-GB1894, SM-OSW-SD-GB2125-GB1894, SM-OSW-SD-GB2126-GB1894, SM-OSW-SD-GB2127-GB1894, SM-OSW-SD-GB2128-GB1894, SM-OSW-SD-GB2129-GB1894, SM-OSW-SD-GB2130-GB1894, SM-OSW-SD-GB2131-GB1894, SM-OSW-SD-GB2132-GB1894, SM-OSW-SD-GB2133-GB1894, SM-OSW-SD-GB2134-GB1894, SM-OSW-SD-GB2135-GB1894, SM-OSW-SD-GB2136-GB1894, SM-OSW-SD-GB2137-GB1894, SM-OSW-SD-GB2138-GB1894, SM-OSW-SD-GB2139-GB1894, SM-OSW-SD-GB2140-GB1894, SM-OSW-SD-GB2141-GB1894, SM-OSW-SD-GB2142-GB1894, SM-OSW-SD-GB2143-GB1894, SM-OSW-SD-GB2144-GB1894, SM-OSW-SD-GB2145-GB1894, SM-OSW-SD-GB2146-GB1894, SM-OSW-SD-GB2147-GB1894, SM-OSW-SD-GB2148-GB1894, SM-OSW-SD-GB2149-GB1894, SM-OSW-SD-GB2150-GB1894, SM-OSW-SD-GB2151-GB1894, SM-OSW-SD-GB2152-GB1894, SM-OSW-SD-GB2153-GB1894, SM-OSW-SD-GB2154-GB1894, SM-OSW-SD-GB2155-GB1894, SM-OSW-SD-GB2156-GB1894, SM-OSW-SD-GB2157-GB1894, SM-OSW-SD-GB2158-GB1894, SM-OSW-SD-GB2159-GB1894, SM-OSW-SD-GB2160-GB1894, SM-OSW-SD-GB2161-GB1894, SM-OSW-SD-GB2162-GB1894, SM-OSW-SD-GB2163-GB1894, SM-OSW-SD-GB2164-GB1894, SM-OSW-SD-GB2165-GB1894, SM-OSW-SD-GB2166-GB1894, SM-OSW-SD-GB2167-GB1894, SM-OSW-SD-GB2168-GB1894, SM-OSW-SD-GB2169-GB1894, SM-OSW-SD-GB2170-GB1894, SM-OSW-SD-GB2171-GB1894, SM-OSW-SD-GB2172-GB1894, SM-OSW-SD-GB2173-GB1894, SM-OSW-SD-GB2174-GB1894, SM-OSW-SD-GB2175-GB1894, SM-OSW-SD-GB2176-GB1894, SM-OSW-SD-GB2177-GB1894, SM-OSW-SD-GB2178-GB1894, SM-OSW-SD-GB2179-GB1894, SM-OSW-SD-GB2180-GB1894, SM-OSW-SD-GB2181-GB1894, SM-OSW-SD-GB2182-GB1894, SM-OSW-SD-GB2183-GB1894, SM-OSW-SD-GB2184-GB1894, SM-OSW-SD-GB2185-GB1894, SM-OSW-SD-GB2186-GB1894, SM-OSW-SD-GB2187-GB1894, SM-OSW-SD-GB2188-GB1894, SM-OSW-SD-GB2189-GB1894, SM-OSW-SD-GB2190-GB1894, SM-OSW-SD-GB2191-GB1894, SM-OSW-SD-GB2192-GB1894, SM-OSW-SD-GB2193-GB1894, SM-OSW-SD-GB2194-GB1894, SM-OSW-SD-GB2195-GB1894, SM-OSW-SD-GB2196-GB1894, SM-OSW-SD-GB2197-GB1894, SM-OSW-SD-GB2198-GB1894, SM-OSW-SD-GB2199-GB1894, SM-OSW-SD-GB2200-GB1894, SM-OSW-SD-GB2201-GB1894, SM-OSW-SD-GB2202-GB1894, SM-OSW-SD-GB2203-GB1894, SM-OSW-SD-GB2204-GB1894, SM-OSW-SD-GB2205-GB1894, SM-OSW-SD-GB2206-GB1894, SM-OSW-SD-GB2207-GB1894, SM-OSW-SD-GB2208-GB1894, SM-OSW-SD-GB2209-GB1894, SM-OSW-SD-GB2210-GB1894, SM-OSW-SD-GB2211-GB1894, SM-OSW-SD-GB2212-GB1894, SM-OSW-SD-GB2213-GB1894, SM-OSW-SD-GB2214-GB1894, SM-OSW-SD-GB2215-GB1894, SM-OSW-SD-GB2216-GB1894, SM-OSW-SD-GB2217-GB1894, SM-OSW-SD-GB2218-GB1894, SM-OSW-SD-GB2219-GB1894, SM-OSW-SD-GB2220-GB1894, SM-OSW-SD-GB2221-GB1894, SM-OSW-SD-GB2222-GB1894, SM-OSW-SD-GB2223-GB1894, SM-OSW-SD-GB2224-GB1894, SM-OSW-SD-GB2225-GB1894, SM-OSW-SD-GB2226-GB1894, SM-OSW-SD-GB2227-GB1894, SM-OSW-SD-GB2228-GB1894, SM-OSW-SD-GB2229-GB1894, SM-OSW-SD-GB2230-GB1894, SM-OSW-SD-GB2231-GB1894, SM-OSW-SD-GB2232-GB1894, SM-OSW-SD-GB2233-GB1894, SM-OSW-SD-GB2234-GB1894, SM-OSW-SD-GB2235-GB1894, SM-OSW-SD-GB2236-GB1894, SM-OSW-SD-GB2237-GB1894, SM-OSW-SD-GB2238-GB1894, SM-OSW-SD-GB2239-GB1894, SM-OSW-SD-GB2240-GB1894, SM-OSW-SD-GB2241-GB1894, SM-OSW-SD-GB2242-GB1894, SM-OSW-SD-GB2243-GB1894, SM-OSW-SD-GB2244-GB1894, SM-OSW-SD-GB2245-GB1894, SM-OSW-SD-GB2246-GB1894, SM-OSW-SD-GB2247-GB1894, SM-OSW-SD-GB2248-GB1894, SM-OSW-SD-GB2249-GB1894, SM-OSW-SD-GB2250-GB1894, SM-OSW-SD-GB2251-GB1894, SM-OSW-SD-GB2252-GB1894, SM-OSW-SD-GB2253-GB1894, SM-OSW-SD-GB2254-GB1894, SM-OSW-SD-GB2255-GB1894, SM-OSW-SD-GB2256-GB1894, SM-OSW-SD-GB2257-GB1894, SM-OSW-SD-GB2258-GB1894, SM-OSW-SD-GB2259-GB1894, SM-OSW-SD-GB2260-GB1894, SM-OSW-SD-GB2261-GB1894, SM-OSW-SD-GB2262-GB1894, SM-OSW-SD-GB2263-GB1894, SM-OSW-SD-GB2264-GB1894, SM-OSW-SD-GB2265-GB1894, SM-OSW-SD-GB2266-GB1894, SM-OSW-SD-GB2267-GB1894, SM-OSW-SD-GB2268-GB1894, SM-OSW-SD-GB2269-GB1894, SM-OSW-SD-GB2270-GB1894, SM-OSW-SD-GB2271-GB1894, SM-OSW-SD-GB2272-GB1894, SM-OSW-SD-GB2273-GB1894, SM-OSW-SD-GB2274-GB1894, SM-OSW-SD-GB2275-GB1894, SM-OSW-SD-GB2276-GB1894, SM-OSW-SD-GB2277-GB1894, SM-OSW-SD-GB2278-GB1894, SM-OSW-SD-GB2279-GB1894, SM-OSW-SD-GB2280-GB1894, SM-OSW-SD-GB2281-GB1894, SM-OSW-SD-GB2282-GB1894, SM-OSW-SD-GB2283-GB1894, SM-OSW-SD-GB2284-GB1894, SM-OSW-SD-GB2285-GB1894, SM-OSW-SD-GB2286-GB1894, SM-OSW-SD-GB2287-GB1894, SM-OSW-SD-GB2288-GB1894, SM-OSW-SD-GB2289-GB1894, SM-OSW-SD-GB2290-GB1894, SM-OSW-SD-GB2291-GB1894, SM-OSW-SD-GB2292-GB1894, SM-OSW-SD-GB2293-GB1894, SM-OSW-SD-GB2294-GB1894, SM-OSW-SD-GB2295-GB1894, SM-OSW-SD-GB2296-GB1894, SM-OSW-SD-GB2297-GB1894, SM-OSW-SD-GB2298-GB1894, SM-OSW-SD-GB2299-GB1894, SM-OSW-SD-GB2300-GB1894, SM-OSW-SD-GB2301-GB1894, SM-OSW-SD-GB2302-GB1894, SM-OSW-SD-GB2303-GB1894, SM-OSW-SD-GB2304-GB1894, SM-OSW-SD-GB2305-GB1894, SM-OSW-SD-GB2306-GB1894, SM-OSW-SD-GB2307-GB1894, SM-OSW-SD-GB2308-GB1894, SM-OSW-SD-GB2309-GB1894, SM-OSW-SD-GB2310-GB1894, SM-OSW-SD-GB2311-GB1894, SM-OSW-SD-GB2312-GB1894, SM-OSW-SD-GB2313-GB1894, SM-OSW-SD-GB2314-GB1894, SM-OSW-SD-GB2315-GB1894, SM-OSW-SD-GB2316-GB1894, SM-OSW-SD-GB2317-GB1894, SM-OSW-SD-GB2318-GB1894, SM-OSW-SD-GB2319-GB1894, SM-OSW-SD-GB2320-GB1894, SM-OSW-SD-GB2321-GB1894, SM-OSW-SD-GB2322-GB1894, SM-OSW-SD-GB2323-GB1894, SM-OSW-SD-GB2324-GB1894, SM-OSW-SD-GB2325-GB1894, SM-OSW-SD-GB2326-GB1894, SM-OSW-SD-GB2327-GB1894, SM-OSW-SD-GB2328-GB1894, SM-OSW-SD-GB2329-GB1894, SM-OSW-SD-GB2330-GB1894, SM-OSW-SD-GB2331-GB1894, SM-OSW-SD-GB2332-GB1894, SM-OSW-SD-GB2333-GB1894, SM-OSW-SD-GB2334-GB1894, SM-OSW-SD-GB2335-GB1894, SM-OSW-SD-GB2336-GB1894, SM-OSW-SD-GB2337-GB1894, SM-OSW-SD-GB2338-GB1894, SM-OSW-SD-GB2339-GB1894, SM-OSW-SD-GB2340-GB1894, SM-OSW-SD-GB2341-GB1894, SM-OSW-SD-GB2342-GB1894, SM-OSW-SD-GB2343-GB1894, SM-OSW-SD-GB2344-GB1894, SM-OSW-SD-GB2345-GB1894, SM-OSW-SD-GB2346-GB1894, SM-OSW-SD-GB2347-GB1894, SM-OSW-SD-GB2348-GB1894, SM-OSW-SD-GB2349-GB1894, SM-OSW-SD-GB2350-GB1894, SM-OSW-SD-GB2351-GB1894, SM-OSW-SD-GB2352-GB1894, SM-OSW-SD-GB2353-GB1894, SM-OSW-SD-GB2354-GB1894, SM-OSW-SD-GB2355-GB1894, SM-OSW-SD-GB2356-GB1894, SM-OSW-SD-GB2357-GB1894, SM-OSW-SD-GB2358-GB1894, SM-OSW-SD-GB2359-GB1894, SM-OSW-SD-GB2360-GB1894, SM-OSW-SD-GB2361-GB1894, SM-OSW-SD-GB2362-GB1894, SM-OSW-SD-GB2363-GB1894, SM-OSW-SD-GB2364-GB1894, SM-OSW-SD-GB2365-GB1894, SM-OSW-SD-GB2366-GB1894, SM-OSW-SD-GB2367-GB1894, SM-OSW-SD-GB2368-GB1894, SM-OSW-SD-GB2369-GB1894, SM-OSW-SD-GB2370-GB1894, SM-OSW-SD-GB2371-GB1894, SM-OSW-SD-GB2372-GB1894, SM-OSW-SD-GB2373-GB1894, SM-OSW-SD-GB2374-GB1894, SM-OSW-SD-GB2375-GB1894, SM-OSW-SD-GB2376-GB1894, SM-OSW-SD-GB2377-GB1894, SM-OSW-SD-GB2378-GB1894, SM-OSW-SD-GB2379-GB1894, SM-OSW-SD-GB2380-GB1894, SM-OSW-SD-GB2381-GB1894, SM-OSW-SD-GB2382-GB1894, SM-OSW-SD-GB2383-GB1894, SM-OSW-SD-GB2384-GB1894, SM-OSW-SD-GB2385-GB1894, SM-OSW-SD-GB2386-GB1894, SM-OSW-SD-GB2387-GB1894, SM-OSW-SD-GB2388-GB1894, SM-OSW-SD-GB2389-GB1894, SM-OSW-SD-GB2390-GB1894, SM-OSW-SD-GB2391-GB1894, SM-OSW-SD-GB2392-GB1894, SM-OSW-SD-GB2393-GB1894, SM-OSW-SD-GB2394-GB1894, SM-OSW-SD-GB2395-GB1894, SM-OSW-SD-GB2396-GB1894, SM-OSW-SD-GB2397-GB1894, SM-OSW-SD-GB2398-GB1894, SM-OSW-SD-GB2399-GB1894, SM-OSW-SD-GB2400-GB1894, SM-OSW-SD-GB2401-GB1894, SM-OSW-SD-GB2402-GB1894, SM-OSW-SD-GB2403-GB1894, SM-OSW-SD-GB2404-GB1894, SM-OSW-SD-GB2405-GB1894, SM-OSW-SD-GB2406-GB1894, SM-OSW-SD-GB2407-GB1894, SM-OSW-SD-GB2408-GB1894, SM-OSW-SD-GB2409-GB1894, SM-OSW-SD-GB2410-GB1894, SM-OSW-SD-GB2411-GB1894, SM-OSW-SD-GB2412-GB1894, SM-OSW-SD-GB2413-GB1894, SM-OSW-SD-GB2414-GB1894, SM-OSW-SD-GB2415-GB1894, SM-OSW-SD-GB2416-GB1894, SM-OSW-SD-GB2417-GB1894, SM-OSW-SD-GB2418-GB1894, SM-OSW-SD-GB2419-GB1894, SM-OSW-SD-GB2420-GB1894, SM-OSW-SD-GB2421-GB1894, SM-OSW-SD-GB2422-GB1894, SM-OSW-SD-GB2423-GB1894, SM-OSW-SD-GB2424-GB1894, SM-OSW-SD-GB2425-GB1894, SM-OSW-SD-GB2426-GB1894, SM-OSW-SD-GB2427-GB1894, SM-OSW-SD-GB2428-GB1894, SM-OSW-SD-GB2429-GB1894, SM-OSW-SD-GB2430-GB1894, SM-OSW-SD-GB2431-GB1894, SM-OSW-SD-GB2432-GB1894, SM-OSW-SD-GB2433-GB1894, SM-OSW-SD-GB2434-GB1894, SM-OSW-SD-GB2435-GB1894, SM-OSW-SD-GB2436-GB1894, SM-OSW-SD-GB2437-GB1894, SM-OSW-SD-GB2438-GB1894, SM-OSW-SD-GB2439-GB1894, SM-OSW-SD-GB2440-GB1894, SM-OSW-SD-GB2441-GB1894, SM-OSW-SD-GB2442-GB1894, SM-OSW-SD-GB2443-GB1894, SM-OSW-SD-GB2444-GB1894, SM-OSW-SD-GB2445-GB1894, SM-OSW-SD-GB2446-GB1894, SM-OSW-SD-GB2447-GB1894, SM-OSW-SD-GB2448-GB1894, SM-OSW-SD-GB2449-GB1894, SM-OSW-SD-GB2450-GB1894, SM-OSW-SD-GB2451-GB1894, SM-OSW-SD-GB2452-GB1894, SM-OSW-SD-GB2453-GB1894, SM-OSW-SD-GB2454-GB1894, SM-OSW-SD-GB2455-GB1894, SM-OSW-SD-GB2456-GB1894, SM-OSW-SD-GB2457-GB1894, SM-OSW-SD-GB2458-GB1894, SM-OSW-SD-GB2459-GB1894, SM-OSW-SD-GB2460-GB1894, SM-OSW-SD-GB2461-GB1894, SM-OSW-SD-GB2462-GB1894, SM-OSW-SD-GB2463-GB1894, SM-OSW-SD-GB2464-GB1894, SM-OSW-SD-GB2465-GB1894, SM-OSW-SD-GB2466-GB1894, SM-OSW-SD-GB2467-GB1894, SM-OSW-SD-GB2468-GB1894, SM-OSW-SD-GB2469-GB1894, SM-OSW-SD-GB2470-GB1894, SM-OSW-SD-GB2471-GB1894, SM-OSW-SD-GB2472-GB1894, SM-OSW-SD-GB2473-GB1894, SM-OSW-SD-GB2474-GB1894, SM-OSW-SD-GB2475-GB1894, SM-OSW-SD-GB2476-GB1894, SM-OSW-SD-GB2477-GB1894, SM-OSW-SD-GB2478-GB1894, SM-OSW-SD-GB2479-GB1894, SM-OSW-SD-GB2480-GB1894, SM-OSW-SD-GB2481-GB1894, SM-OSW-SD-GB2482-GB1894, SM-OSW-SD-GB2483-GB1894, SM-OSW-SD-GB2484-GB1894, SM-OSW-SD-GB2485-GB1894, SM-OSW-SD-GB2486-GB1894, SM-OSW-SD-GB2487-GB1894, SM-OSW-SD-GB2488-GB1894, SM-OSW-SD-GB2489-GB1894, SM-OSW-SD-GB2490-GB1894, SM-OSW-SD-GB2491-GB1894, SM-OSW-SD-GB2492-GB1894, SM-OSW-SD-GB2493-GB1894, SM-OSW-SD-GB2494-GB1894, SM-OSW-SD-GB2495-GB1894, SM-OSW-SD-GB2496-GB1894, SM-OSW-SD-GB2497-GB1894, SM-OSW-SD-GB2498-GB1894, SM-OSW-SD-GB2499-GB1894, SM-OSW-SD-GB2500-GB1894, SM-OSW-SD-GB2501-GB1894, SM-OSW-SD-GB2502-GB1894, SM-OSW-SD-GB2503-GB1894, SM-OSW-SD-GB2504-GB1894, SM-OSW-SD-GB2505-GB1894, SM-OSW-SD-GB2506-GB1894, SM-OSW-SD-GB2507-GB1894, SM-OSW-SD-GB2508-GB1894, SM-OSW-SD-GB2509-GB1894, SM-OSW-SD-GB2510-GB1894, SM-OSW-SD-GB2511-GB1894, SM-OSW-SD-GB2512-GB1894, SM-OSW-SD-GB2513-GB1894, SM-OSW-SD-GB2514-GB1894, SM-OSW-SD-GB2515-GB1894, SM-OSW-SD-GB2516-GB1894, SM-OSW-SD-GB2517-GB1894, SM-OSW-SD-GB2518-GB1894, SM-OSW-SD-GB2519-GB1894, SM-OSW-SD-GB2520-GB1894, SM-OSW-SD-GB2521-GB1894, SM-OSW-SD-GB2522-GB1894, SM-OSW-SD-GB2523-GB1894, SM-OSW-SD-GB2524-GB1894, SM-OSW-SD-GB2525-GB1894, SM-OSW-SD-GB2526-GB1894, SM-OSW-SD-GB2527-GB1894, SM-OSW-SD-GB2528-GB1894, SM-OSW-SD-GB2529-GB1894, SM-OSW-SD-GB2530-GB1894, SM-					

San Juan Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Please J)	Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
87	34	28035 PVIDE	15C	55		36" CMP	Line runs from 28035 PVIDE to 28044 PVIDE			60	9	12/15/14	Holes at various locations: 11' 4", 17' 7", 28' 6" & 50' 5". Deformed pipe at 25' 3". Top portion of pipe is broken. Survey abandoned due to del blockage - 95% (mainly sand and rocks).
88	34	28044 PVIDE	15D	56		18" CMP	Line starts at CB on out-of-sight end to OS on back of property	LALAE-SD-CB0925-OS0925	CB0925 to OS0925	63	150		Heavy corrosion. Missing invert throughout the pipe. Inspection abandoned at 60' due to heavy sediment & debris in pipe - 50%.
89	34	28044 PVIDE	33C	57		12" CMP	Line starts at CB on south side of property to JS east	LALAE-SD-CB3215-JS3216	CB3215 to JS3216	3	120	9/25/14	Heavy corrosion and holes throughout the pipe. Paved invert is deteriorated/missing. Line continues as RCP after 117' from MH1914.
90	34	28044 PVIDE	58			48" CMP	Line starts at CB in front of property to MH in front of property	MH1914 to MH0941	MH1914 to MH0941	117	9	11/17/14	Heavy corrosion and holes throughout the pipe. Paved invert is deteriorated/missing. Line continues as RCP after 117' from MH1914.
91	34	28044 PVIDE	28C	60		48" RCP	Line starts in Rolling Hills Estates and ends in canyon CB behind 28041 Silver Spur	OS0925 to OS0925	CB0411 to MH0409	191	455	9/16/14	The first 110' from CB0411 are RCP in good condition. CMP starts
92	1	26441 Silver Spur Rd. (RHE)	5A	7		24" CMP		OS0925 to OS0925	RHE to OS1547	250' approx in RCP	250		
93	2	26535 Whitcomb Dr.	5C	9		21" RCP	Line runs from MH in front of 26535 Whitcomb to ML-RHE-SD-MH1543-CB1542. ML-RHE-SD-CB1541-CB1542	MH1543 to MC0431	MH1543 to MC0431	165'	165		
94	3	28047 Elm Rd.	6A	14		36" CMP	Line runs along property from CB in front of 28047 Elm to 28047 Elm to 28047 Elm to 28047 Elm	SM-PVW-SD-CB3028-CB3049, SM-PVW-SD-CB3049-OS0950, SM-PVW-SD-CB3050-TS0001, SM-PVW-SD-TS0001-OS1052, SM-PVW-SD-OS1052-MH1291	CB3028 to MH1291	27	This is a repeat of Line 62	6/12/14	Lining failure (severely eroded).
95	4	Hawthorne Blvd. & Indian Peak Rd.	6B	17		UNKNOWN	Intersection (approx. 50' west from the traffic light ML-RHE-SD-CB1455-OS0927, ML-RHE-SD-OS0927-OS1052)	CB1455 to MH0293	CB1455 to MH0293	120'	120		
96	5	Hawthorne Blvd. & Indian Peak Rd.	6B	17		24" RCP	Hawthorne and Indian Peak to CB located west of Indian Peak	MH0293 to MH0293	CB3058 to MH0293	50'	50		
97	6	Hawthorne & Indian Peak Rd.	6B	17		RCP	Intersection to OS 110' south of Indian Peak Rd. ML-RHE-SD-MH0293-OS0926, ML-RHE-SD-MH0296-OS0926, ML-RHE-SD-MH0296-OS0926	MH0296 to OS0926	MH0296 to OS0926	110'	110		
98	7	Crest Rd. at Country Meadow Rd.	12D	25		18" CMP	Meadow to MH in the middle of the road (Crest eastbound)	SM-OSW-SD-CB1181-MH1072	CB3181 to MH1072	80'	80		
99	8	Crest Rd. at Country Meadow Rd.	12D	25		18" CMP	Line runs from CB 85' west of Country Meadow to MH in the middle of road (Crest eastbound)	SM-OSW-SD-CB1074-MH1079	CB1074 to MH1079	75'	75		
100	9	PVIDS by Parking Lot at Fisherman's Trail	22B	35		UNKNOWN	Japanese Garden entrance to CB	IS0564 to CB0552	IS0564 to CB0552	20'	20		
101	10	PVIDS by Parking Lot at Fisherman's Trail	22B	35		UNKNOWN	Line runs from CB on PVIDS median eastbound to CB across PVIDS eastbound	CB0552 to CB0552	CB0552 to CB0552	35'	35		
102	11	PVIDS by Parking Lot at Fisherman's Trail	22B	35		UNKNOWN	Line runs from CB on PVIDS eastbound off of parking lot entrance to OS	CB0552 to OS0564	CB0552 to OS0564	30'	30		
94	12	PVIDS by Parking Lot at Fisherman's Trail	22B	35		UNKNOWN	345' east of Japanese Garden entrance to OS south of PVIDS eastbound	IS0549 to OS0549	IS0549 to OS0549	155'	155		
103	12	PVIDS by Parking Lot at Fisherman's Trail	22B	35		18" RCP	Line runs from MH in front of 26535 Whitcomb to OS on PVIDS westbound (approx. 500' east of Japanese Garden entrance)	OS0925 to OS0925	OS0925 to OS0925	160.6	161	1/16/15	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Map No.	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
104	13	331	PVDS at Sasone Dr.	23B	39		UNKNOWN	Line runs from CB on median east of Sasone Dr. to ??		CB0657 to ??	??			Does NOT exist
105	14	332	PVDS at Sasone Dr.	23B	39		UNKNOWN	Line starts at SW west of dirt road to CB at corner of PVD and 1st Road		IS0657 to CB0656	20'	20		
106	15	335	PVDS at Sasone Dr.	23B	39		UNKNOWN	Line runs from CB at southwest corner of PVDS & Sasone to JS		CB0654 to JS2681	70'	70		
107	16	335.1	PVDS at Sasone Dr.	23B	39		UNKNOWN	Ending line in front of JS2681 running towards the ocean (not shown on GIS)						
108	17	322	PVDS at Nardosa	24A	40		UNKNOWN	Line runs from CB on PVDs eastbound 80' east from Nardosa school gate entrance to JS		CB0659 to JS2682	115'	115		
109	18	326	PVDS at Wayfarer's Chapel	24A	40		24" CMP	Line starts at IS below Wayfarer's Chapel to CB on PVDs median	SM-OSE-SD-5500611-IS00611, SM-OSE-SD-5500811-1550701, SM-OSE-SD-5500701-CB00703	IS0612 to CB0703	80'	800		There is a project in the future to make improvements to the storm sewer at GIS. Line has been reported to not be water tight. There is a project in the future to make improvements to the storm
110	19	318	PVDS at Prigentree	24C	41		24" STL	Line runs from CB on northwest corner to OS across PVDs		CB3456 to OS3457	180'	180		
111	20	314	PVDS landslide area	24D	42		UNKNOWN	Line starts at IS east end of Gateway Parking area to OS west of PVDs		IS0640 to OS0639	245'	245		
112	21	315	PVDS landslide area	24D	42		30" CMP	Line starts at IS north of PVDs to OS south of PVDs by abandoned homes	SM-OSE-SD-5500706-1550707	IS0708 to OS0707	205'	205		
113	22	311	PVDS at Schooner Dr.	26A	43		UNKNOWN	Line starts at CB on PVDs approx. 500' east of Schooner to OS south of PVDs		CB0468 to OS0467	180'	180		
114	23	305.1	PVDS at Conqueror Dr.	26A	44		UNKNOWN	SM-OSE-SD-JS3405-MH0477		MH0405 to OS0477	??			Line needs to be inspected.
115	24	310	PVDS at Conqueror Dr.	26A	44		UNKNOWN	Line starts at CB off of parking area to ??	SM-OSE-SD-CB3409-JS3409	CB3408 to ??	??			
116	25	307	PVDS at Trump National Dr.	26A	45		18" RCP	Line starts at IS 250' west of Trump National to OS 275' west of Trump National	SM-OSE-SD-552796-JS2796	JS2796 to OS2797	75'	75		
117	255	Formal Dr. at Aqua Vista Dr.	26A	46			18" RCP	Line starts at CB on Forrestal approx. 70' north of SM-OSE-SD-552780, SM-OSE-SD-552780-1552785		CB2778 to JS2783	30'	20		No video inspected.

San Jose Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
118	27	300	Forness Dr. at PVDS	28A	46		UNKNOWN	Line starts at IS north of PVDS to OS south of PVDS		IS0457 to OS0456	100'	100'		
119	28	280	PVDS at Seaciff Dr.	28B	48		UNKNOWN	Line runs from MH in PVDS median (approx. 335' east of median west end) to ??		MH1865 to ??				
120	29	275	PVDS at PVDE	28B & 28D	49		48" RCP	Line runs from CB off of main IS south of PVDS (approx. 450' west of PVDE) to JS on mainline		CB0218 to JS2659	10'	10'		
121	30	278	PVDS at PVDE	28B & 28D	49		24" RCP	Line runs from CB on PVDE approx. 50' east of PVDS to JS on mainline		CB0315 to JS2696	75'	75'		
122	31	203	Western Ave. @ De La Sorda Dr.	33A	50		UNKNOWN	Line runs from MH at the intersection of Western Ave. to OS north east corner of intersection LALAN-SD-MH1907-MH0189		MH1907 to OS1169	50'	50'		
123	32	207	PVDE at Sunnyside Ridge Rd.	158	52		18" RCP	Line starts at CB on PVDE south of Sunny-side Ridge to MH in front of property to PVDE		CB3592 to MH3591	190'	190'		
124	33	208	28077 PVDE	159	52		18" RCP	Line runs from CB to MH in front of the property LALAN-SD-CB3593-MH3591		MH3591 to CB3593	12'	12'		
125	34	209	28077 PVDE	159	52		24" RCP	Line runs from MH in front of the property to MH in front of 28045 PVDE		MH3591 to MH3590	335'	335'		
126	35	210	28045 PVDE	159	52		24" RCP	Line runs from MH in front of the property to MH in front of 28003 PVDE	LALAN-SD-MH3590-MH3590 LALAN-SD-MH3590-GE3569, LALAN-SD-CB3569-MH3568	MH3590 to MH3568	365'	365'		
127	36	311	28003 PVDE	159	52		24" RCP	Line runs from CB in front of property to mainline		CB3564 to Mainline	10'	10'		
128	37	212	28003 PVDE	158	52		24" RCP	Line runs from CB to MH in front of property		CB3565 to MH3568	10'	10'		
129	38	213	28012 PVDE	158	52		24" RCP	Line runs from CB to MH in front of property		CB3566 to MH3568	27'	27'		
130	39	214	28012 PVDE	159	52		24" RCP	Line runs from CB to MH in front of property		CB3567 to MH3567	27'	27'		
131	40	215	28003 PVDE	158	52		30" & 36" RCP	Line runs from MH3568 to MH3566	LALAN-SD-MH3568-MH3567, LALAN-SD-MH3567-MH3566	MH3568 to MH3566	73'	73'		

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)		Number of Pipe Segments Per Grade Level	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
132	41	216	26001 & 26003 PYDE	158	53		36" RCP	Line runs from MH in front of property corner to MH in front of 27863 PYDE property	LALAN-SD-MH3566-CB3566, LALAN-SD-CB3566	MH3566 to MH3566	465'	465		
133	42	217	27862 PYDE	158	53		24" RCP	Line runs from CB in front of the property to JS access PYDE		CB3566 to JS2467	45'	45		
134	43	218	27862 PYDE	158	53		36" RCP	Line runs from MH in front of the property to MH in front of 27862 PYDE	LALAN-SD-MH3566-CB3566, LALAN-SD-CB3566	MH3566 to MH3571	395'	395		
135	44	219	27862 PYDE	158	53		30" RCP	Line runs from CB to MH in the middle of the road		CB3573 to MH3571	35'	35		
136	45	220	27862 PYDE	158	53		30" RCP	Line runs from CB to MH in the middle of the road		CB3574 to MH3572	25'	25		
137	46	221	27862 PYDE	158	53		42" RCP	Line runs from MH in front of the property to MH in east corner of 27848 PYDE	LALAN-SD-MH3571-MH3572, LALAN-SD-MH3572-CB3573, LALAN-SD-CB3573-MH3576	MH3571 to MH3576	500'	500		
138	47	222	27848 PYDE	158	53		18" RCP	Line runs from CB to MH in front of the east corner of the property		CB3577 to MH3576	25'	25		
139	48	223	27848 PYDE	158	53		48" RCP	Line runs from MH in front of the east corner of the property to MH in front of 27840 PYDE	LALAN-SD-MH3576-MH3579	MH3576 to MH3579	190'	190		
140	49	224	27840 PYDE	158	53		48" RCP	Line runs from MH in front of 27840 PYDE to MH in front of 27804 PYDE	LALAN-SD-MH3579-MH3581	MH3579 to MH3581	255'	255		
141	50	225	27803 PYDE	158	53		18" RCP	Line runs from CB to MH in front of property	LALAN-SD-CB3582-MH3581	CB3582 to MH3581	20'	20		
142	51	226	27803 PYDE	158	53		48" RCP	Line runs from MH to MH in front of 2477 Sunnyside Ridge	LALAN-SD-MH3581-MH3583	MH3581 to MH3583	75'	75		
143	52	227	27804 PYDE	158	53		24" RCP	Line runs from MH in front of 2477 Sunnyside Ridge to JS 30' west of MH	LALAN-SD-CB3584-MH3583	MH3583 to JS3584	35'	35		
144	53	228	27804 PYDE	158	53		48" RCP	Line runs from MH in the middle of the road to OS in front of 2477 Sunnyside Ridge property	LALAN-SD-MH3581-MH3583, LALAN-SD-MH3583-CB3584	MH3581 to OS3585	235'	235		
145	54	229	18 Station Rd.	15A	54		UNKNOWN	Line runs from CB in behind 18 Station to OS in front of 28012 PYDE		CB3584 to OS3583	40'	40		

San Juan Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I)	Number of Segments Per Grade Level	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
146	55	232	PVIDE at Bronco Dr.	15A	54		36" RCP	Line runs from MH on PVIDE at Bronco Dr. to MH/LA/LAN-SD-MH3491-JS3492, LA/LAN-SD-JS3492-MH3496		MH3491 to MH3496	435'	435		
147	56	233	28500 PVIDE	15A	54		18" RCP	Line runs from CB in front of west corner of property to JS in manhole	LA/LAN-SD-CB3490-JS3492, LA/LAN-SD-MH3491-JS3492	CB3490 to JS3491	10'	10		
148	57	235	PVIDE at West Headland Dr.	15A	54		36" RCP	Line runs from MH on PVIDE at West Headland (LA/LAN-SD-MH3496-CB3497, LA/LAN-SD-GB3497-MH3498) to MH on PVIDE at East Headland	LA/LAN-SD-MH3496-CB3497, LA/LAN-SD-GB3497-MH3498	MH3496 to MH3498	475'	475		
149	58	237	PVIDE at East Headland Dr.	15A	54		36" RCP	Line runs from MH on PVIDE at East Headland to LA/LAN-SD-MH3498-CB3499, LA/LAN-SD-GB3499-JS3500, LA/LAN-SD-JS3500-MH3501	LA/LAN-SD-MH3498-CB3499, LA/LAN-SD-GB3499-JS3500, LA/LAN-SD-JS3500-MH3501	MH3498 to MH3501	485'	485		
150	59	238	28217 PVIDE	15A	54		18" RCP	Line runs from CB in front of 28217 PVIDE to JS in manhole	LA/LAN-SD-CB0688-JS3500	CB0688 to JS3500	15'	15		
151	60	239	28215 PVIDE	15A	54		36" RCP	Line runs from MH in front of 28215 PVIDE to MH in front of 28191 PVIDE	LA/LAN-SD-MH3501-MH3502	MH3501 to MH3502	265'	265		
152	61	240	28191 PVIDE	15A	54		36" RCP	Line runs from MH in front of 28191 PVIDE to OS in 28160 PVIDE property	LA/LAN-SD-MH3502-JS3503, LA/LAN-SD-JS3503-GB3506, LA/LAN-SD-GB3506-GB3507, LA/LAN-SD-GB3507-JS3509, LA/LAN-SD-JS3509-OS3505	MH3502 to OS3505	285'	285		
153	62	241	28191 PVIDE	15A	54		18" RCP	Line runs from CB in front of 28191 PVIDE to JS in manhole	LA/LAN-SD-CB3504-JS3503	CB3504 to JS3503	10'	10		
154	63	243	28800 PVIDE	15C	55		UNKNOWN	Line starts at site behind 5 Mustang Rd. property to OS on 28803 Road	LA/LAN-SD-OS0003-JS2709, LA/LAN-SD-JS2709-OS0003	OS0003 to OS0003	155'	155		
155	64	246	PVIDE at Mustang Rd.	15C	55		UNKNOWN	Line starts at CB south of Mustang to JS 307 north LA/LAN-SD-CB0911-JS2709	LA/LAN-SD-CB0911-JS2709	CB0911 to JS2709	30'	30		
156	65	247	PVIDE at Mustang Rd.	15C	55		UNKNOWN	Line starts at site south of Mustang to outlet on LA/LAN-SD-JS0910-JS2708, LA/LAN-SD-JS2708-Roadhouse	LA/LAN-SD-JS0910-JS2708, LA/LAN-SD-JS2708-Roadhouse	JS0910 to OS0912	150'	150		
157	66	95	OMITTED											
158	67	118.1							30A-OS09-SD-JS2678-JS3254	JS2678 to JS3254				To be inspected

Storm Drain Video Inspection & Cleaning Services FY 13 - 17												
Number of Segments (Phase I)	Pipe Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Year Built	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point (Approx.)	Pipe Length	Video Date	Comments
	131									10.880		
Storm Drain Video Inspection Legend Line has been video inspected (video not reviewed) Line is in good condition Light/minor defect condition Moderate defect condition Average defect condition Heavy defect condition Severe defect condition Not able to locate in the field/Not able to inspect Line does not exist GIS update needed												

Storm Drain Video Inspection & Cleaning Services FY 13 - 14

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
155	15	381	5430 Monteralaga Dr.	5A	62	24" RCP	Line starts at CB in front of property to CB across Monteralaga westbound	ML-PVN-SD-CB1552-CB1559	CB1552 to CB1559	64.5	65	11/24/2014	Exposed rebar around active tap break-in at 39.5'. Overall pipe looks clean and in good condition.
156	26	400	3835 Summit Dr.	12D	81	21" RCP	Line starts at CB in front of property to OS on Crest Rd. north of Los Verdes Dr. to CB across Hawthorne Blvd. (approx. 280' north of Los Verdes Dr.) to CB across Hawthorne Blvd.	SM-OSW-SD-CB1059-OS1058	CB1059 to OS1058	125.7	126	12/22/2015	Hard deposits at the beginning of the pipe to 11' approx. 10%. The rest of the pipe looks clean and in good condition.
157	21	394	Los Verdes Dr.	20B	86	36" CMP	Line starts at CB in front of property to CB in front of Hawthorne Blvd.	SM-OWW-SD-CB1115-CB1154	CB1115 to CB1154	79	79	8/21/2014	Heavy corrosion throughout the pipe. Pipe is good candidate for lining.
158	22	392	6914 Alta Vista Dr.	20B	87	18" RCP	Line starts at CB in front of property to CB in front of Hawthorne Blvd.	SM-OSW-SD-CB0740-CB0739	CB0740 to CB0739	13	30	11/21/2014	Hard deposits (approx. 20%) at the beginning and starting from 13' to end of line.
159	33	328	Bk. at Dupre Dr.	20B	88	36" CMP	Line starts at CB on Hawthorne Blvd. (approx. 110' north of Dupre Dr.) to CB next to median	SM-OSW-SD-CB0745-CB0742	CB0745 to CB0742	33	75	12/18/2015	Water level and debris is at approx. 25% throughout the pipe.
160	24	814	30550 Via La Cresta Rd.	20D	96	36" RCP	Line starts at CB to CB on property	SM-OSW-SD-CB2623-CB2624	CB2623 to CB2624	34	34	12/17/2015	Debris from 32' to 34' approx. 60%.
161	25	814	Hawthorne Blvd. by City Hall	22B	96	36" RCP	Line runs from MH on City Hall yard by driveway entrance to OS	SM-OSW-SD-GB2654-OS2855	OS2855 to OS2855	190	200	10/30/2014	Inspection abandoned at 180' due to debris and standing water (approx. 15%).
162	26	404	Crestview Dr. at Valley View Rd.	13C	82	18" RCP	Line starts at CB on Crestview Blvd. southbound (approx. 160' south of San Camila Pl.) to MH 65' north	SM-OSW-SD-CB0960-OS0956	OS0956 to OS0956	64	64	12/23/2014	Exposed rebar at 24' and broken concrete around the pipe. The pipe is in good condition. Sand and rock deposits starting at 15' to MH 65' from 5' to 40%. Inspection abandoned at 20' due to debris blockage. Pipe seems to be in good condition.
163	27	703	Forestal Dr.	25A & C	108	30" RCP	Line runs from MH to MH west of Forestal Dr.	SM-OSW-SD-MH3521-MH3467	MH3521 to MH3467	200	210	16/2015	Light corrosion throughout the pipe. Debris starting at 15' to IS - 50%.
164	1	303	Los Verdes Golf Course	20B	86	15" CMP	Line starts at CB on Los Verdes Dr. (approx. 190' north of golf course parking entrance) to 72'	DNE	CB0631 to IS 72'	31		10/30/2014	Hard deposits throughout the pipe -40%.
165	2	509	61 Via Del Cielo	20C	89	36" RCP	Line starts at IS on Via Del Cielo northbound to MH in the middle of the steel	SM-OWW-SD-IS1683-CB1682	IS1683 to CB1682	16		10/23/2014	Surface missing well (exposed rebar) from 10' to 2' o'clock (approx. 2' to 3' in length). The rest of the pipe is clean and in good condition.
166	3	509	Hawthorne Blvd. at Vallon Dr.	19C	98	18" RCP	Line starts at CB on Hawthorne median (approx. 200' north of Vallon Dr.) to CB on Hawthorne southbound	SM-OSW-SD-MH3532-JS3535, SM-OSW-SD-JS3535-JS3538, SM-OSW-SD-JS3538-JS3533, SM-OSW-SD-JS3533-MH3538	CB0725 to CB0728	50		11/4/2014	Plastic sheathing blocking pipe -80% at 212' from MH3532; this seems to be at JS3538 where line is full of debris per video CB0679 to JS3538 (line no. 675). Overall line is clean and in good condition.
167	4	671	Barkshire Rd. at Salsone Dr.	23A	104	18" RCP	Line runs from MH in front of 32 Salsone to MH in front of 36 Salsone	LA-LAE-SD-MH0160-GB0161, LA-LAE-SD-GB0161-CB1908	MH3532 to MH3528	242		10/21/2014	The first 187' from MH0160 have been lined; thereafter is RCP. Joint separation at 285'; sand bags hanging from opened joint. Hole at 281' from 5 to 7 o'clock.
168	5	802	Portevestra Dr.	33C	124	30" CP-RCP	Line runs from MH in front of property to CB on Western		MH0160 to CB1908	256		10/6/2014	Inspection abandoned at 20' due to soil in pipe -66%. Overall pipe in in good condition.
169	6	805	Crownview Dr. at PVOE	16C	134	18" RCP	Line runs from IS adjacent to CalWater's driveway to CB	SM-PVN-SD-CB1251-PC1250	IS3121 to CB3122	22		10/13/2014	Hard deposits from the beginning of the pipe to 17' (approx. 10%). Hard deposits from 33' to 60' (approx. 15%). The rest of the pipe is in good condition.
170	7	378	28349 Plainfield Dr.	9B	67	18" RCP	Line runs from CB in front of property to PC behind same property		CB1251 to PC1250	169		11/7/2014	Top portion of pipe is broken at 5.7' from CB. Hard deposits at 153' to 165' (approx. 10%). The rest of the line looks clean and in good condition.
171	8	383	6475 Parklyn Dr.	8C	68	18" RCP	Line starts at CB in front of property to MH on Downridge Dr.	SM-PVN-SD-CB1424-GB2483, SM-PVN-SD-GB2483-MH2522	CB1424 to MH2522	187		11/10/2014	Fine deposits settled starting at 30' to 65' (approx. 5% to 10%) and at 108' to 122' (approx. 10%). The rest of the pipe is clean and in good condition.
172	9	402	7460 Alida Pl.	11C & 11A	74	24" RCP	Line runs from MH in front of property to MH around the corner of same property on PVOE	SM-OWW-SD-MH3129-MH3131	MH3129 to MH3131	122		11/4/2014	Fine deposits settled for the first 37' of the line starting at CB1133 to MH3129. Inspection abandoned at 20' due to debris and cobbles.
173	10	431	30030 Via Victoria	11C	76	21" RCP	Line starts at CB in front of property to CB in front of 30405 Via Victoria	SM-OWW-SD-CB1133-GB2315, SM-OWW-SD-GB2315-CB1134	CB1133 to CB1134	72		11/3/2014	Heavy corrosion for the first 50' from CB. Pipe has been paved previously; pavement has eroded in some areas exposing the metal pipe (heavily corroded). Inspection abandoned at 263' due to large void.
174	11	455	30003 Rue Langlois	20A & 11C	76	30" CMP	Line runs from CB in front of property to JS on open channel behind property	SM-OWW-SD-GB3310-JS3303	CB3302 to JS3303	263		12/10/2014	

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
175	12	440	PVDW 7055 Via Del Mar	20A	18" RCP	Line starts at CB on PVDW median (approx. 1800' north of Hawthorne Blvd.) to CB across PVDW northbound	SM-OWW-SD-CB1628-CB0613	CB1628 to CB1613	25		11/25/2014	Soil deposits settled throughout the pipe from 5% to 40%. Overall pipe is in good condition.
176	13	544	7055 Via Del Mar	20D	42" RCP	Line starts at IS on property to MH	SM-OWW-SD-CB2843-MH2845	IS2843 to MH2845	14		10/27/2014	Approx. 75% of the inlet is covered by soil, rocks and plants. The pipe itself is clean and in good condition.
177	14	461	7055 Via Del Mar	20D	18" RCP & UNKWN	Line starts at CB adjacent to property to MH in front of 7060 Via Del Mar	SM-OWW-SD-CB2837-CB2838, SM-OWW-SD-CB2838-MH2835	CB2837 to MH2835	46.5		11/20/2014	Deposits settled starting at 46' to 77' - 40%. Severely fractured pipe at 6'. Multiple longitudinal cracks in the pipe starting at 14' to 16'. Pipe is misaligned at pipe connections throughout its length. Major cracks at 123'; longitudinal crack starting at 125' to 145'. Longitudinal crack starting at 155' to 165'. Pipe is clean.
178	15	725	6512 Via Colima	26B	12" RCP	Line runs from CB in front of property to OS behind 6316 Via Colima	LA-LAS-SD-CB0249-OS0248	CB0249 to OS0248	229		10/14/2014	The first 10' are RCP; longitudinal crack starting almost immediately after RCP. CMP starts at 130' from CB0254; pipe has average corrosion and settled sand starting at 146' to 157' (approx. 20%).
179	16	725	6337 Via Colima	26B	12" RCP & CMP	Line runs from CB in front of property to CB in front of 6460 Via Colima	LA-LAS-SD-CB0254-CB0253	CB0254 to CB0253	157.5		10/14/2014	Multiple cracks at the beginning of CB0253; longitudinal crack starting at 8' to 13'. Severe pipe cracks at 223'. Inspection abandoned due camera's inability to make turns.
180	17	720	6460 Via Colima	26B	12" RCP	Line runs from CB in front of property to CB in front of 4604 Beaulieu	LA-LAS-SD-CB0253-CB0252	CB0253 to CB0252	30.5		10/14/2014	The first 93' from CB are RCP; multiple cracks at 12.5'; 22.7'; 77'. CMP starts at 83'; light to moderate corrosion.
181	18	732	Via Colima at Crenshaw Blvd. at Crest Rd.	26B	12" RCP & CMP	Line starts at CB at intersection of intersection to OS behind 6304 Via Ciega down the canyon	LA-LAS-SD-CB0257-OS0258	CB0257 to OS0258	142		10/14/2014	Heavy corrosion throughout the pipe. Holes at various locations. Inspection abandoned at 38' from CB0257 due to heavy corrosion and holes throughout the pipe. Pipe is RCP from 30' to 94'; clean and in good condition. Pipe changes to CMP from 94' to 116'; pipe has heavy corrosion and holes.
375	1	401	Crenshaw Blvd. at Crest Rd.	13A	18" CMP	Line starts at CB on Crenshaw Blvd. southbound (approx. 180' north of Crest Rd.) to MH on Crenshaw Blvd. northbound	ML-RHE-SD-CB3447-CB48532	CB3447 to MH3359	60		11/11/2014	Line is completely blocked by debris at the IS. Overall line is in good condition.
376	2	401	Hawthorne Blvd. at Crest Rd.	12C	36" CMP & RCP	Line runs from CB on Hawthorne (approx. 445' south from intersection) to MH on vacant lot behind Ralston's	SM-OWW-SD-CB1096-JS48132, SM-OWW-SD-JS48132-MH1101	JS48132 to MH1101	116		11/3/2014	Holes throughout the pipe. Inspection abandoned at 20' due to voids.
377	3	401	Sedore Dr.	23A	18" RCP	Line runs from CB on Sedore between Barkentine & Pickett to JS	SM-OSW-SD-CB0679-JS3538	CB0679 to JS3538	20		10/21/2014	Pipe has been lined previously. Collapsed pipe at 385'. Overall line is clean and in good condition.
378	4	401	Hawthorne Blvd. at Verde Ridge Rd.	8C	36" CMP	Line starts at CB on Hawthorne northbound (approx. 285' north of intersection to MH on median)	SM-OWW-SD-CB1338-JS38915, SM-PWW-SD-CB2915-MH1345	CB1338 to MH1345	20		11/10/2014	Hole at the end of the OS pipe. Overall line is clean and in good condition.
379	5	411	30545 Rnone Dr.	19A	18" CMP	Line starts at CB in front of property to MH in property backyard	OSW-SD-CB2913-CB2914, SM-OSW-SD-CB2914-CB2915, SM-OSW-SD-CB2915-MH2910	CB2911 to MH2910	389		11/5/2014	Hole at the end of the OS pipe. Overall line is clean and in good condition.
380	6	408	31311 Marne Dr.	19C	24" CMP	Line runs from MH in front of 31311 Marne Dr. to OS in canyon behind property	SM-OSW-SD-CB1868-GB1866, SM-OSW-SD-GB1866-OS0720	MH1819 to OS0720	265		11/5/2014	Heavy corrosion throughout the pipe. Debris and sand starting at 80' to 87' (approx. 20% to 40%). Inspection abandoned at 87' due to hole and debris.
381	7	408	Western Ave. at Crenshaw Blvd. at Memorial Park	32C	24" CMP	Line starts at CB on Western Ave. southbound (approx. 750' north of Green Hill Dr.) to	LA-LAN-SD-CB0213-CB0212	CB0213 to CB0212	87		10/15/2014	Medium to heavy corrosion throughout the pipe. Portion of the pipe invert five lifted up. Inspection abandoned at 7.5' due to broken pipe.
382	8	408	Crenshaw Blvd. at Valley View Rd.	13C	30" CMP	Line runs from MH on Crenshaw Blvd. southbound (approx. 240' south of San Clemente Pl.) to IS across Crenshaw Blvd.	SM-OSW-SD-ISO3292-MH00596, SM-OSW-SD-ISO3291-JS03292	MH00596 to IS03291	6	120	12/8/2014	Pipe is clogged 100% with soil and rocks. Inspection abandoned. Pipe has a hole from 10 to 2 o'clock at 49' to 51'; visible rebar and debris intrusion. Also cracks around the hole at 49'. Outlet is covered by tree or bush branches.
383	9	471	PVDW	20C	48" CMP	Line runs from CB on PVDW northbound (approx. 670' south of Hawthorne) to JS	SM-OSW-SD-CB0679-JS3538	CB2859 to JS2856	79	7	12/8/2014	Line invert five lifted up. Inspection abandoned at 7.5' due to broken pipe.
384	10	471	32503 Saadiff Dr.	28A	18" RCP	Line runs from CB in front of property to JS	SM-OSW-SD-CB0679-JS3538	CB2859 to JS2856	82		11/20/2014	Pipe is clogged 100% with soil and rocks. Inspection abandoned. Pipe has a hole from 10 to 2 o'clock at 49' to 51'; visible rebar and debris intrusion. Also cracks around the hole at 49'. Outlet is covered by tree or bush branches.
385	11	471	Crest Rd. at Ganado Dr.	26A	18" RCP & CMP	Line runs from CB on Crest northbound (approx. 165' south of Ganado Dr.) to 79	CBM413.2 to OSM413.3	CBM413.2 to OSM413.3	132	7	12/15/2014	Line invert five lifted up. Inspection abandoned at 7.5' due to broken pipe.
386	12	471	Forrestal Dr.	25C	36" RCP	Line runs from CB on Crest northbound (approx. 165' south of Ganado Dr.) to 79	MH00596 to IS03291	MH00596 to IS03291	459.6	459	12/15/2014	Hard deposits at the beginning of the pipe from MH2889 to 10' approx. 20%. The rest of the line looks clean and in good condition.
387	13	471	6416 Corni Pl	26B	12" RCP	Line starts at CB in front of property to OS behind property	LA-LAS-SD-CB0228-OS0227	CB0228 to OS0227	60	1580	12/19/2015	Deposits approx. 50%.
388	14	471	4500 Via Colima	26B	12" RCP	Line runs from CB across from property to OS down the canyon	LA-LAS-SD-CB0051-OS0052	CB0051 to OS0052	5	65	12/8/2015	Broken pipe; soil is visible at 1'. Inspection abandoned due to debris blockage at 5'.
389	15	471	6453 Via Colima	26B	12" CMP	Line runs from CB in front of property to CB in front of 6312 Via Colima	LA-LAS-SD-CB0250-CB0249	CB0250 to CB0249	39	165	12/8/2015	Heavy corrosion from 0' to 36'. Pipe material changes after 36' to RCP; pipe is severely broken and blocked 95% by debris (mainly rocks).
390	16	471	2727 Vista Mesa Dr.	26D	18" CMP	Line runs from CB in front of property to CB behind property	LA-LAS-SD-CB0293-CB0292, LA-LAS-SD-GB1905-GB1906, LA-LAS-SD-GB1906-GB4254, LA-LAS-SD-GB4254-CB2608	CB0293 to CB2608	238	260	12/4/2014	Heavy corrosion throughout the pipe. Debris and rock deposits from CB0293 to 30'. Inspection abandoned at 10' from CB0293 along the pipe on both side approx. 2' to 3". Missing invert starting at 238' to 77'. Inspection abandoned due to void.
391	17	405	30462 Camino Poverner	20B	36" CMP	Line runs from MH approx. 160' east of property to MH in the middle of golf course	SM-OWW-SD-MH0629-MH0628	MH0628 to MH0629	330			Inspection abandoned at the beginning of the line starting from CB0630 due to large void and heavy corrosion in pipe.
392	18	405	Van Yordas Golf Course	20B	36" CMP	Line runs from MH in the middle of the golf course to 77	DNE	MH0629 to CB0630	77			Inspection abandoned at 120' from IS due to debris (mainly sand) blocking -90% of the pipe. Confirmed with both that line was clean afterwards.
393	19	405	Forrestal Dr.	25A & C	30" RCP	Line starts at IS off of Forrestal to MH adjacent to Forrestal northbound	SM-OWW-SD-JS2436-JS2438, SM-OWW-SD-JS2438-MH2439	IS2436 to MH2439	122.5	122.5	11/5/2015	This line was not able to be inspected due to inaccessibility. I assumed the line is in the condition as line nb. 500.

Storm Drain Video Inspection & Cleaning Services FY 13 -

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Storm Drain Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
334	1	436	30322 Camino Forrester	11D	36" RCP	Line runs from CB behind 30322 Camino Forrester property to MH behind 30165 Ave. Tranquila	SM-OWW-SD-GH1179-CB2216, SM-OWW-SD-MH1141-GH1179	CB2216 to MH1141	1213		10/31/2014	Exposed rebar at 911' (6 to 3 o'clock) from MH1180. The rest of the pipe is clean and in good condition.
335	2	438.2	Salveta al Esperanza	11D	18" RCP	Line runs from MH at corner to Is 77	SM-OWW-SD-IS1156-MH1157	MH1157 to IS1156 (LACO)	132		10/30/2014	Sealed stones from MH to 10' -10%. Exposed rebar and hole at 120'. CMP starts at 132'. It is light to medium rut.
336	3	508	6915 Alta Vista Dr.	20B	24" CMP	Line starts at CB in front of property to CB in front of 6933 Alta Vista Dr.	SM-OWW-SD-CB0739-MH0741	CB0739 to MH0741	210		11/5/2014	Hard deposits throughout the pipe; they vary from -5% to 15%.
337	4	639	PVOS by St. Francis By the Sea Church	23A	18" RCP	Line runs from CB on PVOS and church driveway to MH in church parking lot	SM-OWW-SD-CB3552-MH3550	CB3552 to MH3550	15		10/20/2014	Sand bags inside the catch basin -80%. Pipe is clean and in good condition.
338	5	607	PVOS between Barentrine Rd. & Packer Rd.	23A	54" CMP	Line runs from MH in between 11 Barentrine & 12 Packer to MH in between 19 Barentrine & 22 Packer.	SM-OWW-SD-MH0680-MH0689	MH0680 to MH0689	347.5		10/17/2014	Invert has been paved with concrete previously. Exposed corrugated invert (missing concrete pavement in the middle of the pipe) starting at 104' to 109'. Line is clean and in good condition.
339	6	608	Sea Gate Dr.	23A	27" CMP	Line runs from CB on Seagate to OS down the cliff	SM-OWW-SD-CB0657-OS0659	CB0657 to OS0659	131.5		10/29/2014	Pipe has been lined previously. Line looks clean and in good condition except for the last -15' of the line that has been collapsed (top portion).
400	7	803	Rena Dr.	33C	18" RCP	Line runs from MH in front of property to CB across the road	LA-LAE-SD-CB0156-CB0158	CB0156 to CB0158	27		10/6/2014	Multiple cracks starting from CB0158 to 7'.
401	8	867	29723 Knoll View Dr.	16C	24" CMP & 24" RCP	Line runs from CB in front of property to CB across the road	LA-LAS-SD-CB0820-CB0818	CB0820 to CB0818	32.5		10/13/2014	The first 7' from CB0820 is CMP (medium corrosion). The rest of the line RCP line is clean and in good condition.
402	9	352	Bridg at Verde Ridge Rd.	8C	36" CMP	Line runs from on Hawthorne southbound approx. 265' north of intersection to MH on median	SM-PWW-SD-CB1339-GB2446, SM-PWW-SD-MH1345-GB2446	CB1339 to MH1345	59		11/10/2014	Medium to heavy corrosion throughout the pipe
403	10	222	30706 Carlier Dr.	19A	30" CMP	Line starts at CB in front of property to MH on Carlier Dr. at Dugre Dr. on westbound southbound approx. 650' at City Hall driveway entrance) to CB on Hawthorne northbound	SM-OWW-SD-CB0747-MH0759	CB0747 to MH0759	82		11/5/2014	Pipe has been lined previously. Gravel deposits starting at 61' to 80' (approx. 15%). The rest of the line is clean and in good condition.
404	11	103	Hall	22B	30" RCP	Line starts at CB in front of property to CB in front of 6433 Via Corolla	SM-OWW-SD-CB0659-CB0687	CB0659 to CB0687	75.5		11/25/2014	Top portion of pipe is broken (rear and son exposed) from 9 to 3 o'clock at 742' from CB0687. Overall line looks clean and in good condition. Traced at the beginning of Casuarina to 6' pipe misaligned at various locations. Longitudinal cracks starting at 14' to 19'. Debris (mainly foliage) starting at 19' to CB0250 (approx. 10%) to Roofs at joint 6' and 23'. Broken concrete at lap break-in 56'.
405	12	728	6432 Via Corolla	26B	12" RCP	Line starts at CB in front of property to CB in front of Highridge Rd.	LA-LAS-SD-CB0247-CB0250	CB0247 to CB0250	30		10/14/2014	Overall line is clean and in good condition.
406	13	307	64 Via Costa	8D	18" RCP	Line runs from MH on Oceanside Blvd. northbound approx. 630' north of Chest Rd.) to MH in front of 28705 Oceanside Rd.	SM-PWW-SD-CB2713-TS2714, SM-PWW-SD-TS2714-OS2715	CB2713 to OS2715	60		11/21/2014	The first 26' are RCP. CMP thereafter. Medium to heavy corrosion. Inspection abandoned due to pipe inclination.
407	14	414	30850 Via La Cresta Rd.	13A	30" RCP & CMP	Line starts at CB in front of property to OS across the road	ML-RHE-SD-SM456A-MH006, ML-RHE-SD-S3399-SM463A	MH3399 to MH1006	90	245	12/1/2014	Sellied debris at 25' (approx. 20%) to 657'.
408	15	611	Verde Dr. at Western Ave.	20D	8" RCP	Line starts at CB in front of property to JS	SM-OWW-SD-CB3819-JS2820	CB3819 to JS2820	65.7	66	12/17/2015	Survey abandoned at 149' due to water level and no downstream access. Overall line is clean and in good condition.
409	16	819	Western Ave. at Redonella	32A	36" RCP	Line runs from MH on Western Ave. northbound to OS across the road	LA-LAN-SD-MH0190-GH1956, LA-LAN-SD-GH1956-OS0189	MH0190 to OS0189	73.3	73	12/16/2015	Inspection abandoned at 73' due to water level. Overall line looks clean and in good condition.
410	17	981	3410 Starline Dr.	26A	18" RCP	Line starts at CB in front of property to OS in front of 3407 Newbridge Dr.	LA-LAS-SD-MH3585-OS0088, LA-LAS-SD-CB0099-MH0565	CB0099 to OS0088	81	81	12/4/2015	Sellied hard deposits from 6.5' to 9' approx. 10%. Overall the line looks clean and in good condition.
412	18	714	3040 Deluna Dr.	26A	18" RCP	Line starts at CB in front of property to CB across De Luna Rd.	LA-LAS-SD-CB0124-CB0123	CB0124 to CB0123	31.7	32	12/4/2015	Moderate root intrusion at joint 5'. Overall the line looks clean and in good condition.
413	20	700	Forrester Dr.	25A & C	30" RCP	Line starts at JS on Forrester northbound to MH west of the road	SM-OWW-SD-IS1156-TS3488, SM-OWW-SD-TS3488-OS0076, SM-OWW-SD-OS0076-OS0077, SM-OWW-SD-OS0077-OS0078, SM-OWW-SD-OS0078-OS0079, SM-OWW-SD-OS0079-OS0080, SM-OWW-SD-OS0080-OS0081, SM-OWW-SD-OS0081-OS0082, SM-OWW-SD-OS0082-OS0083, SM-OWW-SD-OS0083-OS0084, SM-OWW-SD-OS0084-OS0085, SM-OWW-SD-OS0085-OS0086, SM-OWW-SD-OS0086-OS0087, SM-OWW-SD-OS0087-OS0088, SM-OWW-SD-OS0088-OS0089, SM-OWW-SD-OS0089-OS0090, SM-OWW-SD-OS0090-OS0091, SM-OWW-SD-OS0091-OS0092, SM-OWW-SD-OS0092-OS0093, SM-OWW-SD-OS0093-OS0094, SM-OWW-SD-OS0094-OS0095, SM-OWW-SD-OS0095-OS0096, SM-OWW-SD-OS0096-OS0097, SM-OWW-SD-OS0097-OS0098, SM-OWW-SD-OS0098-OS0099, SM-OWW-SD-OS0099-OS0100, SM-OWW-SD-OS0100-OS0101, SM-OWW-SD-OS0101-OS0102, SM-OWW-SD-OS0102-OS0103, SM-OWW-SD-OS0103-OS0104, SM-OWW-SD-OS0104-OS0105, SM-OWW-SD-OS0105-OS0106, SM-OWW-SD-OS0106-OS0107, SM-OWW-SD-OS0107-OS0108, SM-OWW-SD-OS0108-OS0109, SM-OWW-SD-OS0109-OS0110, SM-OWW-SD-OS0110-OS0111, SM-OWW-SD-OS0111-OS0112, SM-OWW-SD-OS0112-OS0113, SM-OWW-SD-OS0113-OS0114, SM-OWW-SD-OS0114-OS0115, SM-OWW-SD-OS0115-OS0116, SM-OWW-SD-OS0116-OS0117, SM-OWW-SD-OS0117-OS0118, SM-OWW-SD-OS0118-OS0119, SM-OWW-SD-OS0119-OS0120, SM-OWW-SD-OS0120-OS0121, SM-OWW-SD-OS0121-OS0122, SM-OWW-SD-OS0122-OS0123, SM-OWW-SD-OS0123-OS0124, SM-OWW-SD-OS0124-OS0125, SM-OWW-SD-OS0125-OS0126, SM-OWW-SD-OS0126-OS0127, SM-OWW-SD-OS0127-OS0128, SM-OWW-SD-OS0128-OS0129, SM-OWW-SD-OS0129-OS0130, SM-OWW-SD-OS0130-OS0131, SM-OWW-SD-OS0131-OS0132, SM-OWW-SD-OS0132-OS0133, SM-OWW-SD-OS0133-OS0134, SM-OWW-SD-OS0134-OS0135, SM-OWW-SD-OS0135-OS0136, SM-OWW-SD-OS0136-OS0137, SM-OWW-SD-OS0137-OS0138, SM-OWW-SD-OS0138-OS0139, SM-OWW-SD-OS0139-OS0140, SM-OWW-SD-OS0140-OS0141, SM-OWW-SD-OS0141-OS0142, SM-OWW-SD-OS0142-OS0143, SM-OWW-SD-OS0143-OS0144, SM-OWW-SD-OS0144-OS0145, SM-OWW-SD-OS0145-OS0146, SM-OWW-SD-OS0146-OS0147, SM-OWW-SD-OS0147-OS0148, SM-OWW-SD-OS0148-OS0149, SM-OWW-SD-OS0149-OS0150, SM-OWW-SD-OS0150-OS0151, SM-OWW-SD-OS0151-OS0152, SM-OWW-SD-OS0152-OS0153, SM-OWW-SD-OS0153-OS0154, SM-OWW-SD-OS0154-OS0155, SM-OWW-SD-OS0155-OS0156, SM-OWW-SD-OS0156-OS0157, SM-OWW-SD-OS0157-OS0158, SM-OWW-SD-OS0158-OS0159, SM-OWW-SD-OS0159-OS0160, SM-OWW-SD-OS0160-OS0161, SM-OWW-SD-OS0161-OS0162, SM-OWW-SD-OS0162-OS0163, SM-OWW-SD-OS0163-OS0164, SM-OWW-SD-OS0164-OS0165, SM-OWW-SD-OS0165-OS0166, SM-OWW-SD-OS0166-OS0167, SM-OWW-SD-OS0167-OS0168, SM-OWW-SD-OS0168-OS0169, SM-OWW-SD-OS0169-OS0170, SM-OWW-SD-OS0170-OS0171, SM-OWW-SD-OS0171-OS0172, SM-OWW-SD-OS0172-OS0173, SM-OWW-SD-OS0173-OS0174, SM-OWW-SD-OS0174-OS0175, SM-OWW-SD-OS0175-OS0176, SM-OWW-SD-OS0176-OS0177, SM-OWW-SD-OS0177-OS0178, SM-OWW-SD-OS0178-OS0179, SM-OWW-SD-OS0179-OS0180, SM-OWW-SD-OS0180-OS0181, SM-OWW-SD-OS0181-OS0182, SM-OWW-SD-OS0182-OS0183, SM-OWW-SD-OS0183-OS0184, SM-OWW-SD-OS0184-OS0185, SM-OWW-SD-OS0185-OS0186, SM-OWW-SD-OS0186-OS0187, SM-OWW-SD-OS0187-OS0188, SM-OWW-SD-OS0188-OS0189, SM-OWW-SD-OS0189-OS0190, SM-OWW-SD-OS0190-OS0191, SM-OWW-SD-OS0191-OS0192, SM-OWW-SD-OS0192-OS0193, SM-OWW-SD-OS0193-OS0194, SM-OWW-SD-OS0194-OS0195, SM-OWW-SD-OS0195-OS0196, SM-OWW-SD-OS0196-OS0197, SM-OWW-SD-OS0197-OS0198, SM-OWW-SD-OS0198-OS0199, SM-OWW-SD-OS0199-OS0200, SM-OWW-SD-OS0200-OS0201, SM-OWW-SD-OS0201-OS0202, SM-OWW-SD-OS0202-OS0203, SM-OWW-SD-OS0203-OS0204, SM-OWW-SD-OS0204-OS0205, SM-OWW-SD-OS0205-OS0206, SM-OWW-SD-OS0206-OS0207, SM-OWW-SD-OS0207-OS0208, SM-OWW-SD-OS0208-OS0209, SM-OWW-SD-OS0209-OS0210, SM-OWW-SD-OS0210-OS0211, SM-OWW-SD-OS0211-OS0212, SM-OWW-SD-OS0212-OS0213, SM-OWW-SD-OS0213-OS0214, SM-OWW-SD-OS0214-OS0215, SM-OWW-SD-OS0215-OS0216, SM-OWW-SD-OS0216-OS0217, SM-OWW-SD-OS0217-OS0218, SM-OWW-SD-OS0218-OS0219, SM-OWW-SD-OS0219-OS0220, SM-OWW-SD-OS0220-OS0221, SM-OWW-SD-OS0221-OS0222, SM-OWW-SD-OS0222-OS0223, SM-OWW-SD-OS0223-OS0224, SM-OWW-SD-OS0224-OS0225, SM-OWW-SD-OS0225-OS0226, SM-OWW-SD-OS0226-OS0227, SM-OWW-SD-OS0227-OS0228, SM-OWW-SD-OS0228-OS0229, SM-OWW-SD-OS0229-OS0230, SM-OWW-SD-OS0230-OS0231, SM-OWW-SD-OS0231-OS0232, SM-OWW-SD-OS0232-OS0233, SM-OWW-SD-OS0233-OS0234, SM-OWW-SD-OS0234-OS0235, SM-OWW-SD-OS0235-OS0236, SM-OWW-SD-OS0236-OS0237, SM-OWW-SD-OS0237-OS0238, SM-OWW-SD-OS0238-OS0239, SM-OWW-SD-OS0239-OS0240, SM-OWW-SD-OS0240-OS0241, SM-OWW-SD-OS0241-OS0242, SM-OWW-SD-OS0242-OS0243, SM-OWW-SD-OS0243-OS0244, SM-OWW-SD-OS0244-OS0245, SM-OWW-SD-OS0245-OS0246, SM-OWW-SD-OS0246-OS0247, SM-OWW-SD-OS0247-OS0248, SM-OWW-SD-OS0248-OS0249, SM-OWW-SD-OS0249-OS0250, SM-OWW-SD-OS0250-OS0251, SM-OWW-SD-OS0251-OS0252, SM-OWW-SD-OS0252-OS0253, SM-OWW-SD-OS0253-OS0254, SM-OWW-SD-OS0254-OS0255, SM-OWW-SD-OS0255-OS0256, SM-OWW-SD-OS0256-OS0257, SM-OWW-SD-OS0257-OS0258, SM-OWW-SD-OS0258-OS0259, SM-OWW-SD-OS0259-OS0260, SM-OWW-SD-OS0260-OS0261, SM-OWW-SD-OS0261-OS0262, SM-OWW-SD-OS0262-OS0263, SM-OWW-SD-OS0263-OS0264, SM-OWW-SD-OS0264-OS0265, SM-OWW-SD-OS0265-OS0266, SM-OWW-SD-OS0266-OS0267, SM-OWW-SD-OS0267-OS0268, SM-OWW-SD-OS0268-OS0269, SM-OWW-SD-OS0269-OS0270, SM-OWW-SD-OS0270-OS0271, SM-OWW-SD-OS0271-OS0272, SM-OWW-SD-OS0272-OS0273, SM-OWW-SD-OS0273-OS0274, SM-OWW-SD-OS0274-OS0275, SM-OWW-SD-OS0275-OS0276, SM-OWW-SD-OS0276-OS0277, SM-OWW-SD-OS0277-OS0278, SM-OWW-SD-OS0278-OS0279, SM-OWW-SD-OS0279-OS0280, SM-OWW-SD-OS0280-OS0281, SM-OWW-SD-OS0281-OS0282, SM-OWW-SD-OS0282-OS0283, SM-OWW-SD-OS0283-OS0284, SM-OWW-SD-OS0284-OS0285, SM-OWW-SD-OS0285-OS0286, SM-OWW-SD-OS0286-OS0287, SM-OWW-SD-OS0287-OS0288, SM-OWW-SD-OS0288-OS0289, SM-OWW-SD-OS0289-OS0290, SM-OWW-SD-OS0290-OS0291, SM-OWW-SD-OS0291-OS0292, SM-OWW-SD-OS0292-OS0293, SM-OWW-SD-OS0293-OS0294, SM-OWW-SD-OS0294-OS0295, SM-OWW-SD-OS0295-OS0296, SM-OWW-SD-OS0296-OS0297, SM-OWW-SD-OS0297-OS0298, SM-OWW-SD-OS0298-OS0299, SM-OWW-SD-OS0299-OS0300, SM-OWW-SD-OS0300-OS0301, SM-OWW-SD-OS0301-OS0302, SM-OWW-SD-OS0302-OS0303, SM-OWW-SD-OS0303-OS0304, SM-OWW-SD-OS0304-OS0305, SM-OWW-SD-OS0305-OS0306, SM-OWW-SD-OS0306-OS0307, SM-OWW-SD-OS0307-OS0308, SM-OWW-SD-OS0308-OS0309, SM-OWW-SD-OS0309-OS0310, SM-OWW-SD-OS0310-OS0311, SM-OWW-SD-OS0311-OS0312, SM-OWW-SD-OS0312-OS0313, SM-OWW-SD-OS0313-OS0314, SM-OWW-SD-OS0314-OS0315, SM-OWW-SD-OS0315-OS0316, SM-OWW-SD-OS0316-OS0317, SM-OWW-SD-OS0317-OS0318, SM-OWW-SD-OS0318-OS0319, SM-OWW-SD-OS0319-OS0320, SM-OWW-SD-OS0320-OS0321, SM-OWW-SD-OS0321-OS0322, SM-OWW-SD-OS0322-OS0323, SM-OWW-SD-OS0323-OS0324, SM-OWW-SD-OS0324-OS0325, SM-OWW-SD-OS0325-OS0326, SM-OWW-SD-OS0326-OS0327, SM-OWW-SD-OS0327-OS0328, SM-OWW-SD-OS0328-OS0329, SM-OWW-SD-OS0329-OS0330, SM-OWW-SD-OS0330-OS0331, SM-OWW-SD-OS0331-OS0332, SM-OWW-SD-OS0332-OS0333, SM-OWW-SD-OS0333-OS0334, SM-OWW-SD-OS0334-OS0335, SM-OWW-SD-OS0335-OS0336, SM-OWW-SD-OS0336-OS0337, SM-OWW-SD-OS0337-OS0338, SM-OWW-SD-OS0338-OS0339, SM-OWW-SD-OS0339-OS0340, SM-OWW-SD-OS0340-OS0341, SM-OWW-SD-OS0341-OS0342, SM-OWW-SD-OS0342-OS0343, SM-OWW-SD-OS0343-OS0344, SM-OWW-SD-OS0344-OS0345, SM-OWW-SD-OS0345-OS0346, SM-OWW-SD-OS0346-OS0347, SM-OWW-SD-OS0347-OS0348, SM-OWW-SD-OS0348-OS0349, SM-OWW-SD-OS0349-OS0350, SM-OWW-SD-OS0350-OS0351, SM-OWW-SD-OS0351-OS0352, SM-OWW-SD-OS0352-OS0353, SM-OWW-SD-OS0353-OS0354, SM-OWW-SD-OS0354-OS0355, SM-OWW-SD-OS0355-OS0356, SM-OWW-SD-OS0356-OS0357, SM-OWW-SD-OS0357-OS0358, SM-OWW-SD-OS0358-OS0359, SM-OWW-SD-OS0359-OS0360, SM-OWW-SD-OS0360-OS0361, SM-OWW-SD-OS0361-OS0362, SM-OWW-SD-OS0362-OS0363, SM-OWW-SD-OS0363-OS0364, SM-OWW-SD-OS0364-OS0365, SM-OWW-SD-OS0365-OS0366, SM-OWW-SD-OS0366-OS0367, SM-OWW-SD-OS0367-OS0368, SM-OWW-SD-OS0368-OS0369, SM-OWW-SD-OS0369-OS0370, SM-OWW-SD-OS0370-OS0371, SM-OWW-SD-OS0371-OS0372, SM-OWW-SD-OS0372-OS0373, SM-OWW-SD-OS0373-OS0374, SM-OWW-SD-OS0374-OS0375, SM-OWW-SD-OS0375-OS0376, SM-OWW-SD-OS0376-OS0377, SM-OWW-SD-OS0377-OS0378, SM-OWW-SD-OS0378-OS0379, SM-OWW-SD-OS0379-OS0380, SM-OWW-SD-OS0380-OS0381, SM-OWW-SD-OS0381-OS0382, SM-OWW-SD-OS0382-OS0383, SM-OWW-SD-OS0383-OS0384, SM-OWW-SD-OS0384-OS0385, SM-OWW-SD-OS0385-OS0386, SM-OWW-SD-OS0386-OS0387, SM-OWW-SD-OS0387-OS0388, SM-OWW-SD-OS0388-OS0389, SM-OWW-SD-OS0389-OS0390, SM-OWW-SD-OS0390-OS0391, SM-OWW-SD-OS0391-OS0392, SM-OWW-SD-OS0392-OS0393, SM-OWW-SD-OS0393-OS0394, SM-OWW-SD-OS0394-OS0395, SM-OWW-SD-OS0395-OS0396, SM-OWW-SD-OS0396-OS0397, SM-OWW-SD-OS0397-OS0398, SM-OWW-SD-OS0398-OS0399, SM-OWW-SD-OS0399-OS0400, SM-OWW-SD-OS0400-OS0401, SM-OWW-SD-OS0401-OS0402, SM-OWW-SD-OS0402-OS0403, SM-OWW-SD-OS0403-OS0404, SM-OWW-SD-OS0404-OS0405, SM-OWW-SD-OS0405-OS0406, SM-OWW-SD-OS0406-OS0407, SM-OWW-SD-OS0407-OS0408, SM-OWW-SD-OS0408-OS0409, SM-OWW-SD-OS0409-OS0410, SM-OWW-SD-OS0410-OS0411, SM-OWW-SD-OS0411-OS0412, SM-OWW-SD-OS0412-OS0413, SM-OWW-SD-OS0413-OS0414, SM-OWW-SD-OS0414-OS0415, SM-OWW-SD-OS0415-OS0416, SM-OWW-SD-OS0416-OS0417, SM-OWW-SD-OS0417-OS0418, SM-OWW-SD-OS0418-OS0419, SM-OWW-SD-OS0419-OS0420, SM-OWW-SD-OS0420-OS0421, SM-OWW-SD-OS0421-OS0422, SM-OWW-SD-OS0422-OS0423, SM-OWW-SD-OS0423-OS0424, SM-OWW-SD-OS0424-OS0425, SM-OWW-SD-OS0425-OS0426, SM-OWW-SD-OS0426-OS0427, SM-OWW-SD-OS0427-OS0428, SM-OWW-SD-OS0428-OS0429, SM-OWW-SD-OS0429-OS0430, SM-OWW-SD-OS0430-OS0431, SM-OWW-SD-OS0431-OS0432, SM-OWW-SD-OS0432-OS0433, SM-OWW-SD-OS0433-OS0434, SM-OWW-SD-OS0434-OS0435, SM-OWW-SD-OS0435-OS0436, SM-OWW-SD-OS0436-OS0437, SM-OWW-SD-OS0437-OS0438, SM-OWW-SD-OS0438-OS0439, SM-OWW-SD-OS0439-OS0440, SM-OWW-SD-OS0440-OS0441, SM-OWW-SD-OS0441-OS0442, SM-OWW-SD-OS0442-OS0443, SM-OWW-SD-OS0443-OS0444, SM-OWW-SD-OS0444-OS0445, SM-OWW-SD-OS0445-OS0446, SM-OWW-SD-OS0446-OS0447, SM-OWW-SD-OS0447-OS0448, SM-OWW-SD-OS0448-OS0449, SM-OWW-SD-OS0449-OS0450, SM-OWW-SD-OS0450-OS0451, SM-OWW-SD-OS0451-OS0452, SM-OWW-SD-OS0452-OS0453, SM-OWW-SD-OS0453-OS0454, SM-OWW-SD-OS0454-OS0455, SM-OWW-SD-OS0455-OS0456, SM-OWW-SD-OS0456-OS0457, SM-OWW-SD-OS0457-OS0458, SM-OWW-SD-OS0458-OS0459, SM-OWW-SD-OS0459-OS0460, SM-OWW-SD-OS0460-OS0461, SM-OWW-SD-OS0461-OS0462, SM-OWW-SD-OS0462-OS0463, SM-OWW-SD-OS0463-OS0464, SM-OWW-SD-OS0464-OS0465, SM-OWW-SD-OS0465-OS0466, SM-OWW-SD-OS0466-OS0467, SM-OWW-SD-OS0467-OS0468, SM-OWW-SD-OS0468-OS0469, SM-OWW-SD-OS0469-OS0470, SM-OWW-SD-OS0470-OS0471, SM-OWW-SD-OS0471-OS0472, SM-OWW-SD-OS0472-OS0473, SM-OWW-SD-OS0473-OS0474, SM-OWW-SD-OS0474-OS0475, SM-OWW-SD-OS0475-OS0476, SM-OWW-SD-OS0476-OS0477, SM-OWW-SD-OS0477-OS0478, SM-OWW-SD-OS0478-OS0479, SM-OWW-SD-OS0479-OS0480, SM-OWW-SD-OS0480-OS0481, SM-OWW-SD-OS0481-OS0482, SM-OWW-SD-OS0482-OS0483, SM-OWW-SD-OS0483-OS0484, SM-OWW-SD-OS0484-OS0485, SM-OWW-SD-OS0485-OS0486, SM-OWW-SD-OS0486-OS0487, SM-OWW-SD-OS0487-OS0488, SM-OWW-SD-OS0488-OS0489, SM-OWW-SD-OS0489-OS0490, SM-OWW-SD-OS0490-OS0491, SM-OWW-SD-OS0491-OS0492, SM-OWW-SD-OS0492-OS0493, SM-OWW-SD-OS0493-OS0494, SM-OWW-SD-OS0494-OS0495, SM-OWW-SD-OS0495-OS0496, SM-OWW-SD-OS0496-OS0497, SM-OWW-SD-OS0497-OS0498, SM-OWW-SD-OS0498-OS0499, SM-OWW-SD-OS0499-OS0500, SM-OWW-SD-OS0500-OS0501, SM-OWW-SD-OS0501-OS0502, SM-OWW-SD-OS0502-OS0503, SM-OWW-SD-OS0503-OS0504, SM-OWW-SD-OS0504-OS0505, SM-OWW-SD-OS0505-OS0506, SM-OWW-SD-OS0506-OS0507, SM-OWW-SD-OS0507-OS0508, SM-OWW-SD-OS0508-OS0509, SM-OWW-SD-OS0509-OS0510, SM-OWW-SD-OS0510-OS0511, SM-OWW-SD-OS0511-OS0512, SM-OWW-SD-OS0512-OS0513, SM-OWW-SD-OS0513-OS0514, SM-OWW-SD-OS0514-OS0515, SM-OWW-SD-OS0515-OS0516, SM-OWW-SD-OS0516-OS0517, SM-OWW-SD-OS0517-OS0518, SM-OWW-SD-OS0518-OS0519, SM-OWW-SD-OS0519-OS0520, SM-OWW-SD-OS0520-OS0521, SM-OWW-SD-OS0521-OS0522, SM-OWW-SD-OS0522-OS0523, SM-OWW-SD-OS0523-OS0524, SM-OWW-SD-OS0524-OS0525, SM-OWW-SD-OS0525-OS0526, SM-OWW-SD-OS0526-OS0527, SM-OWW-SD-OS0527-OS0528, SM-OWW-SD-OS0528-OS0529,					

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
425	10	777	90536 Lucania Dr.	26C	114	18" RCP	Line runs from CB in front of property to CB across the cul-de-sac	SM-OSSE-SD-CB0085-CB0084	CB0085 to CB0084	46		10/13/2014	Hard deposits at starting at 9' to 13' approx. 15% and from 32' to 39' approx. 15%. Also a concrete deposit stuck in the middle of the pipe at 45' approx. 10%. Line is in good condition.
426	11	781	32448 Deluna Dr.	26C	114	18" RCP	Line runs from CB in front of property to MH in front of 3224 Deluna	SM-OSSE-SD-CB0079-MH0082	CB0079 to MH0082	140		2/21/1900	Deposits and debris in the pipe (approx. 5%). Line is in good condition.
427	13	784	28448 Indian Peak Rd.	4D	65	24" RCP	Line starts at CB on southwest corner to CB on northeast corner	SM-PWN-SD-CB2751-CB2750	CB2751 to 2750	26	26	11/18/2014	Hard deposits at 16' to 19' (approx. 10%). Overall line is clean and in good condition.
428	13	778	48 Via Porto Grande	5C	65	24" RCP	Line starts at CB on southeast corner to CB on northeast corner	SM-PWN-SD-CB2754-CB2755	CB2754 to CB2755	24.5	25	11/18/2014	Hard deposits from 6' to 15' (approx. 10%). Overall line is clean and in good condition.
429	14	786	Bld. at Indian Crest Rd.	8D	70	24" RCP	Line starts at CB in front of property to JS	SM-PWN-SD-CB2726-JS2730	CB2726 to JS2730	43	43	11/17/2014	Hard deposits at the beginning and end of line. Large rocks from 7' to 10'. Overall line is in good condition.
430	15	785	30560 Via La Cresta Rd.	12A	72	18" CMP	Line starts at CB on Hawthorne southbound to mainline	SM-PWN-SD-CB1431-JS2815	CB1431 to mainline	15.5	16	8/25/2014	The line is the same as line 149. Medium corrosion. Overall line is clean and in good condition.
431	16	710	30560 Via La Cresta Rd.	20D	96	18" RCP	Line starts at CB in front of property to JS	SM-OSW-SD-CB2617-JS2816	CB2617 to JS2816	53.6	54	12/17/2015	Water infiltration at 2.5' from 3 to 9 o'clock; hard deposits starting at 24' to 29' approx. 5%. Overall line is clean and in good condition.
432	17	833	2 Hardingale Dr.	15A	128	24" CMP	Line runs from CB on Hardingale southbound to OS down the canyon	LA-LAN-SD-CB0882-OS3202	CB0882 to OS3202	187	187	12/10/2014	Pipe is deformed starting at 42' to 47' from 7 to 12 o'clock. Pipe has been lined previously. Line is clean and in good condition.
433	18	865	Via Siena at Miralatte Dr.	16D	135	12" Concrete	Line starts at CB in front of 6617 Via Siena to CB across Miralatte Dr.	LA-LAE-SD-CB0839-CB0838	CB0839 to CB0838	62	62	12/9/2014	Hard deposits at the beginning of the line 10%. Broken pipe at 27' to 28' (repaired previously with PVC). Circumferential fracture at 48' and 56'. Exposed rebar at CB0838.
434	19	820	Bld. by City Hall	22B	96	18" RCP	Line runs from IS on Hawthorne southbound to MH on City Hall yard by driveway entrance	SM-OSW-SD-IS2805-CB2804	IS2805 to CB2804	10	10	1/5/2015	Mud and debris on pipe ~15%. Overall the pipe looks in good condition.
435	20	779	2769 San Ramon Dr.	27A	116	24" CMP	Line runs from CB in front of property to OS down the canyon	SM-OSSE-SD-CB0300-MH0301, SM-OSSE-SD-MH0301-CB3429, SM-OSSE-SD-CB3429-OS0302	CB0300 to OS0302	131	350	12/5/2014	Trash can cover stuck at pipe under unmaped MH. Pipe looks clean and in good condition. Inspection abandoned due to pipe inclination.
436	1	860	29 Via Malona	8D	70	24" RCP	Line runs from MH on property to MH in front of 45 Via Malona property	SM-PWN-SD-MH0726-MH0725, SM-PWN-SD-MH0725-JS2733	MH2726 to MH2733	299		11/7/2014	Hard deposits at JS 2725 from 5 to 7 o'clock. Overall pipe looks clean and in good condition.
437	2	861	45 Via Malona	8D	70	24" RCP	Line runs from MH in front of property to JS close to 43 PWN-SD-GB2733-MH2733, SM-PWN-SD-GB2733-MH2731, SM-PWN-SD-JS2730-GB2732	MH2733 to JS2730	315		11/7/2014	Hard deposits (~5%) for the first 7' from JS2730. Overall line is clean and in good condition.	
438	3	862	43 Via Porto Grande	8D	70	18" RCP	Line starts at CB in front of property to JS	SM-PWN-SD-CB2729-JS2730	CB2729 to JS2730	7		11/7/2014	Sediment and rocks in the pipe ~10%. Overall line is in good condition.
439	4	840	28448 Indian Peak Rd.	12C	78	18" CMP	Line starts at CB on Hawthorne southbound (approx. 520' south of intersection) to JS	SM-OSW-SD-CB1096-JS48112, SM-OSW-SD-MH2633-CB2634, SM-OSW-SD-GB2634-TS2635, SM-OSW-SD-TS2635-GB2636, SM-OSW-SD-TS2636-OS2633	CB1096 to JS2679	17		11/11/2014	Light corrosion throughout the pipe.
440	5	844	Sea View Ave.	19B	80	30" RCP	Line runs from MH in easement to OS	MH2632 to OS2633	170		11/14/2014	Water infiltration at 162' close to the OS from 10 to 2 o'clock. Overall pipe looks clean and in good condition.	
441	6	841	Via Vicente at PWDV at Via Hawthorne	20C	90	18" RCP	Del Cinto to MH in the middle of Via Vicente	SM-OSW-SD-CB1693-GB1694, SM-OSW-SD-GB1694-MH1694	CB1693 to MH1694	19		10/28/2014	Hard deposits starting at 12' from 5 to 7 o'clock ~5%. Overall line is clean and in good condition.
442	7	835	Vicente	20C	92	18" RCP	Line runs from CB on northwest corner of intersection to JS	CB1693 to CB1694	45		10/31/2014	Line has sediment from beginning of CB1711.1 to 12' approx. ~5%. Pipe is in good condition.	
443	8	863	Bld. at Valon Hawthorne	19C	98	18" RCP	Line starts at CB on northeast corner of intersection to JS	SM-OSW-SD-CB0724-JS0727	CB0724 to JS0727	35		11/4/2014	Hard deposits from the beginning of the pipe at CB to 18' (approx. 5% to 10%). Overall line is clean and in good condition.
444	9	864	Bld. at Valon Hawthorne	19C	98	18" RCP	Line starts at CB on southwest corner to OS in canyon	SM-OSW-SD-CB0721-OS0726	CB0721 to OS0726	130		11/4/2014	Pipe has been lined previously. Lining is wrinkled throughout the pipe. Overall line is clean and in good condition.
445	10	846	PWDV at PVC	22A	99	24" CMP	Line starts from IS to MH in front of PVC parking area	SM-OSW-SD-IS3601-MH3600	IS3601 to MH3600	28		10/16/2014	Line has debris (small tree sticks) throughout its length ~10%; overall line is clean and in good condition.
446	11	848	Sea Gate Dr.	23A	105	18" RCP	Line runs from CB to MH on Sea Gate	SM-OSW-SD-CB3541-MH3539	CB3541 to MH3539	17.5		10/24/2014	Hard deposits at 17' from 3 to 6 o'clock ~15%.
447	12	811	28444 Bayard Dr.	34C	126	24" RCP	Line starts at CB in property's corner to CB in front of 28444 Bayard Dr.	CB0021 to CB0022	68		10/6/2014	Hard deposits at the end of the line CB0021 ~5%. Overall pipe is clean and in good condition.	
448	13	815	2006 Noble View Dr.	34C	126	24" RCP	Line starts at CB in front of property on Noble View Dr. to CB in front of 28444 Bayard Dr.	CB0020 to CB0022	82		10/8/2014	Hard deposits from 29' to 41' ~5%. Overall pipe is clean and in good condition.	
449	14	817	1921 Upland St.	34C	126	18" RCP	Line runs from CB in front of property to MH behind the same property	CB3420 to MH0018	199		10/9/2014	Hard deposits at 21' from 5 to 7 ~10%. Overall pipe looks clean and in good condition.	
450	15	867	1982 General St.	34C	127	30" RCP	Line runs from CB in front of property to MH in 1903 Sumnerland St. Community Christian Church backyard	LA-LAE-SD-CB0005-GB0004, LA-LAE-SD-GB0004-GB1922, LA-LAE-SD-GB1922-JS1927, LA-LAE-SD-JS1927-MH1926	CB0005 to MH1926	427		10/9/2014	Small longitudinal crack from 122' to 126'. Circumferential crack from 8 to 4. Overall pipe is clean and in good condition.
451	16	851	Sumnerland St.	34C	127	36" RCP	Line runs from MH in property's backyard to MH on 28641 Western Ave.	LA-LAE-SD-MH1926-CB0001, LA-LAE-SD-GB0001-MH1928	MH1926 to MH1928	413		10/9/2014	Rebar exposure at 141' (position 11 o'clock). Overall pipe looks clean and in good condition.
452	17	854	28725 Grandpoint Ln.	16C	133	18" RCP	Line runs from CB in front of property to CB across the road	LA-LAS-SD-CB0822-CB0821	CB0822 to CB821	29		10/13/2014	Small circumferential crack at 0.5' and 24'. Overall pipe is clean and in good condition.
453	18	813	Water Reservoir	16C	136	18" RCP	PVDE at Cal Water Reservoir property	MH1227 to OS2622	178		10/13/2014	Deformed pipe at 39' (oval shape). Overall pipe is clean and in good condition.	
454	19	860	28722 Lomo Dr.	8A	68	18" RCP	Line starts at CB in front of property to OS in front of 28719 Plainfield Dr.	SM-PWN-SD-CB1372-OS1373	CB1372 to OS1373	93		11/10/2014	Deposits settled compacted at the beginning of the pipe from CB to 3' (approx. 5%).
455	20	841	Hawthorne Blvd. by City Hall	22B	97	30" CMP	Line starts at CB on Hawthorne northbound (approx. 685' east of City Hall driveway entrance) to OS.	CB0587 to OS0684-MH0591 77	172		11/25/2014	The first 27' from CB0587 have been lined previously. The rest of the pipe is unlined CMP with light to moderate corrosion throughout the pipe. Top portion of pipe has an open dent at 132.5'. Little debris in the pipe. CB0060 needs clearing; hard deposits at the beginning of the pipe. Overall pipe is clean and in good condition.	
456	21	780	32448 Deluna Dr.	26C	114	18" RCP	Line starts at CB in front of property to CB across Deluna Dr.	CB0080 to CB0079	36		10/13/2014	Deposits settled at the beginning of the CB to 5' approx. 5%. Overall line is in good condition.	
457	22	816	Peninsula Verde Dr.	32A	137	18" RCP	Line starts at CB in front of property on Western Ave. side to IS in the cemetery side	MH-LAN-SD-IS0214-CB0215, RHE-SD-MH0473-OS1407, RHE-SD-GB1473-OS1407, RHE-SD-GB1473-OS1407	CB0215 to IS0214	62.5		10/15/2014	Hard deposits at 6.5' to 10' approx. 5%. The rest of the pipe is clean and in good condition.
458	23	868	37666 Longhill Dr.	7D	71	24" RCP	Line runs from CB in front of property to OS of 4918 Elbridge Dr.	CB1463 to OS1464	430.7	440	12/22/2015		

Storm Drain Video Inspection & Cleaning Services FY 13-14

Number of Segments (Phase I & II)	Number of Segments after Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
459	34	460	Bldg. at Indian Valley Rd.	12A	24" CMP	Line starts at CB on Hawthorne next to 28457 Indian Valley Rd. to 77	SM-PVN-SD-CB1430-MH1434	CB1430 to MH1434	19	19	8/25/2014	Light to medium corrosion throughout the pipe. Overall the pipe is clean and in good condition.
460	20	461	Bldg. at Dupre Dr.	20B	18" CMP	Line starts at CB on Hawthorne Blvd. (approx. 145' north of Dupre Dr.) to CB 35' south	SM-OSW-SD-CB0746-CB0745	CB0746 to CB0745	35	35	11/26/2014	Black coating is peeling off; light corrosion throughout the pipe. Overall line looks clean and in good condition.
461	39	462	Crest Rd. at Ganado Dr.	26A	18" RCP	Line runs from CB on Crest northbound (approx. 140' south of Ganado Dr.) to CB 25' south	SM-OSW-SD-CB0746-CB0745	CB0746 to CB0745	27	27	12/15/2014	Circumferential crack at 24". Overall line looks clean and in good condition.
462	21	463	30665 PVIDE	26C	24" VCP	Line runs from IS in property to CB across PVIDE in front of 30676 PVIDE	SM-OSW-SD-CB0746-CB0745	CB0746 to CB0745	413	413	12/11/2014	The first 215 are Unfilled Clay pipe. Infiltration stain around the pipe. The rest of the pipe is black. The pipe material changes at 215 to RCP. Line is clean and in good condition.
463	29	464	Dawnless Dr.	25C	30" RCP	Line runs from CB in the grass area next to the Ladara Linda Comm. basketball courts	SM-OSW-SD-CB0746-CB0745	CB0746 to CB0745	754.7	754.7	12/5/2015	Minimal roots at joint 57.9'. Overall the line looks clean and in good condition.
464	23	465	PVIDE at Via Frascati	26B	12" RCP	Line starts at CB on PVIDE northbound (approx. 35' north of Via Frascati) to OS down the canyon.	LA-LAS-SD-CB0111-OS0112	CB0111 to OS0112	48	48	12/4/2015	Moderate joint offset at 41". Overall the line looks clean and in good condition.
465	35	466	4927 Golden Arrow Dr.	7D	18" RCP	Line starts at CB in front of property to CB in front of 4928 Golden Arrow Dr.	ML-RHE-SD-CB1459-CB1458	CB1459 to CB1458	35	35	12/23/2014	A little debris in pipe. Overall line is in good condition.
466	31	467	4926 Golden Arrow Dr.	7D	18" RCP	Line runs from CB in front of property to OS on Beechdale Dr. (behind same property)	ML-RHE-SD-CB1459-CB1458	CB1459 to CB1458	225.8	226	12/23/2014	Hard deposits at from 20' to 27' - 5%.
467	33	468	28702 Chatterbox Rd.	13A	24" RCP	Line starts at CB to MH in front of 28702 Chatterbox Rd.	ML-RHE-SD-CB1017-MH1018	CB1017 to MH1018	5	10	17/2015	Circumferential crack at 9". Overall line is clean and in good condition.
468	30	469	Forestal Dr. at 30676 PVIDE	25A	24" RCP	Line runs from CB at end of Interop cut-de-tac to JS	SM-OSW-SD-CB3199-JS3200	CB3199 to JS3200	81	81	16/2015	Sand and rock deposits throughout the pipe - 5%.
469	34	470	30676 PVIDE	16D	12" RCP	Line runs from CB on median to CB in front of property	LA-LAS-SD-CB0837-CB0836	CB0837 to CB0836	35	35	12/9/2014	Deposits starting at 20' to 30' approx. 5%. Overall line pipe looks clean and in good condition.
470	1	471	30676 PVIDE	20A	30" RCP	Line runs from CB in front of property to MH in front of 30643 Rue Valois	SM-OSW-SD-CB0837-MH1018	CB0837 to MH1018	24	24	10/24/2015	Pipe looks clean and in good condition.
471	2	472	38 Pacifica Del Mar	20C	42" RCP	Line runs from MH in front of property to CB in front of 30 Pacifica Del Mar	SM-OSW-SD-CB1686-CB1687	CB1686 to CB1687	340	340	10/24/2015	Pipe looks clean and in good condition.
472	3	473	3059 De Luna Dr.	26A	15" CMP	Line runs from CB in front of property to OS on 30321 Diamante Ln. backyard	LA-LAS-SD-CB0123-JS34128	CB0123 to JS34128	75.5	75.5	12/4/2015	Pipe looks clean and in good condition.
473	4	474	PVIDE at Via Colima	26B	30" CMP	Line runs from IS on west side of PVIDE to OS across the road	LA-LAS-SD-CB0123-JS34128	CB0123 to JS34128	176.5	176.5	12/4/2015	Pipe looks clean and in good condition.
474	5	475	4500 Via Colima	26B	18" RCP	Line starts at CB in front of property to CB across the road	LA-LAS-SD-CB0123-JS34128	CB0123 to JS34128	33	33	12/9/2015	Pipe looks clean and in good condition.
475	6	476	30534 Santa Luna Dr.	26C	18" RCP	Line starts at CB in front of property to CB across the road	LA-LAS-SD-CB0123-JS34128	CB0123 to JS34128	30	30	12/9/2015	Pipe has been lined previously. Line looks clean and in good condition.
476	7	477	Paseo Del Mar at PVIDE	28A	54" RCP	Line runs from IS east of Paseo Del Mar (approx. 290' south of PVIDE) to OS across Paseo Del Mar	LA-LAS-SD-CB0053-CB0054	CB0053 to CB0054	100	100	12/21/2015	All three videos show a clean pipe in good condition.
477	8	478	29408 Western Ave.	34A	40" RCP	Line starts at CB in front of property to CB in front of 29403 Western (HOP Restaurant)	LA-LAS-SD-CB0053-CB0054	CB0053 to CB0054	285	285	10/9/2015	Pipe looks clean and in good condition.
478	9	479	5412 Ironwood St.	5A	24" RCP	Line runs from CB on Montemalaga (behind 5412 Ironwood) to MH in front of 5412 Ironwood property	ML-PVN-SD-CB1559-TS2673	CB1559 to TS2673	168	168	11/24/2014	Pipe looks clean and in good condition.
479	10	480	26448 Birchfield Ave. @ Ironwood	5A	24" RCP	From MH in front of property to MH in front of 26448 Birchfield Ave. Ironwood St.	ML-PVN-SD-CB1559-TS2673	CB1559 to TS2673	241	241	11/24/2014	Pipe looks clean and in good condition.
480	11	481	5338 Ironwood St.	5A	18" RCP	Line starts at CB on Ironwood to MH on Ironwood westbound	ML-PVN-SD-CB1559-TS2673	CB1559 to TS2673	6	6	11/24/2014	Pipe looks clean and in good condition.
481	12	482	5338 Ironwood St.	5A	18" RCP	Line starts at CB in front of property to MH on Ironwood westbound	ML-PVN-SD-CB1559-TS2673	CB1559 to TS2673	27	27	11/24/2014	Pipe looks clean and in good condition.
482	13	483	5338 Ironwood St.	5A	24" RCP	Line runs from MH on Ironwood St. to OS behind 5321 Ironwood St. property	ML-PVN-SD-CB1559-TS2673	CB1559 to TS2673	603	603	11/24/2014	Uninspected MH at 457' from MH. Pipe looks clean and in good condition.
483	14	484	5305 Whitelock Dr.	5A	8" RCP	Line starts at CB on property corner to PC on Silver Spur Rd.	ML-PVN-SD-CB1549-PC1548	CB1549 to PC1548	21	21	11/16/2014	Line looks clean and in good condition.
484	15	485	26804 Basswood Ave.	4D	45" RCP	Line starts in front of property to MH in front of 26850 Basswood Ave.	SM-PVN-SD-MH2757-MH2762	MH2757 to MH2762	532	532	11/18/2014	Pipe looks clean and in good condition.
485	16	486	26850 Basswood Ave.	4D	45" RCP	Line runs from MH in front of property to OS on northeast corner of Basswood and Indian Peak	SM-PVN-SD-MH2757-MH2762	MH2757 to MH2762	530	530	11/18/2014	Pipe looks clean and in good condition.
486	17	487	26850 Basswood Ave. @ Indian Peak Rd.	4D	24" RCP	Line starts at CB on northwest corner to MH on northeast corner	SM-PVN-SD-CB2755-MH2761	CB2755 to MH2761	60	60	11/18/2014	Pipe looks clean and in good condition.
487	18	488	26850 Basswood Ave. @ Indian Peak Rd.	5C	24" RCP	Line runs from CB to MH on northeast corner	SM-PVN-SD-CB2755-MH2761	CB2755 to MH2761	46	46	11/18/2014	Pipe looks clean and in good condition.
488	19	489	26850 Basswood Ave. @ Indian Peak Rd.	4D & 5C	30" RCP	Line runs from MH on southeast corner to MH on northeast corner	SM-PVN-SD-MH2760-MH2761	MH2760 to MH2761	46	46	11/18/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
489	20	373	Basewood Ave. @ Indian Peak Rd.	5C	30" RCP	Line starts at CB in front of 26937 Basewood to MH in southeast corner of intersection	SM-PVN-SD-CB2752-MH2760	CB2752 to MH2760	32.5	33	11/18/2014	Pipe looks clean and in good condition.
490	21	374	Basewood Ave. @ Indian Peak Rd.	5C	30" RCP	Line starts at CB in front of 26940 Basewood to MH in southeast corner of intersection	SM-PVN-SD-CB2753-MH2760	CB2753 to MH2760	36	36	11/18/2014	Pipe looks clean and in good condition.
491	22	388	27869 Longhill Dr.	7D	34" RCP	Line starts at CB in front of property to CB in front of 27869 Longhill Dr.	ML-RHE-SD-CB1462-CB1463	CB1462 to CB1463	38	38	12/22/2015	
492	23	479	PVDW 30633 Rue	20A	36" RCP	Line runs from JS on PVDW northbound (approx 850' south of Rue Beaupre) to MH across PVDW	SM-OWW-SD-JS1627-JS1628, SM-OWW-SD-CB1625-CB1626	JS1627 to JS1628 to CB1625 to CB1626	105	118	10/24/2014	Pipe looks clean and in good condition.
493	24	491	Langlais 30633 Rue	20A	18" RCP	Line runs from CB in front of property to MH in front of 30625 Rue Langlais	SM-OWW-SD-CB3373-MH0616	CB3373 to MH0616	17	20	12/8/2014	Pipe looks clean and in good condition.
494	25	492	Langlais 30633 Rue	20A	18" RCP	Line starts at CB in front of property to CB across Rue Langlais	SM-OWW-SD-CB0615-CB3373	CB3373 to CB0615	39	39	12/8/2014	Pipe looks clean and in good condition.
495	26	494	Valois 30633 Rue	20A	36" RCP	Line runs from CB in front of property to Rue Valois northbound to CB on southbound	SM-OWW-SD-CB0615-CB0617	CB0615 to CB0617	23.5	23.5	10/24/2014	Pipe looks clean and in good condition.
496	27	504	Los Verdes Dr.	11D	18" RCP	Line starts at CB on Los Verdes Dr. northbound to JS on southbound	Repeat? (Line No. 447)	CB1118 to JS1516	34	34	11/5/2014	Pipe looks clean and in good condition.
497	28	530	Erlandida Highway	19A	34" CB	Line starts at CB on Hawthorne Blvd. to approx. 510' south of Dupre Dr. to CB 30' south	SM-OWW-SD-CB0760-CB0761	CB0760 to CB0761	25	25	11/26/2014	Pipe has been lined previously. Line looks clean and in good condition.
498	29	531	Hawthorne Blvd.	19A	34" CB	Line starts at CB on Hawthorne Blvd. to approx. 540' south of Dupre Dr. to CB across Hawthorne Blvd. on southbound	SM-OWW-SD-CB0761-CB0762	CB0761 to CB0762	77	77	11/26/2014	Pipe has been lined previously. Line looks clean and in good condition.
499	30	546	Mar Pacifica Del Mar	20C	34" RCP	Line runs from MH on Calle Viento to MH at intersection	SM-OWW-SD-JS1691-MH1685	MH1685 to MH1685	78	78	10/24/2014	Pipe looks clean and in good condition.
500	31	547	Calle Viento at Pacifica Del Mar	20C	34" RCP	Line starts at CB on Calle Viento (adjacent to 30 Pacifica Del Mar) to MH in the middle of Calle Viento	SM-OWW-SD-CB1689-MH1688	CB1689 to MH1688	33.5	33.5	10/24/2014	Pipe looks clean and in good condition.
501	32	548	9 Calle Viento	20C	18" RCP	Line starts at CB in front of property to MH in the middle of Calle Viento	SM-OWW-SD-CB1690-MH1688	CB1690 to MH1688	31	31	10/24/2014	Pipe looks clean and in good condition.
502	33	553	PVDW at Vicente	20C	36" RCP	Line runs from CB on PVDW northbound (approx 260' north of Hawthorne) to MH across PVDW in open space	SM-OWW-SD-CB3236-MH2625	MH2625 to MH2625	597	19-Aug	11/3/2014	Pipe looks clean and in good condition.
503	34	607	30971 Via La Cresta Rd.	20D	18" RCP	Line starts at CB in front yard of property to MH at via La Cresta cul-de-sac	SM-OWW-SD-CB2813-JS2812, SM-OWW-SD-JS2811-JS2812	CB2813 to JS2811 to JS2812	110	110	12/17/2015	Pipe looks clean and in good condition.
504	35	613	30980 Via La Cresta Rd.	20D	18" RCP	Line starts at CB between 30960 & 30970 Via La Cresta to MH on hill behind 30950 Via La Cresta	SM-OWW-SD-CB3236-MH2625	CB2625 to MH2625	194.4	194.5	12/19/2015	Pipe looks clean and in good condition.
505	36	615	30950 Via La Cresta Rd.	20D	12" RCP	Line starts at CB to JS on backyard property	SM-OWW-SD-CB3236-JS2822	CB2822 to JS2822	94	94	12/17/2015	Pipe looks clean and in good condition.
506	37	881	42 Seacove Dr.	23A	54" RCP	Line runs from MH in front of property to CB at the end of Seacove cul-de-sac	SM-OWW-SD-MH3526-CB3524	MH3526 to CB3524	107	107	10/21/2014	Pipe looks clean and in good condition.
507	38	687	Sea Gate Dr.	23A	66" STL	Line runs from MH on grass area of apartment complex to OS down the cliff	SM-OWW-SD-MH3539-OS3542	MH3539 to OS3542	291	291	10/20/2014	Pipe looks clean and in good condition.
508	39	753	30676 PVIDE	26C	36" RCP	Line runs from CB in front of property to MH down the canyon	SM-OWW-SD-MH4427-JS0065	CB0065 to MH0064	94	94	12/11/2014	Pipe looks clean and in good condition.
509	40	754	30676 PVIDE	26C	36" Other	Line runs from MH to OS down the canyon	SM-OWW-SD-JS0065-OS0064, SM-OWW-SD-JS0313-OS0312	MH0064 to OS0312	464	464	12/11/2014	Pipe looks clean and in good condition.
510	41	760	2950 PVIDE	27A	18" RCP	Line starts at CB on PVIDE southbound to OS0321	SM-OWW-SD-CB0322-OS0321	CB0322 to OS0321	21	21	12/15/2014	Pipe has been lined previously. Line looks clean and in good condition.
511	42	784	Ganado Dr. at Floweridge Dr.	28B	18" RCP	Line runs from CB on Ganado at Floweridge to OS in front of 31211 Floweridge	SM-OWW-SD-CB0342-OS0341, SM-OWW-SD-JS0311-CB0522, SM-OWW-SD-CB0522-CB0523, SM-OWW-SD-CB0523-MH0307	CB0342 to OS0341	121.6	121	12/22/2015	Pipe looks clean and in good condition.
512	43	785	La Rolonda Dr.	28B	36" RCP	Line starts at JS to MH at end of cul-de-sac	SM-OWW-SD-JS0311-MH0307	JS0311 to MH0307	331	340	12/5/2014	Pipe looks clean and in good condition.
513	44	786	La Rolonda Dr.	28B	36" RCP	Line runs from MH at end of cul-de-sac to OS in Golf Course	SM-OWW-SD-MH0307-JS28116, SM-OWW-SD-JS28116-MC0310	MH0307 to OS0310	204	204	12/5/2014	Pipe looks clean and in good condition.
514	45	788	La Rolonda Dr.	28B	18" RCP	Line runs from CB at end of the cul-de-sac to MH at end of cul-de-sac	SM-OWW-SD-CB0309-MH0307	CB0309 to MH0307	29	29	12/5/2014	Pipe looks clean and in good condition.
515	46	789	La Rolonda Dr.	28B	18" RCP	Line runs from CB to MH on La Rolonda westbound	SM-OWW-SD-CB0304-JS2897	CB0304 to JS2897	11	11	12/5/2014	Pipe looks clean and in good condition.
516	47	790	La Rolonda Dr.	28B	36" RCP	Line runs from CB to MH on La Rolonda eastbound	SM-OWW-SD-CB0303-JS2898	CB0303 to MH JS2898	9	9	12/5/2014	Circumferential crack at the beginning of the pipe. Overall the line looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 14

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments	
517	48	791	La Rolinda Dr.	288	122	36" RCP	Line starts at IS to MH	SM-OSE-SD-MH306-JS297, SM-OSE-SD-JS297-GB6524, SM-OSE-SD-JS298-GB6523, SM-OSE-SD-JS299-GB6522, SM-OSE-SD-JS300-GB6521, SM-OSE-SD-JS301-GB6520, SM-OSE-SD-JS302-GB6519, SM-OSE-SD-JS303-GB6518, SM-OSE-SD-JS304-GB6517, SM-OSE-SD-JS305-GB6516, SM-OSE-SD-JS306-GB6515, SM-OSE-SD-JS307-GB6514, SM-OSE-SD-JS308-GB6513, SM-OSE-SD-JS309-GB6512, SM-OSE-SD-JS310-GB6511, SM-OSE-SD-JS311-GB6510, SM-OSE-SD-JS312-GB6509, SM-OSE-SD-JS313-GB6508, SM-OSE-SD-JS314-GB6507, SM-OSE-SD-JS315-GB6506, SM-OSE-SD-JS316-GB6505, SM-OSE-SD-JS317-GB6504, SM-OSE-SD-JS318-GB6503, SM-OSE-SD-JS319-GB6502, SM-OSE-SD-JS320-GB6501, SM-OSE-SD-JS321-GB6500, SM-OSE-SD-JS322-GB6499, SM-OSE-SD-JS323-GB6498, SM-OSE-SD-JS324-GB6497, SM-OSE-SD-JS325-GB6496, SM-OSE-SD-JS326-GB6495, SM-OSE-SD-JS327-GB6494, SM-OSE-SD-JS328-GB6493, SM-OSE-SD-JS329-GB6492, SM-OSE-SD-JS330-GB6491, SM-OSE-SD-JS331-GB6490, SM-OSE-SD-JS332-GB6489, SM-OSE-SD-JS333-GB6488, SM-OSE-SD-JS334-GB6487, SM-OSE-SD-JS335-GB6486, SM-OSE-SD-JS336-GB6485, SM-OSE-SD-JS337-GB6484, SM-OSE-SD-JS338-GB6483, SM-OSE-SD-JS339-GB6482, SM-OSE-SD-JS340-GB6481, SM-OSE-SD-JS341-GB6480, SM-OSE-SD-JS342-GB6479, SM-OSE-SD-JS343-GB6478, SM-OSE-SD-JS344-GB6477, SM-OSE-SD-JS345-GB6476, SM-OSE-SD-JS346-GB6475, SM-OSE-SD-JS347-GB6474, SM-OSE-SD-JS348-GB6473, SM-OSE-SD-JS349-GB6472, SM-OSE-SD-JS350-GB6471, SM-OSE-SD-JS351-GB6470, SM-OSE-SD-JS352-GB6469, SM-OSE-SD-JS353-GB6468, SM-OSE-SD-JS354-GB6467, SM-OSE-SD-JS355-GB6466, SM-OSE-SD-JS356-GB6465, SM-OSE-SD-JS357-GB6464, SM-OSE-SD-JS358-GB6463, SM-OSE-SD-JS359-GB6462, SM-OSE-SD-JS360-GB6461, SM-OSE-SD-JS361-GB6460, SM-OSE-SD-JS362-GB6459, SM-OSE-SD-JS363-GB6458, SM-OSE-SD-JS364-GB6457, SM-OSE-SD-JS365-GB6456, SM-OSE-SD-JS366-GB6455, SM-OSE-SD-JS367-GB6454, SM-OSE-SD-JS368-GB6453, SM-OSE-SD-JS369-GB6452, SM-OSE-SD-JS370-GB6451, SM-OSE-SD-JS371-GB6450, SM-OSE-SD-JS372-GB6449, SM-OSE-SD-JS373-GB6448, SM-OSE-SD-JS374-GB6447, SM-OSE-SD-JS375-GB6446, SM-OSE-SD-JS376-GB6445, SM-OSE-SD-JS377-GB6444, SM-OSE-SD-JS378-GB6443, SM-OSE-SD-JS379-GB6442, SM-OSE-SD-JS380-GB6441, SM-OSE-SD-JS381-GB6440, SM-OSE-SD-JS382-GB6439, SM-OSE-SD-JS383-GB6438, SM-OSE-SD-JS384-GB6437, SM-OSE-SD-JS385-GB6436, SM-OSE-SD-JS386-GB6435, SM-OSE-SD-JS387-GB6434, SM-OSE-SD-JS388-GB6433, SM-OSE-SD-JS389-GB6432, SM-OSE-SD-JS390-GB6431, SM-OSE-SD-JS391-GB6430, SM-OSE-SD-JS392-GB6429, SM-OSE-SD-JS393-GB6428, SM-OSE-SD-JS394-GB6427, SM-OSE-SD-JS395-GB6426, SM-OSE-SD-JS396-GB6425, SM-OSE-SD-JS397-GB6424, SM-OSE-SD-JS398-GB6423, SM-OSE-SD-JS399-GB6422, LA-LAE-SD-MH0018-CB0014	IS MH306 to MH1874	813	813	12/4/2014	Pipe looks clean and in good condition.	
518	49	794	La Rolinda Dr.	288	122	18" RCP		Line runs from IS to MH in the Golf Course	SM-OSE-SD-JS1870-GB2115, SM-OSE-SD-GB2115-MH1874	IS1870 to MH1874	168	?	12/5/2014	Inspection abandoned due to pipe inclination. Pipe looks clean and in good condition.
519	50	795	La Rolinda Dr.	288	122	36" RCP		Line runs from MH to MH in Golf Course	SM-OSE-SD-MH1874-GB1875, SM-OSE-SD-GB1875-MH1871	MH1874 to MH1871	415	415	12/5/2014	Pipe looks clean and in good condition.
520	51	796	La Rolinda Dr.	288	122	36" RCP		Line runs from MH to OS in Golf Course	SM-OSE-SD-MH1871-MC1872, SM-OSE-SD-MC1872-JS1876, SM-OSE-SD-MC1873-JS1877	MH1871 to OS1877	357	400	12/5/2014	Pipe looks clean and in good condition.
521	52	797	Sunnyvale Pkwy	158	123	18" CP		Line runs from CB at end of cul-de-sac to OS behind	LA-LAN-SD-CB0933-OS0931	CB0930 to OS0931	157	157	10/7/2014	Pipe has been lined previously. Line looks clean and in good condition.
522	53	818	1921 Upland St.	34C	126	36" RCP	Line runs from MH in property's backyard to CB in front of 1843 MacArthur St.	LA-LAE-SD-MH0018-CB0422, LA-LAE-SD-GB3422-MH3423	MH IS0018 to CB0014	659	659	12/19/2015	Pipe looks clean and in good condition.	
523	54	829	Dr.	15A	128	24" CMP	Line starts at CB in front of property to CB across the road	LA-LAN-SD-CB0883-CB0882	CB0883 to CB0882	33	33	12/10/2014	Pipe looks clean and in good condition.	
524	55	831	26087 PVIDE	16A	129	36" CMP	Line runs from IS in property's backyard adjacent to Main St. to OS down the canyon across PVIDE	LA-LAE-SD-ISO876-OS0879	ISO878 to OS0879	330	330	12/11/2014	Pipe has been lined previously. Line is clean and in good condition.	
525	56	832	29088 Clewis Rd.	16A	129	18" CMP	Line runs from OS at end of the cul-de-sac to OS behind property	LA-LAE-SD-CB0881-OS0880	CB0881 to OS0880	125	125	12/10/2014	Pipe has been lined previously. Line is clean and in good condition.	
526	57	834	29088 PVIDE	16A	129	18" CP	Line runs from IS on driveway adjacent to Main St. Library to CB across driveway	LA-LAE-SD-CB0877-CB0875	CB0877 to CB0875	14	14	12/15/2014	Pipe has been lined previously. Line is clean and in good condition.	
527	58	835	29088 PVIDE	16A	129	18" RCP	Line runs from CB on driveway adjacent to Main St. Library to OS down the canyon across PVIDE	LA-LAE-SD-CB0875-OS0872	CB0875 to OS0872	26	26	12/15/2014	Circumferential crack at 1'. Overall line is clean and in good condition.	
528	59	836	PVIDE at Coll Rd.	16A	129	18" CP	Line runs from CB on PVIDE northbound (approx. 350' north of Coll Rd.) to OS down the canyon	LA-LAE-SD-CB0874-OS0873	CB0874 to OS0873	20.5	21	12/15/2014	Pipe has been lined previously. Line is clean and in good condition.	
529	60	837	3330 PVIDE	16A	129	24" CMP	Line runs from CB on PVIDE southbound (approx. 425' south of Coll Rd.) to CB across PVIDE	LA-LAE-SD-CB0869-CB0870, LA-LAE-SD-CB0870-OS0871	CB0869 to CB0870-OS0871	139	139	12/10/2014	Pipe has been lined previously. Line is clean and in good condition.	
530	61	838	3330 PVIDE	16A	129	UNKNOWN	Same as Line 837. Line runs from CB on PVIDE northbound (approx. 425' south of Coll Rd.) to OS.	LA-LAE-SD-CB0870-OS0871	CB0870 to OS0871	40	40	12/10/2014	Same as line 837	
531	62	868	MacArthur St.	16D	135	18" CMP	Line runs from IS behind property to OS2141 Noble View Dr.	LA-LAE-SD-ISO029-GB3414, LA-LAE-SD-GB3414-JS3413	ISO029 to MH3413 OS0409	98	98	12/9/2014	Pipe has been lined previously. Line is clean and in good condition.	
532	63	876	Verde Dr.	32A	137	18" RCP	Line starts at CB in front of property on Western Ave. side to mainline	ML-LAN-SD-CB0218-TS14136	CB0218 to Mainline	44.6	44.6	12/18/2015	Pipe looks clean and in good condition.	
532	65	359	28019 Indian Rock Dr.	3D	63	24" RCP	Line starts at CB in front of property to OS in front of 6910 Maycroft Dr.	SM-PWN-SD-CB3351-GB3356, SM-PWN-SD-GB3356-MH3357, SM-PWN-SD-MH3357-OS3358	CB3351 to OS3358	161	161	11/7/2014	Pipe looks clean and in good condition.	
533	64	877	Penninsula Verde Dr.	32A	137	18" RCP	Line starts at CB in front of property on Western Ave. side to mainline	ML-LAN-SD-CB0215-TS14135	CB0215 to Mainline	75.7	76	12/18/2015	Pipe looks clean and in good condition.	
534	66	359	Ambegalle Dr.	3D	63	24" RCP	Line starts at CB in front of property to OS on southwest corner of Brookford Dr./Ambegalle Dr.	SM-PWN-SD-CB3351-GB3356, SM-PWN-SD-GB3356-MH3357, SM-PWN-SD-MH3357-OS3358	CB3351 to OS3358	115	115	11/7/2014	Pipe looks clean and in good condition.	
535	67	360	Ave.	4D	64	30" RCP	Line starts at CB on property (Mossbank Dr. side) to MH on Mossbank	SM-PVN-SD-CB2759-MH2763	CB2759 to MH2763	6	6	11/19/2014	Pipe looks clean and in good condition.	
536	68	361	Ave.	4D	64	30" RCP	Line starts at CB on property (Mossbank Dr. side) to MH on Mossbank	SM-PVN-SD-CB2759-MH2763	CB2759 to MH2763	26	26	11/19/2014	Pipe looks clean and in good condition.	
537	69	362	Ave.	4D	64	45" RCP	Line starts at MH at end of Mossbank cul-de-sac to MH in front of 26804 Basswood Ave.	SM-PVN-SD-MH2762-MH2763	MH2763 to MH2762	189	189	11/19/2014	Pipe looks clean and in good condition.	
538	70	364	Ave.	4D	64	18" RCP	Line starts at CB in front of property to MH on Basswood northbound	SM-PVN-SD-CB2774-MH2762	CB2774 to MH2762	27	27	11/19/2014	Pipe looks clean and in good condition.	
539	71	367	Basswood @ 27002 Shorewood Rd.		65	18" RCP	Line starts at CB on 27002 Shorewood (Basswood Ave. side) to JS in front of 269002 Basswood Ave.	SM-PVN-SD-CB2756-JS2768	CB2756 to JS2768	27		11/19/2014	Pipe looks clean and in good condition.	
540	72	375	Whitehorn Dr.	5C	66	21" RCP	Line starts at MH in front of property to CB in front of 5108 Elmont Dr.	ML-RHE-SD-MH1543-CB1542	MH1543 to CB1542	365		11/10/2014	Pipe looks clean and in good condition.	
541	73	376	Whitehorn Dr.	5C	66	18" RCP	Line runs from CB in front of property to CB in front of 5108 Elmont Dr.	ML-RHE-SD-CB1541-CB1542	CB1541 to CB1542	30		11/10/2014	Pipe looks clean and in good condition.	
542	74	377	Pinefield Dr.	9B	67	27" RCP	Line runs from MH in front of property to JS in front of 6762 Birchmont Dr.	SM-PWN-SD-MH1282-JS1622	MH1282 to JS1622	411		11/7/2014	Pipe looks clean and in good condition.	
543	75	378	Pinefield Dr.	9B	67	18" RCP	Line runs from JS in front of property to OS in front of 28348 Plainfield Dr.	SM-PWN-SD-CB1252-CB1251	CB1252 to CB1251	32		11/7/2014	Pipe to clean and in good condition.	

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Storm Drain Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
544	76	384	27405 Elmridge Dr.	7B	15" RCP	Line starts at CB in front of property to CB across Elmridge road	ML-RHE-SD-CB1480-CB1479	CB1480 to CB1479	37		11/10/2014	Pipe looks clean and in good condition.
545	77	385	4876 Browder Ln.	7B	18" RCP	Line runs from CB in front of property on Elmridge Dr. side to JS on Browder Ln.	ML-RHE-SD-CB1479-JS2685	CB1479 to JS2685	52		11/10/2014	Pipe looks clean and in good condition.
546	78	418	PVDW at Marguerite Dr.	11C	18" RCP	Line starts at CB on PVDW northbound to CB on center median	SM-OWW-SD-CB1243-JS3197, SM-OWW-SD-JS3197-CB1244	CB1243 to CB1244	293		11/3/2014	Pipe looks clean and in good condition.
547	79	419	PVDW at Marguerite Dr.	11A	24" RCP	Line runs from CB on PVDW median (200' north of Marguerite Dr.) to MH on median, 35' north	SM-OWW-SD-CB1244-MH3462	CB1244 to MH3462	38		11/25/2014	Pipe looks clean and in good condition.
548	80	421	7460 Alida Pl.	11C	24" RCP	Lines runs from CB in front of property to MH 40' west	SM-OWW-SD-CB1245-MH3129	CB1245 to MH3129	41		11/4/2014	Pipe looks clean and in good condition.
549	81	423	PVDW at Alida Pl.	11A	24" RCP	Line runs from MH on PVDW northbound (approx. 95' north of Alida Pl.) to CB on PVDW median	SM-OWW-SD-MH3131-MH3462, SM-OWW-SD-CB1244-MH3462	MH3131 to CB1244	68		11/3/2014	Pipe looks clean and in good condition.
550	82	424	PVDW at Alida Pl.	11A	24" RCP	Line runs from MH on PVDW northbound (approx. 95' north of Alida Pl.) to JS	SM-OWW-SD-JS3130-JS3133, SM-OWW-SD-JS3133-MH3131	MH3131 to JS3130	20		11/11/2014	Pipe looks clean and in good condition.
551	83	427	PVDW	11A	24" RCP	Line runs from MH on PVDW median (approx. 230' north of Marguerite Dr.) to OS	OWW-SD-CB3463-GB3464, SM-OWW-SD-CB3464-GB3465, SM-OWW-SD-CB3465-GB3466	MH3462 to OS1246	1067		11/3/2014	Pipe looks clean and in good condition.
552	84	429	PVDW at Via Lorado	11C	18" RCP	Line runs from CB in front of 7442 Via Lorado to MH on PVDW median	SM-OWW-SD-CB1248-MH1247	CB1248 to MH1247	123		10/31/2014	Pipe looks clean and in good condition.
553	85	432	Pierre at Rue Languois	20A	18" RCP	Line starts at CB on Rue De La Pierre to CB in front of 30507 Rue De La Pierre	SM-OWW-SD-CB1300-CB3299	CB3300 to CB3299	27		11/3/2014	Pipe looks clean and in good condition.
554	86	433	Rue De La Pierre at Rue Languois	20A	24" RCP	Line starts at CB in front of property to CB in front of 30503 Rue Languois	SM-OWW-SD-CB3299-CB3302	CB3299 to CB3302	79		11/3/2014	Pipe looks clean and in good condition.
555	87	434	Pierre at Rue Languois	20A	18" RCP	Line starts at CB on Rue Languois to CB in front of 30503 Rue Languois	SM-OWW-SD-CB3301-CB3302	CB3301 to CB3302	43		11/3/2014	Pipe looks clean and in good condition.
556	88	469	Entrader by Parking Area	20A	18" RCP	Line starts at CB behind 11 Via Del Cielo property to CB across Calle Entrader	SM-OWW-SD-CB1733-GB1734, SM-OWW-SD-GB1734-CB1735	CB1733 to CB1735	27.5		10/20/2014	Pipe looks clean and in good condition.
557	89	470	Entrader by Parking Area	20A	24" RCP	Line runs from CB adjacent to the south entrance/exit of parking area to MH in parking area	SM-OWW-SD-CB1735-MH1736	CB1735 to MH1736	62.5		10/20/2014	Pipe looks clean and in good condition.
558	90	471	Entrader by Parking Area	20A	18" RCP	Line runs from CB in parking area south corner to MH in the middle of parking driveway	SM-OWW-SD-CB1737-MH1738	CB1737 to MH1738	28.5		10/20/2014	Pipe looks clean and in good condition.
559	91	472	10 Via Del Cielo	20A	24" RCP	Line runs from MH on parking area to JS	SM-OWW-SD-MH1736-JS1731	MH1736 to JS1731	382		10/20/2014	Pipe looks clean and in good condition.
560	92	473	Cielo	20A	30" RCP	Line runs from CB in front of property to MH in the middle of the street	SM-OWW-SD-CB1738-MH1738	CB1738 to MH1738	20		10/20/2014	Pipe looks clean and in good condition.
561	93	474	Cielo	20A	30" RCP	Line runs from MH in front of property to MH in the middle of the street	SM-OWW-SD-CB1740-MH1739	CB1740 to MH1739	30		10/20/2014	Pipe looks clean and in good condition.
562	94	475	Cielo	20A	18" RCP	Line runs from MH in front of property to MH on front yard of 5 Via Del Cielo	SM-OWW-SD-MH1739-MH1736	MH1739 to MH1736	166		10/20/2014	Pipe looks clean and in good condition.
563	95	476	PVDW	20A	18" RCP	Line runs from CB on PVDW northbound (approx. 850' north of Hawthorne Blvd.) to MH 70' south	SM-OWW-SD-CB0614-JS1627	CB0614 to MH1627	8		11/25/2014	JS is a MH1627. Pipe looks clean and in good condition.
564	96	481	PVDW	20A	24" RCP	Line runs from CB on PVDW southbound (approx. 1800' north of Hawthorne Blvd.) to MH 70' south	SM-OWW-SD-CB0613-MH1624	CB0613 to MH1624	66		11/25/2014	Pipe looks clean and in good condition.
565	97	482	PVDW	20A	40" RCP	Line runs from MH on PVDW southbound (approx. 1750' north of Hawthorne Blvd.)	OWW-SD-TS0632-GB1628, SM-OWW-SD-GB1628-MH1630	MH1624 to MH1630	270		10/20/2014	Inspection abandoned due to camera inability to make a turn. Pipe looks clean and in good condition.
566	98	483	70 Calle Hawthorne Blvd.	20A	40" RCP	Line runs from MH in front of property to MH on Calle Cordoba (8 Via Del Cielo	SM-OWW-SD-CB1629-MH1630, SM-OWW-SD-TS0632-GB1628	MH1630 to MH1632	244		10/20/2014	Pipe looks clean and in good condition.
567	99	520	30624 Carlier Dr.	19A	24" CMP	Line starts at CB to CB in front of property	SM-OSW-SD-CB0745-CB0748	CB0745 to CB0748	32		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
568	100	521	Carlier Dr.	19A	24" CMP	Line runs from CB to MH on Carlier Dr. at Duque Dr.	SM-OSW-SD-CB0748-MH0759	CB0748 to MH0759	56		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
569	101	523	Duque Dr. at Hawthorne Blvd.	19A	30" CMP	Line runs from MH at intersection to MH on Duque Dr. at Hawthorne Blvd.	SM-OSW-SD-MH0759-MH0758	MH0759 to MH0758	130		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
570	102	524	Hawthorne Blvd.	19A	24" CMP	Line starts at CB on Duque Dr. eastbound to MH in the middle of the road	SM-OSW-SD-CB0743-MH0758	CB0743 to MH0758	28		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
571	103	525	Duque Dr. at Hawthorne Blvd.	19A	24" CMP	Line starts at CB on Duque Dr. westbound to MH in the middle of the road	SM-OSW-SD-CB0744-MH0758	CB0744 to MH0758	9		11/5/2014	Pipe has been lined previously. Overall line is clean and in good condition.
572	104	526	Hawthorne Blvd.	19A	42" CMP	Line runs from MH at intersection to MH on Hawthorne Blvd.	Request? (Line No. 509)	MH1631 to MH1632	497		11/5/2014	Pipe looks clean and in good condition.
573	105	576	PVDW	20C	40" RCP	Line runs from MH on PVDW by St. Paul's Lutheran Church corner with cul-de-sac to 77	SM-OWW-SD-MH2749-CS20928	SM-OWW-SD-MH2749-CS20928	228		10/21/2014	Pipe looks clean and in good condition.
574	106	577	PVDW by St. Paul's Lutheran Church	20C	48" RCP	Line runs from MH at corner of St. Paul's Lutheran Church and cul-de-sac to MH on Via Capri	SM-OWW-SD-MH2749-JS46033, SM-OWW-SD-GB2748-JS46033, SM-OWW-SD-JS2747-GB2748, SM-OWW-SD-JS2745-JS2747, SM-OWW-SD-JS2745-JS2745, SM-OWW-SD-MH2741-JS2743	MH2741 to MH2749	488		10/28/2014	Pipe looks clean and in good condition.
575	107	581	Via Capri	20D & 20C	42" RCP	Line runs from MH on Via Capri to Via San Remo to MH on Via Capri (old curve from Via Capri gated entrance)	SM-OWW-SD-JS2745-JS2746, SM-OWW-SD-JS2746-MH2741	MH2745 to MH2741	305		10/28/2014	Pipe looks clean and in good condition.
576	108	582	Via Capri	20D	18" RCP	Line runs from CB on Via Capri at Via Vento to JS	SM-OWW-SD-CB2739-JS2740	CB2739 to JS2740	20		10/28/2014	Pipe looks clean and in good condition.
577	109	584	Via Capri	20D	18" RCP	Line runs from CB on Via Capri at Via San Remo to MH in the middle of the street	SM-OWW-SD-CB2735-MH2735	CB2735 to MH2735	18		10/28/2014	Pipe looks clean and in good condition.
578	110	585	Via Capri Blvd. at Via Riera	20D	48" RCP	Line runs from MH on undesignated area by Villa Capri gate entrance to MH on Via Capri at Via San Remo	SM-OWW-SD-MH2734-MH2735	MH2734 to MH2735	365		10/28/2014	Pipe looks clean and in good condition.
579	111	587	Rivers	20D	18" RCP	Line runs from CB on Hawthorne northbound (approx. 365' south of Via Riera) to JS	SM-OWW-SD-CB2686-JS2689	CB2686 to JS2689	18		10/28/2014	Pipe looks clean and in good condition.
580	112	588	Rivers Blvd. at Via Hawthorne	20D	40" RCP	Line runs from MH in the middle of Hawthorne southbound (approx. 340' South of Via Riera) to MH on landscaped area by Villa Capri gate entrance	SM-OWW-SD-MH2810-JS2809, SM-OWW-SD-JS2809-MH2734	MH2810 to MH2734	96		10/27/2014	Pipe looks clean and in good condition.
581	113	589	Via Hawthorne Blvd. at Via Rivers	20D	42" RCP	Line runs from MH on Hawthorne southbound (approx. 175' of Via Riera) to MH in the middle of Hawthorne southbound	SM-OWW-SD-MH2852-MH2810	MH2852 to MH2810	47		10/27/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 14

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Storm Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
582	114	590	7095 Via Del Mar	20D	42" RCP	Line runs from MH in front of property to MH on Hawthorne (approx. 175' of Via Rivera)	SM-OSW-SD-MH2845-JS2846, SM-OSW-SD-JS2846-JS2848, SM-OSW-SD-JS2848-JS2850, SM-OSW-SD-JS2850-MH2852	MH2845 to MH2852	173		10/27/2014	Pipe looks clean and in good condition.
583	115	592	7100 Via Del Mar	20D	18" RCP	Line starts at CB between 7100 & 7090 Via Del Mar to JS	SM-OSW-SD-CB2847-JS2848	CB2847 to JS2848	6		10/27/2014	Pipe looks clean and in good condition.
584	116	593	7095 Via Del Mar	20D	18" RCP	Line starts at CB in front of property to MH	SM-OSW-SD-CB2844-MH2845	CB2844 to MH2845	13.5		10/27/2014	Pipe looks clean and in good condition.
585	117	595	7095 Via Del Mar	20D	36" RCP	Line starts at MH between 7100 & 7090 Via Del Mar to MH on Hawthorne (approx. 175' of Via Rivera)	SM-OSW-SD-JS2848-JS2850, SM-OSW-SD-JS2850-MH2852	MH2850 to MH2852	155		10/27/2014	Pipe looks clean and in good condition.
586	118	598	7060 Via Del Mar	20D	18" RCP	Line starts at CB between 7070 & 7060 Via Del Mar to JS	SM-OSW-SD-JS2842-JS2843	CB2842 to JS2843	8		10/27/2014	Pipe looks clean and in good condition.
597	119	599	7065 Via Del Mar	20D	18" RCP	Line starts at CB between 7065 & 7055 Via Del Mar to JS	SM-OSW-SD-CB2832-JS2833	CB2832 to JS2833	5		11/7/2014	Pipe looks clean and in good condition.
598	120	600	7060 Via Del Mar	20D	24" RCP	Line runs from MH in front of property to CB between 7070 & 7060 Via Del Mar	SM-OSW-SD-MH2835-MH2836	MH2835 to MH2836	79		10/27/2014	Pipe looks clean and in good condition.
599	121	602	Via Del Mar cul de-sac	20D	24" RCP	Line runs from MH at end of cul-de-sac to MH in front of 7060 Via Del Mar	SM-OSW-SD-MH2834-MH2835	MH2834 to MH2835	68		11/20/2014	Pipe looks clean and in good condition.
599	122	603	Via Del Mar cul de-sac	20D	24" RCP	Line starts at CB in open space by cul-de-sac to MH at end of cul-de-sac	SM-OSW-SD-CB2833-MH2834	CB2833 to MH2834	63		11/20/2014	Pipe looks clean and in good condition.
599	123	606	Blvd by City Hall	20D	18" RCP	Line runs from CB on Hawthorne southbound (approx. 815' northwest of City Hall driveway) to PC	SM-OSW-SD-CB0584-PC0585	CB0584 to PC0585	110.5		10/30/2014	Pipe looks clean and in good condition.
599	124	608	30963 Via La Cresta Rd.	20D	24" RCP	Line starts at JS between 30959 & 30963 Via La Cresta to JS	SM-OSW-SD-JS2811-JS2812	JS2811 to JS2812	44		10/30/2014	Pipe looks clean and in good condition.
599	125	609	30959 Via La Cresta Rd.	20D	24" RCP	Line starts at CB in front of property to MH in the middle of the road	SM-OSW-SD-CB2815-MH2814	CB2815 to MH2814	40		10/30/2014	Pipe looks clean and in good condition.
594	126	612	30950 Via La Cresta Rd.	20D	30" RCP	Line runs from MH in front of property to MH on hill behind property	SM-OSW-SD-MH2825-MH2827	MH2825 to MH2827	185.5		10/30/2014	Pipe looks clean and in good condition.
595	127	616	30950 Via La Cresta Rd.	22B & 20D	30" RCP	Line runs from MH on hill behind property to MH off of Hawthorne southbound	SM-OSW-SD-MH2827-GB2853, SM-OSW-SD-GB2853-JS2828, SM-OSW-SD-JS2828-MH2829	MH2827 to MH2829	252		10/30/2014	Pipe looks clean and in good condition.
598	128	617	Hawthorne Blvd by City Hall	22B	30" RCP	Line runs from MH Hawthorne southbound to MH on City Hall yard by driveway entrance	SM-OSW-SD-CB0595-CB0595	CB0595 to CB0595	176		10/30/2014	Pipe looks clean and in good condition.
597	129	619	Hawthorne Hall	22B	18" RCP	Line runs from CB on Hawthorne southbound to MH on City Hall yard by driveway entrance	SM-OSW-SD-CB0595-CB0595	CB0595 to CB0595	135.5		10/30/2014	Pipe looks clean and in good condition.
598	130	625	Bivd.	20D	24" RCP	Line starts at CB on Hawthorne southbound (approx. 1300' south of Vallon Dr.) to CB on Hawthorne northbound	SM-OSW-SD-CB0752-CB0751	CB0752 to CB0751	83		11/25/2014	Pipe looks clean and in good condition.
599	131	628	Bivd.	20D	24" CIPP	Line starts at CB on Hawthorne southbound (approx. 1300' south of Vallon Dr.) to OS	SM-OSW-SD-CB0751-CB0750	CB0751 to CB0750	50		11/25/2014	Pipe looks clean and in good condition.
600	132	627	Bivd.	19C	30" RCP	Line starts at CB on Hawthorne southbound (approx. 535' south of Vallon Dr.) to CB on Hawthorne northbound	SM-OSW-SD-CB0751-CB0750	CB0751 to CB0750	104		11/25/2014	Pipe looks clean and in good condition.
601	133	628	Bivd.	19C	30" RCP	Line starts at CB in front of 31325 Mame Dr. to CB across Mame Dr.	SM-OSW-SD-CB0719-MH1619	CB0719 to MH1619	24		11/25/2014	Pipe looks clean and in good condition.
602	134	636	31325 Mame Dr.	19C	30" CMP	Line runs from CB in front of 31326 Mame Dr. to MH in front of 31311 Mame Dr.	SM-OSW-SD-CB0719-MH1619	CB0719 to MH1619	35		11/25/2014	Pipe looks clean and in good condition.
603	135	637	31326 Mame Dr.	19C	36" CMP	Line runs from CB at the east end of road to OS on Coast Side Dr.	SM-OSW-SD-CB2866-OS2867	CB2866 to OS2867	104		11/25/2014	Pipe looks clean and in good condition.
604	136	649	Via Pacifica east cul-de-sac	23A	18" RCP	Line runs from CB at the east end of road to OS on Coast Side Dr.	SM-OSW-SD-CB2866-OS2867	CB2866 to OS2867	128		10/21/2014	Pipe looks clean and in good condition.
605	137	648	Via Baron	23A	18" RCP	Line runs from CB behind 6508 Via Baron to JS in front of 6508 Via Baron	SM-OSW-SD-CB2872-JS2868	CB2872 to JS2868	42		10/21/2014	Pipe looks clean and in good condition.
606	138	649	Via Baron	23A	24" RCP	Line runs from CB in front of 6508 Via Baron to JS	SM-OSW-SD-CB2871-JS2868	CB2871 to JS2868	8.5		10/27/2014	Pipe looks clean and in good condition.
607	139	672	Arrowwood Ln.	23B	36" RCP & 36" CMP	Line runs from MH in front of property to OS on vacant lot next to 6124 PVDS (Firehouse)	SM-OSW-SD-MH0875-CB0874, SM-OSW-SD-GB0674-OS0673, SM-OSW-SD-MH0518-JS0524, SM-OSW-SD-JS0524-CB1919, SM-OSW-SD-GB1919-GB0517, SM-OSW-SD-GB0517-JS1918	MH0875 to OS0673	316.5		10/21/2014	Pipe looks clean and in good condition.
608	140	704	Dauntless Dr.	25C	30" RCP	Line runs from IS to JS in between Schooner and Vitor properties	SM-OSW-SD-MH0075-JS0076, SM-OSW-SD-JS0076-MH0074, SM-OSW-SD-MH0074-GB34125, SM-OSW-SD-GB34125-MH0082	JS0076 to JS1918	432		11/19/2014	Inspection abandoned at 432' due to pipe inclination. Line is clean and in good condition.
609	141	738	30534 Lucania Dr.	26C	18" CMP	Line runs from CB in front of property to MH behind 3227 Delina	SM-OSW-SD-CB0084-MH0083, SM-OSW-SD-MH0083-GB34118, SM-OSW-SD-GB34118-GB34119, SM-OSW-SD-GB34119-GB34120, SM-OSW-SD-GB34120-GB34121, SM-OSW-SD-GB34121-MH0082	CB0084 to MH0083	113		10/13/2014	Pipe looks clean and in good condition.
610	142	739	3227 Delina Dr.	26C	18" CMP	Line runs from MH on property's backyard to MH in front of 3224 Delina	SM-OSW-SD-MH0075-JS0076, SM-OSW-SD-JS0076-MH0074, SM-OSW-SD-MH0074-GB34125, SM-OSW-SD-GB34125-MH0082	MH0083 to MH0082	250		10/13/2014	Pipe looks clean and in good condition.
611	143	746	Crest Rd.	26C	36" CMP	Line runs from MH behind 3134 Corina to OS across Crest Rd.	SM-OSW-SD-MH0075-JS0076, SM-OSW-SD-JS0076-MH0074, SM-OSW-SD-MH0074-GB34125, SM-OSW-SD-GB34125-MH0082	MH0076 to OS0072	116		10/14/2014	Pipe has been lined previously. Line looks clean and in good condition.
612	144	748	Crest Rd.	26C	24" RCP	Line runs from CB to CB on Crest eastbound	SM-OSW-SD-CB34923-CB34924	CB0069 to CB0070	40		10/13/2014	Pipe looks clean and in good condition.
613	145	749	Crest Rd.	26C	30" RCP	Line starts from CB to CB on Crest eastbound	SM-OSW-SD-CB34924-CB0071	CB0070 to CB0071	36.5		10/13/2014	Pipe looks clean and in good condition.
614	146	750	Crest Rd.	26C	30" RCP	Line runs from CB to CB on Crest eastbound	SM-OSW-SD-CB0071-MH0073	CB0071 to MH0073	38		10/13/2014	Pipe looks clean and in good condition.
615	147	874	Peninsula Village Dr.	32A	18" RCP	Line starts at CB in front of property to MH on Peninsula Village Dr. at Western Ave.	SM-OSW-SD-CB0071-MH0073	CB0071 to MH0073	32.5		10/15/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
616	148	875	1802 Peninsula West Dr. at Western Ave.	32A	18" RCP	Line starts at CB in front of property to MH on Peninsula Verde Dr. at Western Ave.	ML-LAN-SD-CB216-MH0223	CB216 to MH0223	10		10/15/2014	Pipe looks clean and in good condition.
617	149	883	883 Dr. at Toscanini	33C	78" RCP	Line runs from JS on Toscanini (approx. 135' east of Western Ave.) to JS on Western Ave. at Toscanini	LA-LAE-SD-JS0149-JS2711	JS2711 to JS0149	229		10/15/2014	Pipe looks clean and in good condition.
618	150	386	2 Via Porto Grande	8D	24" RCP	Line starts at CB in front of property to MH in front of 8 Via Malona	SM-PWV-SD-CB2720-MH2722	CB2720 to MH2722	240		11/10/2014	Pipe looks clean and in good condition.
619	151	387	8 Via Malona	8D	18" RCP	Line starts at CB to MH in front of property	SM-PWV-SD-CB2721-MH2722	CB2721 to MH2722	18		11/10/2014	Pipe looks clean and in good condition.
620	152	388	8 Via Malona	8D	24" RCP	Line runs from MH in front of property to MH in front of 19 Via Malona	SM-PWV-SD-MH2722-MH2727	MH2722 to MH2727	286		11/10/2014	Pipe looks clean and in good condition.
621	153	389	19 Via Malona	8D	24" RCP	Line runs from MH in front of property to MH in front of 29 Via Malona	SM-PWV-SD-MH2727-MH2726	MH2727 to MH2726	160		11/10/2014	Pipe looks clean and in good condition.
622	154	390	30 Via Malona	8D	18" RCP	Line starts at CB in front of property to CB in front of 29 Via Malona	SM-PWV-SD-CB2724-CB2723	CB2724 to CB2723	36		11/7/2014	Pipe looks clean and in good condition.
623	155	391	29 Via Malona	8D	18" RCP	Line runs from CB in front of property to JS	SM-PWV-SD-CB2723-JS2725	CB2723 to JS2725	14		11/7/2014	Pipe looks clean and in good condition.
624	156	392	29 Via Malona	8D	30" RCP	Line runs from MH in front of property to MH on 2826 King Arthur Ct. backyard	SM-PWV-SD-MH2726-MH2719	MH2726 to MH2719	115		11/7/2014	Pipe looks clean and in good condition.
625	157	407	28762 Crestridge Rd.	13A	36" RCP	Line runs from MH in front of property to JS in the middle of the street	ML-RHE-SD-JS3488-MH3489	MH3489 to JS3488	13		11/6/2014	Pipe looks clean and in good condition.
626	158	409	28733 Crestridge Rd.	13A	36" RCP	Line runs from MH in front of property to JS approx. 305' east	ML-RHE-SD-GB3487-JS3488, ML-RHE-SD-MH1007-GB3487	MH1007 to JS3488	317		11/6/2014	Pipe looks clean and in good condition.
627	159	410	28730 Crestridge Rd.	13A	18" RCP	Line starts at CB to MH in front of property	ML-RHE-SD-CB 1008-MH1007	CB 1008 to MH1007	27		11/6/2014	Pipe looks clean and in good condition.
628	160	411	28733 Crestridge Rd.	13A	18" RCP	Line starts at CB to MH in front of property	ML-RHE-SD-CB 1009-MH1007	CB 1009 to MH1007	10		11/6/2014	Pipe looks clean and in good condition.
629	161	412	28705 Crestridge Rd.	13A	36" RCP	Line runs from MH in front of property to MH in front of 28733 Crestridge Rd.	ML-RHE-SD-MH1008-MH1007	MH1008 to MH1007	297		11/20/2014	Pipe looks clean and in good condition.
630	162	413	28641 Crestridge Rd.	13A	30" RCP	Line runs from MH in front of property to MH in front of 28705 Crestridge Rd.	ML-RHE-SD-GB3486-MH1006, ML-RHE-SD-MH1003-GB3486	MH1003 to MH1006	315		11/6/2014	Pipe looks clean and in good condition.
631	163	416	Crest Rd. at Crenshaw Blvd.	13A	18" Lined	Line starts at CB on Crest Rd. eastbound (approx. 580' from Crenshaw Blvd.) to CB across Crest Rd.	ML-RHE-SD-CB0997-CB0998	CB0997 to CB0998	240		11/11/2014	Pipe has been lined previously. Line is clean and in good condition.
632	164	425	PVOW at Alica	11A	18" RCP	Line runs from CB on PVOW northbound (approx. 115' north of Alica Pl.) to JS 30' south	SM-OWW-SD-CB1332-JS1333	CB1332 to JS1333	10		11/4/2014	Pipe looks clean and in good condition.
633	165	437	30026 Cuchan Pl.	12C	78" RCP	Line starts at CB in front of 30026 Cuchan Pl. to CB in front of 30025 Cuchan Pl.	SM-OWW-SD-CB1098-CB1099	CB 1098 to CB 1099	31		11/5/2014	Pipe looks clean and in good condition.
634	166	438	30025 Cuchan Pl.	12C	18" CMP	Line runs from CB in front of property to CB on Hawthorne Blvd. behind same property	SM-OWW-SD-CB1098-CB1098, SM-OWW-SD-CB1097-CB1100	CB 1098 to CB 1100	145		11/3/2014	Pipe has been lined previously. Pipe is clean and in good condition.
635	167	439.1	Hawthorne Blvd. at Crest Rd.	12C	18" Lined	Line runs from CB on Hawthorne (approx. 445' south from intersection) to MH on vacant lot behind Ralph's	SM-OWW-SD-JS48132-MH2719, SM-OWW-SD-JS48132-MH1101	CB 1100 to MH1101	91		11/3/2014	Pipe has been lined previously. Pipe is clean and in good condition.
636	168	441	Bld. at Crest Rd.	12C	36" RCP	Line runs from MH on vacant lot behind Ralph's to MH in front of 30135 Ave. Celestial	SM-OWW-SD-MH1101-CB3160, SM-OWW-SD-MH1101-CB3162	MH1101 to MH3162	408		11/3/2014	Pipe looks clean and in good condition.
637	169	442	30135 Ave. Celestial	11D	36" RCP	Line runs from MH in front of property to MH in front of 30107 Ave. Celestial	SM-OWW-SD-MH3162-JS3163, SM-OWW-SD-JS3163-MH3166	MH3162 to MH3166	238		11/4/2014	Pipe looks clean and in good condition.
638	170	443	30107 Ave. Celestial	11D	24" RCP	Line starts at CB in front of property to JS	SM-OWW-SD-CB3164-JS3163	CB3164 to JS3163	23		11/5/2014	Pipe looks clean and in good condition.
639	171	444	30107 Ave. Celestial	11D	18" RCP	Line starts at CB in front of property to MH	SM-OWW-SD-CB3165-MH3166	CB3165 to MH3166	12		11/4/2014	Pipe looks clean and in good condition.
640	172	446	30107 Ave. Celestial	11D	36" RCP	Line runs from MH in front of property to MH in front of 30134 Ave. Esplanada	SM-OWW-SD-MH3166-GB3167, SM-OWW-SD-JS3169-GB3170, SM-OWW-SD-GB3170-MH2627	MH3166 to MH2627	400		11/4/2014	Hard deposits starting from 300' to 345' ->5%. Pipe looks clean and in good condition.
641	173	447	Los Verdes Dr. at Ave. Esplanada	11B	18" RCP	Line runs from CB on Los Verdes (30156 Ave. Esplanada) to JS	PIPE FOUND	CB1118 to JS3519	34		11/5/2014	Pipe looks clean and in good condition.
642	174	448	Ave. at Sea Terrace	12D	18" RCP	Line starts at CB on Sea Terrace adjacent to 65 Seabreeze	SM-OSW-SD-CB2637-JS2639, SM-OSW-SD-CB2638-JS2639, SM-OSW-SD-JS2639-JS2640, SM-OSW-SD-JS2640-MH1080	CB2637 to JS2639	65		11/14/2014	Pipe looks clean and in good condition.
643	175	449	85 Seabreeze Ave.	12D	24" RCP	Line starts at CB in front of property to MH (approx. 300' west)	SM-OSW-SD-CB2642-JS2640	CB2642 to JS2640	297		11/14/2014	Pipe looks clean and in good condition.
644	176	450	70 Seabreeze Ave.	12D	18" RCP	Line starts at CB adjacent to 70 Seabreeze to JS	SM-OSW-SD-MH2645-GB2646, SM-OSW-SD-GB2646-MH1080	MH2645 to MH1080	20		11/14/2014	Pipe looks clean and in good condition.
645	177	451	Crest Rd. at Sea Terrace	12D	30" RCP	240' west of intersection) to MH adjacent to 70 Seabreeze			118		11/14/2014	Pipe looks clean and in good condition.
646	178	452	Via at Sea Terrace	12D	18" RCP	Line starts at CB on Seabreeze (approx. 210' west of Sea Terrace) to MH across the road	SM-OSW-SD-CB2641-MH1080	CB2641 to MH1080	30		11/14/2014	Pipe looks clean and in good condition.
647	179	453	Ave. at Sea Terrace	12D	36" RCP	Line runs from MH adjacent to 70 Seabreeze to OS	SM-OSW-SD-MH1080-GB2647, SM-OSW-SD-GB2647-JS2643	MH1080 to OS2643	75		11/14/2014	Pipe looks clean and in good condition.
648	180	455	21 Sea View Ave.	12D	18" RCP	Line starts at CB in front of property to JS	SM-OSW-SD-CB2626-JS2624	CB2626 to JS2624	36		11/10/2014	Pipe looks clean and in good condition.
649	181	456	20 Sea View Ave.	12D	24" RCP	Line runs from JS (approx. in front of 20 Seabreeze) to MH in front of 21 Sea View	SM-OSW-SD-JS2624-GB2623, SM-OSW-SD-GB2623-JS2622, SM-OSW-SD-JS2622-MH2621	JS2624 to MH2621	203		11/11/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 14

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
650	192	457	Sea View Ave. at Canal Ave.	120	18" RCP	Line starts at CB in front of property to JS	SM-OSW-SD-CB2620-JS2622	CB2620 to JS2622	26		11/14/2014	Pipe looks clean and in good condition.
651	193	458	Sea View Ave. at Canal Ave.	120	18" RCP	Line starts at CB on Canal Ave. adjacent to 27 Sea View to MH in front of 28 Sea View	SM-OSW-SD-CB2619-MH2621	CB2619 to MH2621	67		11/11/2014	Pipe looks clean and in good condition.
652	194	459	Sea View Ave. at Canal Ave.	120 & 198	24" RCP	Line runs from MH in front of 28 Sea View to MH in front of 34 Sea View	SM-OSW-SD-MH2621-MH2627	MH2621 to MH2627	278		11/11/2014	Pipe looks clean and in good condition.
653	195	460	34 Sea View Ave.	198	24" RCP	Line starts at CB in front of property to MH in the middle of the street	SM-OSW-SD-CB2628-MH2627	CB2628 to MH2627	21		11/14/2014	Pipe looks clean and in good condition.
654	196	461	34 Sea View Ave.	198	24" RCP	Line runs from MH in front of property to MH in front of 40 Sea View	SM-OSW-SD-MH2627-MH2629	MH2627 to MH2629	300		11/14/2014	Pipe looks clean and in good condition.
655	197	462	42 Sea View Ave.	198	30" RCP	Line starts at CB in front of property to TS	SM-OSW-SD-CB2631-TS2630	CB2631 to TS2630	5		11/14/2014	Pipe looks clean and in good condition.
656	198	463	40 Sea View Ave.	198	30" RCP	Line runs from MH in front of property to MH on easement	SM-OSW-SD-MH2631-TS2630	TS2630 to MH2632	127		11/14/2014	Pipe looks clean and in good condition.
657	199	476	51 Paseo De La Luz	20A	18" RCP	Line runs from MH in front of property to MH in front of 5 Via Del Cielo property	SM-OSW-SD-MH1722-SB1725	MH1722 to SB1725	464		10/22/2014	Pipe looks clean and in good condition.
658	190	477	5 Via Del Cielo	20A	18" RCP	Line runs from MH in front of property to OS down the hill	SM-OSW-SD-MH1726-SB1727	MH1726 to SB1727	555		10/22/2014	Pipe looks clean and in good condition.
659	191	484	Calle Coronada at Via Del Cielo	20A	18" RCP	Line starts at CB on Calle Coronada next to 30 Via Del Cielo to MH in the middle of the street of Calle Coronada	SM-OSW-SD-CB1634-MH1632	CB1634 to MH1632	18		10/23/2014	Pipe looks clean and in good condition.
660	192	485	Calle Coronada at Via Del Cielo	20A	18" RCP	Line starts at CB on Calle Coronada next to 32 Via Del Cielo to MH in the middle of the street of Calle Coronada	SM-OSW-SD-CB1634-MH1643	CB1634 to MH1643	18		10/23/2014	Pipe looks clean and in good condition.
661	193	486	Calle Coronada at Via Del Cielo	20A	48" RCP	Line runs from MH on Calle Coronada to MH in front of 33 Via Del Cielo	SM-OSW-SD-MH1632-SB1635	MH1632 to MH1637	77.5		10/23/2014	Pipe looks clean and in good condition.
662	194	487	33 Via Del Cielo	20A	48" RCP	Line runs from MH in front of property to MH on Calle Coronada behind 35 Via Del Cielo	SM-OSW-SD-MH1637-SB1639	MH1637 to MH1642	366		10/23/2014	Pipe looks clean and in good condition.
663	195	488	Enladrado behind 35 Via Del Cielo	20A	48" RCP	Line runs from MH on Calle Enladrado to MH behind 37 Via Del Cielo on Calle Enladrado	SM-OSW-SD-MH1642-MH1643	MH1642 to MH1643	123.5		10/22/2014	Pipe looks clean and in good condition.
664	196	489	Calle Enladrado behind 37 Via Del Cielo	20A	18" RCP	Line starts at CB on Calle Enladrado behind 37 Via Del Cielo to MH in the middle of Calle Enladrado	SM-OSW-SD-CB1645-MH1643	CB1645 to MH1643	12		10/22/2014	Pipe looks clean and in good condition.
665	197	490	Calle Enladrado behind 37 Via Del Cielo	20A	18" RCP	Line starts at CB on Calle Enladrado southbound to MH in the middle of Calle Enladrado	SM-OSW-SD-CB1644-MH1643	CB1644 to MH1643	14		10/22/2014	Pipe looks clean and in good condition.
666	198	495	30606 Via Rivera	20A	30" RCP	Line runs from MH in front of property to MH in front of 30706 Via Rivera	SM-OSW-SD-MH0635-JS1976	MH0635 to JS1976	572.5		10/23/2014	Pipe looks clean and in good condition.
667	199	495.1	Via Rivera at Rue de la Pierre	20A	30" RCP	Line runs from MH on Via Rivera at Rue de la Pierre to MH in front of 30653 Rue Valdes	SM-OSW-SD-MH0635-JS1976	MH0635 to MH0639	305		10/23/2014	Pipe looks clean and in good condition.
668	200	498.1	Avenida Selecta at Los Verdes	11D & 20B	30" RCP	Line runs from MH at corner of intersection to MH adjacent to Los Verdes northbound	SM-OSW-SD-MH1157-MH1158	MH1157 to MH1158	711		10/30/2014	Unmapped MH at 120', 343' and 572'. Pipe is clean and in good condition.
669	201	505	Esplanada	11D	18" RCP	Line starts at CB in front of 30186 Ave. Esplanada to MH	SM-OSW-SD-CB1117-MH1158	CB1117 to MH1158	14.5		11/5/2014	Pipe looks clean and in good condition.
670	202	506.1	Esplanada	20B	27" RCP	Line runs from MH at corner to MH in front of 30235 Ave. Selecta	SM-OSW-SD-MH1116-MH1157	MH1116 to MH1157	310		10/30/2014	Pipe looks clean and in good condition.
671	203	506.2	Esplanada	20B	27" RCP	Line runs from MH in front of 30242 Ave. Selecta to MH in front of 30244 Ave. Selecta	SM-OSW-SD-MH1157-MH1158	MH1157 to MH1158	187		10/30/2014	Pipe looks clean and in good condition.
672	204	510	Dr.	20D	42" RCP	Line runs from MH in the middle of the golf course to MH in the middle of the golf course	SM-OSW-SD-MH0741-JS13717	JS13717 to MH0734	316		11/5/2014	Pipe looks clean and in good condition.
673	205	511	Los Verdes Golf Course	20D	42" RCP	Line runs from MH behind 6767 Vallon Dr. (approx. 90' north of property) to TS adjacent to back property of 6767 Vallon Dr.	SM-OSW-SD-MH0734-JS0756	MH0734 to JS0756	290		11/5/2014	Pipe looks clean and in good condition.
674	206	512	Los Verdes Golf Course	20D	37" RCP	Line runs from MH in front of property to CB in front of 6423 Alta Vista Dr.	SM-OSW-SD-MH0734-JS0756	MH0734 to JS0756	455		11/5/2014	Pipe looks clean and in good condition.
675	207	516	Dr.	20B	18" RCP	Line runs from MH in front of property to CB in front of 6423 Alta Vista Dr.	SM-OSW-SD-CB0735-CB0736	CB0735 to CB0736	35		11/5/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 14

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
710	242	680	PVDS by St. Peter's By the Sea Church	23A	103	66" STL	Line runs from MH by the church driveway to MH in the southeast corner of church property	SM-OSW-SD-MH3550-CB3548, SM-OSW-SD-CB3549-MH3547	MH3550 to MH3547	291.5		10/20/2014	Pipe looks clean and in good condition.
711	243	681	PVDS by St. Peter's By the Sea Church	23A	103	18" RCP	Line runs from CB to MH in the southeast corner of church property	SM-OSW-SD-CB3548-MH3547	CB3548 to MH3547	18		10/17/2014	Pipe looks clean and in good condition.
712	244	682	PVDS by St. Peter's By the Sea Church	23A	103	66" STL	Line runs from MH in the southeast corner of church property to MH on Sea Gale Dr.	SM-OSW-SD-MH3547-MH3544	MH3547 to MH3544	404		10/20/2014	Pipe looks clean and in good condition.
713	245	683	Seagale Dr.	23A	103	18" RCP	Line runs from CB on Sea Gale southbound to MH on the road	SM-OSW-SD-CB3546-MH3544	CB3546 to MH3544	29		10/17/2014	Pipe looks clean and in good condition.
714	246	684	Seagale Dr.	23A	103	18" RCP	Line runs from CB on Sea Gale northbound to MH on the road	SM-OSW-SD-CB3545-MH3544	CB3545 to MH3544	11		10/17/2014	Pipe looks clean and in good condition.
715	247	685	Seagale Dr.	23A	103	66" STL	Line runs from MH to MH on Sea Gale northbound	SM-OSW-SD-MH3544-MH3543	MH3544 to MH3543	371		10/20/2014	Pipe looks clean and in good condition.
716	248	686	PVDS between Barkentine Rd. & Packet Rd.	23A	103	54" CMP	Line runs from MH on PVDS between Packet & Barkentine to MH in between 11 Barkentine & 12 Packet	SM-OSW-SD-MH0692-MH0690	MH0692 to MH0690	344		10/17/2014	Insert has been placed with concrete previously. Line is clean and in good condition.
717	249	688	PVDS between Barkentine Rd. & Packet Rd.	23A	103	54" CMP	Line runs from MH in between 19 Barkentine & 22 Packet to MH on Seacove Dr. off of Packet	SM-OSW-SD-MH0689-JS3320, SM-OSW-SD-JS3320-MH3528	MH0689 to MH3528	314.5		10/17/2014	Insert has been placed with concrete previously. Line is clean and in good condition.
718	250	689	Barkentine Rd. at Seacove Dr.	23A	104	18" RCP	Line runs from CB to CB in corner of street intersection	SM-OSW-SD-CB3534-CB3531	CB3534 to CB3531	6.5		10/21/2014	Pipe looks clean and in good condition.
719	251	670	Barkentine Rd. at Seacove Dr.	23A	104	18" RCP	Line runs from CB on Seacove at Barkentine to MH in front of 32 Seacove Dr.	SM-OSW-SD-CB3531-MH3532	CB3531 to MH3532	23		10/21/2014	Pipe looks clean and in good condition.
720	252	672	32 Seacove Dr.	23A	104	18" RCP	Line runs from CB to CB in front of property	SM-OSW-SD-CB3537-CB3536	CB3537 to CB3536	3		10/21/2014	Pipe looks clean and in good condition.
721	253	673	32 Seacove Dr.	23A	104	18" RCP	Line runs from CB in front of property to JS	SM-OSW-SD-CB3536-JS3535	CB3536 to JS3535	23		10/21/2014	Pipe looks clean and in good condition.
722	254	676	36 Seacove Dr.	23A	104	18" RCP	Line runs from CB to CB in front of property	SM-OSW-SD-CB0678-CB3530	CB0678 to CB3530	5		10/21/2014	Pipe looks clean and in good condition.
723	255	677	38 Seacove Dr.	23A	104	18" RCP	Line runs from CB in front of property to MH on Seacove	SM-OSW-SD-CB3530-MH3528	CB3530 to MH3528	26		10/21/2014	Pipe looks clean and in good condition.
724	256	679	36 Seacove Dr.	23A	105	54" RCP	Line runs from MH in front of property to MH in front of 42 Seacove	SM-OSW-SD-MH3528-CB3527, SM-OSW-SD-CB3527-MH3526	MH3528 to MH3526	255.5		10/21/2014	Pipe looks clean and in good condition.
725	257	680	42 Seacove Dr.	23A	105	18" RCP	Line runs from CB to MH in front of property	SM-OSW-SD-CB3529-MH3526	CB3529 to MH3526	14		10/29/2014	Pipe looks clean and in good condition.
726	258	682	Seacove Dr. cul-de-sac	23A	105	54" RCP	Line runs from CB at the end of Seacove cul-de-sac to MH on Sea Gale Dr.		MH3525 to Mainline	13		10/21/2014	Pipe looks clean and in good condition.
727	259	682.1	Seacove Dr. cul-de-sac	23A	105	54" RCP	Line runs from CB at the end of Seacove cul-de-sac to MH on Sea Gale Dr.	SM-OSW-SD-CB3524-MH3525	CB3524 to MH3525	75.5		10/21/2014	Pipe looks clean and in good condition.
728	260	683	Sea Gale Dr.	23A	105	66" STL	Line runs from MH to MH on Sea Gale northbound	SM-OSW-SD-MH3543-MH3525	MH3543 to MH3525	240		10/20/2014	Pipe looks clean and in good condition.
729	261	684	Sea Gale Dr.	23A	105	66" STL	Line runs from MH on Sea Gale northbound to MH on the road	SM-OSW-SD-MH3525-MH3539	MH3525 to MH3539	133.5		10/20/2014	Pipe looks clean and in good condition.
730	262	685	Sea Gale Dr.	23A	105	18" RCP	Line runs from the CB on Sea Gale next to 44 Seacove to CB across road	SM-OSW-SD-CB3540-CB3541	CB3540 to CB3541	36.5		10/24/2014	Pipe looks clean and in good condition.
731	263	688	Sea Gale Dr.	23A	105	21" RCP	Line runs from CB to CB on Seagale	SM-OSW-SD-CB0659-CB0657	CB0658 to CB0657	35		10/29/2014	Pipe looks clean and in good condition.
732	264	723	30101 Miraleste Dr.	26B	112	48" RCP	Line starts at IS behind property to MH in front of 30121 Miraleste	LA-LAS-SD-IS0240-MH3454	IS0240 to MH3454	201		10/14/2014	Pipe looks clean and in good condition.
733	265	724	30121 Miraleste Dr.	26B	112	48" RCP	Line runs from MH in front of property to OS across Miraleste Dr. down the canyon	LA-LAS-SD-MH3454-CB0238, LA-LAS-SD-CB0238-OS0237	MH3454 to OS0237	246		10/14/2014	Pipe looks clean and in good condition.
734	266	725	4363 Miraleste Dr.	26B	112	21" RCP	Line starts at CB in front of property to OS across the road	LA-LAS-SD-CB3453-OS3452	CB3453 to OS3452	133		10/14/2014	Pipe looks clean and in good condition.
735	267	742	3224 Deluna Dr.	26C	114	24" CMP	Line runs from MH in front of property to MH in front of 3134 Corinna	SM-OSE-SD-MH0082-MH04122, SM-OSE-SD-MH04122-GB00081, SM-OSE-SD-GB00081-GB3502, SM-OSE-SD-GB3502-MH0075, SM-OSE-SD-GB34123-GB34124, SM-OSE-SD-GB34124-MH0075	MH0082 to GB3502, GB3502 to MH0075, GB34123 to GB34124, GB34124 to MH0075	370		10/14/2014	Pipe has been lined previously. Line looks clean and in good condition.
736	268	743	3125 Corinna Dr.	26C	114	18" RCP	Line starts at CB in front of property to JS	SM-OSE-SD-CB00078-MH00075	CB0078 to JS00075	30		10/14/2014	Pipe looks clean and in good condition.
737	269	744	3126 Corinna Dr.	26C	114	18" RCP	Line starts at CB in front of property to MH in front of 3134 Corinna	SM-OSE-SD-CB00077-JS00076	CB0077 to MH0076	30		10/14/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
738	270	745	3134 Corina Dr.	26C	114	24" RCP & 24" CMP	Line starts at MH in front of property to MH on Crest property to OS behind 27625 Audara property to MH on Calabaz Dr.	SM-OSE-SD-MH0075-IS0076, SM-OSE-SD-JS0076-MH0074, SM-OSE-SD-MH0074-GB34126, SM-OSE-SD-GB34126-GB34126, SM-OSE-SD-GB34126-OS0077, SM-OSE-SD-MH0077-OS0077, SM-OSE-SD-MC190-MH0182	MH0182 to OS0077	218		10/14/2014	Pipe has been lined previously. Line looks clean and in good condition.
739	271	798	Alafra Dr.	15C	123	36" RCP	Line starts at OS behind 27625 Audara property to MH on Calabaz Dr.	SM-OSE-SD-MH0182-MC190-MH0182	IS0079 to MH0182	378.5		10/7/2014	Pipe looks clean and in good condition.
740	272	799	Calazas Dr.	15D & 33A	123	36" RCP	Line runs from MH in front of property to MH in front of 28102 Montevista Dr.	LAN-SD-MC193-GB1932, LAN-SD-GB1932-OS0181, LAN-SD-JS0181-MH0180	MH0182 to MH0180	339		10/7/2014	Pipe looks clean and in good condition.
741	273	800	Portavieja Dr.	33C	124	18" RCP	Line runs from CB in property corner to CB across property	LALAE-SD-CB0157-CB0159	CB0157 to CB0159	25.5		10/6/2014	Pipe looks clean and in good condition.
742	274	801	1802 Velaz Dr.	33C	124	21" RCP	Line runs from CB in property corner to MH in front of 28402 Portavieja	LALAE-SD-CB0159-MH0160	CB0159 to MH0160	98		10/6/2014	Pipe looks clean and in good condition.
743	275	804	1811 Santa Rena Dr.	33C	124	21" RCP	Line runs from CB in front of property to MH in front of 28402 Portavieja	LALAE-SD-CB0159-MH0160	CB0159 to MH0160	228		10/6/2014	Pipe looks clean and in good condition.
744	276	805	Bayard Dr.	34A	125	18" RCP	Line runs from CB at end of cul-de-sac to OS behind property	LALAE-SD-CB0045-GB41726, LALAE-SD-GB41726-GB41727, LALAE-SD-GB41727-GB41728, LALAE-SD-GB41728-OS0046	CB0045 to OS0046	210		10/8/2014	Pipe has been lined previously. Overall line is in good condition.
745	277	806	Homesworth Dr.	34A	125	18" RCP	Line runs from MH at end of cul-de-sac to OS behind property	LALAE-SD-CB0045-GB41726, LALAE-SD-GB41726-GB41727, LALAE-SD-GB41727-GB41728, LALAE-SD-GB41728-OS0046	CB0045 to OS0046	152		10/8/2014	Pipe has been lined previously. Line looks clean and in good condition.
746	278	807	Higmore Ave.	34A	125	18" RCP	Line runs from CB at cul-de-sac to OS behind 39302 Higmore Ave.	LALAE-SD-CB0045-GB41726, LALAE-SD-GB41726-GB41727, LALAE-SD-GB41727-GB41728, LALAE-SD-GB41728-OS0046	CB0045 to OS0046	147		10/8/2014	Pipe looks clean and in good condition.
747	279	810	Western Ave. at Park Dr.	34A	125	18" RCP	Line runs from CB in southeast corner of Western Ave. at Park Dr. to OS on Park View Dr.	LALAE-SD-CB0011-OS0009	CB0011 to OS0009	80		10/8/2014	Pipe looks clean and in good condition.
748	280	813	2006 Noble View Dr.	34C	126	18" RCP	Line starts at CB in front of property on Bayard Dr. to CB in front of 29444 Bayard Dr.	LALAE-SD-CB0019-CB0022	CB0019 to CB0022	68		10/8/2014	Pipe looks clean and in good condition.
749	281	814	29444 Bayard Dr.	34C	126	36" RCP & 36" CMP	Line runs from CB in front of property to JS in front of 1921 Upland St.	LALAE-SD-CB0022-GB0023, LALAE-SD-GB0023-JS3416	CB0022 to JS3416	106		10/9/2014	Pipe looks clean and in good condition.
750	282	815	29445 Bayard Dr.	34C	126	36" RCP	Line starts at CB in front of property on Upland St. side to CB across the road	PIPE FOUND	JS3416 to CB3420	45		11/17/2014	Pipe has been lined previously. Line looks clean and in good condition.
751	283	816	Crestwood St.	34C	126	18" RCP	Line starts at CB in front of property on Upland St. side to CB across the road	LALAE-SD-CB0017-CB3420	CB0017 to CB3420	38		10/9/2014	Pipe looks clean and in good condition.
752	284	819	29316 Higmore Ave.	34C	126	21" RCP	Line runs from CB in front of property to MH in property's backyard	LALAE-SD-CB0014-GB3421, LALAE-SD-GB3421-MH3423	CB0014 to MH3423	66		10/9/2014	Pipe looks clean and in good condition.
753	285	822	General St. at Bernice Dr.	34C	127	24" RCP	Line starts at CB on General southbound (approx. 120' west of Bernice Dr.) to CB across General St.	LALAE-SD-CB0006-CB0005	CB0006 to CB0005	37		10/9/2014	Pipe looks clean and in good condition.
754	286	825	1903 Summerland St.	34C	127	18" RCP	Line starts at CB in front of property to MH on Summerland St.	LALAE-SD-CB0002-CB0003, LALAE-SD-GB0003-MH1824	CB0002 to MH1824	225.5		10/9/2014	Pipe looks clean and in good condition.
755	287	826	1903 Summerland St.	34C	127	18" RCP	Line runs from MH by property's driveway to CB in property's parking lot	LALAE-SD-MH1924-GB1925, LALAE-SD-GB1925-CB1923	MH1924 to CB1923	86		10/9/2014	Pipe looks clean and in good condition.
756	288	827	Summerland St. at Western Ave.	34C	127	18" RCP	Line runs from CB in property's parking lot to MH on backyard	LALAE-SD-CB1923-JS1927	CB1923 to JS1927	100		10/9/2014	Pipe looks clean and in good condition.
757	289	827.1	Summerland St.	34C	127	36" RCP	Line runs from MH1928 in front of Eastview Townhouse Building to MH across Western Ave.	MH23128 to MH	MH23128 to MH	200		10/9/2014	Pipe looks clean and in good condition.
758	290	848	3266 Crownview Dr.	16C	132	18" RCP	Line runs from CB in front of property to CB in front of 3249 Crownview Dr.	LALAE-SD-CB0786-CB0787	CB0786 to CB0787	74		10/10/2014	Pipe looks clean and in good condition.
759	291	850	29005 Grandpoint Ln.	16C	132	18" RCP	Line runs from CB in front of property to JS across Grandpoint	LALAE-SD-CB0784-JS2704	CB0784 to JS2704	78.5		10/10/2014	Pipe looks clean and in good condition.
760	292	851	3140 Hillpoint Rd.	16C	132	24" RCP	Line runs from CB in front of property to OS in front of 29624 Grandpoint Ln.	LALAE-SD-CB0785-JS2704	CB0785 to JS2704	85.5		10/10/2014	Pipe looks clean and in good condition.
761	293	851.1	3140 Hillpoint Rd.	16C	132	24" RCP	Line runs from CB in front of property to OS in front of 29624 Grandpoint Ln.	LALAE-SD-JS2704-OS0783	JS2704 to OS0783	111		10/10/2014	Pipe looks clean and in good condition.
762	294	852	2933 Crownview Dr.	16C	133	18" RCP	Line runs from CB in front of property to CB across Crownview Dr.	LALAE-SD-CB0814-CB0815	CB0814 to CB0815	30.5		10/10/2014	Pipe looks clean and in good condition.
763	295	853	2908 Crownview Dr.	16C	133	18" RCP	Line runs from CB in front of property to OS behind property down the canyon	LALAE-SD-CB0815-GB3110, LALAE-SD-GB3110-GB3111, LALAE-SD-GB3111-GB3112, LALAE-SD-GB3112-OS0816	CB0815 to OS0816	553		10/10/2014	Pipe looks clean and in good condition.
764	296	855	29722 Grandpoint Ln.	16C	133	24" RCP	Line runs from CB in front of property to MH in property	LALAE-SD-CB0821-GB3114, LALAE-SD-GB3114-GB3117, LALAE-SD-GB3117-MH3115, LALAE-SD-MH3115-GB3116, LALAE-SD-GB3116-GB0819, LALAE-SD-GB0819-CB0820	CB0821 to MH3115	341		10/13/2014	Pipe has been lined previously. Line looks clean and in good condition.
765	297	858	29716 Knoll View Dr.	16C	133	24" RCP	Line runs from CB in front of property to OS behind property	LALAE-SD-CB0818-OS0817	CB0818 to OS0817	431		10/13/2014	Pipe has been lined previously. Line looks clean and in good condition.
766	298	860	Crownview Dr. at PVUE	16C	134	18" RCP	Line runs from CB adjacent to Calvalier's driveway to CB on the other side of same driveway	LALAE-SD-CB0812 to CB3123	CB3122 to CB3123	44		10/13/2014	Pipe looks clean and in good condition.

Storm Drain Video Inspection & Cleaning Services FY 13 -

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
767	299	861	Crownview Dr. at PVOE	16C	134	18" RCP & 18" CMP	Line runs from CB to OS in southwest corner of PVOE & Via Canada	LA-LAE-SD-CB0798-JS48535	CB3123 to OS3127	101		10/13/2014	Pipe looks clean and in good condition.
768	300	862	PVOE at Via Canada	16C	134	18" RCP	Line runs from CB in southwest corner of PVOE & Via Canada	LA-LAE-SD-CB0798-JS48535	CB3123 to OS3127	27		10/13/2014	Pipe looks clean and in good condition.
769	301	863	PVOE at Via Canada	16C	134	24" RCP	Line runs from CB in southwest corner of PVOE & Via Canada	LA-LAE-SD-CB0798-JS48535	CB3123 to OS3127	101		10/13/2014	Pipe looks clean and in good condition.
770	302	867	Crownview Dr. at PVOE	16C	134	18" RCP	Line runs from CB on PVOE southbound approx. 400' south of Crownview Dr. to OS across PVOE in the canyon	LA-LAE-SD-CB0804-OS0803	CB0804 to OS0803	69		10/16/2014	Pipe looks clean and in good condition.
771	303	873.1	Reservoir PVOE by Cal Water	16C	136	24" RCP	PVOE at Cal Water Reservoir property	LA-LAE-SD-CB0804-OS0803	IS to CB0793	1006			Unmapped structure at 824'. Overall pipe looks clean and in good condition.
772	304	873.2	Reservoir PVOE by Cal Water	16C	136	48" CMP	PVOE at Cal Water Reservoir property	LA-LAE-SD-CB0804-OS0803	IS to CB0793	170			Pipe looks clean and in good condition.
773	305	882	Western Ave. at Toscana	33C	140	30" RCP	Line starts at CB southeast corner of intersection to JS LA-LAE-SD-CB0141-JS0149	SM-OSS-SD-CB0320-JS3292	CB0141 to JS0149	56		11/17/2014	Pipe looks clean and in good condition.
774	306	633	Blvd. at Vallon	19C	98	48" CMP	Line starts at OS north of Vallon Dr. to CB across Hawthorne on line starts at OS north of Vallon Dr. to CB across Hawthorne on	SM-OSW-SD-CB0723-CB0721	CB0722 to CB0721	75		11/4/2014	Pipe looks clean and in good condition.
775	1	363	Basewood Dr.	4D	64	18" RCP	Basewood northbound	SM-PVN-SD-CB2773-MH2762	CB2773 to MH2762	5.5	6	17/2015	Pipe looks clean and in good condition.
776	7	406	Crestridge Rd.	13A	73	24" RCP	Line starts at CB in front of property to JS in the middle of the street	M-LRHE-SD-CB1010-JS3488	CB1010 to JS3488	22	22	17/2015	Pipe looks clean and in good condition.
777	13	467	View Rd.	13C	82	24" RCP	Line starts at CB on Crestridge Blvd. northbound (approx. 165' south of Valley View Rd.) to JS	SM-OSS-SD-CB0320-JS3292	CB3290 to JS3292	38	38	12/23/2014	Pipe looks clean and in good condition.
778	14	466	30006 Via Rivera	20A	85	27" RCP	Line runs from MH in front of property to IS on 30602	SM-OWW-SD-TS3389-MH3387, SM-OWW-SD-TS3384-TS3389, SM-OWW-SD-TS3395-TS3394, SM-OWW-SD-TS3392-TS3395	MH3387 to IS3392	210	245	12/23/2014	Pipe looks clean and in good condition.
779	15	509	Dr.	20B	87	42" CMP	Line runs from MH in front of property to JS	SM-OSW-SD-MH0758-MH0757, SM-OSW-SD-MH0757-JS1901	MH0758 to JS1901	497	497	11/5/2014	Pipe looks clean and in good condition.
780	21	596	PVDW Hawthorne	20C	93	30" RCP	Line runs from OS adjacent to PVDW approx. 640' south of Hawthorne to structure north of OS0076	SM-OSW-SD-MH0758-MH0757, SM-OSW-SD-MH0757-JS1901	MH0758 to JS1901	478.5	479	12/9/2014	Pipe looks clean and in good condition.
781	24	622	Blvd. by City	22B	96	18" RCP	Line starts at IS on median in front of City Hall bus stop	SM-OSW-SD-TS2605-CB2604, SM-OSW-SD-CB2604-MH2629	IS2605 to MH2629	200	200	15/2015	Pipe looks clean and in good condition.
782	28	696	Forestal Dr. at Forestal	25A	107	18" RCP	Line runs from CB to JS on Interp. Dr.	SM-OSE-SD-CB3201-JS3200	CB3201 to JS3200	3	3	15/2015	Pipe looks clean and in good condition.
783	30	698	Forestal Dr.	25A & C	108	18" RCP	Line runs from CB on Forestal northbound to JS	SM-OSE-SD-CB0520-JS2434	CB0520 to JS2434	12	12	16/2015	Pipe looks clean and in good condition.
784	31	699	Forestal Dr.	25A & C	108	18" RCP	Line runs from CB on Forestal southbound to JS	SM-OSE-SD-MH1537-MH1467, SM-OSE-SD-JS2435-MH0467	CB0521 to JS2435	3	3	16/2015	Pipe looks clean and in good condition.
785	36	736	30543 Santa Lina Dr.	26C	113	18" CMP	Line runs from CB in front of property to OS behind the property	LA-LAS-SD-CB0004-CB1904, LA-LAS-SD-CB0004-CB1904, LA-LAS-SD-CB1903-OS0055	CB0004 to OS0055	176	190	12/9/2014	Pipe looks clean and in good condition.
786	39	755	2738 Vista Mesa Dr.	26D	116	18" RCP	Line starts at CB in front of property to CB across the road	LA-LAS-SD-CB0794-CB0293	CB0294 to CB0293	23	23	12/4/2014	Pipe looks clean and in good condition.
787	41	757	2708 San Ramon Dr.	27A	116	24" RCP	Line starts at CB in front of property to CB across the cul-de-sac	SM-OSE-SD-CB0056-CB0300	CB0059 to CB0300	56	56	12/5/2014	Pipe looks clean and in good condition.
788	55	872	4240 Miraloma Dr.	16D	135	12" CMP	Line runs from CB in front of property to OS behind same property	LA-LAE-SD-CB0036-OS0835	CB0036 to OS0835	220	220	12/9/2014	Pipe looks clean and in good condition.
789	56	873	26669 Enrose Ave.	16D	135	18" CMP	Line starts at IS behind property to OS in front of 2166 General St.	LA-LAE-SD-IS0025-JS3411	IS0025 to OS0244-MH3411	185		12/9/2014	Inspection abandoned at IS due to pipe inclination, pipe seems to be clean and in good condition at the IS.
790	4	403	Hawthorne Blvd. at Indian Valley Rd.	12A	72	18" RCP	Line starts at CB in southeast corner to JS across Indian Valley Rd.	SM-PVV-SD-CB1428-JS2096	CB1428 to JS2096	30			Line 457 named incorrectly
791	11	454	20 Sea View Ave.	12D	80	18" RCP	Line starts at CB in front of property to JS	SM-OSW-SD-CB0825-JS2624	CB2625 to JS2624	30		12/19/2014	7777
792	49	820	29318 Highmore Ave. 30120 Ave. Esplanada	34C	126	36" RCP	Line runs from MH in property's backyard to OS on 29312 Highmore Ave. backyard	LA-LAE-SD-MH3423-JS3419	MH3423 to OS3419	50		No access	
793	49	820	29318 Highmore Ave. 30120 Ave. Esplanada	11D	78	18" CMP	Line runs from CB on property's backyard to JS	SM-OWW-SD-CB1168-JS1169	CB1168 to JS1169	15		No access	
794	49	820	29318 Highmore Ave. 30120 Ave. Esplanada	25C	107	UNKWN	Line starts at IS behind property to PC in front of 4343 Dauntless	SM-OSE-SD-IS0528-PC0527	IS0528 to PC0527	255		No US access & D/S curb outlet	
795	49	820	29318 Highmore Ave. 30120 Ave. Esplanada	20C	90	UNKWN	Line starts at IS adjacent to 9 Calle Viento to MH at intersection	SM-OWW-SD-IS1692-JS1691, SM-OWW-SD-JS1691-MH1685	IS1692 to MH1685	60		No access	
796	49	820	29318 Highmore Ave. 30120 Ave. Esplanada	20C	91	UNKWN	Line runs from IS in open space between driveway extension and trail to JS	SM-OWW-SD-IS1687-JS1688	IS1687 to JS1688	90		Cannot locate	
797	49	820	29318 Highmore Ave. 30120 Ave. Esplanada	20C	91	UNKWN	Line runs from MH to MH on open space	SM-OWW-SD-MH1674-MH1669	MH1669 to MH1674	145		Cannot locate	
798	49	820	29318 Highmore Ave. 30120 Ave. Esplanada	20C	91	UNKWN	Line starts at IS at end of the open channel behind 52 Pacifica Del Mar to MH in open space	SM-OWW-SD-IS1676-MH1674	IS1676 to MH1674	130		Cannot locate	
799	49	820	29318 Highmore Ave. 30120 Ave. Esplanada	20C	91	UNKWN	Line starts at IS adjacent to the open channel behind 52 Pacifica Del Mar to MH in open space	SM-OWW-SD-IS1675-MH1674	IS1675 to MH1674	80		Cannot locate	

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
800	8	544	PVDW between PVC & Parking Lot by Terraces	22B	100	UNKWN	Line runs from CB on PVDOS median westbound to CB across PVDOS		CB0557 to CB0555	60			Cannot locate
801	1	545	PVDW between PVC & Parking Lot by Terraces	22B	100	UNKWN	Line runs from CB on PVDOS median eastbound to OS down on the bluff		CB0555 to OS0556	40			Cannot locate
802	9	546	PVDOS at Bakerline Rd.	23A	102	18" CMP	Line starts at trail on PVDOS median eastbound and runs west of intersection to JS on PVDOS at Padrel Rd.	DNE	IS3427 to JS0680	90			Cannot locate
803	9	547	Seacove Dr. at PVDOS	23B	106	UNKWN	Line starts at IS in vacant lot (next to 9 Seacove) to OS in 8 Seacove	SM-OSW-SD-150670-OS0669	IS0670 to OS0669	100			No access
804	11	548	Interpied Dr. at Forestal	25A	107	UNKWN	Line runs from CB in the canyon west of Interpied Dr. to OS		CB0523 to ??				Cannot locate
805	11	549	Forestal Dr. at Forestal	25A	107	UNKWN	Line runs from CB in the canyon west of Interpied Dr. to OS		CB0522 to ??				Cannot locate
806	12	550	Danilest Dr.	25C	109	UNKWN	Line starts at IS between Ladera Linda Community Center and Danilest Dr.	DNE	IS0508 to Mainline	55			Cannot locate
807	12	551	4604 Beavrais	26B	112	UNKWN	Line runs from CB in front of property to OS behind same property	LA-LAS-SD-CB0252-OS0251	CB0252 to OS0251	200			No access
808	12	552	4604 Beavrais	16B	130	UNKWN	Line runs from CB in front of property to JS across Via De Arica		CB0651 to JS3404	200			Cannot locate
809	9	542	PVDW at Alda	11A	74	24" RCP	Line runs from CB on PVDW northbound (approx. 115' north of Alda Pl.) to MH on PVDW median		CB3132 to MH3462	80			
810	16	514	6852 Alta Vista Dr.	20D	87	UNKWN	Line runs from MH adjacent to property to MH in front of 6839 Alta Vista Dr.	DNE	MH0738 to MH0737	280			
811	17	515	6838 Alta Vista Dr.	20B	87	UNKWN	Line runs from MH to CB in front of property	DNE	MH0737 to CB0736	120			
812	26	578	38 Seacove Dr.	23A	104	54" CMP	Line runs from MH in front of property to OS on bluff behind property	SM-OSW-SD-JH3526-JS1618, PIPE FOUND	MH3528 to OS0688	305			
813	37	747	Crest Rd.	26C	114	UNKWN	Line starts at CB on Crest eastbound (approx. 1300' north of PVDOS) to CB	SM-OSE-SD-CB34922-CB34923	CB0068 to CB0069	40			
814	38	751	3001 Crest Rd.	26C	114	UNKWN	Line runs from CB in front of property to ??		CB0067 to ??				
815	1	544	30 Pacifica Del Mar	20C	90	UNKWN	Line runs from CB in front of property to MH on Pacifica Del Mar at Calle Viento	Repeat?	CB1663 to MH1665	40			There is no CB1663; it is a continuous line from MH1656 to MH1685
816	2	564	PVDW	20C	93	UNKWN	Line runs from IS adjacent to St. Paul's Lutheran Church out-of-use to OS across on PVDW	DNE	IS0580 to OS0591	625			Does not exist
817	3	567	PVDW	20C	93	UNKWN	Line runs from CB on PVDW (approx. 640' south of Hawthorne) to OS	DNE	CB0577 to OS0576	50			Does not exist
818	4	568	PVDW	20C	93	UNKWN	Line runs from CB on PVDW median (approx. 660' south of Hawthorne) to OS across PVDW southbound	DNE	CB0578 to CB0577	90			Does not exist
819	5	569	PVDW	20C	93	UNKWN	Line runs from MH on PVDW northbound (approx. 640' south of Hawthorne) to OS	DNE	MH2657 to CB0578	35			Does not exist
820	6	570	PVDW	20C	93	UNKWN	Line runs from MH on PVDW northbound (approx. 680' south of Hawthorne) to MH	DNE	CB0579 to MH2657	10			Does not exist
821	7	571	PVDW	20C	93	48" RCP	Line runs from MH on PVDW northbound (approx. 680' south of Hawthorne) to JS	DNE	MH2657 to JS2656	55			Does not exist
822	8	572	PVDW	20C	93	48" RCP	Line runs from MH on PVDW northbound (approx. 680' south of Hawthorne) to OS	DNE	MH2657 to OS2659	155			Does not exist
823	9	821	Hawthorne Blvd. by City	22B	96	UNKWN	Line runs from CB on Hawthorne northbound by City Hall bus stop to JS	DNE	CB2602 to JS2606	30			Does not exist
824	10	832	Hawthorne Blvd. at Valon Dr.	19C	98	UNKWN	Line starts at CB on northwest corner of intersection to CB	DNE	CB0723 to CB0722	40			Does not exist
825	11	705	Forestal Dr.	25C	109	UNKWN	Line starts at IS in hill east of Forestal to MH adjacent to the road	DNE	IS0511 to MH0689	390			Does not exist
826	12	513	6852 Alta Vista Dr.	20D	87	UNKWN	Line runs from MH adjacent to property to ??	DNE	MH0738 to ??				
827	22	501	Los Verdias Golf Course	20B	86	UNKWN	Line starts at CB on Los Verdias Dr. (approx. 160' north of golf course parking entrance) to ??	DNE	CB0630 to ??	77			Does not exist
828	1	404	Hawthorne Blvd. at Indian Valley Rd.	12A	72	42" RCP	Line starts at CB in front of 29457 Indian Valley Dr. to JS	SM-PWW-SD-CB1426-JS2096	CB1429 to JS2096	15			Same as line no. 149
829	2	417	Cresshaw Blvd.	13A	73	UNKWN	Line starts at CB on Crest Rd. westbound (approx. 580' from Cresshaw Blvd.) to OS on Cresting Rd.	ML-RHE-SD-CB0599-PO0599	CB0598 to PO0599				Continued with line no. 416
830	3	519	30546 Rhone Dr.	19A	88	18" CMP	Line runs from MH in property's backyard to OS in front of 30698 Canter Dr.	SM-OSW-SD-MH0510-CB0511, SM-OSW-SD-CB0512-OS0509	MH2510 to OS2609				Continued with line no. 518
831	4	529	Hawthorne Blvd. at Opere	20B	88	26" CMP	Line runs from CB road to median to MH across Hawthorne Blvd. by Ryan Park driveway entrance	SM-OSW-SD-150742-MH0737	CB0742 to MH0737	100			Continued with line no. 528
832	5	565	PVDW	20C	93	UNKWN	Line runs from OS adjacent to PVDW (approx. 640' south of Hawthorne) to OS in open space	PIPE FOUND	OS0576 to OS0581	415			Included in line no. 188

Storm Drain Video Inspection & Cleaning Services FY 13 - 1.

Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
833	6	575	PVDW	20C	30" CMP & 30" RCP	Line runs from CB on PVDW northbound (approx. 670' south of Hawthorne) to OS on PVDW southbound		CB2859 to OS2862	130			Same as line 572.1
834	7	652	PVDS 4300 Via	23A	48" CMP	Line starts CB on PVDS southbound (approx. 460' west of Bx Rd) to MH on PVDS (approx. 480' east of Bx Rd)	SM-OSW-SD-CB3426-MH0691	CB3426 to MH0691	60			Combined with line no. 651.
835	8	718	Frascati	26B	UNKWN	Line runs from CB on Via Frascati (approx. 50' north of PVE) to CB on PVE	LA-LAS-SD-CB0226-CB0224	CB0226 to CB0224	85			8" Riser
836	9	719	PVE at Via Frascati	26B	UNKWN	Line runs from CB on PVE at Via Frascati to OS down the canyon	LA-LAS-SD-CB0224-OS0225	CB0224 to OS0225	50			8" Riser
837	10	763	PVE	27C	UNKWN	Line runs from IS on PVDS (approx. 1800' east of PVE) to OS across PVDS	SM-OSE-SD-IS0650-OS0949	IS0650 to OS0949	100			Curb outlet
838	11	764	PVE	27C	UNKWN	Line runs from IS on PVDS (approx. 2200' east of PVE) to OS across PVDS	SM-OSE-SD-IS0952-OS0951	IS0952 to OS0951	100			Curb outlet
839	12	787	Dr.	26B	UNKWN	Line runs from CB at end of the cul-de-sac to MH at end of Cul de Sac		CB0308 to MH0307	60			Capped line
840	13	792	Dr.	28B	UNKWN	Line runs from MH to MH across the road	SM-OSE-SD-GB6524-IS2698, SM-OSE-SD-IS2697-GB6524	MH2697 to MH2698	65			Combined with line no. 791
841	14	793	Dr.	28B	UNKWN	Line runs from MH adjacent to the road to MH in the Golf Course	OSE-SD-GB6525-GB6520, SM-OSE-SD-GB6526-GB6527, SM-OSE-SD-GB6528-GB6527	MH2698 to MH1874	725			Combined with line no. 791
842	15	840	Treasure Pl.	16B	UNKWN	Line runs from CB in front of property to CB across the road in front of 8272 El Tesero	LA-LAE-SD-CB0662-CB0663	CB0662 to CB0663	30			8" Riser
843	16	841	6272 El	16B	UNKWN	Line runs from CB in front of property to JS across Via De Anzar	LA-LAE-SD-CB0663-JS0665	CB0663 to JS0665	110			8" Riser
844	17	842	3820 El Pl.	16B	UNKWN	Line runs from CB in front of property to OS down the canyon	LA-LAE-SD-CB0665-OS0665	CB0665 to OS0665	150			8" Riser
845	18	497	Ponderosa	20B	UNKWN	Line runs from CB on property's backyard to MH1121 in the middle of the golf park	LA-LAE-SD-CB1159-CB2245, SM-OHW-SD-MH1121-CB1159	CB0650 to OS0649	180			8" Riser
846	19	498	Park	20B	UNKWN	Line runs from MH adjacent to Los Verdes Dr. to MH in the middle of the golf course	SM-OHW-SD-MH1120-MH1121	MH1121 to CB2245	345			8" Riser
847	23	503	Los Verdes Dr. at Ave. Esplanada	11D	UNKWN	Line starts at CB on Los Verdes Dr. southbound to mainline	SM-OHW-SD-CB1119-JS3520, SM-OHW-SD-JS3519-JS3520, SM-OHW-SD-MH1158-JS3519	MH1120 to MH1121	450			8" Riser
848	24	574	PVDW by St. Paul's Church	20C	18" RCP	Line runs from CB on median (approx. 200' south from the north tip of median) to JS in median		CB1119 to JS3519	15			
849	25	578	Church	20C	24" RCP	Line runs from IS at the end of the cul-de-sac to JS	SM-OHW-SD-IS2746-JS2747	JS2746 to JS2747	50			
850	26	579	Via Capri	20C	24" RCP	Line starts at CB on Via Capri (2nd curve from Villa Capri gated entrance) to JS	SM-OHW-SD-CB2744-JS2745	CB2744 to JS2745	25			
851	27	580	Via Capri	20C	24" RCP	Line starts at CB on Via Capri (2nd curve from Villa Capri gated entrance) to JS	SM-OHW-SD-CB2742-JS2743	CB2742 to JS2743	25			
852	28	583	Via Capri Hawthorne	20D	18" RCP	Line runs from CB on Via Capri at Via Venta to JS south of Via Rivera) to CB across Hawthorne northbound	SM-OHW-SD-CB2737-JS2738	CB2737 to JS2738	15			
853	29	586	Rivera Hawthorne	20D	36" RCP	Line runs from MH in front of property to MH on Hawthorne (approx. 115' of Via Rivera) to JS	SM-OHW-SD-CB2807-CB2808	CB2807 to CB2808	40			
854	30	591	Rivera	20D	UNKWN	Line starts at CB behind property to JS		CB2851 to JS2860	10			
855	31	596	Mar	20D	18" ACP	Line starts at IS between 7065 & 7065 Via Del Mar to MH in the middle of Via Del Mar	SM-OHW-SD-CB2841-JS2842	CB2841 to JS2842	25			
856	32	597	Mar	20D	36" RCP	Line starts at IS off of Hawthorne southbound (approx. 615' northwest of City Hall driveway) to CB on Hawthorne southbound	SM-OHW-SD-IS2831-MH2836	IS2830 to MH2836	40			
857	33	604	Blvd. by City Hall	20D	UNKWN	Line runs from MH adjacent to Forrester northbound to MH west of the road	SM-OHW-SD-IS0582-CB0583	IS0582 to CB0583	40			
858	34	674	Orrilled	—	—	—	—	—	—			
859	36	702	Forrester Dr.	25A & C	30" RCP	Line runs from MH adjacent to Forrester northbound to MH west of the road	SM-OSE-SD-MH2435-GB2440, SM-OSE-SD-GB2440-MH3521	MH2439 to MH3521	135			
860	37	709	Pl.	25C	48" RCP	Line runs from IS on property to TS on Dauphines	SM-OSE-SD-IS0512-MH1912	IS0512 to TS1912	95			
861	38	710	3848 Pirate Dr.	25C	18" RCP	Line runs from IS behind property to MH in front of 3855 Pirate	SM-OSE-SD-IS0479-GB2134, SM-OSE-SD-GB2134-MH0480	IS0479 to MH0480	170			
862	39	733	Via Coluche at Via Ciega	26B	UNKWN	Line starts at CB in front of 6345 Via Colucha to OS behind 6352 Via Colucha and the road	LA-LAS-SD-CB0255-OS0256	CB0255 to OS0256	200			
863	40	734	30259 PVE	26B	UNKWN	Line starts at CB in front of property to OS across PVE and La Vista Verde	LA-LAS-SD-CB0119-OS0120	CB0119 to OS0120	220			
864	41	761	PVE at PVDs	27C	UNKWN	Line runs from IS on PVE (approx. 670' east of PVDs) to OS across PVE	SM-OSE-SD-IS0948-OS0947	IS0948 to OS0947	100			
865	42	762	PVE	27C	UNKWN	Line runs from IS on PVE (approx. 530' east of PVE) to OS across PVDS	SM-OSE-SD-IS4897-JS4896, SM-OSE-SD-JS4896-JS4899	IS0946 to OS0944	100			

Storm Drain Video Inspection & Cleaning Services FY 13 - 17

[illegible]

Storm Drain Video Inspection & Cleaning Services FY 13 - .													
Number of Segments (Phase I & II)	Number of Segments Per Grade Level	Line No.	Location Description	GIS Storm Drain Grid #	Storm Drain Map No.	Size of Pipe	Where in Roadway	RBF Drain Name	Starting Point to Ending Point	LF of Pipe Inspected (Approx.)	Pipe Length	Video Date	Comments
			Line has been video inspected (video not reviewed)										
			Line is in good condition										
			Light/minor defect condition										
			Moderate defect condition										
			Average defect condition										
			Heavy defect condition										
			Severe defect condition										
			Not able to locate in the field/Not able to inspect										
			Line does not exist										
			GIS update needed										

