



Reporting: 753 of 4367 Rcds

City of Rancho Palos Verdes
Rancho Palos Verdes ADA Assessment
Corrective Action Summary Report

Facility ID # 02B - City Hall Buildings



Author: Vaish, B

	Group Total Cost	-- Count --
Summary for Group 309 - Operable Parts:	\$53,160.00	108
Summary for Group 404 - Doors:	\$373,230.00	200
Summary for Group 405 - Ramps:	\$2,227.20	1
Summary for Group 407 - Elevators:	\$13,080.00	5
Summary for Group 504 - Stairways:	\$81,148.80	31
Summary for Group 603 - Toilet and Bathing Rooms:	\$147,150.00	123
Summary for Group 608 - Shower Compartments:	\$16,800.00	2
Summary for Group 702 - Alarms:	\$11,640.00	25
Summary for Group 703 - Signs:	\$12,960.00	70
Summary for Group 706 - Assistive Listening Systems:	\$22,800.00	5
Summary for Group 803 - Dressing, Fitting, and Locker Rooms:	\$600.00	1
Summary for Group 804 - Kitchens and Kitchenettes:	\$18,600.00	7
Summary for Group 902 - Dining Surfaces and Work Surfaces:	\$27,120.00	7
Summary for Group 904 - Check-Out Aisles and Sales and Service Counters:	\$7,200.00	3
Summary for Group 1700 - Miscellaneous:	\$26,130.00	165

DISCLAIMER: Costs are ESTIMATES! See full disclaimer statement at the end of this report.

Application: ©2010 BOA Architecture - 877-225-4ADA

Page 1 of 2

Printed 2013-05-09



Reporting: 753 of 4367 Rcds

City of Rancho Palos Verdes
Rancho Palos Verdes ADA Assessment
Corrective Action Summary Report

Facility ID # 02B - City Hall Buildings



Author: Vaish, B

Group Total Cost

-- Count --

Totals for All Groups:	\$813,846.00	753
-------------------------------	---------------------	------------

DISCLAIMER: Cost Factor calculates the full project cost where Construction Cost is based on an estimate of what a contractor may charge in 2011 to correct identified potential accessibility barriers. Cost Factors will vary and reflect variable delivery approaches. Please note that these reports do not include an assessment of concealed conditions. (Extended Costs)

DISCLAIMER: Costs are ESTIMATES! See full disclaimer statement at the end of this report.

Application: ©2010 BOA Architecture - 877-225-4ADA

Page 2 of 2

Printed 2013-05-09