



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 1 Bus Stops**



Reporting: 11 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

| # | Location                                   | Item Name  | Description   | 1991<br>ADAAG | 2004<br>ADAAG | 2007<br>CBC   | 2005<br>PROWA | Existing<br>Condition  | Use                     | Severity                      | Location Type                                    |
|---|--|--|---|---------------|---------------|---------------|---------------|--|-------------------------|-------------------------------|--|
| 1 | Silver Spur Rd./ Basswood Ave. (SB)        | 02.13A - Bus Stop Shelter - Clear Floor Area         | Clear floor area of 30" by 48" is not completely within the shelter.  | 10.2.1(2<br>) | 810.3         | 1121B.2<br>.1 |               | No WC space provided within the shelter.                     | PV - Public/Visitor Use | C - Partial Barrier to Access | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |
| 2 | Silver Spur Rd./ Basswood Ave. (SB)        | 02.17 - Other - Passenger Loading Zones              | See Additional Comments   | -             | -             | -             |               | Bench (16" high seat, 14" deep seat, 14" high back support). | PV - Public/Visitor Use | C - Partial Barrier to Access | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |
| 3 | Silver Spur Rd./ Basswood Ave. (SB)        | 02.17 - Other - Passenger Loading Zones              | See Additional Comments   | -             | -             | -             |               | 2.1% to 2.9% CS.   | PV - Public/Visitor Use | C - Partial Barrier to Access | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |
| 4 | Hawthorne Blvd./ Highridge Rd. (NB)        | 02.17 - Other - Passenger Loading Zones              | See Additional Comments   | -             | -             | -             |               | 3.0% CS.   | PV - Public/Visitor Use | C - Partial Barrier to Access | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |
| 5 | Hawthorne Blvd./ Grayslake Rd. (SB)        | 02.12B - Bus Stop Pad Slope Perpendicular to Roadway | Bus stop pad slope perpendicular to the roadway exceeds 2%.   | 10.2.1        | 810.2.4       | 1121B.2<br>.1 |               | 8% CS.   | PV - Public/Visitor Use | C - Partial Barrier to Access | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |
| 6 | Hawthorne Blvd./ Grayslake Rd. (SB)        | 02.11A - Bus Stop Pad Size                           | Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway). | 10.2.1        | 810.2.2       | 1121B.1       |               | Bus pad 6' long x 5' wide.                                   | PV - Public/Visitor Use | C - Partial Barrier to Access | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |
| 7 | Basswood Ave./ Silver Spur Elementary (WB) | 02.11A - Bus Stop Pad Size                           | Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway). | 10.2.1        | 810.2.2       | 1121B.1       |               | Bus pad 7'-1" long by 5' wide.                               | PV - Public/Visitor Use | C - Partial Barrier to Access | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 1 Bus Stops**



Reporting: 11 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

| #  | Location                              | Item Name                                    | Description  | 1991       | 2004  | 2007       | Existing PROWA Condition   | Use                     | Severity                            | Location Type                                    |
|----|---------------------------------------|--|--|------------|-------|------------|--|-------------------------|-------------------------------------|--|
|    |                                       |  |  | ADAAG      | ADAAG | CBC        |  |                         |                                     |  |
| 8  | Hawthorne Blvd./ Indian Peak Rd. (SB) | 02.17 - Other - Passenger Loading Zones      | See Additional Comments  | -          | -     | -          | Bench (16" high seat, 14" deep seat, 14 1/2" high back support).         | PV - Public/Visitor Use | E - Non-Mandated Access Improvement | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |
| 9  | Hawthorne Blvd./ Indian Peak Rd. (SB) | 02.17 - Other - Passenger Loading Zones      | See Additional Comments  | -          | -     | -          | 3.1% to 4.3% CS.   | PV - Public/Visitor Use | C - Partial Barrier to Access       | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |
| 10 | Hawthorne Blvd./ Highridge Rd. (NB)   | 02.13A - Bus Stop Shelter - Clear Floor Area | Clear floor area of 30" by 48" is not completely within the shelter. | 10.2.1(2 ) | 810.3 | 1121B.2 .1 | No WC space provided within the shelter.                                 | PV - Public/Visitor Use | C - Partial Barrier to Access       | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |
| 11 | Hawthorne Blvd./ Highridge Rd. (NB)   | 02.17 - Other - Passenger Loading Zones      | See Additional Comments  | -          | -     | -          | 2 benches provided, 0 accessible (17" high back support, 14" deep seat). | PV - Public/Visitor Use | C - Partial Barrier to Access       | 1 - Access into Facilities (28 CFR 36.304(c)(1)) |

Number of Key Notes for Group 02 - Passenger Loading Zone: 11

Number of Key Notes for Facility Area 1 Bus Stops: 11

Total Number of Key Notes for All Groups: 11