



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
 Facility ID # Area 2 Bus Stops



Reporting: 27 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
1	Hawthorne Blvd./ Ridgeway Dr.(NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench (16" high seat, 14" deep seat, 15" high back support).	PV - Public/Visitor Use	E - Non-Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))
2	Hawthorne Blvd./ Ridgeway Dr.(NB)	02.13A - Bus Stop Shelter - Clear Floor Area	Clear floor area of 30" by 48" is not completely within the shelter.	10.2.1(2)	810.3	1121B.2 .1		No WC space provided within the shelter.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
3	Hawthorne Blvd./ Granvia Altamira (SB)	02.12A - Bus Stop Pad Slope Parallel to Roadway	Bus stop pad is not at the same slope as the roadway in the direction parallel to the roadway.	10.2.1	810.2.4	1121B.2 .1		5.3% RS at bus pad , 3.2% RS at the road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
4	Hawthorne Blvd./ Granvia Altamira (SB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		3.3% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
5	Hawthorne Blvd./ Seamount Dr. (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 5' long x 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
6	Hawthorne Blvd./ Seamount Dr. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		4.0% to 4.5% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
7	Hawthorne Blvd./ Seamount Dr. (NB)	02.13A - Bus Stop Shelter - Clear Floor Area	Clear floor area of 30" by 48" is not completely within the shelter.	10.2.1(2)	810.3	1121B.2 .1		No WC space provided within the shelter.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
 Facility ID # Area 2 Bus Stops



Reporting: 27 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
8	Hawthorne Blvd./ Seamount Dr. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench (16" high seat, 14" deep seat, 15" high back rest).	PV - Public/Visitor Use	E - Non-Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))
9	Hawthorne Blvd./ Eddinghill Dr. (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 4' long x 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
10	Hawthorne Blvd./ Eddinghill Dr. (SB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		3.0% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
11	Hawthorne Blvd./ Verde Ridge Rd. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench (16" high seat, 14" deep seat, 14" high back support).	PV - Public/Visitor Use	E - Non-Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))
12	Hawthorne Blvd./ Verde Ridge Rd. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		2.5% to 2.8% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
13	Hawthorne Blvd./ Verde Ridge Rd. (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 6' long x 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
14	Hawthorne Blvd./ Hesse Park (SB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench (16" high seat, 14" deep seat, 14 1/2" high back support).	PV - Public/Visitor Use	E - Non-Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment  
 Compliance Report**  
 Facility ID # Area 2 Bus Stops



Reporting: 27 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
15	Hawthorne Blvd./ Hesse Park (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 5' long x 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
16	Hawthorne Blvd./ Hesse Park (SB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		2.6% to 3.6% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
17	Hawthorne Blvd./ Indian Valley Rd. (NB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		4.3% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
18	Hawthorne Blvd./ Indian Valley Rd. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench (16" high seat, 14" deep seat, 15" high back support).	PV - Public/Visitor Use	E - Non-Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))
19	Hawthorne Blvd./ Indian Valley Rd. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		3.0% to 4.3% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
20	Highridge Rd./ Hilltop Circle (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		76" headroom clearance to bus sign.	PV - Public/Visitor Use	A - Safety Hazard	1 - Access into Facilities (28 CFR 36.304(c)(1))
21	Highridge Rd./ Hilltop Circle (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		1 1/2" level change and gap at asphalt/ concrete transition.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
 Facility ID # Area 2 Bus Stops



Reporting: 27 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
22	Hawthorne Blvd./ Country Ln. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench (16" high seat, 14" deep seat, 15" high back support, no 12" shoulder alignment).	PV - Public/Visitor Use	E - Non-Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))
23	Hawthorne Blvd./ Country Ln. (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 5' long by 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
24	Hawthorne Blvd./ Country Ln. (NB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		2.2% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
25	Hawthorne Blvd./ Ocean Crest Dr. (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 4' long by 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
26	Hawthorne Blvd./ Ocean Crest Dr. (SB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		2.4% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
27	Highridge Rd./ Armaga Spring Rd. (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		None provided (grass).	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))

Number of Key Notes for Group 02 - Passenger Loading Zone: 27

Number of Key Notes for Facility Area 2 Bus Stops: 27

Total Number of Key Notes for All Groups: 27