



City of Rancho Palos Verdes
Rancho Palos Verdes ADA Assessment
Compliance Report
Facility ID # Area 3 Bus Stops



Reporting: 9 of 4367 Rcds

Author: Vaish, B

Group 02 - Passenger Loading Zone

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
1	Hawthorne Blvd./ Blackhorse Dr. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench (16" high seat, 14" deep seat, 15" high back support).	PV - Public/Visitor Use	E - Non-Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))
2	Hawthorne Blvd./ Blackhorse Dr. (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 4'-1" long x 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
3	Hawthorne Blvd./ Blackhorse Dr. (NB)	02.13A - Bus Stop Shelter - Clear Floor Area	Clear floor area of 30" by 48" is not completely within the shelter.	10.2.1(2)	810.3	1121B.2 .1		No WC space provided within the shelter.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
4	Hawthorne Blvd./ Blackhorse Dr. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		2.1% to 5.4% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
5	Hawthorne Blvd./ Blackhorse Dr. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		74" headroom clearance to bus shelter.	PV - Public/Visitor Use	A - Safety Hazard	1 - Access into Facilities (28 CFR 36.304(c)(1))
6	Silver Spur Rd./ Elkmont Dr. (NB)	02.12A - Bus Stop Pad Slope Parallel to Roadway	Bus stop pad is not at the same slope as the roadway in the direction parallel to the roadway.	10.2.1	810.2.4	1121B.2 .1		12.2% RS at bus pad , 10.6% RS at the road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
7	Silver Spur Rd./ Elkmont Dr. (NB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		2.9% to 3.4% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



Reporting: 9 of 4367 Rcds

City of Rancho Palos Verdes
Rancho Palos Verdes ADA Assessment
Compliance Report
 Facility ID # Area 3 Bus Stops



Author: Vaish, B

Group 02 - Passenger Loading Zone

#	Location	Item Name	Description	1991	2004	2007	Existing PROWA Condition	Use	Severity	Location Type
				ADAAG	ADAAG	CBC				
8	Silver Spur Rd./ Elkmont Dr. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-	Bench (10" - 21" high seat, 15" deep seat, 14 1/2" high back support).	PV - Public/Visitor Use	E - Non-Mandated Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
9	Silver Spur Rd./ Elkmont Dr. (NB)	02.13A - Bus Stop Shelter - Clear Floor Area	Clear floor area of 30" by 48" is not completely within the shelter.	10.2.1(2	810.3)	1121B.2 .1	No WC space provided within the shelter.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))

Number of Key Notes for Group 02 - Passenger Loading Zone: 9

Number of Key Notes for Facility Area 3 Bus Stops: 9

Total Number of Key Notes for All Groups: 9