



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 7 Bus Stops**



Reporting: 29 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
1	Palos Verdes Dr. S/ Ocean Trail Dr. (SB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop (planters).	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
2	Palos Verdes Dr. S/ Ocean Trail Dr. (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 3'-6" long by 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
3	Palos Verdes Dr. S/ Ocean Trail Dr. (SB)	02.12A - Bus Stop Pad Slope Parallel to Roadway	Bus stop pad is not at the same slope as the roadway in the direction parallel to the roadway.	10.2.1	810.2.4	1121B.2 .1		3.9% RS at bus pad , 3.8% RS at the road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
4	Palos Verdes Dr. S/ Ocean Trail Dr. (SB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		4.1% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
5	Ganado Dr./Flowerridge Dr. (SB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop (grass).	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
6	Ganado Dr./Flowerridge Dr. (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 3'-11" long by 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
7	Ganado Dr./Flowerridge Dr. (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		None provided.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 7 Bus Stops**



Reporting: 29 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
8	Ganado Dr./ Flowerridge Dr. (NB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
9	Ganado Dr./ Abrazo Dr. (SB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop (shrubs).	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
10	Ganado Dr./ Abrazo Dr. (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 4' long by 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
11	Ganado Dr./ Abrazo Dr. (SB)	02.12A - Bus Stop Pad Slope Parallel to Roadway	Bus stop pad is not at the same slope as the roadway in the direction parallel to the roadway.	10.2.1	810.2.4	1121B.2 .1		4.6% RS at bus pad , 5.2% RS at the road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
12	Ganado Dr./ Abrazo Dr. (SB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		2.1% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
13	Palos Verdes Dr. E/ Marymount College (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		3'-10" long by 5' wide Bus pad	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
14	Palos Verdes Dr. E/ Marymount College (NB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop (grass).	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 7 Bus Stops**



Reporting: 29 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
15	Palos Verdes Dr. E/ Marymount College (NB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		7.5% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
16	Palos Verdes Dr. E/ La Vista Verde Dr. (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		None provided.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
17	Palos Verdes Dr. E/ La Vista Verde Dr. (NB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
18	Palos Verdes Dr. E/ La Vista Verde Dr. (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		None provided.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
19	Palos Verdes Dr. E/ La Vista Verde Dr. (SB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
20	Ganado Dr. Switchback (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Not provided.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
21	Ganado Dr. Switchback (SB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1			PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 7 Bus Stops**



Reporting: 29 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
22	Ganado Dr. Switchback (SB)	02.12A - Bus Stop Pad Slope Parallel to Roadway	Bus stop pad is not at the same slope as the roadway in the direction parallel to the roadway.	10.2.1	810.2.4	1121B.2 .1		12% slope parallel to road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
23	Ganado Dr. Switchback (SB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		3.7% slope perpendicular to road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
24	Ganado Dr. Switchback (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Not Provided.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
25	Ganado Dr. Switchback (NB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1			PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
26	Ganado Dr. Switchback (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Not provided.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
27	Ganado Dr. Switchback (SB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1			PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
28	Ganado Dr. Switchback (SB)	02.12A - Bus Stop Pad Slope Parallel to Roadway	Bus stop pad is not at the same slope as the roadway in the direction parallel to the roadway.	10.2.1	810.2.4	1121B.2 .1		1.2% slope parallel to road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



Reporting: 29 of 4367 Rcds

*City of Rancho Palos Verdes*  
 Rancho Palos Verdes ADA Assessment  
 Compliance Report  
 Facility ID # Area 7 Bus Stops



Author: Vaish, B

Group 02 - Passenger Loading Zone

#	Location	Item Name	Description	1991	2004	2007	2005	Existing PROWA Condition	Use	Severity	Location Type
				ADAAG	ADAAG	CBC	PROWA				
29	Ganado Dr. Switchback (SB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		3.5% slope perpendicular to road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))

Number of Key Notes for Group 02 - Passenger Loading Zone: 29

Number of Key Notes for Facility Area 7 Bus Stops: 29

Total Number of Key Notes for All Groups: 29