



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 8 Bus Stops**



Reporting: 28 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
1	Palos Verdes Dr. E/ Conestoga Dr. (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		None provided.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
2	Palos Verdes Dr. E/ Conestoga Dr. (NB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
3	Palos Verdes Dr. E/ Conestoga Dr. (NB)	02.16 - Hazardous Vehicular Area	Where a walk crosses or adjoins the vehicular way and the walking surface is not separated by curbs, railings, or other elements between the pedestrian areas and vehicular areas, the boundary between the areas is not defined by a continuous detectable warning at least 36" wide complying with CBC 1121B.3.1 item 8(a). (i.e., the warning surface shall contrast visually with adjoining surfaces, either light on dark or dark on light, and shall differ from adjoining walking surfaces in resiliency or sound on cane contact. Color: yellow conforming to Federal Color No. 33538, Table IV/ Standard No. 595B. Where the color value contrast between the yellow warning and the main walking surface is less than 70 percent, a 1" wide black strip shall separate the yellow warning from the main walking surface.)	4.29.5	-	.5	1133B.8	No boundary between shoulder and road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
4	Palos Verdes Dr. E/ Mustang Rd. (SB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench (12" high seat, 14" deep seat, 14" high back support).	PV - Public/Visitor Use	E - Non- Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 8 Bus Stops**



Reporting: 28 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
5	Palos Verdes Dr. E/ Mustang Rd. (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 8' long by 3'-2" wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
6	Palos Verdes Dr. E/ Mustang Rd. (SB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
7	Palos Verdes Dr. E/ Mustang Rd. (SB)	02.16 - Hazardous Vehicular Area	Where a walk crosses or adjoins the vehicular way and the walking surface is not separated by curbs, railings, or other elements between the pedestrian areas and vehicular areas, the boundary between the areas is not defined by a continuous detectable warning at least 36" wide complying with CBC 1121B.3.1 item 8(a). (i.e., the warning surface shall contrast visually with adjoining surfaces, either light on dark or dark on light, and shall differ from adjoining walking surfaces in resiliency or sound on cane contact. Color: yellow conforming to Federal Color No. 33538, Table IV/ Standard No. 595B. Where the color value contrast between the yellow warning and the main walking surface is less than 70 percent, a 1" wide black strip shall separate the yellow warning from the main walking surface.)	4.29.5	-	.5	1133B.8	No boundary from bus stop to road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
8	Palos Verdes Dr. E/ Miraleste Library (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench ( 15" deep seat, 5" shoulder alignment).	PV - Public/Visitor Use	E - Non- Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 8 Bus Stops**



Reporting: 28 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
9	Palos Verdes Dr. E/ Miraleste Library (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 8' long by 4' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
10	Palos Verdes Dr. E/ Miraleste Library (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		7" drop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
11	Palos Verdes Dr. E/ Miraleste Library (NB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		2.3% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
12	Palos Verdes Dr. E/ Miraleste Library (SB)	02.12A - Bus Stop Pad Slope Parallel to Roadway	Bus stop pad is not at the same slope as the roadway in the direction parallel to the roadway.	10.2.1	810.2.4	1121B.2 .1		4.9% RS at bus pad , 3.8% RS at the road.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
13	Palos Verdes Dr. E/ Miraleste Library (SB)	02.12B - Bus Stop Pad Slope Perpendicular to Roadway	Bus stop pad slope perpendicular to the roadway exceeds 2%.	10.2.1	810.2.4	1121B.2 .1		2.3% CS.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
14	Palos Verdes Dr. E/ Miraleste Dr. (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench (16" high seat, 15 1/2" deep seat, 15 1/2" high back support).	PV - Public/Visitor Use	E - Non- Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))
15	Palos Verdes Dr. E/ Miraleste Dr. (NB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		None provided.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 8 Bus Stops**



Reporting: 28 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
16	Palos Verdes Dr. E/ Miraleste Dr. (NB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
17	Via Colinita/ Enrose Ave. (EB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		Bus pad 4' long by 5' wide.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
18	Via Colinita/ Enrose Ave. (EB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
19	Miraleste Dr./ Via Bramante (EB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Uneven surface at bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
20	Miraleste Dr./ Via Bramante (EB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
21	Miraleste Dr./ Via Bramante (EB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Car obstructs access to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
22	Palos Verdes Dr. E/ Via Canada (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Bench ( 14" deep seat, 16" high back support).	PV - Public/Visitor Use	E - Non-Mandated Access Improvement	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 8 Bus Stops**



Reporting: 28 of 4367 Rcds

Author: Vaish, B

**Group 02 - Passenger Loading Zone**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
23	Palos Verdes Dr. E/ Via Canada (NB)	02.13A - Bus Stop Shelter - Clear Floor Area	Clear floor area of 30" by 48" is not completely within the shelter.	10.2.1(2 )	810.3	1121B.2 .1		No WC space provided within the shelter.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
24	Palos Verdes Dr. E/ Via Canada (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		5 1/2" drop	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
26	Palos Verdes Dr. E/ Via Canada (NB)	02.17 - Other - Passenger Loading Zones	See Additional Comments	-	-	-		Uneven surface.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
27	Palos Verdes Dr. E/ Intermediate School (SB)	02.11A - Bus Stop Pad Size	Bus stop pad does not measure 8' long (measured from the curb or vehicle roadway edge) by 5' wide (measured parallel to the vehicle roadway).	10.2.1	810.2.2	1121B.1		None provided.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
28	Palos Verdes Dr. E/ Intermediate School (SB)	02.11B - Bus Stop Pad and Accessible Route	Bus stop pad is not connected to an accessible route.	10.2.1	810.2.3	1121B.1		No accessible route to bus stop.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))

Number of Key Notes for Group 02 - Passenger Loading Zone: 27

**Group 07 - Ramps**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
25	Palos Verdes Dr. E/ Via Canada (NB)	07.07A - Level Landings	Landings at the top or bottom of each ramp or each ramp run is not level (slope is greater than 2% in some or all directions).	4.8.4	405.7; 405.7.1	1133B.5 - .4.1		3.6% slope at top ramp landing.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))

Number of Key Notes for Group 07 - Ramps: 1



Reporting: 28 of 4367 Rcds

*City of Rancho Palos Verdes*  
Rancho Palos Verdes ADA Assessment  
Compliance Report  
Facility ID # Area 8 Bus Stops



Author: Vaish, B

---

---

---

Number of Key Notes for Facility Area 8 Bus Stops: 28

---

Total Number of Key Notes for All Groups: 28