



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**

**Reporting: 30 of 4367 Rcds**



**Facility ID # Area 7 Pedestrian Signals**

**Author: Vaish, B**

**Group 04 - Curb Ramps**

#	Location	Item Name	Description	1991	2004	2007	Existing PROWA Condition	Use	Severity	Location Type	
				ADAAG	ADAAG	CBC					
1	Palos Verdes Dr. East & Crest Rd.	04.40 - Other - Curb Ramps and Pedestrian Crossings	See Additional Comments	-	-	-	-	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))	
2	Palos Verdes Dr. East & Crest Rd.	04.24A - Audible Signal Device	A crosswalk with pedestrian signal indication does not have an audible signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2	PV - Public/Visitor Use	A - Safety Hazard	1 - Access into Facilities (28 CFR 36.304(c)(1))	
3	Palos Verdes Dr. East & Crest Rd.	04.24B - Vibrotactile Signal Device	A crosswalk with pedestrian signal indication does not have a vibrotactile signal device integrated into the signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))	
4	Palos Verdes Dr. East & Crest Rd.	04.32C - Push Button Size	The pedestrian signal push button is not a min.. 2" across in one dimension.	-	-	-	2005 PROWA G- R306.3. 3	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))	
5	Palos Verdes Dr. East & Crest Rd.	04.26A - Pedestrian Signal Device - Location versus Crosswalk Line	Location of pedestrian signal device is not within 5' of crosswalk line.	-	-	-	2006 Cal MUTCD- Sec. 4E- 09, Fig. 4E-2	7'-10" from crosswalk line. PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))	
6	Palos Verdes Dr. East & Crest Rd.	04.25 - Pedestrian Signal Device - Clear Floor Space	Location of pedestrian signal device does not accommodate a level 30" x 48" min.. clear space, centered and parallel to the pedestrian signal push button. (Accessible pedestrian signals shall be located so that the vibrotactile feature can be contacted from the level landing serving a curb ramp, if provided, or from a clear floor or ground space that is in line with the crosswalk line adjacent to the vehicle stop line.)	4.2.4	305.3; Fig. 305.3	1118B.4 item 1	2005 PROWA G- R306.2. 1	8.4%. 33.735678,-118.333444	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**

**Facility ID # Area 7 Pedestrian Signals**



**Reporting: 30 of 4367 Rcds**

**Author: Vaish, B**

**Group 04 - Curb Ramps**

#	Location	Item Name	Description	1991	2004	2007	Existing PROWA Condition	Use	Severity	Location Type	
				ADAAG	ADAAG	CBC					
7	Palos Verdes Dr. East & Crest Rd.	04.40 - Other - Curb Ramps and Pedestrian Crossings	See Additional Comments	-	-	-	Path of travel to pedestrian signal device is not provided.	PV - Public/Visitor Use	B - Severe or Complete Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))	
8	Palos Verdes Dr. East & Crest Rd.	04.32D - Push Button Contrast - Color Coding	The pedestrian signal push button does not contrast visually with its housing or mounting. (i.e., pedestrian signal push button is not identified by color coding immediately above the control button and consisting of a textured horizontal yellow band 2" wide and encircling the pole, and a 1" wide dark border band above and below this yellow band.)	-	-	1117B.5 .9	2005 PROWA G- R306.3. 3	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))	
9	Palos Verdes Dr. East & Crest Rd.	04.24A - Audible Signal Device	A crosswalk with pedestrian signal indication does not have an audible signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2	PV - Public/Visitor Use	A - Safety Hazard	1 - Access into Facilities (28 CFR 36.304(c)(1))	
10	Palos Verdes Dr. East & Crest Rd.	04.24B - Vibrotactile Signal Device	A crosswalk with pedestrian signal indication does not have a vibrotactile signal device integrated into the signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))	
11	Palos Verdes Dr. East & Crest Rd.	04.32C - Push Button Size	The pedestrian signal push button is not a min. 2" across in one dimension.	-	-	-	2005 PROWA G- R306.3. 3	1/2" diameter.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
12	Palos Verdes Dr. East & Crest Rd.	04.32A - Push Button Operating Effort	The force required to activate operable part(s) of pedestrian signal device exceeds 5 lbs.	4.27.4	309.4	1117B.6 item 4	2005 PROWA G- R306.3. 1; R405.4	6 LBF.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 7 Pedestrian Signals**



Reporting: 30 of 4367 Rcds

Author: Vaish, B

**Group 04 - Curb Ramps**

#	Location	Item Name	Description	1991	2004	2007	2005	Existing PROWA Condition	Use	Severity	Location Type
				ADAAG	ADAAG	CBC					
13	Palos Verdes Dr. East & Crest Rd.	04.25 - Pedestrian Signal Device - Clear Floor Space	Location of pedestrian signal device does not accommodate a level 30" x 48" min.. clear space, centered and parallel to the pedestrian signal push button. (Accessible pedestrian signals shall be located so that the vibrotactile feature can be contacted from the level landing serving a curb ramp, if provided, or from a clear floor or ground space that is in line with the crosswalk line adjacent to the vehicle stop line.)	4.2.4	305.3; Fig. 305.3	1118B.4 item 1	2005 PROWA G- R306.2. 1	2.5%.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
14	Palos Verdes Dr. East & Crest Rd.	04.32C - Push Button Size	The pedestrian signal push button is not a min.. 2" across in one dimension.	-	-	-	2005 PROWA G- R306.3. 3	1/2" diameter.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
15	Palos Verdes Dr. East & Crest Rd.	04.26A - Pedestrian Signal Device - Location versus Crosswalk Line	Location of pedestrian signal device is not within 5' of crosswalk line.	-	-	-	2006 Cal MUTCD-Sec. 4E-09, Fig. 4E-2	7'-4" from crosswalk line.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
16	Palos Verdes Dr. East & Crest Rd.	04.24B - Vibrotactile Signal Device	A crosswalk with pedestrian signal indication does not have a vibrotactile signal device integrated into the signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2		PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
17	Palos Verdes Dr. East & Crest Rd.	04.24A - Audible Signal Device	A crosswalk with pedestrian signal indication does not have an audible signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2		PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**  
**Facility ID # Area 7 Pedestrian Signals**



Reporting: 30 of 4367 Rcds

Author: Vaish, B

**Group 04 - Curb Ramps**

#	Location	Item Name	Description	1991	2004	2007	2005	Existing PROWA Condition	Use	Severity	Location Type
				ADAAG	ADAAG	CBC	PROWA				
18	Palos Verdes Dr. East & Crest Rd.	04.25 - Pedestrian Signal Device - Clear Floor Space	Location of pedestrian signal device does not accommodate a level 30" x 48" min.. clear space, centered and parallel to the pedestrian signal push button. (Accessible pedestrian signals shall be located so that the vibrotactile feature can be contacted from the level landing serving a curb ramp, if provided, or from a clear floor or ground space that is in line with the crosswalk line adjacent to the vehicle stop line.)	4.2.4	305.3; Fig. 305.3	1118B.4 item 1	2005 PROWA G-R306.2. 1	2.2% & 2.6%.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
19	Palos Verdes Dr. East & Crest Rd.	04.32D - Push Button Contrast - Color Coding	The pedestrian signal push button does not contrast visually with its housing or mounting. (i.e., pedestrian signal push button is not identified by color coding immediately above the control button and consisting of a textured horizontal yellow band 2" wide and encircling the pole, and a 1" wide dark border band above and below this yellow band.)	-	-	1117B.5 .9	2005 PROWA G-R306.3. 3	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))	
20	Palos Verdes Dr. East & Crest Rd.	04.40 - Other - Curb Ramps and Pedestrian Crossings	See Additional Comments	-	-	-	-	Path of travel to pedestrian signal device is not provided.	PV - Public/Visitor Use	B - Severe or Complete Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
21	Palos Verdes Dr. East & Crest Rd.	04.26A - Pedestrian Signal Device - Location versus Crosswalk Line	Location of pedestrian signal device is not within 5' of crosswalk line.	-	-	-	2006 Cal MUTCD-Sec. 4E-09, Fig. 4E-2	8'-8" from crosswalk line.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
22	Palos Verdes Dr. East & Crest Rd.	04.24A - Audible Signal Device	A crosswalk with pedestrian signal indication does not have an audible signal device to indicate the WALK interval.	-	-	-	2005 PROWA G-R306.2	PV - Public/Visitor Use	A - Safety Hazard	1 - Access into Facilities (28 CFR 36.304(c)(1))	



*City of Rancho Palos Verdes*  
**Rancho Palos Verdes ADA Assessment**  
**Compliance Report**

**Reporting: 30 of 4367 Rcds**



**Facility ID # Area 7 Pedestrian Signals**

**Author: Vaish, B**

**Group 04 - Curb Ramps**

#	Location	Item Name	Description	1991 ADAAG	2004 ADAAG	2007 CBC	2005 PROWA	Existing Condition	Use	Severity	Location Type
23	Palos Verdes Dr. East & Crest Rd.	04.32A - Push Button Operating Effort	The force required to activate operable part(s) of pedestrian signal device exceeds 5 lbs.	4.27.4	309.4	1117B.6 item 4	2005 PROWA G- R306.3. 1; R405.4		PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
24	Palos Verdes Dr. East & Crest Rd.	04.32C - Push Button Size	The pedestrian signal push button is not a min. 2" across in one dimension.	-	-	-	2005 PROWA G- R306.3. 3	1/2" diameter.	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
25	Palos Verdes Dr. East & Crest Rd.	04.24B - Vibrotactile Signal Device	A crosswalk with pedestrian signal indication does not have a vibrotactile signal device integrated into the signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2		PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
26	Palos Verdes Dr. East & Crest Rd.	04.24A - Audible Signal Device	A crosswalk with pedestrian signal indication does not have an audible signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2		PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
27	Palos Verdes Dr. East & Crest Rd.	04.40 - Other - Curb Ramps and Pedestrian Crossings	See Additional Comments	-	-	-	-		PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
28	Palos Verdes Dr. East & Crest Rd.	04.24B - Vibrotactile Signal Device	A crosswalk with pedestrian signal indication does not have a vibrotactile signal device integrated into the signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2		PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))
29	Palos Verdes Dr. East & Crest Rd.	04.24A - Audible Signal Device	A crosswalk with pedestrian signal indication does not have an audible signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2		PV - Public/Visitor Use	A - Safety Hazard	1 - Access into Facilities (28 CFR 36.304(c)(1))



Reporting: 30 of 4367 Rcds

*City of Rancho Palos Verdes*  
 Rancho Palos Verdes ADA Assessment  
**Compliance Report**  
**Facility ID # Area 7 Pedestrian Signals**



**Author: Vaish, B**

**Group 04 - Curb Ramps**

#	Location	Item Name	Description	1991	2004	2007	Existing PROWA Condition	Use	Severity	Location Type
				ADAAG	ADAAG	CBC				
30	Palos Verdes Dr. East & Crest Rd.	04.24B - Vibrotactile Signal Device	A crosswalk with pedestrian signal indication does not have a vibrotactile signal device integrated into the signal device to indicate the WALK interval.	-	-	-	2005 PROWA G- R306.2	PV - Public/Visitor Use	C - Partial Barrier to Access	1 - Access into Facilities (28 CFR 36.304(c)(1))

**Number of Key Notes for Group 04 - Curb Ramps: 30**

**Number of Key Notes for Facility Area 7 Pedestrian Signals: 30**

**Total Number of Key Notes for All Groups: 30**